





Motor Parts




36x
2780
Black




2x



2x
41896c01
Light Bluish Gray




1x
64782
Light Bluish Gray



4x
32184
Light Bluish Gray




2x




4x
32524
White




2x
40490
Dark Red



2x
32009
Blue



4x
32009
Yellow



2x
32525
Yellow






8x
43093
Blue





14x
6558
Blue

Bill of Materials



1





2





3




4





5




6



7






8





1x



9




10





11





12






13





14





15




16





17





18




19




20



21



22



23

