CE 0197

ISO9001 : 2000

XJ11D

Mercurial Sphygmomanometer

CE 0197

Sphygmomanometer (Model XJ11D) is a diagnostic instrument for taking human blood pressure. Before you start the apparatus, please read the operation instructions carefully for a proper and smooth operation during your clinic practice.

This product is manufactured to conform to the relevant part of EN 1060-1 and EN 1060-2 standards.

• NOTICE BEFORE TAKING BLOOD PRESSURE

1. The measuring procedure should be carried out under quiet circumstance.

2. Blood pressure of human being varies during different period of time every day . So please make sure to measure blood pressure at the same time each day.

3. In taking blood pressure, try to keep the patient as calm and relaxed as possible and please do not talk or move.

● PREPARATION BEFORE MEASURING

1. Put the unit horizontally. Open the cover and turn the lock at the mercury reservoir to the left. Check to see that the top of the reservoir column is at zero point.

2. Let the patient sit beside the table, put his arm on the table and keep relaxed. Adjust the position of arm so that the value can be measured with the cuff at the heart level.

3. The optimum bladder size is one with dimensions such that its width is 40% of the limb circumference at the center of

the range for each cuff size and that its length is 80% to 100% of the limb circumference at the center of the range for each cuff size. Please choose the proper size according to the patient's limb circumference.

4. Fasten the cuff on the patient's arm and locate the pulse with the center of the cuff. Please leave 30mm from arm joint to cuff. Don't fasten the cuff too tight. There should be space for one or two fingers.

5. Before inflating the cuff, please locate the pulse with a stethoscope.

6. Screw the screw cap on the rubber bulb and inflate the cuff gradually. Please start monitoring right now. Keep inflating till you could not hear the pulse. Then inflate 20—30mmHg more and stop inflating.

(1) Unscrew the screw cap on the rubber bulb. Discharge the air in the cuff at the speed of 2mmHg—4mmHg.
(2) During decreasing procedure, keep monitoring till the first time you hear the pulse. The top of reservoir column indicates the systolic pressure.
(3) Mercury will keep decreasing till pulse heard from stethoscope becomes muffled. The top of reservoir column indicates the diastolic pressure.

7. Generally, we take blood pressure for 2 to 3 times and get an average value.

● MAINTENANCE

1. Please keep the cuff clean. You are recommended to clean it with soft cloth and neutral detergent. To clean the outer case of the unit, please utilize ethanol cotton.

2. After each use, please tilt the unit rightward at about 45 degrees to enable the mercury to flow back completely to the reservoir and switch it off to keep the mercury from spilling during transportation.

3. Don't kink the rubber rube long. Avoid folding the cuff too small or leaving them in extremely hot place in order to prolong its life span.

4. Please keep the unit at stable place. Try to avoid tilting it or impacting it. Clean the unit and store it in dry place after use. (Humidity ≤ 85%, temperature:-20~70℃)

5. According to EN 1060-1, in order to keep its accuracy and safety, the sphygmomanometer should be checked once a year.

● WARNING ⚠

1. After each use, please tilt the unit rightward at about 45 degrees to enable the mercury to flow back completely to the reservoir and switch it off to keep the mercury from spilling during transportation.

2. If you detect that the pointer can not adjust to "0" or if there is something wrong with the product, please do not repair it by yourself. You are recommended to send it to Service or to leave it at the disposal of trained serviceman.

● OTHERS

As for the disposal of mercury, please refer to Annex A.

Annex A ⚠

Instructions for disposal of mercury:

1. Mercury-type sphygmomanometer should be handled with care. In particular, care should be taken to avoid dropping the instrument or treating it in any way that could result in damage to the manometer. Regular checks should be made to ensure that there are no leaks from the inflation system and to ensure that the manometer has not been damaged so as to cause a loss of mercury.

2. Please do not repair the unit by yourself, or damage may cause the loss of mercury. Exposure to mercury can have serious toxicological effects and do harm to your health. For more extensive repairs, the instrument should be securely packed with adequate padding,

sealed in a plastics bag or container, and returned to a specialist repairer.

3. When dealing with a mercury spillage, wear latex gloves. Collect all the small droplets of spilt mercury into one globule and immediately teamster all the mercury into a container, which should then be sealed. Any material contaminated with mercury should be sealed in a plastic bag before disposal in a refuse receptacle. Allow to dry and ventilate the area.