

Cross Functional Flow chart
Drilling Engineer
Engineering Manager
Operation Manager
SQC
MWD Coordinator
DD coordinator
Workshop Supervisor
Field Engineers
ICD
OFS Manager
VP
Finance
Sales Engineer
Start
Receive and check Data from client
Risk Assessment
Prepare Tool Order/ Send to Workshop Sup
Preparing Directional drilling Proposal
Review and confirm
Deliver the DD proposal to client
End
Inform Client
No
Decision
Yes
1
Approve the plan
Checking the equipment inspection and specification reports
Check the plan
Check Reports
Coordinate DDs and FEs
Check Reports
Prepare Manifest and Package
Receive Equipment / Maintenance
Directional Drilling Operation
Prepare ODR and other reports
Backload Equipment
1
Inform ICD
Prepare and Submit Invoice
1
Inform OFS Manager
1
Inform VP
1
Inform Finance
1
Inform Sales
End
Follow up to Finance