## NATIONWIDE MUTUAL FIRE INS

# Nationwide NWIDE NATIONWIDE IS ON YOUR SIDE P.O. BOX 182068 Columbus, OH 43218

Phone: (678) 428-1510 Fax: (877) 669-2181

Claim #: Workfile ID:

784291-GF-1 537eb491

# Supplement of Record 2 Summary

Written By: JUSTIN HARRIS, 2/21/2018 5:12:19 PM Adjuster: Harris, Justin, (678) 428-1510 Business

Insured: JOSEPH LORI

**OCLARE** 

Owner Policy #:

Claim #: 784291-GF-1

Type of Loss: PD - Property

Damage

Date of Loss: 08/16/2017 05:30 PM Days to Repair:

Point of Impact: 06 Rear Deductible:

Owner (Claimant): Inspection Location:

Russell Copeland Nash Chevrolet 2516 Bridgewater Dr Lawrenceville, GA 30046

Gainesville, GA 30506 Drive-in

Appraiser Information: Repair Facility:

harrj20@nationwide.com Lester's Paint & Body Shop, inc. (678) 428-1510

2118 Browns Bridge Rd Gainesville, GA 30501

(678) 865-7420 Evening

#### **VFHICLE**

2007 TOYO Tacoma Regular Cab Automatic 2D P/U 4-2.7L Gasoline EFI Blue

VIN: 5TENX22N97Z401997 License:

Production Date: Odometer:

03/2007 116461

Interior Color: Exterior Color: Gray

Blue

State: GA Condition:

TRANSMISSION

Tilt Wheel

SAFETY

PAINT

Automatic Transmission

Telescopic Wheel

Drivers Side Air Bag Passenger Air Bag

OTHER

Overdrive

RADIO AM Radio

Anti-Lock Brakes (4)

California Emissions

Clear Coat Paint

Power Steering Power Brakes

**POWER** 

FM Radio Stereo

**SEATS** Cloth Seats **TRUCK** Bedliner

CONVENIENCE

Search/Seek

**WHEELS** Styled Steel Wheels

Intermittent Wipers

CD Player

Claim #: 784291-GF-1 Workfile ID: 537eb491

# Supplement of Record 2 Summary

2007 TOYO Tacoma Regular Cab Automatic 2D P/U 4-2.7L Gasoline EFI Blue

Line			Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#		Rpr	SET UP AND MEASURE				2.0	
2	#	S01		PULL AND ALIGN FRAME		1		4.0 F	
3	#	S01	Rpr	Right frame rail				2.0	
				NOTE: Repair after pull					
4	CAB								
5	*	S01	Rpr	RT Side panel				<u>1.0</u>	2.0
				NOTE: BED HIT SIDE PANEL					
6		S01		Add for Clear Coat					0.8
7	#	S01	Refn	Base Color reduction/Full clear					-1.0
8	PICK	JP BOX							
9		S01	Repl	RT Side panel Regular Cab	6550004901	1	666.26	4.5	3.1
				NOTE: INTERNAL COMPONENTS OF	F BED ARE DAMAGED. O	UTER PAN	EL DMG JUSTIFIES	REPLACEMENT, I	PANEL
10		S01		Overlap Major Adj. Panel					-0.4
11		S01		Add for Clear Coat					0.5
12			R&I	RT Mud guard Regular Cab w/o PreRunner 2WD				0.2	
13			R&I	R&I tailgate assy				Incl.	
14	*	S02	Repl	RT Corner trim	6257104010	1	<u>33.47</u>		
15	**	S01	Repl	RECOND Nameplate "TOYOTA"	TT-0025	1	27.00	0.2	
16	*	S01	Rpr	Tail gate				<u>7.0</u>	2.0
				NOTE: Inner panel damaged and se	eam cracked				
17		S01		Overlap Major Adj. Panel					-0.4
18				Add for Clear Coat					0.3
19	#		Refn	Base color reduction with full clear					-0.5
20			R&I	Protector				0.2	
21	**	S01	Repl	RECOND Nameplate "TACOMA"	TT-0022	1	38.50	0.2	
22	*	S01	R&I	RT Inner panel				Incl.	
23			R&I	Handle				0.5	
24		S01	R&I	RT Wheelhouse liner				Incl.	
25		S01	R&I	R&I box assy				2.5	
26		S01	Repl	RT Protector	6624804020	1	81.43	0.4	
27	**	S01	Repl	A/M RT Wheelhouse liner grommet	1457513	6	3.42		
28	*	S01	Rpr	Rear cross sill				<u>6.0</u>	0.6
				NOTE: RIGHT LAMP POCKET AFTER	R PULL. DAMAGED BEHIN	ND BUMPE	R IN CENTER OF P	ANEL AS WELL	
29		S01	Repl	RT Lower molding	7563104010	1	33.47	0.2	
30	#	S01	R&I	Tool Box				1.5	
31	REAR	LAMPS							
32			R&I	RT Tail lamp assy				Incl.	
33				O/H rear bumper				1.8	

784291-GF-1 537eb491

# Supplement of Record 2 Summary

34			R&I	RT License lamp				Incl.	
35			R&I	LT License lamp				Incl.	
36	DEAG	R BUMPER		LT License lamp				IIICI.	
37	**	BUIVIPER	Repl	A/M NSF Bumper w/o SR5 package w/o X-Runner	TO1102241N	1	338.00	Incl.	
38	* *	S02	Repl	A/M Step pad	7106571	1	<u>129.00</u>	Incl.	
				NOTE: TO1191100 LKQ/KEYSTONE 770-504-7653					
39	**	S02	Repl	A/M LT Side plate	TO1146100	1	44.00	0.3	
40	**		Repl	Opt OEM Cover	5215904020	1	75.29	Incl.	
41	**		Repl	Opt OEM Reinforce bar	5204304010	1	184.88	Incl.	
42	**	S02	Repl	A/M NSF RT Corner reinf	TO1167115N	1	<u>32.00</u>	0.2	
43	*	S02	Repl	Cover outer seal	5259204010	1	<u>8.68</u>		
44	**	S02	Repl	A/M RT Side plate	7106573	1	<u>44.00</u>	0.3	
				NOTE: TO1147100 LKQ/KEYSTONE 770-504-7653					
45	*	S02	Repl	RT Arm	5201504010	1	<u>68.30</u>		
46	#		Subl	CAR COVER		1	5.00 T		
47	#		Subl	CORROSION PROTECTION		1	10.00 T		
48	**	S02	Repl	A/M LT Arm	7106562	1	<u>50.00</u>		
				NOTE: TO1067114N LKQ/KEYSTONE 770-504-7653					
49	OTHE	R CHARC	SES						
50	#			E.P.C.		1	3.00		
					SUBTOTALS		1,875.70	35.0	7.C

# **NOTES**

#### Estimate Notes:

\*\*\*\*\* FOR SUPPLEMENT REQUESTS CONTACT Justin Harris 678.428.1510 - DO NOT FAX SUPPLEMENT REQUESTS WITHOUT PRIOR APPROVAL.

\*\*\*\*\* ALL PARTS MUST BE SAVED FOR INSPECTION. ANY PARTS NOT AVAILABLE FOR PHOTOS WILL NOT BE INCLUDED ON THE SUPPLEMENT

OEM BED SELECTED, COST EFFECTIVE WHEN FIT/TRIM TIME CONSIDED FOR LKQ PANEL.

Shop advised that emblems selected are adhesive only

Contacted Gina with Alternative Emblems.

Confirmed Nameplates come with adhesive backing and peel off tape for application.

Confirmed yes-Phone number 866-462-3484

No search needed for rt coner trim and rt molding.

-----AM STEP PAD, AM-CORNER-NOT AVAIL THROUGH KSI-Karen 877-277-2787

LT/RT ARM-Shop ordered RT arm through Go-Part 2 seperate time and wrong part kept being delivered, photo of part attached.Left arm listed for 65.25 per Rachell-770-965-6400 not cost effective

OEM PRICE CHANGE FOR CORNER TRIM AND RT SEAL

Prior Damage Notes:

Prior Damage - Right bedside

784291-GF-1 537eb491

# Supplement of Record 2 Summary

2007 TOYO Tacoma Regular Cab Automatic 2D P/U 4-2.7L Gasoline EFI Blue

# **ESTIMATE TOTALS**

Category	Basis		Rate	Cost \$
Parts				1,857.70
Body Labor	31.0 hrs	@	\$ 44.00 /hr	1,364.00
Paint Labor	7.0 hrs	@	\$ 44.00 /hr	308.00
Frame Labor	4.0 hrs	@	\$ 65.00 /hr	260.00
Paint Supplies	7.0 hrs	@	\$ 30.00 /hr	210.00
Miscellaneous				15.00
Other Charges				3.00
Subtotal				4,017.70
Sales Tax	\$ 2,082.70	@	7.0000 %	145.79
Total Cost of Repairs				4,163.49
Deductible				0.00
Total Adjustments				0.00
Net Cost of Repairs				4,163.49

784291-GF-1 537eb491

## Supplement of Record 2 Summary

2007 TOYO Tacoma Regular Cab Automatic 2D P/U 4-2.7L Gasoline EFI Blue

# SUPPLEMENT SUMMARY

Line			Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
Chang	jed I tem	ıs							
14		S01	Repl	RT Corner trim	6257104010	1	-33.27		
14	*	S02	Repl	RT Corner trim	6257104010	1	33.47		
38	**		Repl	A/M Step pad	7106571	1	-115.36	Incl.	
38	**	S02	Repl	A/M Step pad	7106571	1	129.00	Incl.	
				NOTE: TO1191100 LKQ/KEYSTONE 770-504-7653					
39	**	S01	Repl	A/M LT Side plate	TO1146100	1	-40.70	-0.3	
39	**	S02	Repl	A/M LT Side plate	TO1146100	1	44.00	0.3	
42	**		Repl	A/M NSF RT Corner reinf	TO1167115N	1	-31.00	-0.2	
42	**	S02	Repl	A/M NSF RT Corner reinf	TO1167115N	1	32.00	0.2	
43			Repl	Cover outer seal	5259204010	1	-8.59		
43	*	S02	Repl	Cover outer seal	5259204010	1	<u>8.68</u>		
44	**		Repl	A/M RT Side plate	7106573	1	-41.20	-0.3	
44	**	S02	Repl	A/M RT Side plate	7106573	1	<u>44.00</u>	0.3	
				NOTE: TO1147100 LKQ/KEYSTONE 770-504-7653					
45	**		Repl	A/M RT Arm	7106561	1	-38.00		
45	*	S02	Repl	RT Arm	5201504010	1	<u>68.30</u>		
48	**	S01	Repl	A/M LT Arm	7106562	1	-38.00		
48	**	S02	Repl	A/M LT Arm	7106562	1	50.00		
				NOTE: TO1067114N LKQ/KEYSTONE 770-504-7653					
Delete	ed Items								
1	#			FOR SUPPLEMENT PLEASE CALL CHAD MEADOWS (770)713-0346		1			
					SUBTOTALS		63.33	0.0	0.0

#### **NOTES**

#### Estimate Notes:

\*\*\*\*\* FOR SUPPLEMENT REQUESTS CONTACT Justin Harris 678.428.1510 - DO NOT FAX SUPPLEMENT REQUESTS WITHOUT PRIOR APPROVAL.

\*\*\*\*\* ALL PARTS MUST BE SAVED FOR INSPECTION. ANY PARTS NOT AVAILABLE FOR PHOTOS WILL NOT BE INCLUDED ON THE SUPPLEMENT

OEM BED SELECTED, COST EFFECTIVE WHEN FIT/TRIM TIME CONSIDED FOR LKQ PANEL.

Shop advised that emblems selected are adhesive only

Contacted Gina with Alternative Emblems.

Confirmed Nameplates come with adhesive backing and peel off tape for application.

Confirmed yes-Phone number 866-462-3484

No search needed for rt coner trim and rt molding.

-----AM STEP PAD, AM-CORNER-NOT AVAIL THROUGH KSI-Karen 877-277-2787

LT/RT ARM-Shop ordered RT arm through Go-Part 2 seperate time and wrong part kept being delivered, photo of part attached. Left arm listed for 65.25 per Rachell-770-965-6400 not cost effective

784291-GF-1 537eb491

## Supplement of Record 2 Summary

2007 TOYO Tacoma Regular Cab Automatic 2D P/U 4-2.7L Gasoline EFI Blue

OEM PRICE CHANGE FOR CORNER TRIM AND RT SEAL

Prior Damage Notes: Prior Damage - Right bedside

## **TOTALS SUMMARY**

Category	Basis		Rate	Cost \$
Parts				63.33
Subtotal				63.33
Sales Tax	\$ 63.33	@	7.0000 %	4.43
Total Supplement Amount				67.76
NET COST OF SUPPLEMENT				67.76

#### CUMULATIVE EFFECTS OF SUPPLEMENT(S)

Estimate	2,124.00	CHAD MEADOWS
Supplement S01	1,971.73	JUSTIN HARRIS
Supplement S02	67.76	JUSTIN HARRIS
Workfile Total:	\$ 4,163.49	
NET COST OF REPAIRS:	\$ 4,163.49	

The limit of your coverage is the actual cash value of your auto or its damaged parts at the time of loss. Fair market value, age and condition of your damaged vehicle will be considered when determining the actual cash value of a loss. Certain parts lose value or depreciate because of age, condition, and/or wear and tear. Betterment is the increase in value of a vehicle or any of its parts as a result of replacing certain parts damaged in a loss. If the replacement of certain parts results in an increase in value to your vehicle or any of its parts, a deduction for betterment may be made to your loss payment to reflect the actual cash value you are owed under your policy.

CAPA=Certified Automotive Parts Association NSF=NSF International Certified Part AQRP = Assured Quality Replacement Parts

784291-GF-1 537eb491

## Supplement of Record 2 Summary

2007 TOYO Tacoma Regular Cab Automatic 2D P/U 4-2.7L Gasoline EFI Blue

\*

NOTIFICATION TO THIRD PARTY ABOUT IMPROPER USE OF INSURANCE PROCEEDS AS SET FORTH IN SECTION 33-7-11.1(C) OF THE OFFICIAL CODE OF GEORGIA ANNOTATED, AN INSURER THAT PREPARES A LOSS ESTIMATE MUST INCLUDE THE FOLLOWING NOTICE TO A THIRD PARTY WHEN MAKING PAYMENT FOR DAMAGE TO AN AUTOMOBILE FOR

ANY LOSS: FAILURE TO USE THE INSURANCE PROCEEDS IN ACCORDANCE WITH A SECURITY AGREEMENT BETWEEN YOU AND A LIENHOLDER, IF ANY, MAY BE A VIOLATION OF CODE SECTION 16-8-4 OF THE O.C.G.A. IF YOU HAVE ANY QUESTIONS, CONTACT YOUR LENDING INSTITUTION. SECTION 16-8-4 CROSS-REFERENCED ABOVE IS ACTUALLY THE THEFT BY CONVERSION STATUTE. IT SHOULD BE NOTED, TOO, THAT THE NOTICE PRESCRIBED ABOVE DOES NOT

HAVE TO BE PRINTED ON A LOSS ESTIMATE TO A THIRD PARTY IF SOMEONE OTHER THAN THE INSURER PREPARED THE ESTIMATE OR IF THE ESTIMATE WAS PREPARED OUTSIDE THE STATE OF GEORGIA.

NOTICE TO THIRD PARTY CLAIMANTS: Failure to use the insurance proceeds in accordance with a security agreement between you and a lienholder, if any, may be a violation of Code Section 16-8-4 of the O.C.G.A. If you have any questions, contact your lending institution.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. THE AFTER MARKET CRASH PARTS USED IN THE PREPARATION OF THIS ESTIMATE ARE WARRANTED BY THE MANUFACTURER OR DISTRIBUTOR OF SUCH PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

Nationwide will replace any defective Like Kind and Quality (Used), Reconditioned, and any Aftermarket (non-OEM) parts as specified on the appraisal for as long as you own or lease the vehicle.

784291-GF-1 537eb491

## Supplement of Record 2 Summary

2007 TOYO Tacoma Regular Cab Automatic 2D P/U 4-2.7L Gasoline EFI Blue

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ARM8512, CCC Data Date 2/14/2018, and potentially other third party sources of data; and (b) the parts presented are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may reflect some specific, special, or unique pricing or discount. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2017 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

#### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

#### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

# OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

784291-GF-1 537eb491

# Supplement of Record 2 Summary

2007 TOYO Tacoma Regular Cab Automatic 2D P/U 4-2.7L Gasoline EFI Blue

# ALTERNATE PARTS SUPPLIERS

Line	Supplier	Description	Price
15	Alternative Emblems	#TT-0025	\$ 27.00
	1812 Mt. Carmel Church Rd	RECOND Nameplate "TOYOTA"	
	Chapel Hill NC 27517	Quote: 223464253	
	(866) 462-3484	Expires: 02/14/18	
21	Alternative Emblems	#TT-0022	\$ 38.50
	1812 Mt. Carmel Church Rd	RECOND Nameplate "TACOMA"	
	Chapel Hill NC 27517	Quote: 223464253	
	(866) 462-3484	Expires: 02/14/18	
27	Kent Automotive	#1457513	\$ 0.57
	Customer Service	A/M RT Wheelhouse liner grommet	
	8770 W. Bryn Mawr		
	Chicago IL 60631		
	(888) 937-5368		
37	KEYSTONE - ATLANTA, GA	#TO1102241N	\$ 338.00
	1700 WESTGATE PARKWAY SOUTHWEST	A/M NSF Bumper w/o SR5 package w/o X-Runner	
	ATLANTA GA 30336	Quote: 162804490	
	(404) 691-6930	Expires: 12/21/17	
38	KSI-Atlanta, GA(Crash & Rust)	#7106571	\$ 129.00
	Willie Niles	A/M Step pad	
	2861 Bankers Industrial Drive		
	Atlanta GA 30360		
	(877) 277-2787		
39	Go-Parts (FedEx)	#TO1146100	\$ 44.00
	1050 CAMBRIDGE SQ STE C	A/M LT Side plate	
	ALPHARETTA GA 30009	Quote: 333q-945706-8102	
	(770) 965-6400	Expires: 02/14/18	
40	Automotive Alliance-FLORIDA	#5215904020	\$ 75.29
	4050 NW 126 Ave, suite 100	Opt OEM Cover	
	Coral Springs FL 33065	Quote: 4749994	
	(954) 742-7661	Expires: 11/16/17	
41	Automotive Alliance-FLORIDA	#5204304010	\$ 184.88
	4050 NW 126 Ave, suite 100	Opt OEM Reinforce bar	
	Coral Springs FL 33065	Quote: 4749994	
	(954) 742-7661	Expires: 11/16/17	
42	Hayes Wholesale Parts	#TO1167115N	\$ 32.00

784291-GF-1 537eb491

# Supplement of Record 2 Summary

2007 TOYO Tacoma Regular Cab Automatic 2D P/U 4-2.7L Gasoline EFI Blue CHUCK GARNER A/M NSF RT Corner reinf 719 PIKE ST LAWRENCEVILLE GA 30045 (770) 963-6263 44 KSI-Atlanta, GA(Crash & Rust) #7106573 \$ 44.00 Willie Niles A/M RT Side plate 2861 Bankers Industrial Drive Atlanta GA 30360 (877) 277-2787 KSI-Atlanta, GA(Crash & Rust) #7106562 48 \$ 50.00 Willie Niles A/M LT Arm 2861 Bankers Industrial Drive Atlanta GA 30360 (877) 277-2787