

Thermal inspection report: MCC-2 AG-4B34

L2 terminal 74.2 C; L1 41.8 C; load 82 percent