How to Update Your X360USB PRO (Fix PhatKey Failed Verification Error!)


I am making this because from what I have seen there are quite a few people receiving the "PhatKey Failed" error. This is an error when, in JF, you receive the "Extraction Complete" dialog after probing a LiteOn. After using my X360USB PRO a while back, I had this error and had no idea how to fix it. However, it is easily fixed by updating your USB PRO firmware.

Things you will need:

- Your X360USB PRO
- New firmware
- Update tool

Step 1:

Extract the files to somewhere on your computer. Then open the update tool. It should look something



like this:

Step 2:

Turn the switch on your USB PRO to ON and press reset. This enables the new firmware to be written to it.

Step 3:

Load your firmware into the update tool and press update. While it is updating, turn the switch back to OFF. When it is finished updating, the tool will automatically reset.

Enjoy! If I was not specific enough at some point, please tell me and I will update it. Again, I know this is a simple process, but I am posting it because it will fix the "PhatKey Failed Verification" error.

Leave the XUSBPRO in the OFF position, the ON position is only for firmware updates.	