
test of a new configuration
re-test
true utility of the incumbent
measured / true utility
(% of optimum)
100
90
80
70
60
50
40
20
40
60
80
100
test number (live testbed)
knobs of the incumbent configuration (dark = on)
knob
F1alt
F2alt
F3alt
F4alt
F5alt
PRalt
meterF1
meterF2
sleepS4
sleepS23
20
40
60
80
100
test number (live testbed)