THE HONG KONG INSTITUTE OF SURVEYORS QUANTITY SURVEYING DIVISION ASSESSMENT OF PROFESSIONAL COMPETENCE FINAL ASSESSMENT – 17TH & 18TH SEPTEMBER 2014 PRACTICE PROBLEMS / PART II WRITTEN TEST NOTES TO ASSESSORS



Question No. 1 - Cost Estimate

NOTES TO ASSESSORS

Attachment A

Upgrading the podium façade by replacing all existing wall tiles (approximate façade area 1,000 m2)

	Qty Unit	Rate	HK\$	
Take down existing wall tiles (1000m2 less glass area say 30%) [The PQS should verify the quantity before any reply to the Owner]	700 m2	100	70,000	/
Prepare surface to receive new tiles including applying waterproofing and screeding	700 m2	350	245,000	/
Supply and install new wall tiles (Supply only \$300/m2)	700 m2	550	385,000	/
Scaffolding and protection	1000 m2	300	300,000	/
Preliminaries (15%)			150,000	/
Contingencies (10%)			115,000	/
	Total	HK\$	1,265,000	/
	round Say	HK\$	1,300,000	/
		arith	metical	

assumption, exclusion, items for clarification

Items for clarification should include:

- · Wall tile specification
- · Survey on existing substrate condition may be required to estimate the extent of preparation work
- · Extent of scaffolding and protection

A list of assumptions, exclusions and items for clarification is required.

VE - upgrade unit mix (2014)

THE HONG KONG INSTITUTE OF SURVEYORS QUANTITY SURVEYING DIVISION ASSESSMENT OF PROFESSIONAL COMPETENCE FINAL ASSESSMENT – 17TH & 18TH SEPTEMBER 2014 PRACTICE PROBLEMS / PART II WRITTEN TEST NOTES TO ASSESSORS



Question No. 1 - Cost Estimate

NOTES TO ASSESSORS

Attachment B

Upgrading th	e interior of all existing 150 no. apartment units				
		Past Project (Base) HK\$	Studio HK\$	1-Bedroom HK\$	2-Bedroom HK\$
<u>Doors</u> Studio	\$20,000 less one bedroom door say \$5,000 = \$15,000	20,000	15,000	20,000	30,000
2-bedroom	\$20,000 add two doors say \$5,000 x 2 no. = \$30,000	(90)			
	hange to layout and no new quired. Allow for making good under "Additiona	20,000 I Items"		•	
Floor finishes Studio 2-bedroom	<u>- Bedroom, living room</u> \$40,000 x 24m2 / 52m2 = \$18,461 \$40,000 x 77m2 / 52m2 = \$59,231	40,000	18,500	40,000	59,200
Floor finishes Studio 2-bedroom	- Bathroom Same as 1-bedroom \$10,000 x 2	10,000	10,000	10,000	20,000
Wall finishes Studio 2-bedroom	- <u>Bedroom, living room</u> \$30,000 / 2 \$30,000 x 3/2	30,000	15,000	30,000	45,000
Wall finishes Studio 2-bedroom	- <u>Bathroom</u> Same as 1-bedroom \$30,000 x 2	30,000	30,000	30,000	60,000

THE HONG KONG INSTITUTE OF SURVEYORS QUANTITY SURVEYING DIVISION ASSESSMENT OF PROFESSIONAL COMPETENCE FINAL ASSESSMENT – $17^{\rm TH}_{\rm A}$ & $18^{\rm TH}_{\rm SEPTEMBER}$ 2014 PRACTICE PROBLEMS / PART II WRITTEN TEST NOTES TO ASSESSORS



Question No. 1 - Cost Estimate

NOTES TO ASSESSORS

Attachment B

Upgrading the	interior of all existing 150 no. apartment units	Past Project (Base) HK\$	Studio HK\$	1-Bedroom HK\$	2-Bedroom HK\$
Ceiling finishe Studio 2-bedroom	<u>ss - Bedroom, living room</u> \$25,000 x 24m2 / 52m2 = \$11,538 \$25,000 x 77m2 / 52m2 = \$37,019	25,000	11,500	25,000	37,000
Ceiling finishe Studio 2-bedroom	ss - Bath <u>room</u> Same as 1-bedroom \$5,000 x 2	5,000	5,000	5,000	10,000
Kitchen cabin Studio 2-bedroom	<u>et</u> Same as 1-bedroom Same as 1-bedroom	25,000	25,000	25,000	25,000
Furniture Studio	Base \$60,000, omit 1 sofa set, omit 1 TV cabinet, smaller dining table, less chairs, say less \$25,000 overall = \$35,000 Base \$60,000, add 2nd bedroom (allow 1	60,000	35,000	60,000	85,000
2-bourdonn	King bed, 2 bedside tables, 1 wardrobe, 1 TV cabinet), say add \$25,000 overall = \$85,000	•			
Sanitary fitting Studio 2-bedroom	<u>is</u> Same as 1-bedroom \$30,000 x 2	30,000	30,000	30,000	60,000

THE HONG KONG INSTITUTE OF SURVEYORS QUANTITY SURVEYING DIVISION ASSESSMENT OF PROFESSIONAL COMPETENCE FINAL ASSESSMENT – 17TH & 18TH SEPTEMBER 2014 PRACTICE PROBLEMS / PART II WRITTEN TEST NOTES TO ASSESSORS



Question No. 1 - Cost Estimate

NOTES TO ASSESSORS

Attachment B

	W 35			
Upgrading the interior of all existing 150 no. apartment un	Past Project (Base) HK\$	Studio HK\$	1-Bedroom HK\$	2-Bedroom HK\$
Lighting fittings Studio \$20,000 / 2 2-bedroom \$20,000 x 3 / 2	20,000	10,000	20,000	30,000
AV equipment Studio \$30,000 / 2 2-bedroom \$30,000 x 3 / 2	30,000	15,000	30,000	45,000
Miscellaneous e.g. curtains, signage, decoration, etc. Studio \$20,000 / 2 2-bedroom \$20,000 x 3 / 2	20,000	10,000	20,000	30,000
Additional Items Allow for demolition and making good		5,000	10,000	15,000
Preliminaries Base \$37,000 (approx. 10%, allow 15% here due to works in live building i.e. more protection, restriction of working hours)	37,000	35,300	53,300	82,700
Allow for adjustment for price fluctuation say average 8% per year (overall 26%)		70,300	106,200	164,800
Allow for premium by negotiation with one contractor instead of competitive tendering (say-10%)		34,100	51,500	79,900
Contingencies (5%)		18,700	28,300	43,900
′н	K\$/unit 402,000	393,400	594,300	922,500
	Say HK\$/unit	393,000	594,000	923,000
	X	100	40	10
	Total HK\$	39,300,000	23,760,000	9,230,000
	Total (S	tudio, 1-bedroo	m + 2-bedroom) Hi	K\$ 72,290,000

Question No. 1 - Cost Estimate (Cont'd)

NOTES TO ASSESSORS

Optional VE Item - Adopting Windows / Glazed Screen instead of Curtain Walling

Base Scheme (per floor):

Length of curtain wall = 63.4m Area of curtain wall = 63.4m x 3.3m = 209.22m2 Cost of curtain wall = 209.22m2 x \$9,000/m2 = **\$1,882,980**

Alternative Scheme (per floor):

Area of curtain wall replaced by:

(assume 700mm deep beam along building perimeter)

Length of glazed screen with sliding door at balconies = 2.5 m x 8 flats = 20 mLength of window = (63.4 m - 20 m) = 43.4 m

- Area of glazed screen with sliding door at balconies = 20m x (3.3m beam 0.7m)
 = 52m2
- Area of window = 43.4m x 1.5m high = 65.1m2
- Area of external RC wall (150mm thick) = 43.4m x (3.3m beam 0.7m window 1.5m) = 47.74m2
- Area of ceramic tiles = 209.22m2 glazed screen 52m2 window 65.1m2 = 92.12m2

Cost of glazed screen with sliding door = $52m2 \times \$6,000/m2 = \$312,000$ Cost of window = $65.1m2 \times \$4,500/m2 = \$292,950$ Cost of external RC wall (150mm thick) with paint to surface facing interior = $47.74m2 \times \$1,800/m2 = \$85,932$ Cost of ceramic tiles = $92.12m2 \times \$800/m2 = \$73,696$ Total cost = \$764,578

Estimated cost saving for adopting window / glazed screen = \$1,882,980 - \$764,578 = \$1,118,402 per floor

Total estimated cost saving = \$1,118,402 per floor x 20 floors x 1.15 for preliminaries x 1.1 for contingencies = \$28,295,571, say \$28M

Candidates' answer covering 80% of the points above should have full mark.

[12 marks]

VE item check (2017 D1Q2)

<u>2017 PP</u> <u>2017 PP</u>

- change of sow (base, finish of double faces, joint) (builder & MEP & BWIC)

- arithmetical error
- rate
- quantity

Question No. 2 - Value Engineering

NOTES TO ASSESSORS

Objective

The objective of this question is to test Candidates' ability to carry out cost studies of specific design changes. To come up with a more realistic estimate, Candidates should list the points already clarified with or subject to clarification by the design consultants and/or the Client. Candidates should demonstrate sanity check on the quantities and rates in the assistant's backup calculations by giving their own estimate with clear build-up.

VE No. 1 – Structural reinforced concrete columns

Candidates should address the following after reviewing the assistant's backup calculation:

- Formwork Apart from the unit rates, the quantity of formwork will change.
 Candidates should check the quantity for round columns and estimate the quantity for square columns.
- Concrete Similar to formwork, the volume of concrete will change as well.
 Candidates should show the adjustment of the volume of concrete.
- Reinforcement The reinforcement designs of round columns and square columns are different. The structural engineer should advise on the difference.
 At scheme design stage, it is acceptable to apply the same reinforcement ratio.
- Finishes to columns The quantity and unit rate will change. The rates for circular wall finishes (like cladding / tiles) should be higher than those for flat wall finishes.

Cost implication of other building elements e.g. concrete shoulders of different mixes, floor finishes, ceiling finishes, building services can be considered relatively insignificant.

VE No. 2 – Atrium glass skylight

Candidates should address the following after reviewing the assistant's backup calculation:

- The unit rate for skylight with structural frame is approximately HK\$15,000/m2.
 This is considered reasonable for a typical glass skylight.
- In addition to the omission of glass skylight, interfacing details such as curbs and
 joints between the glass skylight and adjacent structure and finishes could also
 be omitted.

Page 28

THE HONG KONG INSTITUTE OF SURVEYORS QUANTITY SURVEYING DIVISION ASSESSMENT OF PROFESSIONAL COMPETENCE FINAL ASSESSMENT - 19[™] & 20[™] SEPTEMBER 2017 PRACTICE PROBLEMS

NOTES TO ASSESSORS



Question No. 2 - Value Engineering (Cont'd)

NOTES TO ASSESSORS

VE No. 2 - Atrium glass skylight (Cont'd)

- The unit rate for the green roof is too low. The structure supporting the green roof is apparently missing. It can be reinforced concrete or steel. Candidates should add back the cost of the structure based on his assumption.
- Waterproofing, insulation, roof finishes, and ceiling finishes should be added back.
- Candidates should state the green roof system (soil and plant) and associated irrigation system and review the rate.

Bonus

Bonus marks for Candidates who have considered design changes to lighting and building services installation.

VE No. 3 - Western restaurant on G/F

The relocation of 300m2 dining area from indoor to outdoor can only mean a change of use, not necessarily a reduction of the CFA. A change of use without reduction of the CFA would not save a lot and there would be extra cost to provide the dining area outdoor. It is therefore not appropriate to report any cost saving without further descriptions of the actual changes, as evidenced by records of clarification with the design consultants and the client. Candidates should demonstrate that they have considered (but not necessarily adopting) the following possible scope changes in the answer:

- Reduction or not of CFA, stating the new use if CFA is not to be reduced.
- Reduction of extent or standard of interior finishes to indoor dining area.
- Reduction of extent or standard of M&E provisions to indoor dining area.
- Addition of canopy, umbrellas or similar covering outdoor dining area.
- Upgrading of indoor furniture to outdoor weatherproof furniture.
- Downgrading of the outdoor furniture to simpler style.
- Revision of external area to accommodate outdoor dining.
- Addition of outdoor lighting.
- Addition of outdoor ventilation and heating.

Page 29

THE HONG KONG INSTITUTE OF SURVEYORS QUANTITY SURVEYING DIVISION ASSESSMENT OF PROFESSIONAL COMPETENCE FINAL ASSESSMENT - 19TH & 20TH SEPTEMBER 2017 PRACTICE PROBLEMS NOTES TO ASSESSORS



Question No. 2 - Value Engineering (Cont'd)

NOTES TO ASSESSORS

VE No. 3 – Western restaurant on G/F (Cont'd)

Bonus

 Bonus marks to Candidates who have considered modification of façade design to allow for more open access between indoor and outdoor.

VE No. 4 - Back-of-house (BOH) false ceiling

Candidates should address the following after reviewing the assistant's backup calculation:

- Arithmetical error in the assistant's calculation of the omission is found, 300m2 x HK\$800/m2 = HK\$240.000 not HK\$24.000.
- Typically, with false ceiling, fire sprinklers are installed at the soffit of false ceiling and inside ceiling void. With the omission of the false ceiling, ceiling void fire sprinklers and associated pipework, fittings etc. should also be omitted.
- Similar to the above, ceiling void smoke detectors and associated wiring, control etc. should be omitted.
- Wall finishes to the exposed ceiling void should be added back.
- Painting to building services at the exposed ceiling void might be required.
- Plastering and painting to concrete ceilings and beams should be added back. The area on plan plus 10 to 20% addition for sides of beams would be a reasonable assumption. Having said that plastering may be ignored to reduce cost.
- The type of lighting fittings and fixing method will change.

Bonus

If air conditioning is provided at BOH area, its loading will increase due to the omission of false ceiling.

2017 PP 2017 PP

> THE HONG KONG INSTITUTE OF SURVEYORS QUANTITY SURVEYING DIVISION ASSESSMENT OF PROFESSIONAL COMPETENCE FINAL ASSESSMENT - 19TH & 20TH SEPTEMBER 2017 PRACTICE PROBLEMS NOTES TO ASSESSORS



Question No. 2 - Value Engineering (Cont'd)

NOTES TO ASSESSORS

VE No. 5 – Transformers

Candidates should address the following after reviewing the assistant's backup calculation:

- The transformer itself is supplied and installed by the electricity supply company. However, a service charge is normally paid by the client to the electricity supply company, and could be reduced.
- Reduction in the costs of main switchboard and rising mains.
- Possible reduction of CFA due to the reduction in size of the transformer room. or a change of use. Similar to VE No. 3 (Western restaurant on G/F), Candidates should record the queries raised with the design consultants about the changes.
- Reduction of associated builder's works e.g. cable trench, ventilation, louvre, lighting etc. in the transformer room.

Corresponding changes to preliminaries and contingencies

Preliminaries and contingencies are usually allowed for simply as percentage markups on the basic costs when preparing the Scheme Design cost estimate. With every change in the basic costs, the preliminaries and contingencies should in theory also be changed arithmetically. In reality, the preliminaries should not change so responsive to the change in the basic costs, especially when the change is small. It is therefore acceptable to include or exclude the corresponding changes to preliminaries and contingencies at every cost study. In case of exclusion, it should be so stated to signify that it is not forgotten.

Candidates' answers covering 80% of the points above should have full mark.

[16 marks]