

The diagram illustrates the wiring harness for the ECM. It shows a central vertical harness with four main wires. At the top, there is a connector labeled E54 with terminals 1, 2, and 3. An arrow points from terminal 3 to a rectangular box representing the ECU. Below E54, the harness passes through a connector labeled E4 with terminals 20, 21, and 19. Further down, it passes through a connector labeled B73 with terminals 20, 21, and 19. At the bottom, the harness connects to a connector labeled B134 with terminals 19, 26, 29, and an empty terminal. The label ECM is placed next to the B134 connector.

