

1. Measurement of the external voltage requires the same ground reference as rest of circuit, else a dangerous short circuit occurs.
2. Measurement is done using internal 1.1V adc reference.

