

Sheet: PSU

File: PSU.sch

Sheet: MK312B MCU

File: MK312B_MCU.sch

Sheet: Panel Circuit


File: Panel_Circuit.sch


Sheet: Input stage


File: Input_stage.sch

Sheet: Output stage

File: Output_stage.sch







Notes:
 Replace 390 Ohm Resistors with 1K when using high intensity LEDs
 All potentiometers are 10K
 Multi-Adjust potentiometer is dual gang
 Populate solder side components on display panel before component side
 Front panel mounting screws are M2.5 x 20mm



