

	Connected using wires
	Soldered

—	Soldered
---	----------



GND of Motor Driver,
GND of ESP32 and
OUT- of Buck Converter
were connected together.