



Measurement Units = (mm) decimal inches

Non-Captive Shaft



Thrust vs. Full Steps/Second

Bipolar • 100% Duty Cycle



NOTE: All chopper drive curves were created with a 5 volt motor and a 40 volt power supply.

Ramping can increase the performance of a motor either by increasing the top speed or getting a heavier load accelerated up to speed faster. Also, deceleration can be used to stop the motor without overshoot.