







TODO: Add current protection resistor to U1 Pin 8 incase power jumper is missing or wrong position?



ESP32 Stepper Motor Analyzer