



TROUBLE SHOOTING REPORT

PSMD (SABHAN)

Ref. No:	88/05/21	Date:	09/05/2021	Prnt.Time :	13:25
Substation:	OMERIEH-W	Make:	COG	P.M:	08/03/2018
		Maint:	ALSTOM	Comm:	11/27/1982

Equip./Unit Affected : 300MVA Tr.# 4

Nature of Fault : Protection clearance is required for the mentioned transformer. PME has to follow.

Concerned Group & Engr: Ali Boualiyan
Section Head : _____
Technicians:- 1-
2-

Action Taken :

Protection o/c e/f is clear and ref stability was clear for HT side. we found 3 master trip relays faulty and replaced them from TR3 and now the Protection side is clear. the copt contactor is isolated due To gauges being out of service and it is giving positive continiusly. ncc is informed

4A

9/5/2021

Concerned Group & Engr : _____ **Date:** / /

Director : _____ **Section Head :** _____