



TROUBLE SHOOTING REPORT

PSMD (SABHAN)

Ref. No:	65/05/21	Date:	06/05/2021	Prnt.Time :	10:48
Substation:	BAYAN-M	Make:	TRE	P.M:	16/03/2015
		Maint:	TRE	Comm:	09/30/1979

Equip./Unit Affected : 20MVA Tr.# 2

Nature of Fault : The mentioned transformer was tripped on differential on 04/05/21 due to 33kV VT flash over. SME Abdur Rahman Awadi requested to check the CTs for the mentioned transformers. PME has to follow.

Concerned Group & Engr: Abdullah ALjuwaisri
Yousef ALotaibi
Section Head : _____
Technicians:- 1-
2-

Action Taken :

Ct saturation test has been done for above mentioned transformer.
All are ok

6/5/2021

Abdullah ALjuwaisri

Concerned Group & Engr :

Date: / /

Director : _____

Section Head : _____