


Solder the 3 legs of the “Tone” potentiometer from the top side as it is very difficult to reach them from the bottom side



Cut the little stand so that it doesn't touch the solder joint of the trimmer

