




Looking at the back of the connector



Looking at the back of the connector



PT5 WILL HAVE TO BE LOOPED BETWEEN THE TWO CONNECTORS.  
26 PIN CONNECTOR DOES NOT HAVE ENOUGH PASSTHROUGH LINES



comma.ai  
you can copy this!

,

TITLE: Subaru\_B\_Harness

Design by:

REV:

Date: not saved!

Sheet: 1/1