




Looking at the back of the connector



Looking at the back of the connector



PT5 WILL HAVE TO BE LOOPED BETWEEN THE TWO CONNECTORS.
26 PIN CONNECTOR DOES NOT HAVE ENOUGH PASSTHROUGH LINES

comma.ai
you can copy this!

,

TITLE: Toyota_B_Harness

Design by:

REV:

Date: 6/5/23 6:31 PM

Sheet: 1/1