



PT5, PT6, PT7 WILL HAVE TO BE LOOPED BETWEEN THE TWO CONNECTORS.
26 PIN CONNECTOR DOES NOT HAVE ENOUGH PASSTHROUGH LINES

comma.ai
you can copy this!

,

TITLE: Toyota_B_Harness

Design by:

REV:

Date: not saved!

Sheet: 1/1