





TUTORIAL -02

Three-dimensional Deformation and Stress and Analysis on a Stepped and Composite Bar

Q3. Solve for complete analysis.





OUTPUT

