




When you SmartMeter is able to supply 5V, then add the jumper.




MountingHole_Pad



P1 PORT INTERFACE





Reset the configuration settings by holding this button during system startup.



<https://nl.mouser.com/ProductDetail/Kingbright/WP154A4SEJ3VBDZGC-CA?qs=YCa%2FAAYMW01T13YiwBKGSw%3D%3D>

STATUS LED



Lectoraat Smart Energy
Expertisecentrum Technische Innovatie
Avans Hogeschool

Sheet: /
File: SmartMeter.sch

Title: Smart Meter

Size: A4 Date: 2021-11-22
KiCad E.D.A. kicad (5.1.9)-1

Rev: v2.1
Id: 1/1