



Errata:

PD5 and PB5 are correct on schematics, but incorrectly swapped in PCB
 Additional diode (VD6) and pullup (R22) are added to improve AC line missing detection

* Select R17 to fit ADC input range (2.56V)
 R19 and C14 are optional