



ALL FOLDS ARE FIXED WITH HOT GLUE

PW-00-0 AND PW-01-0 SHALL BE GLUED
IN PLACE DURING THE PROCESS

FUSELAGE

CUT & FOLD

SCALE

2 : 3

PROJECT

PART NUMBER



PAGE
2/2

RC Trainer V1

PF-01-0-0