


(1 : 2)



Paper

FUSELAGE

MATERIAL	Foam board
MASS	16 g
METHOD	Hand cut
NUMBER	1

SCALE

1 : 2

PROJECT



PART NUMBER



PAGE
1/2

RC Trainer V1

PF-01-0-0



ALL FOLDS ARE FIXED WITH HOT GLUE

PW-00-0 AND PW-01-0 SHALL BE GLUED
IN PLACE DURING THE PROCESS

FUSELAGE

CUT & FOLD

SCALE

2 : 3

PROJECT

PART NUMBER



PAGE
2/2

RC Trainer V1

PF-01-0-0