





JTAG




USB





Ports and Connectors




UART2 - MASTER, for radio modems






UART3 - SLAVE, for autopilot connection




Title *			
Size: A4	Number:*	Revision:*	
Date: 10/09/2015	Time: 7:22:05 PM	Sheet* of *	
File: F:\Current Work\00_0 git\Pixhawk OS Hardware\PX4-FLOW-2.1X0\PX4FLOW2.1 Connectors_X0.SchDoc			




CPU Ports




<http://www.oshwa.org/>
<http://creativecommons.org/licenses/by-sa/3.0/>



Title: PX4FLOW2.1 CPU X0.SchDoc			 3DRobotics
Date: 10/09/2015	Time: 7:22:06 PM		
Sheet: * of: *	Drawn By: Philip Rowse		
Approved: *	Checked By: *		



<http://www.oshwa.org/>
<http://creativecommons.org/licenses/by-sa/3.0/>

Title: PX4FLOW2.1 Sensors CAN X0.SchDoc		 3DRobotics
Date: 10/09/2015	Time: 7:22:06 PM	
Sheet:* of: *	Drawn By: Philip Rowse	
Approved: *	Checked By: *	