

mwo_dataset

mach	date_received	issue	info	tech
A71	04/03/2015	Machine is unpowered	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A6	14/09/2015	Leak in side B hydraulic line	Cristian Santos noted: No further details.	cristian_santos
A61	25/03/2015	Leak in side B hydraulic line	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A3	06/04/2015	Spindle indexing error with overfeed	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A47	08/07/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A65	13/04/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A39	12/10/2015	Accumulator inspection and charging required	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A47	18/06/2015	Inspect and recharge accumulators	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A17	22/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A68	06/01/2016	Milling spindle requires repair	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A90	12/08/2015	Accumulators need checking and charging	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A81	30/03/2015	Spindle fails to index, overfeeding	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A43	30/12/2015	Turret A and B are leaking	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A92	08/12/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A55	11/05/2015	Leak in side B hydraulic line	Michele Williams noted: Repair completed.	michele_williams
A97	07/08/2015	Inspect and recharge accumulators	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A96	08/03/2015	Repair work needed on milling spindle	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A53	07/11/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: No further details.	cristian_santos
A53	29/06/2015	Spindle fails to index, overfeeding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A32	05/05/2015	Power supply failure detected	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A96	25/12/2015	Unit lost electrical power	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A15	19/06/2015	Turret A and B are leaking	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A7	08/02/2015	Turret A and B are leaking	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A21	07/04/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Repair completed.	michele_williams
A78	12/07/2015	Leak in side B hydraulic line	Gina Moore noted: No further details.	gina_moore, dylan_miller
A78	06/02/2015	Machine is unpowered	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A93	12/04/2015	Turret A and B are leaking	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A91	20/08/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A94	20/06/2015	Turret A and B are leaking	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A6	14/08/2015	Accumulator inspection and charging required	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A67	26/10/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A58	11/09/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A88	13/04/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A58	30/12/2015	Spindle indexing error with overfeed	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A85	16/11/2015	Spindle indexing error with overfeed	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A22	16/04/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A22	25/07/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A96	02/10/2015	Milling spindle requires repair	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A6	27/12/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A73	26/02/2015	Spindle indexing error with overfeed	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A1	22/04/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Detail not recorded.	cristian_santos
A91	13/05/2015	Unit lost electrical power	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A47	02/04/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A32	06/03/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A28	28/07/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Maintenance action successful.	michele_williams
A68	21/06/2015	Inspect and recharge accumulators	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A30	15/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A8	05/07/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Fixed and tested.	cristian_santos
A38	01/10/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A60	25/11/2015	Leaks found at turrets A and B	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A99	03/02/2015	Machine is unpowered	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A13	12/08/2015	Unit lost electrical power	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A40	14/09/2015	Milling spindle requires repair	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A42	28/05/2015	Unit lost electrical power	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A27	14/10/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A42	28/07/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A16	19/12/2015	Hydraulic line leak on side B	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A78	13/02/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A54	30/05/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A61	03/01/2016	Leak in side B hydraulic line	Cristian Santos noted: Fixed and tested.	cristian_santos
A37	18/09/2015	Spindle indexing error with overfeed	Michele Williams noted: No further details.	michele_williams
A29	19/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A4	31/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Detail not recorded.	michele_williams
A69	01/06/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A76	18/10/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A75	16/03/2015	Leak in side B hydraulic line	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A83	13/07/2015	Accumulator inspection and charging required	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A6	16/10/2015	Milling spindle requires repair	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos

A71	18/07/2015	Milling spindle requires repair	Cristian Santos noted: No additional information provided.	cristian_santos
A43	16/05/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A19	11/01/2016	Machine is unpowered	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A73	25/04/2015	Spindle fails to index, overfeeding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A32	01/08/2015	Power supply failure detected	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A5	25/11/2015	Machine is unpowered	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A20	26/05/2015	Unit lost electrical power	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A61	09/04/2015	Inspect and recharge accumulators	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A16	07/12/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A23	02/09/2015	Unit lost electrical power	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A60	27/04/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A87	05/10/2015	Power supply failure detected	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A97	30/12/2015	Milling spindle requires repair	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A84	14/04/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A16	04/07/2015	Milling spindle requires repair	Nathan Maldonado noted: No further details.	nathan_maldonado
A32	12/01/2016	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A51	20/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: No further details.	nathan_maldonado
A10	27/08/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A93	08/11/2015	Milling spindle requires repair	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A1	28/01/2015	Spindle fails to index, overfeeding	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A41	01/08/2015	Repair work needed on milling spindle	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A88	21/08/2015	Turret sections A & B showing leaks	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A66	19/02/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A79	02/07/2015	Power supply failure detected	Nathan Maldonado noted: No further details.	nathan_maldonado
A82	20/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A70	19/03/2015	Repair work needed on milling spindle	Gina Moore noted: No further details.	gina_moore, dylan_miller
A75	02/03/2015	Power supply failure detected	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A97	27/10/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A12	18/03/2015	Spindle indexing error with overfeed	Michele Williams noted: No further details.	michele_williams
A75	30/12/2015	Power supply failure detected	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A19	07/09/2015	Spindle indexing error with overfeed	Cristian Santos noted: No additional information provided.	cristian_santos
A73	26/05/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A30	04/04/2015	Leaks found at turrets A and B	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A76	15/04/2015	Maintenance on milling spindle needed	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A89	05/10/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A32	15/10/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A73	12/08/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A61	03/05/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A35	02/11/2015	Leaks found at turrets A and B	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A10	24/03/2015	Spindle fails to index, overfeeding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A40	29/04/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A58	25/04/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A26	03/03/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A55	09/06/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A39	30/07/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A29	25/06/2015	Unit lost electrical power	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A88	24/12/2015	Leak in side B hydraulic line	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A12	29/06/2015	Accumulator inspection and charging required	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A88	20/03/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A76	08/04/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A98	17/04/2015	Accumulator inspection and charging required	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A3	17/09/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A95	27/05/2015	Machine is unpowered	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A28	08/02/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A20	11/09/2015	Unit lost electrical power	Michele Williams noted: System checked and accumulators charged.	michele_williams
A93	27/12/2015	Turret sections A & B showing leaks	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A91	07/02/2015	Spindle fails to index, overfeeding	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A61	15/06/2015	Accumulator inspection and charging required	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A99	22/07/2015	Turret sections A & B showing leaks	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A24	21/12/2015	Milling spindle requires repair	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A96	31/12/2015	Repair work needed on milling spindle	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A19	27/10/2015	Machine is unpowered	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A37	18/02/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A49	08/10/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A46	13/10/2015	Machine is unpowered	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A43	02/01/2016	Saw attachment gears are binding and grinding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A36	22/01/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A98	20/03/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A82	02/08/2015	Turret sections A & B showing leaks	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A98	13/02/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams

A22	21/02/2015	Turret A and B are leaking	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A51	12/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A42	02/08/2015	Hydraulic line leak on side B	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A62	06/01/2016	Spindle indexing error with overfeed	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A38	11/03/2015	Milling spindle requires repair	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A15	12/04/2015	Accumulator inspection and charging required	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A49	13/07/2015	Maintenance on milling spindle needed	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A93	11/02/2015	Inspect and recharge accumulators	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A89	20/03/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A43	17/06/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A77	08/04/2015	Repair work needed on milling spindle	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A75	23/07/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A21	19/12/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A17	02/04/2015	Accumulator inspection and charging required	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A70	31/05/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A44	04/07/2015	Turret sections A & B showing leaks	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A28	20/06/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A11	24/04/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A14	25/01/2015	Repair work needed on milling spindle	Gina Moore noted: No further details.	gina_moore, dylan_miller
A1	12/01/2016	Saw attachment is leaking hydraulics	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A92	10/01/2016	Saw attachment gears are binding and grinding	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A12	08/11/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A5	14/10/2015	Power supply failure detected	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A10	22/01/2015	Inspect and recharge accumulators	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A90	05/10/2015	Turret A and B are leaking	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A29	04/10/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A24	06/07/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A32	15/07/2015	Leak in side B hydraulic line	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A68	29/03/2015	Machine is unpowered	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A20	08/02/2015	Spindle indexing error with overfeed	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A25	16/09/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A44	30/08/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A73	26/05/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A36	08/12/2015	Turret A and B are leaking	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A78	23/08/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A29	07/05/2015	Milling spindle requires repair	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A69	30/08/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A8	11/01/2016	Turret A and B are leaking	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A64	10/01/2016	Repair work needed on milling spindle	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A23	07/02/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A35	19/09/2015	Accumulator inspection and charging required	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A59	19/04/2015	Inspect and recharge accumulators	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A75	05/06/2015	Milling spindle requires repair	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A57	18/09/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A63	10/02/2015	Machine is unpowered	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A62	07/09/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: No further details.	nathan_maldonado
A52	20/05/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A66	31/08/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A30	20/10/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A18	07/05/2015	Turret A and B are leaking	Cristian Santos noted: Maintenance action successful.	cristian_santos
A81	13/05/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A15	01/10/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A20	09/04/2015	Accumulators need checking and charging	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A52	21/11/2015	Unit lost electrical power	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A20	21/03/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A88	23/12/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A4	08/05/2015	Maintenance on milling spindle needed	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A9	05/07/2015	Accumulator inspection and charging required	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A28	16/11/2015	Unit lost electrical power	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A49	05/04/2015	Turret sections A & B showing leaks	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A14	02/12/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A92	18/07/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A41	16/01/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A5	18/04/2015	Leak in side B hydraulic line	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A38	28/11/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A18	17/10/2015	Accumulator inspection and charging required	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A62	24/12/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A12	06/07/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A83	26/02/2015	Leak in side B hydraulic line	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A5	31/01/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado

A53	03/04/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A13	17/07/2015	Turret sections A & B showing leaks	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A85	03/12/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A67	30/12/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A98	04/01/2016	Hydraulic line leak on side B	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A65	18/08/2015	Maintenance on milling spindle needed	Michele Williams noted: System checked and accumulators charged.	michele_williams
A86	20/01/2015	Accumulator inspection and charging required	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A50	12/04/2015	Turret sections A & B showing leaks	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A68	11/11/2015	Leak in side B hydraulic line	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A73	08/10/2015	Turret A and B are leaking	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A56	01/06/2015	Power supply failure detected	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A42	04/08/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A12	21/08/2015	Leak in side B hydraulic line	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A86	25/03/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A39	28/12/2015	Turret sections A & B showing leaks	Michele Williams noted: No further details.	michele_williams
A97	08/06/2015	Unit lost electrical power	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A48	19/05/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A28	01/03/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Maintenance action successful.	cristian_santos
A73	13/10/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A44	08/10/2015	Repair work needed on milling spindle	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A22	06/09/2015	Accumulators need checking and charging	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A60	19/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A58	23/03/2015	Repair work needed on milling spindle	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A11	22/02/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A83	03/11/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A69	20/03/2015	Hydraulic line leak on side B	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A3	17/04/2015	Maintenance on milling spindle needed	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A59	05/01/2016	Turret A and B are leaking	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A89	10/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A36	27/02/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A44	26/03/2015	Inspect and recharge accumulators	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A22	20/06/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A32	05/01/2016	Unit lost electrical power	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A53	11/03/2015	Turret A and B are leaking	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A96	18/06/2015	Unit lost electrical power	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A88	20/09/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A6	22/11/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A47	06/04/2015	Machine is unpowered	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A25	30/04/2015	Maintenance on milling spindle needed	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A4	17/11/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A61	12/10/2015	Turret sections A & B showing leaks	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A14	06/03/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A80	29/03/2015	Spindle indexing error with overfeed	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A96	04/05/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A59	07/04/2015	Maintenance on milling spindle needed	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A96	22/01/2015	Inspect and recharge accumulators	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A30	21/11/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A54	23/03/2015	Accumulators need checking and charging	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A60	13/03/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A9	10/08/2015	Repair work needed on milling spindle	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A83	27/11/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A21	01/03/2015	Power supply failure detected	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A66	31/10/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A92	13/04/2015	Hydraulic line leak on side B	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A70	31/10/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A59	02/08/2015	Inspect and recharge accumulators	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A91	15/05/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A28	02/05/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A34	29/10/2015	Accumulators need checking and charging	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A86	22/12/2015	Hydraulic line leak on side B	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A55	12/12/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A49	18/10/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A52	16/02/2015	Turret A and B are leaking	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A22	14/08/2015	Unit lost electrical power	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A58	02/12/2015	Unit lost electrical power	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A93	29/03/2015	Repair work needed on milling spindle	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A60	17/08/2015	Repair work needed on milling spindle	Cristian Santos noted: Maintenance action successful.	cristian_santos
A11	16/03/2015	Accumulator inspection and charging required	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A59	19/07/2015	Turret A and B are leaking	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A76	16/09/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado

A94	06/08/2015	Hydraulic line leak on side B	Cristian Santos noted: Detail not recorded.	cristian_santos
A25	02/11/2015	Hydraulic line leak on side B	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A3	15/07/2015	Leak in side B hydraulic line	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A85	25/08/2015	Machine is unpowered	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A38	19/03/2015	Milling spindle requires repair	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A61	16/11/2015	Leak in side B hydraulic line	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A99	23/12/2015	Power supply failure detected	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A66	11/10/2015	Inspect and recharge accumulators	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A34	16/12/2015	Milling spindle requires repair	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A19	29/07/2015	Leak in side B hydraulic line	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A64	07/01/2016	Milling spindle requires repair	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A98	09/01/2016	Turret A and B are leaking	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A64	28/08/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Repair completed.	cristian_santos
A81	04/06/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Maintenance action successful.	cristian_santos
A75	12/01/2016	Hydraulic fluid leak at saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A17	14/11/2015	Leaks found at turrets A and B	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A76	03/03/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A24	08/04/2015	Leaks found at turrets A and B	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A28	04/06/2015	Spindle indexing error with overfeed	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A54	27/12/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Repair completed.	michele_williams
A19	19/03/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A48	25/02/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A37	13/12/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Fixed and tested.	michele_williams
A4	11/11/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A93	11/06/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A76	03/08/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A20	30/12/2015	Repair work needed on milling spindle	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A33	15/01/2015	Machine is unpowered	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A52	12/09/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A53	03/06/2015	Turret A and B are leaking	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A60	26/03/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A68	26/10/2015	Machine is unpowered	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A47	26/11/2015	Accumulator inspection and charging required	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A52	02/12/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A96	04/11/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A46	02/03/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A5	04/12/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A85	04/04/2015	Spindle indexing error with overfeed	Gina Moore noted: No further details.	gina_moore, dylan_miller
A51	18/08/2015	Leak in side B hydraulic line	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A4	17/07/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A38	17/02/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A16	26/06/2015	Accumulator inspection and charging required	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A12	23/09/2015	Accumulators need checking and charging	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A29	11/11/2015	Leak in side B hydraulic line	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A35	22/03/2015	Unit lost electrical power	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A35	09/01/2016	Turret A and B are leaking	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A49	31/12/2015	Machine is unpowered	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A23	14/04/2015	Leaks found at turrets A and B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A84	19/06/2015	Inspect and recharge accumulators	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A75	05/05/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A29	17/09/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A34	02/12/2015	Spindle fails to index, overfeeding	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A21	29/01/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A42	17/01/2015	Accumulator inspection and charging required	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A63	06/07/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A41	02/12/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Repair completed.	cristian_santos
A80	31/07/2015	Leaks found at turrets A and B	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A27	07/01/2016	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A57	01/12/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A45	18/06/2015	Accumulator inspection and charging required	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A5	09/02/2015	Spindle indexing error with overfeed	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A21	07/02/2015	Machine is unpowered	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A82	10/05/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A59	12/11/2015	Milling spindle requires repair	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A13	21/09/2015	Accumulator inspection and charging required	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A32	19/06/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A2	07/01/2016	Spindle fails to index, overfeeding	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A39	11/12/2015	Power supply failure detected	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A48	19/10/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A11	01/10/2015	Power supply failure detected	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams

A68	22/06/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A22	29/09/2015	Machine is unpowered	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A5	16/05/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A93	24/02/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A33	05/06/2015	Spindle indexing error with overfeed	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A45	27/09/2015	Spindle fails to index, overfeeding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A38	19/12/2015	Unit lost electrical power	Michele Williams noted: System checked and accumulators charged.	michele_williams
A56	10/03/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A15	30/11/2015	Accumulators need checking and charging	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A93	20/10/2015	Hydraulic line leak on side B	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A72	20/12/2015	Maintenance on milling spindle needed	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A39	29/10/2015	Milling spindle requires repair	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A49	28/01/2015	Power supply failure detected	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A30	01/07/2015	Repair work needed on milling spindle	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A75	12/03/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A55	16/02/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A36	09/09/2015	Repair work needed on milling spindle	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A17	18/04/2015	Milling spindle requires repair	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A56	06/11/2015	Spindle indexing error with overfeed	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A73	28/11/2015	Unit lost electrical power	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A41	27/02/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A83	10/05/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A49	10/01/2016	Repair work needed on milling spindle	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A22	21/05/2015	Maintenance on milling spindle needed	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A35	28/07/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A83	15/07/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A36	21/02/2015	Inspect and recharge accumulators	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A90	25/05/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A71	05/04/2015	Milling spindle requires repair	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A73	02/07/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A17	01/11/2015	Machine is unpowered	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A96	28/03/2015	Milling spindle requires repair	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A3	12/01/2016	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A23	10/06/2015	Turret sections A & B showing leaks	Michele Williams noted: Fixed and tested.	michele_williams
A79	23/02/2015	Leak in side B hydraulic line	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A20	19/03/2015	Repair work needed on milling spindle	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A33	16/01/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Fixed and tested.	michele_williams
A73	06/03/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A59	17/06/2015	Unit lost electrical power	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A60	05/09/2015	Power supply failure detected	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A42	07/10/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A9	21/06/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Fixed and tested.	cristian_santos
A98	09/09/2015	Machine is unpowered	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A91	02/09/2015	Accumulator inspection and charging required	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A61	10/05/2015	Milling spindle requires repair	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A34	20/05/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A88	26/02/2015	Repair work needed on milling spindle	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A38	18/01/2015	Milling spindle requires repair	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A54	18/08/2015	Milling spindle requires repair	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A97	07/02/2015	Machine is unpowered	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A68	24/09/2015	Spindle indexing error with overfeed	Gina Moore noted: No further details.	gina_moore, dylan_miller
A40	02/04/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A77	27/11/2015	Unit lost electrical power	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A74	08/08/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: No further details.	cristian_santos
A91	08/04/2015	Spindle indexing error with overfeed	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A37	27/10/2015	Unit lost electrical power	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A10	01/09/2015	Accumulator inspection and charging required	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A97	03/04/2015	Milling spindle requires repair	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A56	01/06/2015	Maintenance on milling spindle needed	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A2	31/01/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A6	18/05/2015	Spindle fails to index, overfeeding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A30	19/03/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A4	26/09/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A3	14/03/2015	Hydraulic line leak on side B	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A21	16/05/2015	Spindle fails to index, overfeeding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A81	14/05/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A1	23/10/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Repair completed.	cristian_santos
A56	07/08/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A8	26/08/2015	Power supply failure detected	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A83	06/01/2016	Maintenance on milling spindle needed	Nathan Maldonado noted: No further details.	nathan_maldonado

A41	20/12/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A97	03/07/2015	Spindle fails to index, overfeeding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A98	11/10/2015	Machine is unpowered	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A36	31/08/2015	Maintenance on milling spindle needed	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A12	07/06/2015	Leak in side B hydraulic line	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A19	18/04/2015	Accumulator inspection and charging required	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A43	01/12/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A99	31/05/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A28	25/02/2015	Unit lost electrical power	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A21	16/07/2015	Turret A and B are leaking	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A34	18/08/2015	Maintenance on milling spindle needed	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A74	01/01/2016	Unit lost electrical power	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A87	28/02/2015	Unit lost electrical power	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A71	10/09/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A3	25/09/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: No further details.	michele_williams
A84	24/07/2015	Unit lost electrical power	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A17	23/06/2015	Spindle indexing error with overfeed	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A1	17/05/2015	Turret sections A & B showing leaks	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A1	20/01/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A88	14/10/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Repair completed.	cristian_santos
A44	18/06/2015	Milling spindle requires repair	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A81	23/07/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A31	25/06/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A48	24/07/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A16	07/09/2015	Accumulators need checking and charging	Michele Williams noted: Detail not recorded.	michele_williams
A75	04/11/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: No further details.	cristian_santos
A91	22/02/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A47	02/07/2015	Accumulators need checking and charging	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A61	01/07/2015	Maintenance on milling spindle needed	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A42	30/06/2015	Inspect and recharge accumulators	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A45	23/09/2015	Accumulators need checking and charging	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A62	09/06/2015	Unit lost electrical power	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A69	20/05/2015	Unit lost electrical power	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A19	02/07/2015	Machine is unpowered	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A97	09/12/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A85	18/01/2015	Leak in side B hydraulic line	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A96	19/11/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A75	08/07/2015	Accumulator inspection and charging required	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A11	01/10/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A64	27/10/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A23	21/02/2015	Power supply failure detected	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A4	10/06/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A89	09/06/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A63	29/12/2015	Maintenance on milling spindle needed	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A17	26/11/2015	Power supply failure detected	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A32	22/12/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A88	14/10/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A3	15/04/2015	Milling spindle requires repair	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A57	26/12/2015	Leak in side B hydraulic line	Cristian Santos noted: No additional information provided.	cristian_santos
A88	24/04/2015	Power supply failure detected	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A35	15/03/2015	Power supply failure detected	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A33	15/11/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A9	17/02/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: No additional information provided.	cristian_santos
A68	28/04/2015	Leak in side B hydraulic line	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A78	25/09/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A18	23/04/2015	Maintenance on milling spindle needed	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A89	14/03/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A29	25/09/2015	Accumulators need checking and charging	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A47	19/08/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A50	07/03/2015	Machine is unpowered	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A74	30/01/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A42	12/04/2015	Inspect and recharge accumulators	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A23	07/09/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A50	21/01/2015	Hydraulic line leak on side B	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A85	23/01/2015	Hydraulic line leak on side B	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A6	21/01/2015	Power supply failure detected	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A87	17/04/2015	Unit lost electrical power	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A79	12/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: No additional information provided.	michele_williams
A39	15/12/2015	Spindle indexing error with overfeed	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A29	05/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado

A91	14/04/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A58	26/11/2015	Accumulator inspection and charging required	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A28	30/06/2015	Leaks found at turrets A and B	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A98	24/05/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A84	27/05/2015	Unit lost electrical power	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A6	11/11/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A91	31/08/2015	Machine is unpowered	Cristian Santos noted: Detail not recorded.	cristian_santos
A76	08/03/2015	Unit lost electrical power	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A45	27/08/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A99	28/09/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A14	26/02/2015	Machine is unpowered	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A87	03/04/2015	Machine is unpowered	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A14	19/03/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A84	08/06/2015	Turret sections A & B showing leaks	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A3	10/07/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Detail not recorded.	michele_williams
A52	06/03/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A38	01/11/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A45	30/03/2015	Repair work needed on milling spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A27	21/07/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A36	15/12/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A86	27/11/2015	Power supply failure detected	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A20	19/01/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A89	15/06/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A59	08/05/2015	Accumulators need checking and charging	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A78	16/05/2015	Inspect and recharge accumulators	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A62	11/08/2015	Milling spindle requires repair	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A8	03/07/2015	Hydraulic line leak on side B	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A94	23/10/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: No further details.	gina_moore, dylan_miller
A30	20/12/2015	Accumulator inspection and charging required	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A17	26/05/2015	Milling spindle requires repair	Michele Williams noted: No additional information provided.	michele_williams
A96	23/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A36	19/10/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A42	18/07/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A81	20/12/2015	Spindle fails to index, overfeeding	Cristian Santos noted: No additional information provided.	cristian_santos
A37	08/08/2015	Hydraulic line leak on side B	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A9	18/11/2015	Maintenance on milling spindle needed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A11	16/09/2015	Maintenance on milling spindle needed	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A3	20/05/2015	Inspect and recharge accumulators	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A36	21/11/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A25	12/11/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A67	22/07/2015	Leak in side B hydraulic line	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A58	08/12/2015	Leak in side B hydraulic line	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A12	02/08/2015	Hydraulic line leak on side B	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A30	30/07/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A52	26/06/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A83	01/11/2015	Turret sections A & B showing leaks	Cristian Santos noted: No further details.	cristian_santos
A39	16/12/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A33	25/12/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A84	08/08/2015	Milling spindle requires repair	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A60	10/05/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A76	25/06/2015	Unit lost electrical power	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A33	22/08/2015	Repair work needed on milling spindle	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A12	06/07/2015	Machine is unpowered	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A79	02/06/2015	Unit lost electrical power	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A65	23/08/2015	Unit lost electrical power	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A72	02/03/2015	Milling spindle requires repair	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A93	24/07/2015	Turret sections A & B showing leaks	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A60	27/04/2015	Accumulators need checking and charging	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A73	28/03/2015	Machine is unpowered	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A50	11/12/2015	Maintenance on milling spindle needed	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A93	15/02/2015	Hydraulic hose on side B is leaking	Michele Williams noted: No additional information provided.	michele_williams
A89	02/12/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A8	08/10/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A36	28/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A32	16/01/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A16	01/11/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A44	12/04/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A66	26/02/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A86	11/06/2015	Machine is unpowered	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A11	15/11/2015	Turret sections A & B showing leaks	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller

A92	07/03/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A46	07/12/2015	Accumulators need checking and charging	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A96	17/10/2015	Accumulators need checking and charging	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A63	15/03/2015	Accumulators need checking and charging	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A52	20/11/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A62	07/10/2015	Repair work needed on milling spindle	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A33	18/11/2015	Machine is unpowered	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A67	28/10/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A56	14/07/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A67	12/12/2015	Machine is unpowered	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A20	15/11/2015	Leak in side B hydraulic line	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A16	07/11/2015	Turret sections A & B showing leaks	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A15	24/08/2015	Accumulator inspection and charging required	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A29	16/03/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A85	04/06/2015	Accumulator inspection and charging required	Cristian Santos noted: Repair completed.	cristian_santos
A53	23/12/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A86	04/05/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A39	22/04/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A39	28/09/2015	Accumulators need checking and charging	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A68	13/12/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A48	04/06/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A83	21/05/2015	Turret sections A & B showing leaks	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A73	26/04/2015	Turret sections A & B showing leaks	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A18	26/11/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A90	30/01/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A69	30/08/2015	Machine is unpowered	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A79	13/01/2016	Hydraulic fluid leak at saw attachment	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A56	08/11/2015	Accumulators need checking and charging	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A27	29/11/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A79	11/03/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A48	28/02/2015	Turret sections A & B showing leaks	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A92	26/10/2015	Accumulators need checking and charging	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A29	30/09/2015	Leak in side B hydraulic line	Gina Moore noted: No further details.	gina_moore, dylan_miller
A54	20/10/2015	Inspect and recharge accumulators	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A16	12/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A84	28/07/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A68	12/05/2015	Turret A and B are leaking	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A94	06/04/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A46	20/07/2015	Machine is unpowered	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A18	09/04/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A23	16/03/2015	Accumulators need checking and charging	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A47	27/05/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A3	30/10/2015	Repair work needed on milling spindle	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A22	19/11/2015	Inspect and recharge accumulators	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A8	02/12/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A1	14/11/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A89	02/08/2015	Maintenance on milling spindle needed	Michele Williams noted: Detail not recorded.	michele_williams
A6	05/10/2015	Spindle indexing error with overfeed	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A57	06/07/2015	Power supply failure detected	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A43	25/05/2015	Turret A and B are leaking	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A10	11/03/2015	Repair work needed on milling spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A83	29/07/2015	Inspect and recharge accumulators	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A86	27/01/2015	Inspect and recharge accumulators	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A10	17/03/2015	Leaks found at turrets A and B	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A36	15/03/2015	Unit lost electrical power	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A48	05/02/2015	Turret A and B are leaking	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A53	13/07/2015	Turret A and B are leaking	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A43	29/04/2015	Maintenance on milling spindle needed	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A19	05/06/2015	Inspect and recharge accumulators	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A10	26/02/2015	Machine is unpowered	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A17	15/02/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A88	26/11/2015	Spindle indexing error with overfeed	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A58	05/10/2015	Unit lost electrical power	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A43	30/08/2015	Accumulators need checking and charging	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A10	20/01/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A43	23/02/2015	Power supply failure detected	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A95	04/12/2015	Machine is unpowered	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A47	07/09/2015	Maintenance on milling spindle needed	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A19	06/06/2015	Repair work needed on milling spindle	Nathan Maldonado noted: No further details.	nathan_maldonado
A14	12/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams

A2	05/01/2016	Repair work needed on milling spindle	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A27	12/09/2015	Turret A and B are leaking	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A31	13/04/2015	Repair work needed on milling spindle	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A90	31/07/2015	Turret A and B are leaking	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A79	05/03/2015	Leak in side B hydraulic line	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A74	28/04/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A6	13/11/2015	Hydraulic line leak on side B	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A14	01/09/2015	Maintenance on milling spindle needed	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A36	04/12/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A70	28/09/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A50	20/01/2015	Repair work needed on milling spindle	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A83	05/07/2015	Milling spindle requires repair	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A81	31/01/2015	Accumulator inspection and charging required	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A88	17/03/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A14	06/07/2015	Milling spindle requires repair	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A15	27/08/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A31	27/06/2015	Leaks found at turrets A and B	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A26	04/07/2015	Maintenance on milling spindle needed	Cristian Santos noted: Detail not recorded.	cristian_santos
A27	25/03/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A96	03/01/2016	Spindle fails to index, overfeeding	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A24	08/05/2015	Accumulator inspection and charging required	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A47	11/06/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A75	15/04/2015	Spindle fails to index, overfeeding	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A55	30/10/2015	Milling spindle requires repair	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A63	06/11/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A13	17/01/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A63	01/05/2015	Maintenance on milling spindle needed	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A12	13/07/2015	Unit lost electrical power	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A62	18/01/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A53	09/04/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A44	12/11/2015	Hydraulic line leak on side B	Cristian Santos noted: Repair completed.	cristian_santos
A59	27/06/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A48	18/06/2015	Spindle fails to index, overfeeding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A24	21/04/2015	Unit lost electrical power	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A90	11/05/2015	Leaks found at turrets A and B	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A98	17/12/2015	Inspect and recharge accumulators	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A99	08/08/2015	Spindle indexing error with overfeed	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A43	29/03/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A13	08/12/2015	Accumulator inspection and charging required	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A55	24/09/2015	Maintenance on milling spindle needed	Michele Williams noted: No further details.	michele_williams
A10	01/03/2015	Hydraulic line leak on side B	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A80	23/07/2015	Accumulators need checking and charging	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A96	13/04/2015	Spindle indexing error with overfeed	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A67	22/07/2015	Hydraulic line leak on side B	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A60	21/07/2015	Machine is unpowered	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A6	06/01/2016	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A31	17/06/2015	Maintenance on milling spindle needed	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A25	19/07/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A92	12/10/2015	Leaks found at turrets A and B	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A15	29/11/2015	Leaks found at turrets A and B	Michele Williams noted: Fixed and tested.	michele_williams
A2	30/01/2015	Power supply failure detected	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A4	08/06/2015	Power supply failure detected	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A64	14/07/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A28	18/03/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A10	21/02/2015	Leak in side B hydraulic line	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A54	21/02/2015	Accumulators need checking and charging	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A3	18/10/2015	Accumulator inspection and charging required	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A72	21/08/2015	Accumulator inspection and charging required	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A93	31/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A79	27/09/2015	Machine is unpowered	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A75	13/06/2015	Milling spindle requires repair	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A85	29/05/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A85	16/03/2015	Turret A and B are leaking	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A63	11/05/2015	Accumulator inspection and charging required	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A97	22/04/2015	Unit lost electrical power	Gina Moore noted: No further details.	gina_moore, dylan_miller
A81	17/03/2015	Leak in side B hydraulic line	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A36	24/11/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A14	28/02/2015	Milling spindle requires repair	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A37	04/05/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A10	03/01/2016	Maintenance on milling spindle needed	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams

A24	16/09/2015	Turret sections A & B showing leaks	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A56	02/08/2015	Milling spindle requires repair	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A84	12/07/2015	Machine is unpowered	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A65	18/05/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A97	06/11/2015	Accumulator inspection and charging required	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A18	18/02/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A29	15/07/2015	Accumulators need checking and charging	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A11	01/11/2015	Accumulator inspection and charging required	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A3	13/02/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A95	05/04/2015	Power supply failure detected	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A33	24/08/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A2	06/11/2015	Repair work needed on milling spindle	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A73	13/06/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A85	26/06/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A1	09/02/2015	Milling spindle requires repair	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A88	17/01/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A23	01/10/2015	Hydraulic line leak on side B	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A21	21/01/2015	Turret sections A & B showing leaks	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A82	22/08/2015	Accumulators need checking and charging	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A60	18/01/2015	Spindle fails to index, overfeeding	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A77	10/05/2015	Turret sections A & B showing leaks	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A83	11/06/2015	Unit lost electrical power	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A7	21/04/2015	Unit lost electrical power	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A49	06/02/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A12	07/07/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A69	22/06/2015	Hydraulic line leak on side B	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A59	31/08/2015	Maintenance on milling spindle needed	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A93	18/10/2015	Power supply failure detected	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A16	11/06/2015	Machine is unpowered	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A93	12/07/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A99	20/01/2015	Accumulators need checking and charging	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A77	14/06/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A30	01/06/2015	Inspect and recharge accumulators	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A64	26/10/2015	Inspect and recharge accumulators	Cristian Santos noted: Maintenance action successful.	cristian_santos
A22	20/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A63	12/03/2015	Leaks found at turrets A and B	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A60	16/03/2015	Turret A and B are leaking	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A30	26/07/2015	Milling spindle requires repair	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A73	19/10/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A12	22/11/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A55	01/03/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A30	02/03/2015	Inspect and recharge accumulators	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A97	12/09/2015	Hydraulic line leak on side B	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A49	23/04/2015	Accumulator inspection and charging required	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A38	08/04/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A88	17/10/2015	Spindle fails to index, overfeeding	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A19	20/12/2015	Machine is unpowered	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A35	01/11/2015	Accumulators need checking and charging	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A67	10/09/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A76	20/10/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A43	11/11/2015	Maintenance on milling spindle needed	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A53	14/07/2015	Unit lost electrical power	Michele Williams noted: Detail not recorded.	michele_williams
A33	02/07/2015	Accumulators need checking and charging	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A5	18/08/2015	Hydraulic line leak on side B	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A75	11/03/2015	Machine is unpowered	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A75	03/07/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A92	07/01/2016	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A32	05/09/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A95	22/07/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A18	30/12/2015	Maintenance on milling spindle needed	Michele Williams noted: No additional information provided.	michele_williams
A19	27/02/2015	Hydraulic hose on side B is leaking	Michele Williams noted: No further details.	michele_williams
A63	12/11/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A53	03/05/2015	Unit lost electrical power	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A41	01/07/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A49	02/10/2015	Accumulators need checking and charging	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A27	20/04/2015	Inspect and recharge accumulators	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A88	21/04/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Maintenance action successful.	cristian_santos
A11	20/12/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A46	19/10/2015	Repair work needed on milling spindle	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A43	14/08/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos

A72	23/12/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A56	21/06/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A35	25/07/2015	Spindle indexing error with overfeed	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A52	26/09/2015	Hydraulic line leak on side B	Michele Williams noted: Maintenance action successful.	michele_williams
A15	02/01/2016	Hydraulic hose on side B is leaking	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A42	15/09/2015	Spindle indexing error with overfeed	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A88	30/04/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A44	28/08/2015	Spindle indexing error with overfeed	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A29	27/03/2015	Inspect and recharge accumulators	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A73	22/01/2015	Accumulator inspection and charging required	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A47	28/05/2015	Turret A and B are leaking	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A36	05/06/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A66	11/05/2015	Hydraulic line leak on side B	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A68	28/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A71	18/05/2015	Spindle fails to index, overfeeding	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A64	17/03/2015	Power supply failure detected	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A44	09/02/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Detail not recorded.	michele_williams
A48	25/04/2015	Leak in side B hydraulic line	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A81	10/04/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A9	07/03/2015	Unit lost electrical power	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A88	29/10/2015	Machine is unpowered	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A95	22/07/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A1	14/08/2015	Accumulator inspection and charging required	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A50	19/12/2015	Power supply failure detected	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A97	23/09/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A74	21/03/2015	Accumulator inspection and charging required	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A19	28/11/2015	Unit lost electrical power	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A49	09/01/2016	Accumulators need checking and charging	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A60	18/05/2015	Accumulators need checking and charging	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A41	12/11/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A51	14/09/2015	Leaks found at turrets A and B	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A28	22/04/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A16	20/09/2015	Unit lost electrical power	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A87	23/08/2015	Milling spindle requires repair	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A41	06/01/2016	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A93	17/11/2015	Leak in side B hydraulic line	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A10	28/06/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Maintenance action successful.	cristian_santos
A5	21/06/2015	Milling spindle requires repair	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A11	30/01/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A19	15/09/2015	Repair work needed on milling spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A92	17/12/2015	Machine is unpowered	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A36	17/02/2015	Inspect and recharge accumulators	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A17	16/04/2015	Repair work needed on milling spindle	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A80	01/09/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A70	03/06/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A94	15/08/2015	Machine is unpowered	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A4	28/05/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A10	20/12/2015	Repair work needed on milling spindle	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A71	02/03/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A91	25/07/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A22	17/01/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A78	13/06/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A35	28/12/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A60	06/04/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A62	05/02/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A82	02/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A62	08/12/2015	Turret A and B are leaking	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A44	14/02/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A75	02/08/2015	Accumulator inspection and charging required	Michele Williams noted: No additional information provided.	michele_williams
A61	11/04/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A16	28/11/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A70	16/08/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A10	11/10/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A37	26/09/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A91	04/04/2015	Leaks found at turrets A and B	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A2	17/10/2015	Repair work needed on milling spindle	Cristian Santos noted: Repair completed.	cristian_santos
A89	01/12/2015	Power supply failure detected	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A28	06/06/2015	Accumulators need checking and charging	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A27	07/03/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A53	03/06/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos

A36	16/01/2015	Accumulators need checking and charging	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A74	10/04/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A21	23/08/2015	Machine is unpowered	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A10	01/07/2015	Inspect and recharge accumulators	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A48	04/02/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A10	01/10/2015	Repair work needed on milling spindle	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A38	17/06/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A75	22/03/2015	Turret sections A & B showing leaks	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A16	08/06/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A67	14/08/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A26	08/01/2016	Leak in side B hydraulic line	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A36	04/06/2015	Machine is unpowered	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A88	10/04/2015	Repair work needed on milling spindle	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A10	25/09/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A80	14/04/2015	Accumulator inspection and charging required	Gina Moore noted: No further details.	gina_moore, dylan_miller
A88	01/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A56	29/10/2015	Maintenance on milling spindle needed	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A64	05/02/2015	Spindle fails to index, overfeeding	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A46	27/07/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A31	09/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A43	25/07/2015	Accumulator inspection and charging required	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A78	07/09/2015	Accumulator inspection and charging required	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A43	18/04/2015	Unit lost electrical power	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A69	25/02/2015	Machine is unpowered	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A49	12/03/2015	Accumulators need checking and charging	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A74	17/04/2015	Milling spindle requires repair	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A4	23/10/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A28	13/12/2015	Accumulators need checking and charging	Nathan Maldonado noted: No further details.	nathan_maldonado
A83	03/07/2015	Turret A and B are leaking	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A26	20/12/2015	Maintenance on milling spindle needed	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A99	05/08/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A44	02/06/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A23	12/11/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: No further details.	cristian_santos
A97	09/08/2015	Turret A and B are leaking	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A9	17/07/2015	Turret sections A & B showing leaks	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A55	08/01/2016	Spindle fails to index, overfeeding	Michele Williams noted: Detail not recorded.	michele_williams
A50	23/07/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A64	14/06/2015	Repair work needed on milling spindle	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A46	28/09/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A66	14/04/2015	Unit lost electrical power	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A32	22/12/2015	Accumulator inspection and charging required	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A14	05/08/2015	Power supply failure detected	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A57	07/03/2015	Spindle indexing error with overfeed	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A75	03/05/2015	Milling spindle requires repair	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A4	02/03/2015	Spindle indexing error with overfeed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A67	12/11/2015	Turret A and B are leaking	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A43	13/01/2016	Machine is unpowered	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A31	28/01/2015	Inspect and recharge accumulators	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A85	12/01/2016	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A51	21/04/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A45	29/08/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A71	19/12/2015	Leak in side B hydraulic line	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A98	09/12/2015	Leaks found at turrets A and B	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A72	26/02/2015	Spindle indexing error with overfeed	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A68	18/04/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A94	11/06/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A50	08/02/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A55	14/05/2015	Turret sections A & B showing leaks	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A53	16/08/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A97	19/09/2015	Turret sections A & B showing leaks	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A19	06/11/2015	Hydraulic line leak on side B	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A25	19/10/2015	Repair work needed on milling spindle	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A11	16/06/2015	Milling spindle requires repair	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A36	22/05/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A18	07/12/2015	Accumulators need checking and charging	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A40	20/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A3	12/07/2015	Accumulators need checking and charging	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A77	24/07/2015	Turret A and B are leaking	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A33	23/07/2015	Turret sections A & B showing leaks	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A96	24/05/2015	Leaks found at turrets A and B	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado

A14	15/10/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A36	13/04/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A53	08/11/2015	Accumulators need checking and charging	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A24	24/05/2015	Leak in side B hydraulic line	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A67	12/02/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A78	29/04/2015	Milling spindle requires repair	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A98	28/09/2015	Maintenance on milling spindle needed	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A41	07/06/2015	Turret A and B are leaking	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A23	03/09/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A56	04/03/2015	Leaks found at turrets A and B	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A27	06/10/2015	Unit lost electrical power	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A83	11/10/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A85	22/03/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A8	09/06/2015	Spindle indexing error with overfeed	Cristian Santos noted: No further details.	cristian_santos
A10	13/08/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A81	24/08/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A33	13/08/2015	Turret sections A & B showing leaks	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A65	16/04/2015	Spindle indexing error with overfeed	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A10	22/02/2015	Turret A and B are leaking	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A50	15/07/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A43	11/09/2015	Inspect and recharge accumulators	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A99	05/03/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A54	21/04/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A36	05/10/2015	Inspect and recharge accumulators	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A39	04/06/2015	Unit lost electrical power	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A89	07/10/2015	Leaks found at turrets A and B	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A17	15/09/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A11	21/06/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A2	12/03/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A24	09/12/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A32	12/06/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A98	23/11/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A36	01/06/2015	Unit lost electrical power	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A32	30/01/2015	Accumulators need checking and charging	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A57	17/10/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A3	03/08/2015	Turret sections A & B showing leaks	Cristian Santos noted: No further details.	cristian_santos
A11	02/08/2015	Turret A and B are leaking	Michele Williams noted: Maintenance action successful.	michele_williams
A8	07/11/2015	Accumulators need checking and charging	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A6	09/10/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Repair completed.	cristian_santos
A14	21/11/2015	Unit lost electrical power	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A21	30/04/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A8	13/09/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A28	02/09/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A25	17/07/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A72	11/05/2015	Milling spindle requires repair	Cristian Santos noted: Repair completed.	cristian_santos
A80	22/11/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A78	03/03/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A44	26/08/2015	Maintenance on milling spindle needed	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A1	08/01/2016	Maintenance on milling spindle needed	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A74	18/09/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A91	23/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A52	17/12/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A67	02/09/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A19	28/01/2015	Inspect and recharge accumulators	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A68	13/01/2016	Saw attachment gears are binding and grinding	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A94	02/01/2016	Accumulators need checking and charging	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A79	05/03/2015	Spindle fails to index, overfeeding	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A16	04/05/2015	Power supply failure detected	Cristian Santos noted: No further details.	cristian_santos
A55	16/04/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A89	21/08/2015	Unit lost electrical power	Cristian Santos noted: Repair completed.	cristian_santos
A57	01/04/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A74	19/03/2015	Unit lost electrical power	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A20	13/08/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A92	20/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A37	01/12/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A13	04/02/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A20	14/06/2015	Leaks found at turrets A and B	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A9	13/05/2015	Repair work needed on milling spindle	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A97	03/07/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A38	23/05/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado

A10	21/03/2015	Accumulator inspection and charging required	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A46	18/09/2015	Turret sections A & B showing leaks	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A12	05/11/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A22	03/06/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A97	12/06/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A13	18/06/2015	Repair work needed on milling spindle	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A1	13/10/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A1	12/08/2015	Turret A and B are leaking	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A51	24/12/2015	Repair work needed on milling spindle	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A75	20/10/2015	Leak in side B hydraulic line	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A37	17/04/2015	Power supply failure detected	Michele Williams noted: No additional information provided.	michele_williams
A76	08/02/2015	Repair work needed on milling spindle	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A23	30/04/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A76	06/07/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A85	04/05/2015	Turret sections A & B showing leaks	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A99	29/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A75	23/09/2015	Turret A and B are leaking	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A25	20/03/2015	Milling spindle requires repair	Michele Williams noted: System checked and accumulators charged.	michele_williams
A77	27/01/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A58	05/10/2015	Leak in side B hydraulic line	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A67	27/11/2015	Accumulator inspection and charging required	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A68	09/05/2015	Leak in side B hydraulic line	Michele Williams noted: System checked and accumulators charged.	michele_williams
A31	18/12/2015	Power supply failure detected	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A86	18/03/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A7	24/12/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A59	11/10/2015	Hydraulic line leak on side B	Cristian Santos noted: No additional information provided.	cristian_santos
A83	07/08/2015	Turret A and B are leaking	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A75	12/07/2015	Hydraulic line leak on side B	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A27	10/12/2015	Accumulator inspection and charging required	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A70	10/10/2015	Turret sections A & B showing leaks	Cristian Santos noted: No further details.	cristian_santos
A23	31/10/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Fixed and tested.	cristian_santos
A6	14/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A5	25/07/2015	Accumulators need checking and charging	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A32	02/12/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A16	17/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A6	16/12/2015	Hydraulic line leak on side B	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A60	05/12/2015	Turret sections A & B showing leaks	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A38	21/07/2015	Repair work needed on milling spindle	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A43	16/01/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A74	13/08/2015	Power supply failure detected	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A16	16/12/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A55	10/08/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Detail not recorded.	cristian_santos
A67	30/12/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A30	22/06/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A93	07/01/2016	Turret A and B are leaking	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A62	21/07/2015	Spindle fails to index, overfeeding	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A79	20/05/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A90	24/03/2015	Spindle indexing error with overfeed	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A66	23/11/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A4	20/02/2015	Power supply failure detected	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A41	10/10/2015	Hydraulic line leak on side B	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A13	20/04/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A80	11/12/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A87	16/01/2015	Accumulators need checking and charging	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A40	21/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A22	11/11/2015	Machine is unpowered	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A38	23/09/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A55	01/03/2015	Hydraulic hose on side B is leaking	Michele Williams noted: No further details.	michele_williams
A82	20/08/2015	Turret sections A & B showing leaks	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A78	03/07/2015	Turret sections A & B showing leaks	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A55	09/12/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A21	13/08/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A31	18/07/2015	Unit lost electrical power	Michele Williams noted: System checked and accumulators charged.	michele_williams
A3	14/08/2015	Leak in side B hydraulic line	Gina Moore noted: No further details.	gina_moore, dylan_miller
A99	10/03/2015	Repair work needed on milling spindle	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A84	24/07/2015	Leak in side B hydraulic line	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A93	22/03/2015	Accumulators need checking and charging	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A23	10/01/2016	Maintenance on milling spindle needed	Michele Williams noted: Maintenance action successful.	michele_williams
A44	24/11/2015	Leaks found at turrets A and B	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A80	27/03/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller

A68	06/01/2016	Unit lost electrical power	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A68	12/01/2016	Spindle indexing error with overfeed	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A24	03/06/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A13	12/10/2015	Saw attachment is leaking hydraulics	Michele Williams noted: No further details.	michele_williams
A99	27/12/2015	Machine is unpowered	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A35	12/05/2015	Turret A and B are leaking	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A49	25/11/2015	Spindle indexing error with overfeed	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A44	24/05/2015	Turret sections A & B showing leaks	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A65	09/10/2015	Turret A and B are leaking	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A44	08/06/2015	Turret sections A & B showing leaks	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A72	28/01/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A22	05/03/2015	Accumulators need checking and charging	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A50	25/10/2015	Accumulators need checking and charging	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A15	21/05/2015	Milling spindle requires repair	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A16	10/07/2015	Spindle indexing error with overfeed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A33	16/10/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Maintenance action successful.	michele_williams
A23	18/03/2015	Spindle fails to index, overfeeding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A37	31/08/2015	Turret sections A & B showing leaks	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A37	20/08/2015	Accumulator inspection and charging required	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A44	30/08/2015	Leak in side B hydraulic line	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A86	12/09/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A6	06/09/2015	Unit lost electrical power	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A16	15/03/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A82	06/12/2015	Spindle fails to index, overfeeding	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A55	23/02/2015	Unit lost electrical power	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A32	27/06/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A87	20/04/2015	Turret A and B are leaking	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A24	02/09/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A84	24/07/2015	Spindle indexing error with overfeed	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A66	28/11/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A21	23/07/2015	Power supply failure detected	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A90	31/12/2015	Repair work needed on milling spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A58	23/11/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: No further details.	nathan_maldonado
A58	01/04/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A56	11/02/2015	Machine is unpowered	Michele Williams noted: No further details.	michele_williams
A93	04/08/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A28	15/06/2015	Inspect and recharge accumulators	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A11	08/02/2015	Turret A and B are leaking	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A40	16/02/2015	Turret A and B are leaking	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A69	17/03/2015	Maintenance on milling spindle needed	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A61	08/12/2015	Turret A and B are leaking	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A67	15/02/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A40	17/11/2015	Spindle indexing error with overfeed	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A34	01/10/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A10	08/10/2015	Inspect and recharge accumulators	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A34	31/08/2015	Leaks found at turrets A and B	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A72	04/09/2015	Leak in side B hydraulic line	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A35	03/11/2015	Accumulator inspection and charging required	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A35	24/04/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A94	06/06/2015	Power supply failure detected	Michele Williams noted: No additional information provided.	michele_williams
A55	03/10/2015	Hydraulic line leak on side B	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A25	19/03/2015	Unit lost electrical power	Michele Williams noted: System checked and accumulators charged.	michele_williams
A87	18/04/2015	Hydraulic line leak on side B	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A72	26/11/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A32	25/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A38	25/10/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A51	30/01/2015	Repair work needed on milling spindle	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A42	25/02/2015	Maintenance on milling spindle needed	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A14	21/08/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A1	19/03/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A72	22/05/2015	Turret A and B are leaking	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A14	14/08/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A57	19/12/2015	Inspect and recharge accumulators	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A61	17/07/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A28	01/02/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A39	20/02/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: No further details.	cristian_santos
A88	23/05/2015	Turret A and B are leaking	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A53	16/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A28	23/09/2015	Maintenance on milling spindle needed	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A10	13/07/2015	Hydraulic line leak on side B	Gina Moore noted: No further details.	gina_moore, dylan_miller

A46	11/05/2015	Milling spindle requires repair	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A2	28/10/2015	Milling spindle requires repair	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A4	05/04/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A39	06/08/2015	Unit lost electrical power	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A27	10/09/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A99	09/07/2015	Unit lost electrical power	Gina Moore noted: No further details.	gina_moore, dylan_miller
A12	31/10/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A69	05/08/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A49	21/08/2015	Leak in side B hydraulic line	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A52	06/08/2015	Milling spindle requires repair	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A20	23/10/2015	Milling spindle requires repair	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A50	07/12/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Detail not recorded.	cristian_santos
A81	05/11/2015	Accumulators need checking and charging	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A77	14/02/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A25	15/07/2015	Accumulator inspection and charging required	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A33	23/03/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A40	15/01/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A40	23/06/2015	Turret A and B are leaking	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A45	06/01/2016	Leaks found at turrets A and B	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A5	22/06/2015	Turret sections A & B showing leaks	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A90	14/04/2015	Milling spindle requires repair	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A96	18/05/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A70	18/11/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A99	02/11/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A52	15/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A64	05/09/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A4	26/02/2015	Hydraulic line leak on side B	Cristian Santos noted: Detail not recorded.	cristian_santos
A39	06/04/2015	Hydraulic line leak on side B	Michele Williams noted: Detail not recorded.	michele_williams
A18	22/08/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: System checked and accumulators charged.	michele_williams
A26	11/03/2015	Turret sections A & B showing leaks	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A3	29/12/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Maintenance action successful.	cristian_santos
A15	26/04/2015	Maintenance on milling spindle needed	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A31	04/08/2015	Accumulator inspection and charging required	Cristian Santos noted: Repair completed.	cristian_santos
A2	30/12/2015	Machine is unpowered	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A52	13/09/2015	Milling spindle requires repair	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A90	19/02/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A11	07/04/2015	Accumulators need checking and charging	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A61	22/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A98	02/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A8	11/01/2016	Maintenance on milling spindle needed	Cristian Santos noted: Detail not recorded.	cristian_santos
A73	17/02/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A24	26/08/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A53	24/04/2015	Inspect and recharge accumulators	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A73	20/07/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A27	25/01/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A68	16/05/2015	Hydraulic line leak on side B	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A59	07/10/2015	Inspect and recharge accumulators	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A33	10/11/2015	Maintenance on milling spindle needed	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A10	24/09/2015	Turret A and B are leaking	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A23	25/06/2015	Leak in side B hydraulic line	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A69	11/07/2015	Accumulator inspection and charging required	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A81	18/05/2015	Power supply failure detected	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A7	27/12/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A84	30/05/2015	Accumulators need checking and charging	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A83	14/03/2015	Machine is unpowered	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A75	25/10/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A20	02/06/2015	Accumulator inspection and charging required	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A87	09/12/2015	Power supply failure detected	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A65	11/02/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A13	11/11/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A1	03/04/2015	Machine is unpowered	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A56	02/03/2015	Power supply failure detected	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A64	15/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A72	21/08/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A9	17/06/2015	Unit lost electrical power	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A84	19/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A50	18/03/2015	Leaks found at turrets A and B	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A16	08/09/2015	Power supply failure detected	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A25	17/09/2015	Inspect and recharge accumulators	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A39	24/04/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams

A33	23/05/2015	Leaks found at turrets A and B	Cristian Santos noted: Detail not recorded.	cristian_santos
A86	07/11/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A73	25/08/2015	Milling spindle requires repair	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A83	13/07/2015	Repair work needed on milling spindle	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A14	14/10/2015	Turret sections A & B showing leaks	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A30	22/01/2015	Spindle indexing error with overfeed	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A17	12/08/2015	Accumulators need checking and charging	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A42	19/02/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A18	15/06/2015	Power supply failure detected	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A27	22/11/2015	Unit lost electrical power	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A2	22/01/2015	Turret A and B are leaking	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A73	03/03/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A52	31/03/2015	Maintenance on milling spindle needed	Cristian Santos noted: Detail not recorded.	cristian_santos
A17	04/03/2015	Turret A and B are leaking	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A75	17/09/2015	Power supply failure detected	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A45	04/05/2015	Spindle fails to index, overfeeding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A62	16/06/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A99	19/10/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A80	08/03/2015	Milling spindle requires repair	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A3	23/02/2015	Maintenance on milling spindle needed	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A35	23/12/2015	Unit lost electrical power	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A62	11/01/2016	Unit lost electrical power	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A33	25/04/2015	Accumulator inspection and charging required	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A44	23/09/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A5	17/01/2015	Hydraulic line leak on side B	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A12	29/01/2015	Hydraulic line leak on side B	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A30	29/10/2015	Power supply failure detected	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A50	19/10/2015	Leaks found at turrets A and B	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A32	07/06/2015	Turret A and B are leaking	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A62	02/08/2015	Maintenance on milling spindle needed	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A33	12/06/2015	Turret A and B are leaking	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A35	20/03/2015	Milling spindle requires repair	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A3	27/02/2015	Accumulator inspection and charging required	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A19	18/09/2015	Machine is unpowered	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A47	01/12/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: No further details.	nathan_maldonado
A62	21/04/2015	Spindle indexing error with overfeed	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A33	29/03/2015	Leaks found at turrets A and B	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A56	10/03/2015	Hydraulic line leak on side B	Cristian Santos noted: No additional information provided.	cristian_santos
A31	19/02/2015	Turret sections A & B showing leaks	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A16	18/09/2015	Milling spindle requires repair	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A54	08/12/2015	Turret A and B are leaking	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A4	20/02/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A49	03/05/2015	Inspect and recharge accumulators	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A13	15/09/2015	Inspect and recharge accumulators	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A4	13/08/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A70	21/01/2015	Spindle indexing error with overfeed	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A9	28/08/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A16	01/08/2015	Turret A and B are leaking	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A43	16/11/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A67	15/08/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A81	08/10/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Maintenance action successful.	michele_williams
A87	08/01/2016	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A3	28/06/2015	Hydraulic line leak on side B	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A62	04/05/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A47	10/12/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A38	26/10/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A32	10/12/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A44	24/11/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A2	09/05/2015	Maintenance on milling spindle needed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A9	26/04/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A77	16/08/2015	Hydraulic line leak on side B	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A29	16/10/2015	Leak in side B hydraulic line	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A15	17/04/2015	Accumulators need checking and charging	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A39	11/11/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: System checked and accumulators charged.	michele_williams
A6	05/05/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: No further details.	nathan_maldonado
A98	24/02/2015	Maintenance on milling spindle needed	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A49	04/02/2015	Accumulator inspection and charging required	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A51	06/01/2016	Hydraulic hose on side B is leaking	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A70	21/11/2015	Unit lost electrical power	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A10	13/05/2015	Turret sections A & B showing leaks	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller

A34	30/09/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A15	13/03/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A71	12/05/2015	Leaks found at turrets A and B	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A86	07/01/2016	Hydraulic line leak on side B	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A31	06/12/2015	Saw attachment gears are binding and grinding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A20	18/11/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A4	28/06/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A19	30/11/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A5	05/02/2015	Repair work needed on milling spindle	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A64	17/05/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A73	05/04/2015	Machine is unpowered	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A58	06/07/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A56	23/07/2015	Milling spindle requires repair	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A74	27/01/2015	Power supply failure detected	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A5	30/04/2015	Turret sections A & B showing leaks	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A12	03/10/2015	Leak in side B hydraulic line	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A86	20/10/2015	Inspect and recharge accumulators	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A62	29/11/2015	Unit lost electrical power	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A69	01/08/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A31	08/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Detail not recorded.	cristian_santos
A63	09/12/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A2	20/03/2015	Turret A and B are leaking	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A55	04/03/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A85	29/12/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A97	19/06/2015	Accumulators need checking and charging	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A91	31/05/2015	Milling spindle requires repair	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A37	28/12/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A25	29/10/2015	Machine is unpowered	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A97	27/11/2015	Machine is unpowered	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A8	16/05/2015	Inspect and recharge accumulators	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A99	25/03/2015	Turret sections A & B showing leaks	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A35	06/11/2015	Machine is unpowered	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A74	12/11/2015	Power supply failure detected	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A52	21/06/2015	Leak in side B hydraulic line	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A36	09/10/2015	Spindle indexing error with overfeed	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A54	06/02/2015	Hydraulic line leak on side B	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A35	22/06/2015	Unit lost electrical power	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A65	07/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A7	25/09/2015	Hydraulic line leak on side B	Michele Williams noted: Detail not recorded.	michele_williams
A90	25/11/2015	Unit lost electrical power	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A6	26/05/2015	Spindle indexing error with overfeed	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A91	08/07/2015	Leak in side B hydraulic line	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A21	20/10/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A77	22/03/2015	Power supply failure detected	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A49	13/06/2015	Turret sections A & B showing leaks	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A36	20/07/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A52	13/01/2016	Unit lost electrical power	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A71	25/03/2015	Leak in side B hydraulic line	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A97	03/10/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A7	21/01/2015	Spindle indexing error with overfeed	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A84	01/02/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A76	10/12/2015	Turret A and B are leaking	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A55	06/02/2015	Accumulator inspection and charging required	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A97	16/08/2015	Unit lost electrical power	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A71	01/06/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A39	23/04/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A20	15/06/2015	Turret sections A & B showing leaks	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A79	15/02/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A75	17/11/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A97	28/02/2015	Accumulator inspection and charging required	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A89	01/09/2015	Turret A and B are leaking	Michele Williams noted: Detail not recorded.	michele_williams
A30	08/11/2015	Machine is unpowered	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A38	12/05/2015	Unit lost electrical power	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A35	01/10/2015	Inspect and recharge accumulators	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A49	10/08/2015	Leak in side B hydraulic line	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A50	23/11/2015	Unit lost electrical power	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A97	03/01/2016	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A83	18/06/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A27	09/03/2015	Power supply failure detected	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A93	23/06/2015	Maintenance on milling spindle needed	Cristian Santos noted: Repair completed.	cristian_santos

A90	09/07/2015	Maintenance on milling spindle needed	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A1	18/09/2015	Unit lost electrical power	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A81	08/10/2015	Unit lost electrical power	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A81	08/10/2015	Leak in side B hydraulic line	Cristian Santos noted: Repair completed.	cristian_santos
A88	13/11/2015	Power supply failure detected	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A16	23/04/2015	Spindle indexing error with overfeed	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A20	31/05/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A94	24/04/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Maintenance action successful.	michele_williams
A98	29/09/2015	Turret sections A & B showing leaks	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A17	28/02/2015	Milling spindle requires repair	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A4	29/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A35	07/10/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A83	06/06/2015	Turret sections A & B showing leaks	Cristian Santos noted: Repair completed.	cristian_santos
A82	27/06/2015	Power supply failure detected	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A49	08/02/2015	Milling spindle requires repair	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A77	14/09/2015	Hydraulic line leak on side B	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A61	22/05/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A18	30/09/2015	Machine is unpowered	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A48	11/09/2015	Spindle indexing error with overfeed	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A33	28/05/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: No additional information provided.	cristian_santos
A49	26/10/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A26	28/11/2015	Inspect and recharge accumulators	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A27	01/02/2015	Leaks found at turrets A and B	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A29	26/01/2015	Inspect and recharge accumulators	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A17	25/02/2015	Milling spindle requires repair	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A65	10/05/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A80	05/06/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A49	21/07/2015	Repair work needed on milling spindle	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A78	17/04/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A45	15/02/2015	Accumulator inspection and charging required	Michele Williams noted: No further details.	michele_williams
A89	04/04/2015	Leak in side B hydraulic line	Gina Moore noted: No further details.	gina_moore, dylan_miller
A30	20/10/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A23	31/08/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A62	04/10/2015	Inspect and recharge accumulators	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A3	21/09/2015	Hydraulic line leak on side B	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A42	14/05/2015	Leaks found at turrets A and B	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A75	28/07/2015	Leaks found at turrets A and B	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A3	01/01/2016	Unit lost electrical power	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A2	26/05/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A89	31/01/2015	Power supply failure detected	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A44	22/11/2015	Accumulators need checking and charging	Cristian Santos noted: No additional information provided.	cristian_santos
A58	01/03/2015	Spindle indexing error with overfeed	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A37	20/08/2015	Power supply failure detected	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A13	09/06/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A46	26/01/2015	Accumulators need checking and charging	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A26	11/01/2016	Spindle fails to index, overfeeding	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A58	17/05/2015	Leaks found at turrets A and B	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A91	25/04/2015	Spindle indexing error with overfeed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A83	15/11/2015	Leak in side B hydraulic line	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A51	09/11/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: No additional information provided.	cristian_santos
A67	17/02/2015	Leaks found at turrets A and B	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A51	15/12/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A38	21/10/2015	Turret sections A & B showing leaks	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A6	28/08/2015	Power supply failure detected	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A95	05/05/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A85	11/06/2015	Accumulators need checking and charging	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A13	11/04/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A52	04/01/2016	Saw attachment gears are binding and grinding	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A90	26/02/2015	Unit lost electrical power	Michele Williams noted: Detail not recorded.	michele_williams
A19	22/02/2015	Machine is unpowered	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A23	28/12/2015	Power supply failure detected	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A51	08/01/2016	Repair work needed on milling spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A17	29/12/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A68	08/03/2015	Machine is unpowered	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A50	27/08/2015	Hydraulic line leak on side B	Michele Williams noted: Fixed and tested.	michele_williams
A58	11/10/2015	Turret A and B are leaking	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A25	05/02/2015	Maintenance on milling spindle needed	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A37	07/12/2015	Leak in side B hydraulic line	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A48	21/02/2015	Accumulators need checking and charging	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A25	10/11/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Maintenance action successful.	cristian_santos

A25	31/07/2015	Turret sections A & B showing leaks	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A30	10/12/2015	Unit lost electrical power	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A13	25/01/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A76	07/06/2015	Leaks found at turrets A and B	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A57	14/08/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A17	11/02/2015	Power supply failure detected	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A62	15/08/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A37	03/04/2015	Spindle fails to index, overfeeding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A64	29/01/2015	Power supply failure detected	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A78	25/10/2015	Hydraulic line leak on side B	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A97	25/09/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A37	31/05/2015	Leaks found at turrets A and B	Gina Moore noted: No further details.	gina_moore, dylan_miller
A82	23/07/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A59	20/04/2015	Inspect and recharge accumulators	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A41	23/12/2015	Inspect and recharge accumulators	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A51	25/07/2015	Accumulators need checking and charging	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A95	24/04/2015	Maintenance on milling spindle needed	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A83	26/03/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A32	03/03/2015	Accumulator inspection and charging required	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A11	06/01/2016	Accumulators need checking and charging	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A99	26/10/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A1	14/02/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A42	17/09/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A40	26/08/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A93	24/08/2015	Leaks found at turrets A and B	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A26	21/04/2015	Milling spindle requires repair	Michele Williams noted: Maintenance action successful.	michele_williams
A47	06/09/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A81	04/10/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A94	09/11/2015	Turret sections A & B showing leaks	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A57	05/04/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: No further details.	gina_moore, dylan_miller
A16	28/09/2015	Machine is unpowered	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A58	01/06/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: No additional information provided.	michele_williams
A83	03/12/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A77	18/07/2015	Repair work needed on milling spindle	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A68	04/07/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A56	09/05/2015	Accumulators need checking and charging	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A28	13/03/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A96	11/08/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A62	09/12/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A68	14/07/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A92	12/08/2015	Leaks found at turrets A and B	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A99	20/04/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A89	25/09/2015	Hydraulic line leak on side B	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A61	29/04/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A6	22/07/2015	Repair work needed on milling spindle	Cristian Santos noted: Repair completed.	cristian_santos
A12	25/09/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A52	27/03/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A52	10/07/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A16	11/05/2015	Hydraulic line leak on side B	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A47	14/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A23	18/09/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A11	02/11/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A63	01/03/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A89	13/02/2015	Spindle indexing error with overfeed	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A11	22/01/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A25	25/01/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A34	03/11/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A8	28/09/2015	Spindle indexing error with overfeed	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A24	02/06/2015	Machine is unpowered	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A57	19/01/2015	Spindle indexing error with overfeed	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A24	20/11/2015	Hydraulic line leak on side B	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A72	29/12/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A73	13/06/2015	Machine is unpowered	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A31	14/12/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A46	29/08/2015	Inspect and recharge accumulators	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A19	31/12/2015	Turret sections A & B showing leaks	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A66	21/02/2015	Maintenance on milling spindle needed	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A16	24/09/2015	Turret sections A & B showing leaks	Michele Williams noted: System checked and accumulators charged.	michele_williams
A65	11/03/2015	Spindle indexing error with overfeed	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A36	07/04/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams

A92	06/09/2015	Accumulator inspection and charging required	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A38	05/06/2015	Leaks found at turrets A and B	Cristian Santos noted: Detail not recorded.	cristian_santos
A67	30/12/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A8	04/10/2015	Machine is unpowered	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A29	02/05/2015	Machine is unpowered	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A57	25/07/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A77	05/09/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A56	09/11/2015	Inspect and recharge accumulators	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A3	27/02/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A93	18/02/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A18	25/06/2015	Milling spindle requires repair	Michele Williams noted: Fixed and tested.	michele_williams
A34	09/02/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A40	27/11/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A7	02/05/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A94	08/07/2015	Power supply failure detected	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A21	22/01/2015	Accumulators need checking and charging	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A55	10/10/2015	Spindle indexing error with overfeed	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A42	26/12/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A52	28/01/2015	Leaks found at turrets A and B	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A20	26/11/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A96	23/06/2015	Unit lost electrical power	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A81	04/03/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A29	11/06/2015	Maintenance on milling spindle needed	Michele Williams noted: System checked and accumulators charged.	michele_williams
A7	13/12/2015	Leak in side B hydraulic line	Michele Williams noted: System checked and accumulators charged.	michele_williams
A14	13/12/2015	Hydraulic line leak on side B	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A47	12/04/2015	Leak in side B hydraulic line	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A67	13/10/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A18	25/12/2015	Turret sections A & B showing leaks	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A89	24/07/2015	Power supply failure detected	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A95	16/08/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A72	27/03/2015	Turret sections A & B showing leaks	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A18	02/06/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: System checked and accumulators charged.	michele_williams
A93	13/07/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A85	04/12/2015	Leaks found at turrets A and B	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A25	06/12/2015	Milling spindle requires repair	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A12	29/01/2015	Spindle indexing error with overfeed	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A11	11/10/2015	Accumulators need checking and charging	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A84	30/10/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Fixed and tested.	michele_williams
A70	16/08/2015	Turret sections A & B showing leaks	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A55	27/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A98	26/08/2015	Spindle indexing error with overfeed	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A75	29/12/2015	Milling spindle requires repair	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A43	19/08/2015	Hydraulic line leak on side B	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A17	21/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A35	06/04/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A25	08/03/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A5	17/09/2015	Unit lost electrical power	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A32	25/04/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A91	10/12/2015	Milling spindle requires repair	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A52	21/05/2015	Milling spindle requires repair	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A94	04/07/2015	Unit lost electrical power	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A74	16/10/2015	Leak in side B hydraulic line	Michele Williams noted: Maintenance action successful.	michele_williams
A28	14/08/2015	Accumulators need checking and charging	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A50	06/08/2015	Inspect and recharge accumulators	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A4	01/07/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A77	30/05/2015	Accumulators need checking and charging	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A52	01/06/2015	Accumulators need checking and charging	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A95	20/05/2015	Milling spindle requires repair	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A18	22/07/2015	Repair work needed on milling spindle	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A23	11/09/2015	Unit lost electrical power	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A17	19/06/2015	Maintenance on milling spindle needed	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A67	27/08/2015	Unit lost electrical power	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A23	02/05/2015	Repair work needed on milling spindle	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A7	12/06/2015	Spindle indexing error with overfeed	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A32	29/05/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A4	05/07/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A57	13/08/2015	Power supply failure detected	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A44	09/05/2015	Turret A and B are leaking	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A57	02/09/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A57	26/01/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams

A70	08/06/2015	Machine is unpowered	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A53	02/11/2015	Inspect and recharge accumulators	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A61	17/03/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A75	10/05/2015	Hydraulic line leak on side B	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A58	07/08/2015	Power supply failure detected	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A78	14/03/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A86	11/10/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A58	02/07/2015	Accumulator inspection and charging required	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A67	05/06/2015	Machine is unpowered	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A7	26/06/2015	Spindle indexing error with overfeed	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A18	19/08/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A56	24/02/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A19	12/09/2015	Turret A and B are leaking	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A91	27/09/2015	Turret sections A & B showing leaks	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A60	15/08/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A18	23/02/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A21	26/04/2015	Milling spindle requires repair	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A36	19/12/2015	Spindle fails to index, overfeeding	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A75	06/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A25	19/05/2015	Spindle fails to index, overfeeding	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A55	20/10/2015	Spindle indexing error with overfeed	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A45	02/08/2015	Machine is unpowered	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A3	23/01/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A49	27/01/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A43	08/11/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A82	30/11/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A70	02/03/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A93	18/11/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A89	02/08/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A51	23/12/2015	Accumulators need checking and charging	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A47	26/05/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A81	17/09/2015	Spindle indexing error with overfeed	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A38	13/11/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A38	23/09/2015	Maintenance on milling spindle needed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A61	03/01/2016	Hydraulic line leak on side B	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A34	15/01/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A39	24/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A77	01/02/2015	Maintenance on milling spindle needed	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A68	30/01/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A22	11/01/2016	Hydraulic hose on side B is leaking	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A89	21/05/2015	Milling spindle requires repair	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A59	29/06/2015	Milling spindle requires repair	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A30	27/03/2015	Turret A and B are leaking	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A92	01/09/2015	Machine is unpowered	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A19	01/04/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A88	01/04/2015	Inspect and recharge accumulators	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A39	28/04/2015	Leaks found at turrets A and B	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A85	23/08/2015	Spindle indexing error with overfeed	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A84	18/01/2015	Power supply failure detected	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A92	26/03/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A65	17/12/2015	Spindle fails to index, overfeeding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A33	22/05/2015	Leaks found at turrets A and B	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A79	24/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A7	28/02/2015	Repair work needed on milling spindle	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A66	08/12/2015	Inspect and recharge accumulators	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A78	03/03/2015	Turret A and B are leaking	Michele Williams noted: Repair completed.	michele_williams
A86	06/12/2015	Power supply failure detected	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A73	09/10/2015	Saw attachment gears are binding and grinding	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A59	02/03/2015	Hydraulic line leak on side B	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A24	06/08/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A48	28/08/2015	Power supply failure detected	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A72	21/08/2015	Leaks found at turrets A and B	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A15	25/03/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A83	11/12/2015	Leak in side B hydraulic line	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A86	09/03/2015	Repair work needed on milling spindle	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A21	01/04/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A36	08/03/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A54	22/10/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A90	29/06/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A2	31/03/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos

A24	04/10/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A77	23/02/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A38	18/04/2015	Turret sections A & B showing leaks	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A13	24/08/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A82	19/09/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A21	11/05/2015	Accumulators need checking and charging	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A38	13/11/2015	Leaks found at turrets A and B	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A89	24/10/2015	Hydraulic line leak on side B	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A95	24/06/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: No further details.	nathan_maldonado
A37	21/07/2015	Unit lost electrical power	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A56	23/01/2015	Leak in side B hydraulic line	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A76	14/04/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A2	14/02/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A73	15/05/2015	Power supply failure detected	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A6	14/07/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A32	22/08/2015	Repair work needed on milling spindle	Michele Williams noted: No further details.	michele_williams
A28	26/06/2015	Hydraulic line leak on side B	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A69	16/06/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A99	16/01/2015	Power supply failure detected	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A36	09/05/2015	Power supply failure detected	Cristian Santos noted: Repair completed.	cristian_santos
A19	01/01/2016	Leaks found at turrets A and B	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A34	22/02/2015	Machine is unpowered	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A81	11/12/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A34	30/05/2015	Turret A and B are leaking	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A68	27/08/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A8	03/01/2016	Accumulator inspection and charging required	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A8	12/12/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A56	21/04/2015	Inspect and recharge accumulators	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A72	28/06/2015	Unit lost electrical power	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A88	21/02/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A6	22/05/2015	Accumulator inspection and charging required	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A65	22/10/2015	Leak in side B hydraulic line	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A88	28/07/2015	Leaks found at turrets A and B	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A74	18/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A46	05/09/2015	Milling spindle requires repair	Cristian Santos noted: No further details.	cristian_santos
A78	11/03/2015	Accumulators need checking and charging	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A34	17/08/2015	Power supply failure detected	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A71	10/02/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A47	11/05/2015	Turret sections A & B showing leaks	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A15	02/08/2015	Hydraulic line leak on side B	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A1	28/09/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A67	23/12/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A93	07/04/2015	Power supply failure detected	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A49	13/02/2015	Hydraulic line leak on side B	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A70	17/07/2015	Accumulators need checking and charging	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A56	15/03/2015	Accumulator inspection and charging required	Michele Williams noted: Fixed and tested.	michele_williams
A76	09/10/2015	Inspect and recharge accumulators	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A3	27/04/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Fixed and tested.	cristian_santos
A23	30/07/2015	Power supply failure detected	Cristian Santos noted: Detail not recorded.	cristian_santos
A93	28/07/2015	Machine is unpowered	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A73	21/11/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A73	11/08/2015	Machine is unpowered	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A33	14/01/2015	Repair work needed on milling spindle	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A47	11/09/2015	Accumulators need checking and charging	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A98	16/06/2015	Unit lost electrical power	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A58	16/10/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A45	24/08/2015	Inspect and recharge accumulators	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A73	01/07/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A59	16/07/2015	Inspect and recharge accumulators	Michele Williams noted: Repair completed.	michele_williams
A84	29/10/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A85	10/08/2015	Turret A and B are leaking	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A83	27/05/2015	Leak in side B hydraulic line	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A64	24/10/2015	Spindle fails to index, overfeeding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A57	05/01/2016	Accumulators need checking and charging	Michele Williams noted: Fixed and tested.	michele_williams
A22	03/08/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A32	23/05/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A2	18/09/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A30	17/08/2015	Machine is unpowered	Gina Moore noted: No further details.	gina_moore, dylan_miller
A68	03/12/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A40	29/03/2015	Hydraulic line leak on side B	Michele Williams noted: Reviewed; system operating normally.	michele_williams

A40	23/07/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A6	25/03/2015	Power supply failure detected	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A56	02/11/2015	Hydraulic line leak on side B	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A73	23/01/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A77	20/10/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A47	20/11/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A60	09/01/2016	Accumulator inspection and charging required	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A57	26/01/2015	Machine is unpowered	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A71	12/10/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A38	30/08/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A77	17/05/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A90	29/05/2015	Accumulators need checking and charging	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A15	29/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A16	23/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A51	10/03/2015	Repair work needed on milling spindle	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A39	30/03/2015	Repair work needed on milling spindle	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A78	24/08/2015	Machine is unpowered	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A76	04/06/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A27	30/11/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A93	23/04/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A22	21/01/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A90	08/12/2015	Turret sections A & B showing leaks	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A83	21/02/2015	Spindle indexing error with overfeed	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A91	28/11/2015	Inspect and recharge accumulators	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A60	19/04/2015	Power supply failure detected	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A19	05/10/2015	Leak in side B hydraulic line	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A93	03/01/2016	Turret sections A & B showing leaks	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A2	03/04/2015	Maintenance on milling spindle needed	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A83	17/10/2015	Leaks found at turrets A and B	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A99	03/10/2015	Machine is unpowered	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A92	27/04/2015	Spindle indexing error with overfeed	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A32	21/09/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A90	14/11/2015	Leaks found at turrets A and B	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A19	02/08/2015	Accumulator inspection and charging required	Michele Williams noted: Repair completed.	michele_williams
A27	09/02/2015	Machine is unpowered	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A18	25/03/2015	Turret A and B are leaking	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A5	11/10/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A98	09/06/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A31	20/03/2015	Power supply failure detected	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A7	08/04/2015	Milling spindle requires repair	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A55	24/02/2015	Inspect and recharge accumulators	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A10	27/03/2015	Turret sections A & B showing leaks	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A14	24/10/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A21	04/06/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A86	22/05/2015	Accumulator inspection and charging required	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A54	29/10/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A35	02/12/2015	Accumulator inspection and charging required	Michele Williams noted: Fixed and tested.	michele_williams
A24	17/02/2015	Power supply failure detected	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A67	16/12/2015	Turret A and B are leaking	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A67	27/12/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A86	18/09/2015	Accumulators need checking and charging	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A4	03/11/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: No further details.	nathan_maldonado
A34	26/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Detail not recorded.	michele_williams
A22	10/12/2015	Milling spindle requires repair	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A31	17/04/2015	Unit lost electrical power	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A69	28/07/2015	Hydraulic line leak on side B	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A95	16/07/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A74	12/05/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A71	30/10/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: System checked and accumulators charged.	michele_williams
A55	27/09/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A19	13/08/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A87	05/10/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A32	07/06/2015	Repair work needed on milling spindle	Nathan Maldonado noted: No further details.	nathan_maldonado
A35	16/03/2015	Spindle indexing error with overfeed	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A3	16/11/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A88	04/03/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A57	10/12/2015	Spindle indexing error with overfeed	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A83	19/01/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A30	16/04/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A96	23/06/2015	Leak in side B hydraulic line	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams

A98	08/01/2016	Unit lost electrical power	Michele Williams noted: Maintenance action successful.	michele_williams
A17	27/12/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A32	07/07/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A67	16/09/2015	Machine is unpowered	Cristian Santos noted: No additional information provided.	cristian_santos
A28	14/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A26	27/05/2015	Spindle indexing error with overfeed	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A71	19/11/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A49	05/04/2015	Power supply failure detected	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A78	23/02/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A21	12/01/2016	Spindle fails to index, overfeeding	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A82	13/02/2015	Unit lost electrical power	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A98	14/01/2015	Milling spindle requires repair	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A25	21/07/2015	Repair work needed on milling spindle	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A22	14/02/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A47	27/11/2015	Unit lost electrical power	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A45	04/08/2015	Turret sections A & B showing leaks	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A46	29/05/2015	Inspect and recharge accumulators	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A74	04/07/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A33	18/07/2015	Milling spindle requires repair	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A52	19/03/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A60	29/11/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A8	08/01/2016	Inspect and recharge accumulators	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A48	19/12/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A88	11/12/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Detail not recorded.	michele_williams
A55	30/11/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A57	01/09/2015	Power supply failure detected	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A45	27/02/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A79	19/01/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A36	17/11/2015	Turret A and B are leaking	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A63	27/03/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A1	05/07/2015	Hydraulic line leak on side B	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A63	25/07/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A5	14/11/2015	Spindle indexing error with overfeed	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A83	28/12/2015	Milling spindle requires repair	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A44	05/01/2016	Inspect and recharge accumulators	Cristian Santos noted: Maintenance action successful.	cristian_santos
A35	05/06/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A65	14/02/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A69	30/09/2015	Milling spindle requires repair	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A85	16/02/2015	Unit lost electrical power	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A90	12/11/2015	Turret sections A & B showing leaks	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A47	30/07/2015	Repair work needed on milling spindle	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A71	21/11/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A13	14/07/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A76	26/01/2015	Maintenance on milling spindle needed	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A82	19/01/2015	Maintenance on milling spindle needed	Cristian Santos noted: Fixed and tested.	cristian_santos
A74	16/02/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A2	28/02/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A1	26/10/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A53	02/03/2015	Maintenance on milling spindle needed	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A48	19/11/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A15	23/01/2015	Turret sections A & B showing leaks	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A87	17/06/2015	Leak in side B hydraulic line	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A65	21/11/2015	Machine is unpowered	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A28	13/04/2015	Repair work needed on milling spindle	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A57	15/07/2015	Power supply failure detected	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A65	20/02/2015	Milling spindle requires repair	Michele Williams noted: System checked and accumulators charged.	michele_williams
A13	21/09/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A72	14/01/2015	Milling spindle requires repair	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A19	25/05/2015	Inspect and recharge accumulators	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A94	02/04/2015	Inspect and recharge accumulators	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A83	24/04/2015	Hydraulic line leak on side B	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A16	07/01/2016	Unit lost electrical power	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A59	08/10/2015	Accumulator inspection and charging required	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A87	17/11/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A84	19/07/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A57	08/10/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A45	31/08/2015	Milling spindle requires repair	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A57	18/04/2015	Unit lost electrical power	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A59	13/11/2015	Power supply failure detected	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A8	14/04/2015	Leaks found at turrets A and B	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams

A20	21/11/2015	Repair work needed on milling spindle	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A29	27/05/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A83	03/08/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A77	26/05/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A8	24/02/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: No further details.	michele_williams
A2	15/12/2015	Maintenance on milling spindle needed	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A34	26/03/2015	Accumulators need checking and charging	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A85	12/11/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A92	30/05/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A14	20/01/2015	Unit lost electrical power	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A35	09/09/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A54	08/09/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A73	23/09/2015	Machine is unpowered	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A84	22/02/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A71	22/02/2015	Turret A and B are leaking	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A36	07/07/2015	Power supply failure detected	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A97	25/06/2015	Leak in side B hydraulic line	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A10	26/03/2015	Milling spindle requires repair	Cristian Santos noted: Maintenance action successful.	cristian_santos
A91	01/02/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A52	13/07/2015	Machine is unpowered	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A99	08/02/2015	Turret A and B are leaking	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A20	17/05/2015	Accumulators need checking and charging	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A70	30/05/2015	Accumulator inspection and charging required	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A1	07/07/2015	Maintenance on milling spindle needed	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A85	20/10/2015	Accumulators need checking and charging	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A6	31/08/2015	Machine is unpowered	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A29	23/01/2015	Spindle indexing error with overfeed	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A15	23/05/2015	Milling spindle requires repair	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A61	10/11/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A33	01/02/2015	Inspect and recharge accumulators	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A50	10/02/2015	Unit lost electrical power	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A14	24/11/2015	Turret A and B are leaking	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A78	17/12/2015	Hydraulic line leak on side B	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A55	31/07/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A50	18/12/2015	Machine is unpowered	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A31	31/07/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A37	11/01/2016	Turret A and B are leaking	Cristian Santos noted: Detail not recorded.	cristian_santos
A35	06/10/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A68	06/05/2015	Power supply failure detected	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A43	20/01/2015	Turret A and B are leaking	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A41	13/01/2016	Indexing issue causing overfeed on spindle	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A4	29/11/2015	Leak in side B hydraulic line	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A54	15/08/2015	Inspect and recharge accumulators	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A40	01/09/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Repair completed.	cristian_santos
A57	02/10/2015	Accumulator inspection and charging required	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A58	10/09/2015	Accumulators need checking and charging	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A32	07/08/2015	Machine is unpowered	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A86	05/05/2015	Machine is unpowered	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A37	20/04/2015	Machine is unpowered	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A29	17/11/2015	Accumulator inspection and charging required	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A4	17/11/2015	Inspect and recharge accumulators	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A32	02/02/2015	Milling spindle requires repair	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A40	23/12/2015	Spindle indexing error with overfeed	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A4	03/08/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A51	31/05/2015	Repair work needed on milling spindle	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A26	17/06/2015	Spindle fails to index, overfeeding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A20	17/11/2015	Repair work needed on milling spindle	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A52	14/04/2015	Leak in side B hydraulic line	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A68	14/11/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A99	14/06/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A95	26/11/2015	Spindle indexing error with overfeed	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A80	19/07/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A83	29/04/2015	Spindle indexing error with overfeed	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A58	20/12/2015	Saw attachment gears are binding and grinding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A89	07/01/2016	Saw attachment is leaking hydraulics	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A9	02/09/2015	Hydraulic line leak on side B	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A56	06/05/2015	Accumulators need checking and charging	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A58	03/06/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A21	14/03/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: No further details.	nathan_maldonado
A57	01/05/2015	Turret sections A & B showing leaks	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams

A10	01/12/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: No further details.	gina_moore, dylan_miller
A20	23/11/2015	Spindle indexing error with overfeed	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A64	27/07/2015	Maintenance on milling spindle needed	Michele Williams noted: Repair completed.	michele_williams
A26	10/04/2015	Repair work needed on milling spindle	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A13	16/03/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A89	18/09/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A11	26/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A64	05/09/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A31	27/10/2015	Milling spindle requires repair	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A9	14/07/2015	Power supply failure detected	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A53	02/09/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A51	05/12/2015	Repair work needed on milling spindle	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A33	31/07/2015	Inspect and recharge accumulators	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A93	06/07/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A11	31/08/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A57	01/10/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A15	27/07/2015	Accumulator inspection and charging required	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A63	24/12/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Fixed and tested.	cristian_santos
A38	02/02/2015	Turret A and B are leaking	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A85	25/07/2015	Leaks found at turrets A and B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A5	24/06/2015	Leak in side B hydraulic line	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A98	03/08/2015	Leaks found at turrets A and B	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A25	28/12/2015	Power supply failure detected	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A52	15/09/2015	Machine is unpowered	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A54	18/06/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A12	09/12/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A42	16/11/2015	Maintenance on milling spindle needed	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A58	17/01/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A70	20/10/2015	Spindle fails to index, overfeeding	Michele Williams noted: Fixed and tested.	michele_williams
A57	08/11/2015	Inspect and recharge accumulators	Michele Williams noted: No additional information provided.	michele_williams
A15	17/03/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A64	17/12/2015	Unit lost electrical power	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A77	10/11/2015	Accumulators need checking and charging	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A17	26/05/2015	Leak in side B hydraulic line	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A21	30/09/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Repair completed.	michele_williams
A74	25/11/2015	Leak in side B hydraulic line	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A17	30/04/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A59	06/08/2015	Milling spindle requires repair	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A44	07/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A72	15/03/2015	Spindle indexing error with overfeed	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A83	16/09/2015	Turret sections A & B showing leaks	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A15	05/01/2016	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A16	21/02/2015	Repair work needed on milling spindle	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A20	19/08/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A89	12/04/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A84	11/10/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A11	17/12/2015	Accumulators need checking and charging	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A63	19/09/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A4	25/02/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A61	20/11/2015	Inspect and recharge accumulators	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A23	07/10/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A21	19/05/2015	Spindle fails to index, overfeeding	Cristian Santos noted: No additional information provided.	cristian_santos
A79	04/07/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A63	22/07/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A68	29/07/2015	Maintenance on milling spindle needed	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A17	02/07/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A81	31/03/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A53	01/04/2015	Turret sections A & B showing leaks	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A71	29/10/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A86	23/01/2015	Leaks found at turrets A and B	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A28	11/12/2015	Machine is unpowered	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A61	19/09/2015	Power supply failure detected	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A65	18/03/2015	Turret A and B are leaking	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A60	08/01/2016	Unit lost electrical power	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A96	16/08/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A53	08/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A78	15/10/2015	Accumulator inspection and charging required	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A12	22/05/2015	Turret A and B are leaking	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A65	04/05/2015	Unit lost electrical power	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A37	18/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Repair completed.	nathan_maldonado

A97	14/04/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A51	21/05/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A95	11/12/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A4	01/09/2015	Spindle fails to index, overfeeding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A77	17/10/2015	Machine is unpowered	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A90	07/06/2015	Leak in side B hydraulic line	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A93	13/10/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A52	16/06/2015	Hydraulic line leak on side B	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A41	05/04/2015	Turret sections A & B showing leaks	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A51	25/10/2015	Machine is unpowered	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A57	09/02/2015	Turret sections A & B showing leaks	Michele Williams noted: System checked and accumulators charged.	michele_williams
A90	10/04/2015	Power supply failure detected	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A15	02/06/2015	Turret sections A & B showing leaks	Michele Williams noted: No additional information provided.	michele_williams
A3	25/04/2015	Inspect and recharge accumulators	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A54	16/05/2015	Machine is unpowered	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A35	25/11/2015	Turret sections A & B showing leaks	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A99	25/11/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A56	06/01/2016	Hydraulic line leak on side B	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A93	18/06/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Repair completed.	cristian_santos
A99	10/05/2015	Machine is unpowered	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A56	28/07/2015	Repair work needed on milling spindle	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A84	28/02/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A16	09/02/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A34	20/11/2015	Accumulator inspection and charging required	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A58	02/03/2015	Leaks found at turrets A and B	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A68	12/01/2016	Accumulator inspection and charging required	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A23	21/02/2015	Inspect and recharge accumulators	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A16	02/04/2015	Unit lost electrical power	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A35	26/08/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A73	05/10/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A51	15/06/2015	Accumulator inspection and charging required	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A67	17/04/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A35	19/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A64	19/08/2015	Milling spindle requires repair	Michele Williams noted: No further details.	michele_williams
A95	25/10/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A62	01/01/2016	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A81	03/11/2015	Turret A and B are leaking	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A83	15/04/2015	Accumulator inspection and charging required	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A12	17/06/2015	Milling spindle requires repair	Cristian Santos noted: Fixed and tested.	cristian_santos
A57	19/09/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A77	28/04/2015	Power supply failure detected	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A26	09/04/2015	Machine is unpowered	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A20	16/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A22	07/08/2015	Leaks found at turrets A and B	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A22	18/06/2015	Turret A and B are leaking	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A50	11/06/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A32	24/09/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A93	08/09/2015	Inspect and recharge accumulators	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A34	28/11/2015	Milling spindle requires repair	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A68	21/07/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A32	29/09/2015	Hydraulic line leak on side B	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A10	03/09/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A56	22/05/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A29	21/10/2015	Inspect and recharge accumulators	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A66	04/06/2015	Unit lost electrical power	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A23	10/07/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A85	30/06/2015	Milling spindle requires repair	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A63	09/05/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A43	23/09/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A61	27/10/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A17	17/04/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A69	20/04/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A58	09/07/2015	Hydraulic line leak on side B	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A15	22/09/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A52	26/11/2015	Repair work needed on milling spindle	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A97	21/10/2015	Unit lost electrical power	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A80	27/09/2015	Inspect and recharge accumulators	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A42	26/10/2015	Spindle indexing error with overfeed	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A94	29/10/2015	Inspect and recharge accumulators	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A78	19/10/2015	Machine is unpowered	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller

A61	09/12/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A78	25/03/2015	Machine is unpowered	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A75	02/07/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A75	15/01/2015	Turret sections A & B showing leaks	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A41	10/06/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A28	22/03/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A89	05/04/2015	Maintenance on milling spindle needed	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A71	17/10/2015	Spindle fails to index, overfeeding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A44	06/08/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A4	24/07/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A39	13/02/2015	Spindle indexing error with overfeed	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A55	16/02/2015	Power supply failure detected	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A79	16/06/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A9	10/02/2015	Leaks found at turrets A and B	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A53	22/11/2015	Accumulators need checking and charging	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A36	08/05/2015	Hydraulic line leak on side B	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A44	22/06/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A78	02/05/2015	Power supply failure detected	Michele Williams noted: No additional information provided.	michele_williams
A86	29/03/2015	Hydraulic line leak on side B	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A3	18/04/2015	Power supply failure detected	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A65	03/10/2015	Turret A and B are leaking	Michele Williams noted: Detail not recorded.	michele_williams
A1	19/06/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A49	13/05/2015	Turret A and B are leaking	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A45	02/04/2015	Accumulator inspection and charging required	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A58	21/11/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A55	20/09/2015	Accumulator inspection and charging required	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A50	20/06/2015	Spindle indexing error with overfeed	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A30	24/10/2015	Accumulators need checking and charging	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A68	15/10/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A53	16/02/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A70	17/05/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A40	24/06/2015	Accumulator inspection and charging required	Nathan Maldonado noted: No further details.	nathan_maldonado
A51	30/03/2015	Milling spindle requires repair	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A72	28/05/2015	Spindle indexing error with overfeed	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A45	01/11/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: No further details.	cristian_santos
A85	25/05/2015	Spindle fails to index, overfeeding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A73	11/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A97	17/04/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A36	14/06/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A87	14/10/2015	Repair work needed on milling spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A86	10/04/2015	Machine is unpowered	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A74	06/11/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A59	11/01/2016	Saw attachment gears are binding and grinding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A74	13/02/2015	Accumulators need checking and charging	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A37	18/11/2015	Accumulators need checking and charging	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A7	17/03/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A40	06/05/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A76	03/10/2015	Milling spindle requires repair	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A52	27/02/2015	Repair work needed on milling spindle	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A18	26/12/2015	Leak in side B hydraulic line	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A7	01/11/2015	Hydraulic line leak on side B	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A40	01/08/2015	Turret A and B are leaking	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A44	11/04/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A9	16/03/2015	Power supply failure detected	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A13	17/07/2015	Accumulator inspection and charging required	Michele Williams noted: Repair completed.	michele_williams
A76	12/04/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A78	18/09/2015	Power supply failure detected	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A27	06/08/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A39	13/03/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A38	29/06/2015	Leaks found at turrets A and B	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A22	25/11/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A98	02/04/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A97	02/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Fixed and tested.	michele_williams
A62	16/08/2015	Accumulators need checking and charging	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A34	15/07/2015	Repair work needed on milling spindle	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A58	20/02/2015	Repair work needed on milling spindle	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A7	14/02/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A68	15/05/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: No further details.	nathan_maldonado
A4	07/09/2015	Machine is unpowered	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A73	11/05/2015	Inspect and recharge accumulators	Michele Williams noted: Inspection complete; no issues found.	michele_williams

A98	05/10/2015	Accumulators need checking and charging	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A4	24/08/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A21	31/05/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A53	04/02/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A62	11/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A67	09/01/2016	Maintenance on milling spindle needed	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A68	13/02/2015	Turret sections A & B showing leaks	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A98	19/06/2015	Saw attachment gears are binding and grinding	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A73	08/11/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A39	20/08/2015	Unit lost electrical power	Nathan Maldonado noted: No further details.	nathan_maldonado
A64	21/05/2015	Leaks found at turrets A and B	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A32	22/11/2015	Spindle indexing error with overfeed	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A49	14/05/2015	Accumulator inspection and charging required	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A58	18/06/2015	Accumulators need checking and charging	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A32	08/09/2015	Power supply failure detected	Michele Williams noted: Repair completed.	michele_williams
A39	30/03/2015	Inspect and recharge accumulators	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A54	02/01/2016	Repair work needed on milling spindle	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A20	03/11/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A81	26/12/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A33	03/06/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A87	20/10/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A59	20/01/2015	Spindle fails to index, overfeeding	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A33	11/02/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A76	15/02/2015	Turret A and B are leaking	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A11	06/10/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A30	13/12/2015	Machine is unpowered	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A64	14/12/2015	Turret A and B are leaking	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A4	29/10/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A64	05/10/2015	Leaks found at turrets A and B	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A13	31/12/2015	Inspect and recharge accumulators	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A54	26/08/2015	Repair work needed on milling spindle	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A84	11/03/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A2	30/03/2015	Leak in side B hydraulic line	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A57	17/08/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Detail not recorded.	cristian_santos
A2	12/10/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A70	11/04/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A42	02/01/2016	Inspect and recharge accumulators	Michele Williams noted: Maintenance action successful.	michele_williams
A31	27/11/2015	Leaks found at turrets A and B	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A16	03/06/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A10	01/07/2015	Turret A and B are leaking	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A95	17/07/2015	Machine is unpowered	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A79	08/06/2015	Spindle indexing error with overfeed	Gina Moore noted: No further details.	gina_moore, dylan_miller
A74	23/06/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Fixed and tested.	michele_williams
A22	30/05/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A67	14/02/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A81	22/12/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: System checked and accumulators charged.	michele_williams
A6	10/10/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A34	10/02/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A16	23/03/2015	Turret A and B are leaking	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A52	31/12/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A84	05/03/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A11	24/02/2015	Turret A and B are leaking	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A65	23/07/2015	Machine is unpowered	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A79	26/12/2015	Leak in side B hydraulic line	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A19	31/03/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A56	12/11/2015	Maintenance on milling spindle needed	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A84	01/04/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A20	15/01/2015	Turret A and B are leaking	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A14	13/06/2015	Accumulators need checking and charging	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A90	09/11/2015	Accumulators need checking and charging	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A10	02/01/2016	Saw attachment gears are binding and grinding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A66	05/09/2015	Power supply failure detected	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A42	27/05/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A6	15/12/2015	Saw attachment gears are binding and grinding	Michele Williams noted: No additional information provided.	michele_williams
A38	24/07/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A40	12/05/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A62	21/06/2015	Inspect and recharge accumulators	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A58	19/12/2015	Accumulators need checking and charging	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A31	24/01/2015	Leaks found at turrets A and B	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A69	02/06/2015	Spindle fails to index, overfeeding	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams

A49	27/12/2015	Accumulators need checking and charging	Cristian Santos noted: Maintenance action successful.	cristian_santos
A99	17/08/2015	Accumulator inspection and charging required	Michele Williams noted: No further details.	michele_williams
A45	22/05/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A62	06/03/2015	Repair work needed on milling spindle	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A40	21/01/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A50	08/11/2015	Leaks found at turrets A and B	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A38	21/08/2015	Power supply failure detected	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A41	29/12/2015	Spindle indexing error with overfeed	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A9	24/10/2015	Maintenance on milling spindle needed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A94	26/03/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Repair completed.	michele_williams
A66	08/03/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A45	10/08/2015	Hydraulic line leak on side B	Cristian Santos noted: Fixed and tested.	cristian_santos
A68	17/02/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A14	29/11/2015	Hydraulic line leak on side B	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A78	02/05/2015	Power supply failure detected	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A59	13/11/2015	Milling spindle requires repair	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A85	04/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A75	24/09/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Fixed and tested.	cristian_santos
A83	07/03/2015	Accumulators need checking and charging	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A40	04/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A16	08/02/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A64	19/04/2015	Unit lost electrical power	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A62	09/08/2015	Repair work needed on milling spindle	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A56	01/11/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Detail not recorded.	cristian_santos
A64	19/03/2015	Power supply failure detected	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A34	15/07/2015	Turret A and B are leaking	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A41	31/12/2015	Maintenance on milling spindle needed	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A40	06/09/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A94	12/09/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A75	22/08/2015	Maintenance on milling spindle needed	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A47	23/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A81	06/01/2016	Machine is unpowered	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A14	25/12/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A20	17/03/2015	Repair work needed on milling spindle	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A10	05/07/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A98	17/07/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A1	23/04/2015	Machine is unpowered	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A89	27/10/2015	Machine is unpowered	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A81	13/12/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A38	05/09/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A17	22/02/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A43	21/05/2015	Power supply failure detected	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A8	16/11/2015	Leak in side B hydraulic line	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A51	25/04/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A12	25/10/2015	Inspect and recharge accumulators	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A96	25/03/2015	Leaks found at turrets A and B	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A95	01/01/2016	Turret A and B are leaking	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A8	11/09/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A32	26/05/2015	Hydraulic line leak on side B	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A91	08/05/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A94	11/01/2016	Accumulator inspection and charging required	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A73	12/04/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A24	17/08/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A75	31/01/2015	Turret A and B are leaking	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A93	04/06/2015	Unit lost electrical power	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A3	14/03/2015	Maintenance on milling spindle needed	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A85	16/03/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A68	10/12/2015	Accumulators need checking and charging	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A42	19/12/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A12	31/03/2015	Leak in side B hydraulic line	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A90	25/12/2015	Leaks found at turrets A and B	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A32	28/07/2015	Spindle indexing error with overfeed	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A99	01/01/2016	Hydraulic line leak on side B	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A39	20/02/2015	Repair work needed on milling spindle	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A74	19/06/2015	Machine is unpowered	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A65	23/07/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A6	24/11/2015	Spindle fails to index, overfeeding	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A60	05/08/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A4	26/01/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A63	23/10/2015	Inspect and recharge accumulators	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams

A59	01/11/2015	Spindle fails to index, overfeeding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A27	08/08/2015	Inspect and recharge accumulators	Michele Williams noted: System checked and accumulators charged.	michele_williams
A89	15/08/2015	Hydraulic line leak on side B	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A79	25/07/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A24	17/08/2015	Turret sections A & B showing leaks	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A20	20/09/2015	Repair work needed on milling spindle	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A86	26/02/2015	Leak in side B hydraulic line	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A98	25/10/2015	Leak in side B hydraulic line	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A13	09/10/2015	Machine is unpowered	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A10	06/10/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A92	18/06/2015	Hydraulic line leak on side B	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A46	28/05/2015	Unit lost electrical power	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A18	31/01/2015	Accumulator inspection and charging required	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A18	15/11/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A47	04/02/2015	Machine is unpowered	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A88	19/04/2015	Maintenance on milling spindle needed	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A15	19/10/2015	Repair work needed on milling spindle	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A43	14/05/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A13	13/01/2016	Milling spindle requires repair	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A14	18/11/2015	Spindle indexing error with overfeed	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A61	27/11/2015	Leaks found at turrets A and B	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A77	11/02/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A50	16/05/2015	Turret A and B are leaking	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A47	25/12/2015	Repair work needed on milling spindle	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A68	25/07/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A89	15/12/2015	Accumulators need checking and charging	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A48	15/01/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A55	05/09/2015	Inspect and recharge accumulators	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A70	29/09/2015	Accumulator inspection and charging required	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A18	24/02/2015	Hydraulic line leak on side B	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A46	11/03/2015	Accumulator inspection and charging required	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A30	16/06/2015	Hydraulic line leak on side B	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A83	28/06/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A62	21/03/2015	Spindle indexing error with overfeed	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A74	05/02/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A32	01/12/2015	Milling spindle requires repair	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A86	04/07/2015	Milling spindle requires repair	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A24	17/08/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A69	18/09/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A64	19/10/2015	Machine is unpowered	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A57	30/05/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A8	16/03/2015	Unit lost electrical power	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A44	14/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A34	10/11/2015	Repair work needed on milling spindle	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A57	17/08/2015	Leak in side B hydraulic line	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A56	14/11/2015	Leak in side B hydraulic line	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A22	11/07/2015	Machine is unpowered	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A40	31/12/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A41	03/10/2015	Accumulators need checking and charging	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A95	16/02/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Repair completed.	michele_williams
A53	12/01/2016	Turret A and B are leaking	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A54	27/07/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A31	27/12/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A30	29/12/2015	Unit lost electrical power	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A83	21/05/2015	Unit lost electrical power	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A49	18/08/2015	Saw attachment is leaking hydraulics	Gina Moore noted: No further details.	gina_moore, dylan_miller
A52	16/10/2015	Turret A and B are leaking	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A88	25/11/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A10	24/09/2015	Leaks found at turrets A and B	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A98	14/10/2015	Repair work needed on milling spindle	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A4	04/09/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A90	02/05/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A12	11/07/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A27	16/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A73	16/06/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A71	05/03/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A67	17/01/2015	Leaks found at turrets A and B	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A61	09/05/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Repair completed.	michele_williams
A99	04/04/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A1	05/05/2015	Power supply failure detected	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams

A9	11/12/2015	Machine is unpowered	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A95	07/11/2015	Maintenance on milling spindle needed	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A67	29/05/2015	Spindle indexing error with overfeed	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A34	04/09/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A78	26/01/2015	Power supply failure detected	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A88	28/10/2015	Hydraulic line leak on side B	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A44	01/02/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A4	18/04/2015	Power supply failure detected	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A45	07/12/2015	Turret sections A & B showing leaks	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A30	29/06/2015	Leaks found at turrets A and B	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A23	25/03/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A44	05/06/2015	Accumulator inspection and charging required	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A49	02/01/2016	Turret sections A & B showing leaks	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A72	19/10/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A74	11/10/2015	Milling spindle requires repair	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A7	06/05/2015	Turret A and B are leaking	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A45	05/02/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Maintenance action successful.	cristian_santos
A78	06/03/2015	Leaks found at turrets A and B	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A41	06/12/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A49	19/06/2015	Unit lost electrical power	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A63	22/04/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A8	06/07/2015	Maintenance on milling spindle needed	Cristian Santos noted: No additional information provided.	cristian_santos
A44	28/09/2015	Leaks found at turrets A and B	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A87	28/06/2015	Accumulator inspection and charging required	Michele Williams noted: Detail not recorded.	michele_williams
A51	05/01/2016	Grinding noise from tight gears on saw attachment	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A81	02/10/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A97	18/05/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A45	06/10/2015	Spindle indexing error with overfeed	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A32	01/05/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A91	11/07/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A5	11/03/2015	Leak in side B hydraulic line	Cristian Santos noted: No further details.	cristian_santos
A25	10/10/2015	Turret A and B are leaking	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A52	25/09/2015	Machine is unpowered	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A50	08/12/2015	Repair work needed on milling spindle	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A26	07/12/2015	Accumulator inspection and charging required	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A51	12/05/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A56	15/02/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A50	20/02/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A47	04/08/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A79	21/06/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A16	11/09/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A84	18/02/2015	Hydraulic line leak on side B	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A32	29/04/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A94	15/02/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A24	01/11/2015	Power supply failure detected	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A37	28/01/2015	Hydraulic line leak on side B	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A28	04/03/2015	Turret A and B are leaking	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A92	29/07/2015	Machine is unpowered	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A37	07/01/2016	Inspect and recharge accumulators	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A83	14/11/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A53	21/07/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A53	01/04/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A63	18/02/2015	Leaks found at turrets A and B	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A88	30/07/2015	Machine is unpowered	Michele Williams noted: No further details.	michele_williams
A67	15/01/2015	Hydraulic line leak on side B	Michele Williams noted: System checked and accumulators charged.	michele_williams
A2	18/08/2015	Leaks found at turrets A and B	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A33	03/01/2016	Maintenance on milling spindle needed	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A35	01/03/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A9	05/04/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A38	01/02/2015	Accumulators need checking and charging	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A2	31/08/2015	Unit lost electrical power	Michele Williams noted: No additional information provided.	michele_williams
A68	17/03/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A4	20/09/2015	Turret sections A & B showing leaks	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A41	29/01/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A33	02/12/2015	Saw attachment gears are binding and grinding	Michele Williams noted: No additional information provided.	michele_williams
A98	30/06/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: No further details.	michele_williams
A34	18/12/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A6	01/08/2015	Milling spindle requires repair	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A17	29/04/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A80	22/09/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado

A90	10/12/2015	Machine is unpowered	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A24	25/09/2015	Maintenance on milling spindle needed	Michele Williams noted: Fixed and tested.	michele_williams
A28	28/06/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A97	22/04/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A46	07/06/2015	Leak in side B hydraulic line	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A26	22/12/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A40	25/07/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A91	19/08/2015	Leak in side B hydraulic line	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A41	14/01/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Detail not recorded.	michele_williams
A51	20/08/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A41	02/07/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A58	11/02/2015	Unit lost electrical power	Michele Williams noted: Fixed and tested.	michele_williams
A20	29/03/2015	Hydraulic line leak on side B	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A37	05/07/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A20	16/02/2015	Hydraulic line leak on side B	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A27	16/04/2015	Turret sections A & B showing leaks	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A37	17/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A75	17/06/2015	Accumulators need checking and charging	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A98	26/07/2015	Spindle indexing error with overfeed	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A62	23/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A25	16/09/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A27	22/07/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A8	16/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A29	31/05/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A57	22/10/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A21	09/12/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A45	10/06/2015	Turret A and B are leaking	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A89	31/12/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A23	05/12/2015	Maintenance on milling spindle needed	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A27	09/07/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A7	13/02/2015	Accumulator inspection and charging required	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A55	23/03/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A67	08/09/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A68	01/05/2015	Hydraulic line leak on side B	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A27	24/05/2015	Inspect and recharge accumulators	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A9	06/07/2015	Machine is unpowered	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A75	06/09/2015	Accumulators need checking and charging	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A89	09/12/2015	Maintenance on milling spindle needed	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A97	28/06/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A36	03/02/2015	Maintenance on milling spindle needed	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A80	06/10/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Detail not recorded.	michele_williams
A6	25/07/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A9	16/05/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A8	25/04/2015	Power supply failure detected	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A79	27/02/2015	Turret sections A & B showing leaks	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A47	03/02/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A34	10/10/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A2	16/02/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A38	12/03/2015	Hydraulic hose on side B is leaking	Michele Williams noted: No additional information provided.	michele_williams
A3	13/05/2015	Accumulators need checking and charging	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A65	01/06/2015	Unit lost electrical power	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A87	22/02/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A3	13/03/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A57	06/07/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A58	23/04/2015	Turret A and B are leaking	Gina Moore noted: No further details.	gina_moore, dylan_miller
A57	19/11/2015	Leak in side B hydraulic line	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A76	29/06/2015	Maintenance on milling spindle needed	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A63	08/11/2015	Leaks found at turrets A and B	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A51	02/02/2015	Accumulator inspection and charging required	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A39	18/03/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A10	03/11/2015	Accumulator inspection and charging required	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A58	20/05/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A93	27/06/2015	Milling spindle requires repair	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A79	01/04/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A29	05/02/2015	Spindle fails to index, overfeeding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A90	30/09/2015	Hydraulic hose on side B is leaking	Michele Williams noted: No further details.	michele_williams
A2	26/06/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A65	04/10/2015	Leak in side B hydraulic line	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A6	14/04/2015	Turret sections A & B showing leaks	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A55	31/07/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams

A32	18/10/2015	Accumulator inspection and charging required	Michele Williams noted: No further details.	michele_williams
A57	06/09/2015	Unit lost electrical power	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A74	28/02/2015	Spindle indexing error with overfeed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A71	06/10/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A25	03/10/2015	Repair work needed on milling spindle	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A25	05/04/2015	Repair work needed on milling spindle	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A98	12/02/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A87	29/12/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A89	18/03/2015	Turret A and B are leaking	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A76	28/12/2015	Power supply failure detected	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A21	06/10/2015	Machine is unpowered	Michele Williams noted: No additional information provided.	michele_williams
A92	17/12/2015	Accumulator inspection and charging required	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A76	08/06/2015	Power supply failure detected	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A39	11/08/2015	Inspect and recharge accumulators	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A43	04/10/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A85	27/06/2015	Milling spindle requires repair	Michele Williams noted: System checked and accumulators charged.	michele_williams
A50	30/08/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A13	25/03/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A31	29/12/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A18	18/10/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A32	20/07/2015	Machine is unpowered	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A28	16/08/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A69	13/11/2015	Hydraulic line leak on side B	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A8	24/06/2015	Unit lost electrical power	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A31	19/01/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A96	13/11/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A63	30/07/2015	Repair work needed on milling spindle	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A71	03/03/2015	Power supply failure detected	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A26	16/12/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A89	05/10/2015	Leaks found at turrets A and B	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A97	01/05/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A59	10/10/2015	Maintenance on milling spindle needed	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A24	10/02/2015	Accumulator inspection and charging required	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A2	24/01/2015	Unit lost electrical power	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A77	17/01/2015	Inspect and recharge accumulators	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A98	08/11/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A35	11/01/2016	Inspect and recharge accumulators	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A27	29/03/2015	Accumulator inspection and charging required	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A52	03/09/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A17	16/04/2015	Hydraulic hose on side B is leaking	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A6	05/03/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A65	03/04/2015	Turret A and B are leaking	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A44	21/01/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A96	24/04/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A76	23/08/2015	Spindle fails to index, overfeeding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A32	09/01/2016	Saw attachment is leaking hydraulics	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A49	29/08/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A64	19/06/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A39	29/11/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A67	28/05/2015	Machine is unpowered	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A66	12/01/2016	Accumulators need checking and charging	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A75	22/06/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A60	03/02/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A4	30/07/2015	Machine is unpowered	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A16	24/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Fixed and tested.	michele_williams
A66	16/10/2015	Repair work needed on milling spindle	Michele Williams noted: No additional information provided.	michele_williams
A52	23/03/2015	Unit lost electrical power	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A21	01/05/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A75	06/06/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A14	19/12/2015	Turret A and B are leaking	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A55	08/05/2015	Machine is unpowered	Nathan Maldonado noted: No further details.	nathan_maldonado
A64	21/05/2015	Turret A and B are leaking	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A71	31/10/2015	Machine is unpowered	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A79	24/10/2015	Turret sections A & B showing leaks	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A33	16/06/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A12	16/02/2015	Accumulators need checking and charging	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A53	18/06/2015	Accumulators need checking and charging	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A74	17/04/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A16	16/03/2015	Power supply failure detected	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A91	14/06/2015	Leaks found at turrets A and B	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams

A31	16/04/2015	Maintenance on milling spindle needed	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A30	07/12/2015	Saw attachment gears are binding and grinding	Michele Williams noted: No additional information provided.	michele_williams
A74	01/07/2015	Power supply failure detected	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A57	15/08/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A75	29/05/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A11	16/07/2015	Hydraulic line leak on side B	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A15	10/10/2015	Milling spindle requires repair	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A44	12/06/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A99	09/04/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A55	29/03/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A12	18/08/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A80	10/03/2015	Turret A and B are leaking	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A65	14/06/2015	Repair work needed on milling spindle	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A25	22/08/2015	Accumulators need checking and charging	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A44	29/08/2015	Accumulators need checking and charging	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A17	08/03/2015	Machine is unpowered	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A35	13/08/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A8	12/09/2015	Turret A and B are leaking	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A59	09/11/2015	Accumulator inspection and charging required	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A66	22/09/2015	Saw attachment gears are binding and grinding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A60	15/04/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A3	09/12/2015	Inspect and recharge accumulators	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A79	26/02/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A94	01/07/2015	Turret A and B are leaking	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A27	31/08/2015	Hydraulic line leak on side B	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A31	09/10/2015	Hydraulic line leak on side B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A22	02/04/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A83	07/01/2016	Saw attachment gears are binding and grinding	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A41	24/06/2015	Inspect and recharge accumulators	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A61	27/09/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A47	26/02/2015	Repair work needed on milling spindle	Michele Williams noted: Maintenance action successful.	michele_williams
A34	30/09/2015	Unit lost electrical power	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A13	29/05/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A91	29/12/2015	Accumulators need checking and charging	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A85	09/02/2015	Repair work needed on milling spindle	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A88	19/06/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A64	30/06/2015	Accumulators need checking and charging	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A13	17/02/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A53	19/03/2015	Unit lost electrical power	Cristian Santos noted: Repair completed.	cristian_santos
A52	03/10/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A19	10/09/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A94	19/02/2015	Turret A and B are leaking	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A26	02/10/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A92	16/11/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A28	11/07/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A31	13/03/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A62	16/12/2015	Inspect and recharge accumulators	Nathan Maldonado noted: No further details.	nathan_maldonado
A36	25/06/2015	Milling spindle requires repair	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A99	03/09/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A96	03/09/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A62	01/02/2015	Turret A and B are leaking	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A89	30/07/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Detail not recorded.	michele_williams
A4	11/10/2015	Machine is unpowered	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A42	15/01/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A1	22/09/2015	Inspect and recharge accumulators	Michele Williams noted: No further details.	michele_williams
A68	08/04/2015	Accumulators need checking and charging	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A56	10/11/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A21	12/10/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A20	28/12/2015	Spindle indexing error with overfeed	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A53	13/10/2015	Machine is unpowered	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A74	01/02/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A1	19/09/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A80	18/08/2015	Maintenance on milling spindle needed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A29	17/05/2015	Inspect and recharge accumulators	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A8	15/09/2015	Unit lost electrical power	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A22	17/12/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A48	19/04/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A92	20/05/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A36	09/12/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A49	05/01/2016	Hydraulic fluid leak at saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams

A77	19/04/2015	Hydraulic line leak on side B	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A46	25/12/2015	Machine is unpowered	Cristian Santos noted: No additional information provided.	cristian_santos
A26	15/05/2015	Saw attachment is leaking hydraulics	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A67	01/12/2015	Power supply failure detected	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A20	19/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A89	10/09/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A15	20/11/2015	Machine is unpowered	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A27	09/03/2015	Accumulators need checking and charging	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A42	17/08/2015	Maintenance on milling spindle needed	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A97	10/08/2015	Leak in side B hydraulic line	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A47	07/11/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A9	24/09/2015	Machine is unpowered	Michele Williams noted: System checked and accumulators charged.	michele_williams
A26	02/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A92	11/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A75	13/02/2015	Spindle indexing error with overfeed	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A66	18/01/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A32	28/11/2015	Leak in side B hydraulic line	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A45	16/09/2015	Spindle indexing error with overfeed	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A69	04/02/2015	Spindle indexing error with overfeed	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A77	10/11/2015	Machine is unpowered	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A58	27/01/2015	Accumulators need checking and charging	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A21	18/04/2015	Maintenance on milling spindle needed	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A6	15/03/2015	Unit lost electrical power	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A87	18/03/2015	Hydraulic line leak on side B	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A66	24/03/2015	Unit lost electrical power	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A53	11/01/2016	Leaks found at turrets A and B	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A72	25/02/2015	Leak in side B hydraulic line	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A96	12/08/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A76	17/12/2015	Turret A and B are leaking	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A94	11/05/2015	Milling spindle requires repair	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A38	07/09/2015	Accumulators need checking and charging	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A61	26/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A85	28/05/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A32	17/08/2015	Accumulator inspection and charging required	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A18	29/01/2015	Leak in side B hydraulic line	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A42	20/02/2015	Repair work needed on milling spindle	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A72	18/04/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A60	07/01/2016	Saw attachment gears are binding and grinding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A63	01/02/2015	Accumulators need checking and charging	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A74	13/07/2015	Accumulator inspection and charging required	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A4	16/02/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A87	18/08/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A12	13/09/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A42	25/09/2015	Repair work needed on milling spindle	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A60	20/09/2015	Machine is unpowered	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A33	05/10/2015	Maintenance on milling spindle needed	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A65	04/05/2015	Turret sections A & B showing leaks	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A39	06/08/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A96	31/03/2015	Spindle indexing error with overfeed	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A61	25/08/2015	Hydraulic line leak on side B	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A38	14/01/2015	Leak in side B hydraulic line	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A40	03/02/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A45	04/11/2015	Unit lost electrical power	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A72	17/01/2015	Repair work needed on milling spindle	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A72	19/02/2015	Leak in side B hydraulic line	Nathan Maldonado noted: No further details.	nathan_maldonado
A64	21/02/2015	Leaks found at turrets A and B	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A82	19/09/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: No further details.	nathan_maldonado
A88	04/04/2015	Turret sections A & B showing leaks	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A41	31/05/2015	Spindle indexing error with overfeed	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A72	23/08/2015	Unit lost electrical power	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A67	11/11/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: No further details.	michele_williams
A21	31/10/2015	Turret sections A & B showing leaks	Cristian Santos noted: No further details.	cristian_santos
A41	16/04/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A30	23/04/2015	Machine is unpowered	Cristian Santos noted: Repair completed.	cristian_santos
A10	20/05/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A77	19/02/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A85	19/03/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A79	30/10/2015	Unit lost electrical power	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A3	18/12/2015	Machine is unpowered	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A17	07/04/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: No additional information provided.	nathan_maldonado

A23	19/01/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A17	06/12/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A58	24/10/2015	Leaks found at turrets A and B	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A2	03/10/2015	Accumulators need checking and charging	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A3	12/08/2015	Unit lost electrical power	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A31	10/12/2015	Spindle indexing error with overfeed	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A38	02/08/2015	Machine is unpowered	Michele Williams noted: Maintenance action successful.	michele_williams
A81	04/01/2016	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A59	17/09/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A25	15/02/2015	Milling spindle requires repair	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A61	24/06/2015	Leaks found at turrets A and B	Michele Williams noted: No additional information provided.	michele_williams
A84	23/07/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A1	04/07/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A49	25/05/2015	Machine is unpowered	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A94	16/02/2015	Turret A and B are leaking	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A8	02/01/2016	Machine is unpowered	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A85	15/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A88	21/09/2015	Spindle fails to index, overfeeding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A42	06/12/2015	Repair work needed on milling spindle	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A3	17/03/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A2	27/11/2015	Repair work needed on milling spindle	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A81	03/10/2015	Saw attachment is leaking hydraulics	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A7	26/01/2015	Accumulator inspection and charging required	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A62	28/09/2015	Maintenance on milling spindle needed	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A31	04/01/2016	Repair work needed on milling spindle	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A92	14/12/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A68	17/03/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A20	12/02/2015	Power supply failure detected	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A37	22/02/2015	Spindle indexing error with overfeed	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A42	04/06/2015	Power supply failure detected	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A77	17/09/2015	Unit lost electrical power	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A84	05/09/2015	Machine is unpowered	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A80	11/02/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A6	01/06/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A22	26/05/2015	Leak in side B hydraulic line	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A72	22/08/2015	Milling spindle requires repair	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A30	08/02/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A79	13/03/2015	Power supply failure detected	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A63	07/05/2015	Hydraulic hose on side B is leaking	Michele Williams noted: No additional information provided.	michele_williams
A27	03/08/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A90	23/08/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A21	09/06/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A57	21/01/2015	Turret A and B are leaking	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A72	04/01/2016	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A64	17/06/2015	Unit lost electrical power	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A5	13/03/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A36	07/09/2015	Spindle indexing error with overfeed	Michele Williams noted: Maintenance action successful.	michele_williams
A54	20/09/2015	Accumulator inspection and charging required	Michele Williams noted: No additional information provided.	michele_williams
A66	20/09/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A85	19/09/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A60	27/12/2015	Spindle indexing error with overfeed	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A66	05/07/2015	Machine is unpowered	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A48	15/12/2015	Spindle indexing error with overfeed	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A18	15/04/2015	Inspect and recharge accumulators	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A41	05/01/2016	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A17	01/04/2015	Spindle indexing error with overfeed	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A85	23/04/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A2	03/09/2015	Unit lost electrical power	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A12	12/11/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A22	01/04/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A24	26/07/2015	Turret A and B are leaking	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A42	06/03/2015	Spindle fails to index, overfeeding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A72	25/01/2015	Hydraulic line leak on side B	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A18	23/12/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A50	29/03/2015	Leaks found at turrets A and B	Cristian Santos noted: Maintenance action successful.	cristian_santos
A78	11/08/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A39	09/10/2015	Leak in side B hydraulic line	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A3	21/11/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A18	13/05/2015	Turret sections A & B showing leaks	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A5	05/09/2015	Spindle indexing error with overfeed	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos

A56	13/07/2015	Leaks found at turrets A and B	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A95	16/06/2015	Accumulators need checking and charging	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A57	13/03/2015	Milling spindle requires repair	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A98	24/06/2015	Inspect and recharge accumulators	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A77	01/11/2015	Inspect and recharge accumulators	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A57	23/05/2015	Leak in side B hydraulic line	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A85	22/02/2015	Leak in side B hydraulic line	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A54	31/08/2015	Accumulators need checking and charging	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A33	07/09/2015	Accumulators need checking and charging	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A22	31/07/2015	Spindle indexing error with overfeed	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A49	11/01/2016	Machine is unpowered	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A20	18/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: No further details.	cristian_santos
A95	24/09/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A77	07/10/2015	Spindle fails to index, overfeeding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A47	20/05/2015	Maintenance on milling spindle needed	Gina Moore noted: No further details.	gina_moore, dylan_miller
A97	20/07/2015	Repair work needed on milling spindle	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A23	27/12/2015	Machine is unpowered	Michele Williams noted: Repair completed.	michele_williams
A57	15/04/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A18	21/02/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A29	23/10/2015	Hydraulic line leak on side B	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A20	31/07/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: No further details.	nathan_maldonado
A50	14/07/2015	Turret A and B are leaking	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A79	05/10/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A36	09/06/2015	Maintenance on milling spindle needed	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A56	01/07/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A23	10/01/2016	Turret sections A & B showing leaks	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A12	03/11/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A65	14/04/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Maintenance action successful.	michele_williams
A70	24/12/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A93	30/01/2015	Hydraulic line leak on side B	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A90	27/03/2015	Machine is unpowered	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A95	16/01/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A35	13/11/2015	Machine is unpowered	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A87	25/03/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A90	20/12/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A56	27/01/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A65	13/09/2015	Accumulator inspection and charging required	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A68	04/06/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A26	24/05/2015	Repair work needed on milling spindle	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A92	30/04/2015	Milling spindle requires repair	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A14	26/06/2015	Accumulators need checking and charging	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A7	04/07/2015	Leak in side B hydraulic line	Michele Williams noted: No additional information provided.	michele_williams
A20	16/05/2015	Spindle indexing error with overfeed	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A13	23/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A72	30/05/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A14	24/09/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A92	23/07/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Repair completed.	michele_williams
A58	11/10/2015	Accumulator inspection and charging required	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A74	10/01/2016	Leaks found at turrets A and B	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A59	17/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A90	14/10/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A73	09/02/2015	Milling spindle requires repair	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A26	05/08/2015	Machine is unpowered	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A94	18/04/2015	Hydraulic line leak on side B	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A95	10/11/2015	Unit lost electrical power	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A30	01/02/2015	Accumulator inspection and charging required	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A96	16/02/2015	Hydraulic line leak on side B	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A6	21/04/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A34	28/11/2015	Turret A and B are leaking	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A7	20/08/2015	Spindle indexing error with overfeed	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A82	07/03/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A94	05/10/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A74	01/01/2016	Spindle indexing error with overfeed	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A8	23/11/2015	Spindle indexing error with overfeed	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A57	20/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A33	11/11/2015	Accumulator inspection and charging required	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A78	28/09/2015	Turret A and B are leaking	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A52	23/07/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A75	19/08/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A36	14/07/2015	Turret sections A & B showing leaks	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos

A21	02/05/2015	Milling spindle requires repair	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A83	27/03/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A11	18/09/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A20	04/07/2015	Maintenance on milling spindle needed	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A82	23/10/2015	Spindle indexing error with overfeed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A58	20/11/2015	Machine is unpowered	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A35	18/09/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A77	02/08/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A20	06/05/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A92	10/08/2015	Turret A and B are leaking	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A1	04/10/2015	Machine is unpowered	Cristian Santos noted: Repair completed.	cristian_santos
A57	06/10/2015	Leaks found at turrets A and B	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A49	07/09/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A39	07/05/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A39	26/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A65	12/06/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A24	02/09/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A87	30/07/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A27	05/10/2015	Repair work needed on milling spindle	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A8	26/03/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A29	20/03/2015	Turret sections A & B showing leaks	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A83	08/11/2015	Accumulators need checking and charging	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A21	12/06/2015	Machine is unpowered	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A42	30/08/2015	Maintenance on milling spindle needed	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A26	28/05/2015	Leaks found at turrets A and B	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A21	26/05/2015	Leaks found at turrets A and B	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A35	13/01/2016	Saw attachment gears are binding and grinding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A27	26/07/2015	Spindle indexing error with overfeed	Michele Williams noted: Maintenance action successful.	michele_williams
A38	04/03/2015	Hydraulic line leak on side B	Michele Williams noted: Maintenance action successful.	michele_williams
A89	23/08/2015	Milling spindle requires repair	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A98	02/11/2015	Machine is unpowered	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A71	08/03/2015	Hydraulic line leak on side B	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A15	16/12/2015	Machine is unpowered	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A85	25/10/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A58	28/02/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A60	10/02/2015	Hydraulic line leak on side B	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A49	04/09/2015	Unit lost electrical power	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A76	02/04/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A73	06/07/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A29	24/04/2015	Accumulator inspection and charging required	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A4	25/08/2015	Maintenance on milling spindle needed	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A23	27/09/2015	Turret A and B are leaking	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A48	10/12/2015	Turret A and B are leaking	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A91	22/11/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A50	30/12/2015	Maintenance on milling spindle needed	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A95	23/08/2015	Repair work needed on milling spindle	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A35	25/05/2015	Maintenance on milling spindle needed	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A84	23/10/2015	Machine is unpowered	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A15	16/01/2015	Machine is unpowered	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A88	11/08/2015	Turret sections A & B showing leaks	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A11	04/03/2015	Repair work needed on milling spindle	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A49	18/06/2015	Machine is unpowered	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A47	06/01/2016	Unit lost electrical power	Cristian Santos noted: Detail not recorded.	cristian_santos
A76	25/03/2015	Spindle fails to index, overfeeding	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A4	15/07/2015	Turret A and B are leaking	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A20	15/06/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A46	21/07/2015	Maintenance on milling spindle needed	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A88	18/05/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A87	05/12/2015	Leak in side B hydraulic line	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A93	05/06/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A51	08/01/2016	Leak in side B hydraulic line	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A75	03/06/2015	Accumulators need checking and charging	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A44	28/02/2015	Machine is unpowered	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A47	24/03/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A71	22/05/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A58	13/09/2015	Turret sections A & B showing leaks	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A28	03/01/2016	Maintenance on milling spindle needed	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A7	20/06/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A25	22/08/2015	Turret A and B are leaking	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A93	23/05/2015	Accumulators need checking and charging	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams

A33	24/08/2015	Milling spindle requires repair	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A7	02/04/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A49	17/10/2015	Leak in side B hydraulic line	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A64	28/03/2015	Accumulators need checking and charging	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A1	02/07/2015	Machine is unpowered	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A90	06/12/2015	Turret sections A & B showing leaks	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A49	19/05/2015	Turret A and B are leaking	Michele Williams noted: System checked and accumulators charged.	michele_williams
A16	01/06/2015	Unit lost electrical power	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A95	09/10/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A91	16/08/2015	Spindle fails to index, overfeeding	Michele Williams noted: Repair completed.	michele_williams
A78	11/03/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A95	16/07/2015	Hydraulic line leak on side B	Michele Williams noted: No additional information provided.	michele_williams
A61	08/02/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A14	30/03/2015	Power supply failure detected	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A84	14/08/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A73	16/11/2015	Leaks found at turrets A and B	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A28	19/03/2015	Power supply failure detected	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A60	14/02/2015	Turret A and B are leaking	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A27	06/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A69	17/10/2015	Accumulators need checking and charging	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A28	31/03/2015	Unit lost electrical power	Nathan Maldonado noted: No further details.	nathan_maldonado
A2	10/08/2015	Leaks found at turrets A and B	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A54	24/04/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Repair completed.	cristian_santos
A90	21/01/2015	Maintenance on milling spindle needed	Cristian Santos noted: Repair completed.	cristian_santos
A17	09/11/2015	Accumulator inspection and charging required	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A33	18/01/2015	Milling spindle requires repair	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A85	04/03/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Maintenance action successful.	cristian_santos
A27	29/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A33	16/01/2015	Maintenance on milling spindle needed	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A4	17/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A1	25/12/2015	Spindle fails to index, overfeeding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A58	29/06/2015	Accumulators need checking and charging	Michele Williams noted: Detail not recorded.	michele_williams
A24	27/11/2015	Turret A and B are leaking	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A58	15/03/2015	Leak in side B hydraulic line	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A53	12/05/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A41	09/06/2015	Leaks found at turrets A and B	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A22	30/04/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A51	12/03/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A31	23/01/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A59	10/12/2015	Unit lost electrical power	Michele Williams noted: Maintenance action successful.	michele_williams
A52	24/10/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A71	21/03/2015	Unit lost electrical power	Michele Williams noted: System checked and accumulators charged.	michele_williams
A22	01/01/2016	Machine is unpowered	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A34	22/12/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A51	02/09/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: No further details.	cristian_santos
A78	23/03/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: No further details.	michele_williams
A88	31/05/2015	Accumulators need checking and charging	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A77	30/04/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A31	29/01/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A1	06/06/2015	Unit lost electrical power	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A36	29/06/2015	Hydraulic line leak on side B	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A19	20/06/2015	Leak in side B hydraulic line	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A56	02/08/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Repair completed.	cristian_santos
A96	20/11/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A22	25/05/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A71	10/10/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A1	13/01/2016	Power supply failure detected	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A57	22/06/2015	Machine is unpowered	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A89	09/02/2015	Hydraulic line leak on side B	Cristian Santos noted: Repair completed.	cristian_santos
A34	16/04/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A37	10/08/2015	Repair work needed on milling spindle	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A33	01/05/2015	Turret sections A & B showing leaks	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A77	18/05/2015	Leaks found at turrets A and B	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A80	21/03/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A19	11/08/2015	Power supply failure detected	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A58	04/08/2015	Repair work needed on milling spindle	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A13	13/03/2015	Milling spindle requires repair	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A87	12/10/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A76	07/02/2015	Spindle fails to index, overfeeding	Michele Williams noted: No further details.	michele_williams
A5	31/10/2015	Accumulators need checking and charging	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams

A91	25/06/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A79	16/05/2015	Accumulators need checking and charging	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A25	15/05/2015	Inspect and recharge accumulators	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A11	30/07/2015	Spindle indexing error with overfeed	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A94	30/05/2015	Repair work needed on milling spindle	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A83	03/03/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A24	10/03/2015	Power supply failure detected	Cristian Santos noted: Repair completed.	cristian_santos
A78	17/10/2015	Power supply failure detected	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A61	09/06/2015	Unit lost electrical power	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A91	12/02/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: No further details.	michele_williams
A13	25/09/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Detail not recorded.	cristian_santos
A84	06/09/2015	Maintenance on milling spindle needed	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A35	05/05/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A28	07/11/2015	Spindle fails to index, overfeeding	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A55	18/07/2015	Inspect and recharge accumulators	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A16	09/05/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A18	03/10/2015	Accumulators need checking and charging	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A18	16/01/2015	Turret A and B are leaking	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A53	03/05/2015	Milling spindle requires repair	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A4	25/01/2015	Leak in side B hydraulic line	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A40	20/10/2015	Maintenance on milling spindle needed	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A67	30/10/2015	Machine is unpowered	Michele Williams noted: No further details.	michele_williams
A97	01/03/2015	Inspect and recharge accumulators	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A43	05/05/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A75	21/03/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A65	16/04/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A96	30/06/2015	Turret sections A & B showing leaks	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A58	11/07/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A23	21/07/2015	Power supply failure detected	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A5	02/10/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A89	13/06/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Fixed and tested.	michele_williams
A70	26/12/2015	Hydraulic line leak on side B	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A91	19/10/2015	Accumulator inspection and charging required	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A65	26/10/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A18	05/07/2015	Repair work needed on milling spindle	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A5	31/10/2015	Inspect and recharge accumulators	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A61	17/05/2015	Leak in side B hydraulic line	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A49	18/07/2015	Milling spindle requires repair	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A82	06/01/2016	Repair work needed on milling spindle	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A19	24/03/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A15	11/10/2015	Accumulators need checking and charging	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A28	03/07/2015	Repair work needed on milling spindle	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A88	18/12/2015	Power supply failure detected	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A77	03/11/2015	Spindle indexing error with overfeed	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A67	15/09/2015	Leak in side B hydraulic line	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A60	27/02/2015	Unit lost electrical power	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A1	25/02/2015	Milling spindle requires repair	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A75	14/06/2015	Hydraulic line leak on side B	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A7	06/07/2015	Accumulators need checking and charging	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A18	10/12/2015	Accumulators need checking and charging	Cristian Santos noted: No further details.	cristian_santos
A57	21/12/2015	Maintenance on milling spindle needed	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A65	06/08/2015	Unit lost electrical power	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A41	30/05/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A41	03/04/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A35	06/07/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A47	08/03/2015	Machine is unpowered	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A31	05/11/2015	Milling spindle requires repair	Michele Williams noted: No additional information provided.	michele_williams
A57	22/05/2015	Unit lost electrical power	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A89	10/03/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Detail not recorded.	cristian_santos
A55	10/07/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A75	04/07/2015	Turret A and B are leaking	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A45	14/05/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A76	15/01/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A6	30/05/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A67	13/10/2015	Leak in side B hydraulic line	Gina Moore noted: No further details.	gina_moore, dylan_miller
A35	23/07/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: No further details.	cristian_santos
A2	01/03/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Repair completed.	cristian_santos
A55	27/08/2015	Spindle indexing error with overfeed	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A55	28/04/2015	Power supply failure detected	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A50	22/01/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams

A19	21/03/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A56	26/10/2015	Repair work needed on milling spindle	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A44	06/07/2015	Leak in side B hydraulic line	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A32	02/01/2016	Saw attachment is leaking hydraulics	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A54	17/12/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A33	08/05/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A10	05/02/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A54	06/09/2015	Spindle indexing error with overfeed	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A20	14/08/2015	Machine is unpowered	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A80	07/11/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A24	04/05/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A71	17/07/2015	Leak in side B hydraulic line	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A12	04/08/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A95	13/03/2015	Leaks found at turrets A and B	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A38	30/08/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A13	26/06/2015	Spindle indexing error with overfeed	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A59	20/11/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A20	02/12/2015	Repair work needed on milling spindle	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A43	25/08/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A32	30/04/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A8	02/12/2015	Power supply failure detected	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A45	23/01/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A72	23/03/2015	Turret sections A & B showing leaks	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A52	14/02/2015	Milling spindle requires repair	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A1	08/06/2015	Leak in side B hydraulic line	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A36	17/06/2015	Accumulator inspection and charging required	Michele Williams noted: No further details.	michele_williams
A10	20/02/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A36	11/04/2015	Repair work needed on milling spindle	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A49	30/09/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A40	02/05/2015	Power supply failure detected	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A33	06/02/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A6	05/06/2015	Leak in side B hydraulic line	Michele Williams noted: No further details.	michele_williams
A88	31/03/2015	Milling spindle requires repair	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A55	03/01/2016	Saw attachment is leaking hydraulics	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A29	06/05/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A8	03/09/2015	Turret sections A & B showing leaks	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A20	20/02/2015	Hydraulic line leak on side B	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A42	08/04/2015	Hydraulic line leak on side B	Michele Williams noted: No further details.	michele_williams
A83	01/08/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A33	25/04/2015	Turret sections A & B showing leaks	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A93	27/06/2015	Accumulators need checking and charging	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A75	13/11/2015	Turret A and B are leaking	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A43	25/11/2015	Accumulators need checking and charging	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A83	29/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A59	11/07/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A63	05/03/2015	Power supply failure detected	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A46	25/04/2015	Machine is unpowered	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A4	10/07/2015	Leak in side B hydraulic line	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A18	06/11/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A37	22/11/2015	Accumulator inspection and charging required	Michele Williams noted: Maintenance action successful.	michele_williams
A32	29/09/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A89	19/02/2015	Machine is unpowered	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A48	26/11/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A24	19/02/2015	Milling spindle requires repair	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A68	04/01/2016	Turret sections A & B showing leaks	Cristian Santos noted: Fixed and tested.	cristian_santos
A37	31/03/2015	Accumulators need checking and charging	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A32	28/07/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A76	13/09/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A96	17/01/2015	Turret A and B are leaking	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A6	22/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A50	13/11/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A16	02/04/2015	Maintenance on milling spindle needed	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A52	15/09/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A59	30/10/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Maintenance action successful.	cristian_santos
A8	11/01/2016	Saw attachment gears are binding and grinding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A81	11/03/2015	Power supply failure detected	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A22	04/12/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A86	17/05/2015	Hydraulic line leak on side B	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A81	11/01/2016	Milling spindle requires repair	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A64	07/11/2015	Machine is unpowered	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams

A66	29/01/2015	Spindle indexing error with overfeed	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A12	18/12/2015	Inspect and recharge accumulators	Michele Williams noted: Fixed and tested.	michele_williams
A78	01/09/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A75	11/08/2015	Inspect and recharge accumulators	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A47	06/02/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A91	11/05/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A96	30/12/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A71	29/09/2015	Milling spindle requires repair	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A95	05/07/2015	Inspect and recharge accumulators	Michele Williams noted: Fixed and tested.	michele_williams
A47	26/03/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Maintenance action successful.	cristian_santos
A16	25/01/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A46	28/08/2015	Hydraulic line leak on side B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A57	12/01/2016	Accumulator inspection and charging required	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A97	12/02/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A29	12/02/2015	Accumulators need checking and charging	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A52	07/07/2015	Spindle fails to index, overfeeding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A57	16/02/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A28	20/10/2015	Inspect and recharge accumulators	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A26	05/06/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A90	03/03/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A1	23/12/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A64	11/05/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A32	24/01/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A70	16/04/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A6	31/05/2015	Inspect and recharge accumulators	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A80	13/03/2015	Machine is unpowered	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A31	15/02/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A22	11/05/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A72	29/06/2015	Power supply failure detected	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A69	13/11/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A31	02/02/2015	Spindle fails to index, overfeeding	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A48	03/02/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A58	18/06/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A13	22/03/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A59	06/06/2015	Repair work needed on milling spindle	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A94	10/12/2015	Inspect and recharge accumulators	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A32	17/12/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A80	24/05/2015	Machine is unpowered	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A29	01/07/2015	Accumulator inspection and charging required	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A75	02/07/2015	Turret sections A & B showing leaks	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A79	18/04/2015	Turret A and B are leaking	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A17	13/08/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A34	19/03/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A24	28/01/2015	Hydraulic line leak on side B	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A85	17/08/2015	Accumulator inspection and charging required	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A69	19/06/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A90	16/03/2015	Spindle indexing error with overfeed	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A61	21/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A30	26/09/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A60	03/01/2016	Leaks found at turrets A and B	Cristian Santos noted: Detail not recorded.	cristian_santos
A21	24/04/2015	Machine is unpowered	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A97	16/11/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Repair completed.	cristian_santos
A88	09/02/2015	Maintenance on milling spindle needed	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A90	31/05/2015	Leak in side B hydraulic line	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A85	29/10/2015	Milling spindle requires repair	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A78	17/06/2015	Turret A and B are leaking	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A13	02/03/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A1	16/04/2015	Milling spindle requires repair	Nathan Maldonado noted: No further details.	nathan_maldonado
A28	10/02/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A89	01/06/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A29	24/11/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A11	28/08/2015	Maintenance on milling spindle needed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A86	05/11/2015	Hydraulic line leak on side B	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A64	12/07/2015	Hydraulic line leak on side B	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A75	22/01/2015	Spindle fails to index, overfeeding	Michele Williams noted: Fixed and tested.	michele_williams
A93	15/11/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: No further details.	nathan_maldonado
A14	26/05/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A27	08/01/2016	Accumulator inspection and charging required	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A53	22/09/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A94	10/05/2015	Hydraulic line leak on side B	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos

A51	01/09/2015	Spindle indexing error with overfeed	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A40	09/10/2015	Turret A and B are leaking	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A61	28/08/2015	Accumulator inspection and charging required	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A52	01/02/2015	Machine is unpowered	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A1	27/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A26	19/03/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A36	15/03/2015	Turret A and B are leaking	Michele Williams noted: Maintenance action successful.	michele_williams
A90	10/07/2015	Turret sections A & B showing leaks	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A32	29/08/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A99	06/10/2015	Repair work needed on milling spindle	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A42	12/10/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A11	25/06/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A8	28/09/2015	Power supply failure detected	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A36	07/03/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A45	13/07/2015	Unit lost electrical power	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A98	19/12/2015	Accumulators need checking and charging	Cristian Santos noted: Detail not recorded.	cristian_santos
A84	16/12/2015	Inspect and recharge accumulators	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A62	27/02/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A44	23/01/2015	Inspect and recharge accumulators	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A74	29/01/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A27	27/11/2015	Spindle fails to index, overfeeding	Michele Williams noted: Maintenance action successful.	michele_williams
A24	26/05/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A19	05/03/2015	Milling spindle requires repair	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A24	28/03/2015	Machine is unpowered	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A51	08/04/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A64	10/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A67	08/10/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A64	18/11/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A79	20/06/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Maintenance action successful.	michele_williams
A63	26/08/2015	Turret A and B are leaking	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A94	22/09/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A13	02/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A80	05/10/2015	Leaks found at turrets A and B	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A10	16/04/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A24	30/05/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A63	22/06/2015	Hydraulic line leak on side B	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A50	08/07/2015	Accumulators need checking and charging	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A6	08/08/2015	Milling spindle requires repair	Michele Williams noted: Maintenance action successful.	michele_williams
A50	07/09/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A80	12/09/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A76	17/07/2015	Accumulators need checking and charging	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A59	19/01/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: No further details.	nathan_maldonado
A84	14/06/2015	Accumulators need checking and charging	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A12	04/10/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A77	13/09/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A11	03/01/2016	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A80	02/10/2015	Leak in side B hydraulic line	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A93	29/10/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A72	22/10/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A74	17/11/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A65	11/01/2016	Unit lost electrical power	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A31	03/05/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A58	28/11/2015	Milling spindle requires repair	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A30	06/01/2016	Turret A and B are leaking	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A36	10/05/2015	Leak in side B hydraulic line	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A85	06/11/2015	Spindle indexing error with overfeed	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A84	31/10/2015	Accumulators need checking and charging	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A69	03/06/2015	Turret A and B are leaking	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A71	05/01/2016	Indexing issue causing overfeed on spindle	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A90	24/12/2015	Inspect and recharge accumulators	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A87	11/07/2015	Turret sections A & B showing leaks	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A30	09/01/2016	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A89	20/03/2015	Spindle indexing error with overfeed	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A65	06/06/2015	Accumulators need checking and charging	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A51	03/08/2015	Repair work needed on milling spindle	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A40	18/01/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A75	26/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A31	14/10/2015	Hydraulic line leak on side B	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A93	13/08/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A88	09/08/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams

A20	04/12/2015	Unit lost electrical power	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A39	24/11/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A89	05/11/2015	Repair work needed on milling spindle	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A7	12/02/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A92	09/07/2015	Milling spindle requires repair	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A50	21/04/2015	Machine is unpowered	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A48	26/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A93	15/03/2015	Accumulators need checking and charging	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A56	02/12/2015	Accumulators need checking and charging	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A1	02/06/2015	Inspect and recharge accumulators	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A85	29/12/2015	Turret sections A & B showing leaks	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A70	20/05/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Fixed and tested.	michele_williams
A63	03/06/2015	Turret sections A & B showing leaks	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A55	28/08/2015	Leaks found at turrets A and B	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A97	08/01/2016	Inspect and recharge accumulators	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A16	20/09/2015	Leak in side B hydraulic line	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A55	03/01/2016	Spindle fails to index, overfeeding	Michele Williams noted: System checked and accumulators charged.	michele_williams
A20	31/07/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A71	11/11/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A36	11/04/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A54	26/10/2015	Hydraulic line leak on side B	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A88	27/07/2015	Accumulator inspection and charging required	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A54	23/08/2015	Maintenance on milling spindle needed	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A59	14/12/2015	Maintenance on milling spindle needed	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A29	13/04/2015	Hydraulic line leak on side B	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A63	04/01/2016	Turret sections A & B showing leaks	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A16	23/07/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A31	26/06/2015	Unit lost electrical power	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A7	30/08/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A11	08/10/2015	Milling spindle requires repair	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A55	11/04/2015	Turret sections A & B showing leaks	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A1	23/12/2015	Hydraulic line leak on side B	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A26	12/03/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A68	07/10/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A30	06/11/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A37	13/10/2015	Accumulator inspection and charging required	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A75	21/08/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A48	28/09/2015	Turret sections A & B showing leaks	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A20	03/12/2015	Machine is unpowered	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A56	01/09/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A83	24/06/2015	Inspect and recharge accumulators	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A77	17/02/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A45	21/01/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A67	07/12/2015	Inspect and recharge accumulators	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A66	11/09/2015	Turret sections A & B showing leaks	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A54	30/09/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A49	08/04/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A93	18/11/2015	Repair work needed on milling spindle	Cristian Santos noted: No further details.	cristian_santos
A56	24/09/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A12	13/06/2015	Accumulators need checking and charging	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A4	05/03/2015	Accumulator inspection and charging required	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A69	09/11/2015	Maintenance on milling spindle needed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A15	11/07/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A82	04/09/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A68	27/07/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A33	01/02/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: No further details.	gina_moore, dylan_miller
A25	05/08/2015	Repair work needed on milling spindle	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A29	07/03/2015	Machine is unpowered	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A59	31/01/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A57	18/09/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A21	05/07/2015	Leak in side B hydraulic line	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A89	24/12/2015	Maintenance on milling spindle needed	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A89	18/06/2015	Spindle fails to index, overfeeding	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A58	06/07/2015	Machine is unpowered	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A67	15/08/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A85	11/06/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A90	05/04/2015	Turret A and B are leaking	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A39	29/09/2015	Hydraulic line leak on side B	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A39	04/04/2015	Maintenance on milling spindle needed	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A39	25/07/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado

A26	08/09/2015	Unit lost electrical power	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A42	22/01/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A54	02/01/2016	Hydraulic hose on side B is leaking	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A40	04/02/2015	Machine is unpowered	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A13	14/02/2015	Accumulators need checking and charging	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A98	04/04/2015	Turret sections A & B showing leaks	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A31	23/09/2015	Leaks found at turrets A and B	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A35	31/05/2015	Hydraulic line leak on side B	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A43	27/04/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A44	21/10/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A14	27/09/2015	Leak in side B hydraulic line	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A38	03/01/2016	Hydraulic line leak on side B	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A63	06/12/2015	Inspect and recharge accumulators	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A84	05/01/2016	Accumulators need checking and charging	Michele Williams noted: Repair completed.	michele_williams
A15	15/03/2015	Repair work needed on milling spindle	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A17	03/03/2015	Power supply failure detected	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A25	05/01/2016	Hydraulic line leak on side B	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A12	03/07/2015	Spindle indexing error with overfeed	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A42	16/10/2015	Inspect and recharge accumulators	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A39	09/10/2015	Maintenance on milling spindle needed	Cristian Santos noted: No further details.	cristian_santos
A87	28/12/2015	Machine is unpowered	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A50	25/12/2015	Saw attachment gears are binding and grinding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A56	04/06/2015	Accumulator inspection and charging required	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A62	21/06/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A21	25/10/2015	Spindle indexing error with overfeed	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A45	05/07/2015	Hydraulic line leak on side B	Cristian Santos noted: Repair completed.	cristian_santos
A42	10/06/2015	Leak in side B hydraulic line	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A92	13/10/2015	Accumulators need checking and charging	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A68	20/05/2015	Accumulators need checking and charging	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A60	23/07/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A41	10/12/2015	Machine is unpowered	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A83	22/02/2015	Milling spindle requires repair	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A29	09/04/2015	Repair work needed on milling spindle	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A93	22/12/2015	Spindle indexing error with overfeed	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A71	06/10/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A9	07/02/2015	Leaks found at turrets A and B	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A56	12/12/2015	Spindle indexing error with overfeed	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A51	03/02/2015	Unit lost electrical power	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A83	16/03/2015	Leaks found at turrets A and B	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A2	17/12/2015	Machine is unpowered	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A57	19/03/2015	Repair work needed on milling spindle	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A18	14/01/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A80	02/08/2015	Leak in side B hydraulic line	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A40	04/12/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A34	14/06/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A88	01/09/2015	Inspect and recharge accumulators	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A89	20/05/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A82	27/01/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Repair completed.	cristian_santos
A78	17/06/2015	Hydraulic line leak on side B	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A1	20/02/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A43	31/10/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A71	21/06/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A6	24/11/2015	Spindle indexing error with overfeed	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A7	29/10/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A79	23/06/2015	Repair work needed on milling spindle	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A1	24/12/2015	Repair work needed on milling spindle	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A85	16/06/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A72	23/06/2015	Hydraulic line leak on side B	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A25	21/12/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A68	18/03/2015	Leak in side B hydraulic line	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A68	24/09/2015	Spindle indexing error with overfeed	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A4	28/02/2015	Machine is unpowered	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A83	28/01/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A98	06/02/2015	Turret A and B are leaking	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A87	09/11/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A17	08/12/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A7	07/10/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Fixed and tested.	cristian_santos
A21	13/04/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A62	29/09/2015	Accumulators need checking and charging	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A6	29/04/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams

A82	17/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A83	15/12/2015	Machine is unpowered	Gina Moore noted: No further details.	gina_moore, dylan_miller
A92	26/09/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A33	18/11/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A13	01/12/2015	Machine is unpowered	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A39	09/07/2015	Maintenance on milling spindle needed	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A59	29/01/2015	Unit lost electrical power	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A22	21/11/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A73	20/06/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A74	20/02/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A52	09/01/2016	Repair work needed on milling spindle	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A8	06/05/2015	Maintenance on milling spindle needed	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A14	22/10/2015	Accumulator inspection and charging required	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A32	18/01/2015	Unit lost electrical power	Nathan Maldonado noted: No further details.	nathan_maldonado
A30	15/12/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A21	30/04/2015	Accumulators need checking and charging	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A74	09/12/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A40	26/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A86	20/11/2015	Milling spindle requires repair	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A91	15/11/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A35	12/04/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A97	25/06/2015	Leak in side B hydraulic line	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A22	25/05/2015	Turret sections A & B showing leaks	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A70	12/04/2015	Accumulators need checking and charging	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A34	25/05/2015	Leaks found at turrets A and B	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A5	14/12/2015	Milling spindle requires repair	Michele Williams noted: System checked and accumulators charged.	michele_williams
A25	02/10/2015	Milling spindle requires repair	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A22	29/08/2015	Turret A and B are leaking	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A28	12/12/2015	Turret sections A & B showing leaks	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A30	02/07/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A18	14/07/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A89	03/10/2015	Spindle indexing error with overfeed	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A72	07/12/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A59	07/05/2015	Accumulators need checking and charging	Michele Williams noted: Repair completed.	michele_williams
A21	19/10/2015	Repair work needed on milling spindle	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A1	02/12/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A7	29/05/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A43	15/09/2015	Repair work needed on milling spindle	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A32	04/06/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Detail not recorded.	cristian_santos
A29	20/07/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: System checked and accumulators charged.	michele_williams
A17	29/06/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A62	09/03/2015	Milling spindle requires repair	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A21	25/03/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A49	14/08/2015	Turret A and B are leaking	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A37	11/03/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A15	09/06/2015	Repair work needed on milling spindle	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A57	12/04/2015	Power supply failure detected	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A48	07/09/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A40	21/07/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A7	08/04/2015	Maintenance on milling spindle needed	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A24	15/09/2015	Turret A and B are leaking	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A90	11/03/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Detail not recorded.	cristian_santos
A11	16/04/2015	Accumulators need checking and charging	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A99	14/01/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A75	08/07/2015	Spindle indexing error with overfeed	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A87	23/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A52	05/03/2015	Turret A and B are leaking	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A10	12/04/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A40	04/05/2015	Power supply failure detected	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A17	26/08/2015	Accumulators need checking and charging	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A79	06/07/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A30	06/12/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A80	15/09/2015	Turret sections A & B showing leaks	Cristian Santos noted: No further details.	cristian_santos
A58	14/07/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A84	16/06/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A47	27/10/2015	Spindle indexing error with overfeed	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A60	01/04/2015	Repair work needed on milling spindle	Cristian Santos noted: Repair completed.	cristian_santos
A90	28/09/2015	Machine is unpowered	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A88	14/04/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A55	31/07/2015	Spindle indexing error with overfeed	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams

A18	28/08/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A67	14/05/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A33	02/08/2015	Accumulators need checking and charging	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A80	05/03/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A74	24/07/2015	Accumulator inspection and charging required	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A43	10/12/2015	Unit lost electrical power	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A70	27/03/2015	Accumulators need checking and charging	Michele Williams noted: Maintenance action successful.	michele_williams
A95	11/05/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A94	26/03/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A80	20/12/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A4	11/07/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A87	12/01/2016	Turret A and B are leaking	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A71	18/07/2015	Inspect and recharge accumulators	Michele Williams noted: System checked and accumulators charged.	michele_williams
A86	09/04/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: No further details.	nathan_maldonado
A21	31/05/2015	Machine is unpowered	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A65	10/11/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A51	04/08/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A68	31/10/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A34	30/05/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A42	12/06/2015	Saw attachment gears are binding and grinding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A78	06/09/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A53	28/03/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A50	21/05/2015	Inspect and recharge accumulators	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A5	13/04/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Maintenance action successful.	michele_williams
A28	24/03/2015	Milling spindle requires repair	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A68	09/02/2015	Machine is unpowered	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A33	18/05/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A3	02/06/2015	Unit lost electrical power	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A17	09/06/2015	Hydraulic line leak on side B	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A5	17/08/2015	Turret A and B are leaking	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A92	06/09/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A72	30/12/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A28	13/12/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A4	16/06/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A22	12/03/2015	Inspect and recharge accumulators	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A51	20/08/2015	Machine is unpowered	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A70	05/11/2015	Machine is unpowered	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A61	05/08/2015	Machine is unpowered	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A23	22/02/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A30	07/06/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A76	23/05/2015	Turret A and B are leaking	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A1	20/05/2015	Hydraulic line leak on side B	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A86	22/01/2015	Maintenance on milling spindle needed	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A98	03/03/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A26	21/02/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A24	10/11/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A36	31/05/2015	Spindle indexing error with overfeed	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A32	04/05/2015	Hydraulic line leak on side B	Michele Williams noted: No further details.	michele_williams
A44	21/07/2015	Milling spindle requires repair	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A51	13/12/2015	Repair work needed on milling spindle	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A28	18/03/2015	Accumulators need checking and charging	Cristian Santos noted: Detail not recorded.	cristian_santos
A10	23/01/2015	Accumulators need checking and charging	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A30	08/04/2015	Accumulator inspection and charging required	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A18	05/01/2016	Power supply failure detected	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A43	21/11/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A57	18/04/2015	Repair work needed on milling spindle	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A40	09/11/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A18	30/10/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A20	09/09/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A80	30/01/2015	Milling spindle requires repair	Cristian Santos noted: Fixed and tested.	cristian_santos
A78	08/09/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A27	03/12/2015	Accumulators need checking and charging	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A62	25/04/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A21	31/08/2015	Spindle indexing error with overfeed	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A39	06/01/2016	Turret A and B are leaking	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A77	23/03/2015	Accumulators need checking and charging	Cristian Santos noted: Repair completed.	cristian_santos
A88	03/07/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A93	07/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A55	21/04/2015	Maintenance on milling spindle needed	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A21	06/01/2016	Unit lost electrical power	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams

A63	11/11/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A3	03/05/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A76	11/07/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A96	12/09/2015	Hydraulic line leak on side B	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A69	15/10/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A71	28/02/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A29	23/08/2015	Saw attachment is leaking hydraulics	Gina Moore noted: No further details.	gina_moore, dylan_miller
A31	06/06/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A36	19/11/2015	Accumulators need checking and charging	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A10	10/12/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A36	17/11/2015	Power supply failure detected	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A13	23/11/2015	Leaks found at turrets A and B	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A97	25/02/2015	Spindle indexing error with overfeed	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A9	27/01/2015	Maintenance on milling spindle needed	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A52	28/02/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A54	16/08/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A70	17/03/2015	Milling spindle requires repair	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A67	12/08/2015	Machine is unpowered	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A98	02/12/2015	Repair work needed on milling spindle	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A72	27/05/2015	Milling spindle requires repair	Cristian Santos noted: No further details.	cristian_santos
A24	23/12/2015	Leaks found at turrets A and B	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A43	23/08/2015	Accumulator inspection and charging required	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A20	26/08/2015	Turret sections A & B showing leaks	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A53	04/03/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A96	19/08/2015	Repair work needed on milling spindle	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A29	24/08/2015	Maintenance on milling spindle needed	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A52	10/06/2015	Repair work needed on milling spindle	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A7	01/07/2015	Inspect and recharge accumulators	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A97	21/10/2015	Spindle indexing error with overfeed	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A80	01/06/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A47	15/08/2015	Turret A and B are leaking	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A5	19/12/2015	Machine is unpowered	Michele Williams noted: Maintenance action successful.	michele_williams
A87	30/09/2015	Turret sections A & B showing leaks	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A95	11/04/2015	Maintenance on milling spindle needed	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A31	15/12/2015	Repair work needed on milling spindle	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A63	04/05/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A99	08/07/2015	Repair work needed on milling spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A90	22/06/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A26	13/04/2015	Unit lost electrical power	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A85	29/03/2015	Milling spindle requires repair	Gina Moore noted: No further details.	gina_moore, dylan_miller
A51	04/07/2015	Leaks found at turrets A and B	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A52	18/12/2015	Hydraulic line leak on side B	Cristian Santos noted: Detail not recorded.	cristian_santos
A83	03/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A52	02/06/2015	Spindle fails to index, overfeeding	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A15	25/08/2015	Maintenance on milling spindle needed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A2	29/10/2015	Power supply failure detected	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A28	06/05/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A83	03/02/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A22	20/01/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A99	13/10/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A10	30/03/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A44	09/01/2016	Repair work needed on milling spindle	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A32	05/07/2015	Power supply failure detected	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A40	27/01/2015	Maintenance on milling spindle needed	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A3	10/06/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A92	01/03/2015	Inspect and recharge accumulators	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A22	17/12/2015	Maintenance on milling spindle needed	Cristian Santos noted: No further details.	cristian_santos
A11	05/06/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A23	27/02/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Repair completed.	michele_williams
A94	19/09/2015	Inspect and recharge accumulators	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A39	25/03/2015	Milling spindle requires repair	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A95	23/04/2015	Inspect and recharge accumulators	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A37	24/04/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A72	28/11/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A52	09/11/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A27	16/12/2015	Turret sections A & B showing leaks	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A91	20/03/2015	Maintenance on milling spindle needed	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A57	08/01/2016	Repair work needed on milling spindle	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A16	24/10/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A40	12/08/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos

A17	17/06/2015	Spindle indexing error with overfeed	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A82	11/11/2015	Machine is unpowered	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A91	02/05/2015	Power supply failure detected	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A49	13/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Maintenance action successful.	michele_williams
A39	15/11/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A7	20/05/2015	Maintenance on milling spindle needed	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A37	04/08/2015	Unit lost electrical power	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A51	15/09/2015	Accumulators need checking and charging	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A34	14/10/2015	Power supply failure detected	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A48	16/10/2015	Spindle indexing error with overfeed	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A33	24/10/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A24	14/02/2015	Spindle indexing error with overfeed	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A69	26/06/2015	Spindle fails to index, overfeeding	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A45	13/02/2015	Leak in side B hydraulic line	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A5	13/12/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A61	07/12/2015	Inspect and recharge accumulators	Cristian Santos noted: Fixed and tested.	cristian_santos
A8	10/10/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A97	11/11/2015	Inspect and recharge accumulators	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A4	22/08/2015	Unit lost electrical power	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A59	15/09/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A72	23/11/2015	Accumulators need checking and charging	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A52	26/09/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A40	09/08/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A54	18/12/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A87	02/10/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A69	06/01/2016	Turret sections A & B showing leaks	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A63	18/05/2015	Maintenance on milling spindle needed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A28	19/09/2015	Inspect and recharge accumulators	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A91	03/02/2015	Spindle indexing error with overfeed	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A97	15/07/2015	Accumulator inspection and charging required	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A69	12/10/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A79	07/09/2015	Power supply failure detected	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A93	25/09/2015	Leaks found at turrets A and B	Michele Williams noted: Repair completed.	michele_williams
A89	21/12/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: No further details.	cristian_santos
A87	10/12/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A24	03/11/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A22	01/06/2015	Hydraulic line leak on side B	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A81	07/04/2015	Spindle indexing error with overfeed	Cristian Santos noted: No further details.	cristian_santos
A70	07/04/2015	Turret A and B are leaking	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A9	15/04/2015	Machine is unpowered	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A45	18/06/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A54	25/03/2015	Spindle indexing error with overfeed	Michele Williams noted: Maintenance action successful.	michele_williams
A59	10/07/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A58	26/06/2015	Power supply failure detected	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A17	24/07/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A74	23/11/2015	Turret sections A & B showing leaks	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A75	16/02/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A31	26/08/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A95	18/04/2015	Inspect and recharge accumulators	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A33	24/01/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A84	20/09/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A79	16/03/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A93	11/01/2016	Power supply failure detected	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A46	14/09/2015	Maintenance on milling spindle needed	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A37	08/01/2016	Leak in side B hydraulic line	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A44	10/06/2015	Accumulators need checking and charging	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A4	10/03/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A18	12/09/2015	Milling spindle requires repair	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A32	15/11/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A77	15/08/2015	Accumulator inspection and charging required	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A87	06/03/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A29	24/12/2015	Spindle indexing error with overfeed	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A59	10/10/2015	Hydraulic line leak on side B	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A96	09/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A25	23/04/2015	Milling spindle requires repair	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A35	13/01/2016	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A94	02/08/2015	Turret A and B are leaking	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A45	22/04/2015	Inspect and recharge accumulators	Gina Moore noted: No further details.	gina_moore, dylan_miller
A89	20/06/2015	Machine is unpowered	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A19	02/11/2015	Unit lost electrical power	Gina Moore noted: No further details.	gina_moore, dylan_miller

A1	13/07/2015	Hydraulic line leak on side B	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A60	05/07/2015	Inspect and recharge accumulators	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A55	13/09/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A23	08/01/2016	Unit lost electrical power	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A52	07/06/2015	Inspect and recharge accumulators	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A68	06/03/2015	Turret A and B are leaking	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A40	27/06/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: No further details.	cristian_santos
A29	30/07/2015	Repair work needed on milling spindle	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A2	02/12/2015	Turret A and B are leaking	Michele Williams noted: System checked and accumulators charged.	michele_williams
A59	19/07/2015	Spindle fails to index, overfeeding	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A10	20/05/2015	Leak in side B hydraulic line	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A98	16/04/2015	Spindle fails to index, overfeeding	Michele Williams noted: Maintenance action successful.	michele_williams
A12	14/07/2015	Repair work needed on milling spindle	Michele Williams noted: Maintenance action successful.	michele_williams
A34	14/07/2015	Spindle indexing error with overfeed	Michele Williams noted: System checked and accumulators charged.	michele_williams
A24	04/10/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A53	04/02/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A96	24/01/2015	Hydraulic line leak on side B	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A64	02/10/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A7	04/06/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Detail not recorded.	michele_williams
A29	03/01/2016	Leaks found at turrets A and B	Michele Williams noted: No additional information provided.	michele_williams
A54	07/07/2015	Turret A and B are leaking	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A4	08/05/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A64	21/01/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A29	20/05/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A11	20/06/2015	Accumulator inspection and charging required	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A66	12/10/2015	Milling spindle requires repair	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A56	18/03/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A38	16/06/2015	Accumulators need checking and charging	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A88	26/10/2015	Leak in side B hydraulic line	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A71	09/07/2015	Spindle indexing error with overfeed	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A43	09/06/2015	Leaks found at turrets A and B	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A90	10/01/2016	Spindle indexing error with overfeed	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A16	12/02/2015	Turret A and B are leaking	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A5	31/08/2015	Hydraulic line leak on side B	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A8	14/10/2015	Spindle indexing error with overfeed	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A11	22/05/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A32	04/11/2015	Turret sections A & B showing leaks	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A54	12/04/2015	Unit lost electrical power	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A43	12/02/2015	Leaks found at turrets A and B	Nathan Maldonado noted: No further details.	nathan_maldonado
A14	27/12/2015	Leaks found at turrets A and B	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A20	08/06/2015	Turret sections A & B showing leaks	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A25	30/07/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A55	19/10/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A6	17/06/2015	Leaks found at turrets A and B	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A73	15/08/2015	Leaks found at turrets A and B	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A17	26/04/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A44	02/08/2015	Machine is unpowered	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A29	26/02/2015	Unit lost electrical power	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A79	10/11/2015	Milling spindle requires repair	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A72	26/11/2015	Power supply failure detected	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A65	11/10/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A72	26/04/2015	Spindle indexing error with overfeed	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A39	03/12/2015	Machine is unpowered	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A51	20/08/2015	Accumulator inspection and charging required	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A99	08/04/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A52	08/07/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A53	03/09/2015	Unit lost electrical power	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A31	30/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A81	30/08/2015	Unit lost electrical power	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A45	25/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A16	03/11/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A75	14/08/2015	Machine is unpowered	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A66	21/05/2015	Inspect and recharge accumulators	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A35	02/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A78	09/03/2015	Accumulators need checking and charging	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A32	07/10/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A44	14/10/2015	Milling spindle requires repair	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A28	07/11/2015	Maintenance on milling spindle needed	Cristian Santos noted: No further details.	cristian_santos
A57	07/02/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A41	10/06/2015	Maintenance on milling spindle needed	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos

A13	04/08/2015	Inspect and recharge accumulators	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A62	27/02/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A2	27/02/2015	Leaks found at turrets A and B	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A85	11/12/2015	Milling spindle requires repair	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A70	20/10/2015	Power supply failure detected	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A60	21/09/2015	Spindle indexing error with overfeed	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A26	07/05/2015	Accumulator inspection and charging required	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A69	18/02/2015	Accumulators need checking and charging	Cristian Santos noted: No additional information provided.	cristian_santos
A2	06/10/2015	Turret sections A & B showing leaks	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A56	02/11/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A77	24/06/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: System checked and accumulators charged.	michele_williams
A34	11/11/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A73	10/09/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A78	30/06/2015	Accumulator inspection and charging required	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A33	18/12/2015	Turret sections A & B showing leaks	Cristian Santos noted: Repair completed.	cristian_santos
A22	02/04/2015	Maintenance on milling spindle needed	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A88	21/09/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A11	21/12/2015	Turret sections A & B showing leaks	Cristian Santos noted: Maintenance action successful.	cristian_santos
A33	17/08/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A26	07/12/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A33	05/07/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A52	17/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A37	31/01/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A30	04/09/2015	Accumulator inspection and charging required	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A70	22/09/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A51	10/12/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A62	30/07/2015	Turret sections A & B showing leaks	Michele Williams noted: Maintenance action successful.	michele_williams
A55	20/03/2015	Repair work needed on milling spindle	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A25	19/10/2015	Machine is unpowered	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A64	05/06/2015	Repair work needed on milling spindle	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A88	01/02/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A94	04/08/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A50	28/04/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A65	08/10/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A33	16/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A52	01/03/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A31	16/11/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Maintenance action successful.	michele_williams
A65	15/07/2015	Leak in side B hydraulic line	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A82	06/08/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A29	20/06/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: No additional information provided.	cristian_santos
A39	29/01/2015	Machine is unpowered	Cristian Santos noted: Detail not recorded.	cristian_santos
A50	14/09/2015	Leaks found at turrets A and B	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A15	27/05/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A24	01/08/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Repair completed.	michele_williams
A11	18/06/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A98	21/12/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A76	16/08/2015	Maintenance on milling spindle needed	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A90	19/01/2015	Repair work needed on milling spindle	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A81	21/05/2015	Leaks found at turrets A and B	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A94	08/06/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A3	22/02/2015	Leak in side B hydraulic line	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A96	30/10/2015	Inspect and recharge accumulators	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A4	25/12/2015	Turret sections A & B showing leaks	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A60	15/02/2015	Repair work needed on milling spindle	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A89	22/12/2015	Power supply failure detected	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A41	25/01/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A70	15/06/2015	Machine is unpowered	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A76	28/09/2015	Spindle indexing error with overfeed	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A75	10/09/2015	Leak in side B hydraulic line	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A40	14/01/2015	Leak in side B hydraulic line	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A42	21/07/2015	Hydraulic line leak on side B	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A19	13/02/2015	Spindle fails to index, overfeeding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A13	01/12/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A30	07/09/2015	Accumulator inspection and charging required	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A34	25/10/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A33	09/09/2015	Turret sections A & B showing leaks	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A90	07/08/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A69	22/04/2015	Inspect and recharge accumulators	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A92	13/04/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A47	08/06/2015	Inspect and recharge accumulators	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller

A45	07/06/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A87	17/06/2015	Repair work needed on milling spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A50	02/08/2015	Unit lost electrical power	Michele Williams noted: No further details.	michele_williams
A44	25/03/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A82	14/01/2015	Repair work needed on milling spindle	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A18	21/07/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A4	09/12/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A3	02/09/2015	Hydraulic line leak on side B	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A91	19/02/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A46	14/08/2015	Turret A and B are leaking	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A5	29/06/2015	Leak in side B hydraulic line	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A49	28/11/2015	Spindle indexing error with overfeed	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A31	20/12/2015	Milling spindle requires repair	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A33	16/08/2015	Maintenance on milling spindle needed	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A70	22/05/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: No further details.	michele_williams
A80	06/07/2015	Spindle indexing error with overfeed	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A53	13/05/2015	Accumulator inspection and charging required	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A51	06/02/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A51	17/05/2015	Machine is unpowered	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A26	13/05/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A26	30/03/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A34	23/10/2015	Hydraulic line leak on side B	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A73	24/06/2015	Maintenance on milling spindle needed	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A39	20/08/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: System checked and accumulators charged.	michele_williams
A12	16/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A36	15/05/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A97	29/12/2015	Leaks found at turrets A and B	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A79	22/09/2015	Leak in side B hydraulic line	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A44	26/10/2015	Hydraulic line leak on side B	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A49	06/05/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A29	14/10/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Repair completed.	michele_williams
A55	02/03/2015	Turret sections A & B showing leaks	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A28	31/03/2015	Repair work needed on milling spindle	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A79	04/07/2015	Spindle indexing error with overfeed	Gina Moore noted: No further details.	gina_moore, dylan_miller
A76	22/02/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A5	18/08/2015	Accumulators need checking and charging	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A70	20/07/2015	Leaks found at turrets A and B	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A64	29/01/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A45	09/06/2015	Machine is unpowered	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A89	12/10/2015	Repair work needed on milling spindle	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A17	12/02/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A94	04/03/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: No further details.	nathan_maldonado
A59	15/12/2015	Leak in side B hydraulic line	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A41	09/01/2016	Accumulator inspection and charging required	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A54	10/05/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A75	04/12/2015	Maintenance on milling spindle needed	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A76	21/04/2015	Accumulators need checking and charging	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A97	04/03/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A9	23/11/2015	Spindle fails to index, overfeeding	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A75	22/10/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A80	13/01/2016	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A37	30/08/2015	Unit lost electrical power	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A62	28/09/2015	Turret sections A & B showing leaks	Cristian Santos noted: Maintenance action successful.	cristian_santos
A29	01/04/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A47	10/11/2015	Unit lost electrical power	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A6	09/07/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A70	09/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A80	09/09/2015	Turret A and B are leaking	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A42	01/10/2015	Spindle indexing error with overfeed	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A24	05/11/2015	Maintenance on milling spindle needed	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A96	01/05/2015	Accumulators need checking and charging	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A30	24/10/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A90	28/01/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A56	16/08/2015	Leaks found at turrets A and B	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A10	10/12/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A88	18/05/2015	Accumulators need checking and charging	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A7	17/08/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A5	19/09/2015	Power supply failure detected	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A54	06/05/2015	Turret sections A & B showing leaks	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A19	23/06/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado

A21	23/07/2015	Repair work needed on milling spindle	Gina Moore noted: No further details.	gina_moore, dylan_miller
A34	27/05/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A38	11/10/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A30	01/11/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A10	17/03/2015	Maintenance on milling spindle needed	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A38	24/06/2015	Inspect and recharge accumulators	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A39	21/03/2015	Milling spindle requires repair	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A16	07/05/2015	Turret A and B are leaking	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A73	06/09/2015	Leak in side B hydraulic line	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A9	19/05/2015	Unit lost electrical power	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A88	10/01/2016	Spindle fails to index, overfeeding	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A55	21/09/2015	Turret A and B are leaking	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A8	13/01/2016	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A84	24/05/2015	Accumulators need checking and charging	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A50	05/03/2015	Leaks found at turrets A and B	Gina Moore noted: No further details.	gina_moore, dylan_miller
A47	27/11/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A85	20/09/2015	Accumulator inspection and charging required	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A54	21/06/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A24	19/10/2015	Unit lost electrical power	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A74	10/12/2015	Turret A and B are leaking	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A30	26/09/2015	Spindle indexing error with overfeed	Cristian Santos noted: No additional information provided.	cristian_santos
A98	08/12/2015	Power supply failure detected	Cristian Santos noted: Repair completed.	cristian_santos
A82	05/05/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A30	11/10/2015	Hydraulic line leak on side B	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A80	26/11/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A53	06/03/2015	Turret sections A & B showing leaks	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A61	17/01/2015	Accumulators need checking and charging	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A39	08/05/2015	Unit lost electrical power	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A74	25/12/2015	Unit lost electrical power	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A28	01/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A39	04/08/2015	Unit lost electrical power	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A3	23/06/2015	Accumulator inspection and charging required	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A35	16/03/2015	Spindle indexing error with overfeed	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A92	16/03/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A28	16/03/2015	Saw attachment gears are binding and grinding	Michele Williams noted: No further details.	michele_williams
A74	14/02/2015	Machine is unpowered	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A98	12/08/2015	Accumulators need checking and charging	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A23	09/01/2016	Hydraulic hose on side B is leaking	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A3	31/05/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A50	03/04/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A78	19/03/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A83	15/12/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A91	29/07/2015	Power supply failure detected	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A78	23/06/2015	Turret A and B are leaking	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A76	10/10/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A19	25/08/2015	Inspect and recharge accumulators	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A90	31/12/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A56	11/06/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A36	13/02/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A96	23/08/2015	Leaks found at turrets A and B	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A3	25/04/2015	Leaks found at turrets A and B	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A74	01/02/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A1	20/09/2015	Maintenance on milling spindle needed	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A3	24/10/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A89	02/03/2015	Spindle fails to index, overfeeding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A45	13/01/2016	Repair work needed on milling spindle	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A53	14/05/2015	Milling spindle requires repair	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A54	17/11/2015	Maintenance on milling spindle needed	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A27	19/04/2015	Power supply failure detected	Cristian Santos noted: Detail not recorded.	cristian_santos
A81	23/07/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A23	07/03/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A67	22/09/2015	Maintenance on milling spindle needed	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A31	31/01/2015	Machine is unpowered	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A96	31/03/2015	Leaks found at turrets A and B	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A76	27/12/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A57	14/11/2015	Milling spindle requires repair	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A2	05/12/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A2	01/04/2015	Accumulator inspection and charging required	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A36	21/03/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A99	22/06/2015	Spindle indexing error with overfeed	Ethan Adams noted: No further details.	ethan_adams, michele_williams

A35	03/06/2015	Power supply failure detected	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A4	17/08/2015	Leaks found at turrets A and B	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A49	11/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A64	22/12/2015	Hydraulic line leak on side B	Michele Williams noted: No further details.	michele_williams
A55	02/04/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A96	09/03/2015	Power supply failure detected	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A76	08/09/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A21	15/10/2015	Accumulators need checking and charging	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A79	19/12/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Fixed and tested.	michele_williams
A91	13/05/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A50	08/08/2015	Inspect and recharge accumulators	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A18	15/06/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A52	23/09/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A9	17/01/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A15	12/08/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A67	11/07/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A90	29/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A12	16/08/2015	Leaks found at turrets A and B	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A30	17/09/2015	Maintenance on milling spindle needed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A15	05/08/2015	Milling spindle requires repair	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A30	23/03/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A80	01/03/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A73	22/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A82	01/04/2015	Spindle indexing error with overfeed	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A62	31/07/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A33	12/12/2015	Milling spindle requires repair	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A34	14/09/2015	Inspect and recharge accumulators	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A74	14/12/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A50	13/11/2015	Unit lost electrical power	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A66	06/11/2015	Power supply failure detected	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A7	22/06/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A84	24/05/2015	Hydraulic line leak on side B	Cristian Santos noted: Repair completed.	cristian_santos
A8	15/06/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A67	12/04/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A65	16/07/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A68	05/02/2015	Power supply failure detected	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A28	16/05/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A76	14/06/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: No additional information provided.	cristian_santos
A81	01/11/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A61	16/04/2015	Turret sections A & B showing leaks	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A63	28/01/2015	Hydraulic line leak on side B	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A41	15/09/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A33	07/08/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: No further details.	nathan_maldonado
A5	22/09/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A87	17/10/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A94	02/09/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A94	08/07/2015	Accumulators need checking and charging	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A48	29/01/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A37	30/12/2015	Turret sections A & B showing leaks	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A78	02/02/2015	Turret sections A & B showing leaks	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A79	03/08/2015	Power supply failure detected	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A27	10/08/2015	Turret sections A & B showing leaks	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A94	28/02/2015	Machine is unpowered	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A80	16/06/2015	Turret sections A & B showing leaks	Michele Williams noted: Repair completed.	michele_williams
A82	08/02/2015	Spindle indexing error with overfeed	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A70	11/04/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A33	14/08/2015	Unit lost electrical power	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A87	14/06/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A1	26/02/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Fixed and tested.	cristian_santos
A13	13/05/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A35	21/02/2015	Power supply failure detected	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A61	29/08/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A26	03/03/2015	Unit lost electrical power	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A85	30/01/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A19	07/04/2015	Turret A and B are leaking	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A63	01/07/2015	Unit lost electrical power	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A14	16/05/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A71	02/04/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A1	14/04/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A21	14/11/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams

A1	10/11/2015	Leaks found at turrets A and B	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A41	27/05/2015	Accumulators need checking and charging	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A61	09/04/2015	Accumulator inspection and charging required	Cristian Santos noted: Detail not recorded.	cristian_santos
A24	04/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A71	18/08/2015	Maintenance on milling spindle needed	Michele Williams noted: System checked and accumulators charged.	michele_williams
A86	23/05/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A40	25/03/2015	Power supply failure detected	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A72	04/08/2015	Milling spindle requires repair	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A10	03/05/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A50	09/01/2016	Hydraulic hose on side B is leaking	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A34	21/06/2015	Leaks found at turrets A and B	Cristian Santos noted: Fixed and tested.	cristian_santos
A23	30/07/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A70	05/11/2015	Leak in side B hydraulic line	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A7	01/10/2015	Repair work needed on milling spindle	Gina Moore noted: No further details.	gina_moore, dylan_miller
A93	06/11/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A30	17/09/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A58	25/02/2015	Maintenance on milling spindle needed	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A27	09/04/2015	Turret A and B are leaking	Cristian Santos noted: No additional information provided.	cristian_santos
A72	06/04/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A30	01/06/2015	Power supply failure detected	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A33	17/01/2015	Leaks found at turrets A and B	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A92	31/07/2015	Power supply failure detected	Cristian Santos noted: Fixed and tested.	cristian_santos
A14	20/02/2015	Spindle fails to index, overfeeding	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A95	25/03/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A91	28/02/2015	Leaks found at turrets A and B	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A65	26/03/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A75	02/02/2015	Hydraulic line leak on side B	Cristian Santos noted: Detail not recorded.	cristian_santos
A10	20/04/2015	Turret A and B are leaking	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A83	31/05/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A5	17/08/2015	Leaks found at turrets A and B	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A77	05/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A68	11/02/2015	Spindle indexing error with overfeed	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A74	10/08/2015	Power supply failure detected	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A54	14/01/2015	Accumulator inspection and charging required	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A30	01/04/2015	Milling spindle requires repair	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A57	04/07/2015	Accumulators need checking and charging	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A44	08/02/2015	Turret sections A & B showing leaks	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A39	24/04/2015	Power supply failure detected	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A57	31/03/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Repair completed.	cristian_santos
A73	11/02/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A2	06/01/2016	Spindle fails to index, overfeeding	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A26	03/09/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A5	07/03/2015	Spindle indexing error with overfeed	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A47	01/04/2015	Leak in side B hydraulic line	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A21	30/03/2015	Maintenance on milling spindle needed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A31	22/01/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A95	21/02/2015	Unit lost electrical power	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A53	11/01/2016	Indexing issue causing overfeed on spindle	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A67	23/05/2015	Milling spindle requires repair	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A86	01/05/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A46	01/03/2015	Unit lost electrical power	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A57	17/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A76	09/09/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A74	15/03/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A18	19/12/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A8	18/01/2015	Accumulator inspection and charging required	Michele Williams noted: System checked and accumulators charged.	michele_williams
A63	17/10/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A33	16/08/2015	Machine is unpowered	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A18	05/05/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A67	21/09/2015	Machine is unpowered	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A27	23/10/2015	Accumulators need checking and charging	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A11	17/09/2015	Milling spindle requires repair	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A89	14/07/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A56	24/08/2015	Milling spindle requires repair	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A28	04/11/2015	Power supply failure detected	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A93	15/04/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A82	26/01/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A56	29/07/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A77	16/04/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A86	28/02/2015	Accumulators need checking and charging	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams

A32	14/04/2015	Leaks found at turrets A and B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A38	31/10/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A46	12/07/2015	Unit lost electrical power	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A86	06/05/2015	Milling spindle requires repair	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A87	16/01/2015	Leaks found at turrets A and B	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A9	17/04/2015	Inspect and recharge accumulators	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A90	18/03/2015	Accumulator inspection and charging required	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A97	16/03/2015	Accumulators need checking and charging	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A43	27/04/2015	Hydraulic line leak on side B	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A31	07/02/2015	Accumulator inspection and charging required	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A71	02/08/2015	Power supply failure detected	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A2	22/11/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A32	03/10/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A48	29/03/2015	Maintenance on milling spindle needed	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A27	02/02/2015	Spindle indexing error with overfeed	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A14	11/10/2015	Milling spindle requires repair	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A51	08/03/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A46	17/03/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A63	22/09/2015	Leaks found at turrets A and B	Michele Williams noted: System checked and accumulators charged.	michele_williams
A68	09/04/2015	Power supply failure detected	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A32	17/08/2015	Unit lost electrical power	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A16	28/07/2015	Accumulators need checking and charging	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A93	13/02/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A18	24/04/2015	Power supply failure detected	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A26	07/11/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A95	09/03/2015	Accumulator inspection and charging required	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A67	16/04/2015	Power supply failure detected	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A20	05/01/2016	Unit lost electrical power	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A63	06/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A39	11/01/2016	Maintenance on milling spindle needed	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A90	22/02/2015	Leak in side B hydraulic line	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A85	18/04/2015	Machine is unpowered	Michele Williams noted: No further details.	michele_williams
A63	12/10/2015	Leak in side B hydraulic line	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A11	30/03/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A95	14/06/2015	Leak in side B hydraulic line	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A46	27/09/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A82	18/04/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A32	10/07/2015	Accumulators need checking and charging	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A53	19/10/2015	Machine is unpowered	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A55	20/11/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A73	01/09/2015	Milling spindle requires repair	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A3	11/12/2015	Milling spindle requires repair	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A4	21/01/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A6	10/12/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A73	27/01/2015	Accumulator inspection and charging required	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A28	20/10/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A29	18/07/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A21	03/03/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A3	28/05/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A57	04/12/2015	Unit lost electrical power	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A1	06/07/2015	Power supply failure detected	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A67	08/04/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A43	27/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A72	30/07/2015	Accumulator inspection and charging required	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A72	07/01/2016	Saw attachment is leaking hydraulics	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A76	17/07/2015	Spindle indexing error with overfeed	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A58	25/10/2015	Leaks found at turrets A and B	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A32	18/01/2015	Leak in side B hydraulic line	Michele Williams noted: Repair completed.	michele_williams
A58	25/08/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A50	22/07/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A95	05/04/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A19	05/02/2015	Power supply failure detected	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A84	17/04/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A54	28/06/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A67	22/05/2015	Leak in side B hydraulic line	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A13	14/09/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A64	05/11/2015	Maintenance on milling spindle needed	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A63	25/06/2015	Leak in side B hydraulic line	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A24	14/09/2015	Turret A and B are leaking	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A86	11/02/2015	Turret A and B are leaking	Angie Henderson noted: No further details.	angie_henderson, michele_williams

A11	02/06/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A11	21/02/2015	Saw attachment is leaking hydraulics	Michele Williams noted: No additional information provided.	michele_williams
A38	24/02/2015	Leaks found at turrets A and B	Cristian Santos noted: No further details.	cristian_santos
A22	06/08/2015	Accumulator inspection and charging required	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A99	14/07/2015	Turret sections A & B showing leaks	Cristian Santos noted: Maintenance action successful.	cristian_santos
A16	13/03/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A51	24/03/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A48	05/01/2016	Hydraulic fluid leak at saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A29	08/12/2015	Power supply failure detected	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A76	16/10/2015	Leaks found at turrets A and B	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A67	06/05/2015	Accumulator inspection and charging required	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A75	11/08/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A84	15/04/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A13	08/07/2015	Machine is unpowered	Michele Williams noted: No additional information provided.	michele_williams
A78	08/01/2016	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: No further details.	cristian_santos
A83	15/07/2015	Accumulator inspection and charging required	Cristian Santos noted: Repair completed.	cristian_santos
A20	16/01/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A50	25/01/2015	Repair work needed on milling spindle	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A67	07/01/2016	Unit lost electrical power	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A10	15/03/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A14	14/07/2015	Hydraulic line leak on side B	Michele Williams noted: System checked and accumulators charged.	michele_williams
A79	07/02/2015	Power supply failure detected	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A60	27/03/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Detail not recorded.	cristian_santos
A58	27/10/2015	Milling spindle requires repair	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A50	12/07/2015	Leaks found at turrets A and B	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A74	14/09/2015	Spindle fails to index, overfeeding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A96	17/05/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A93	05/07/2015	Leak in side B hydraulic line	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A98	23/06/2015	Inspect and recharge accumulators	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A66	07/05/2015	Power supply failure detected	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A39	19/10/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A43	05/09/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A71	05/03/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A87	26/01/2015	Milling spindle requires repair	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A20	31/03/2015	Leaks found at turrets A and B	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A83	30/11/2015	Unit lost electrical power	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A33	24/12/2015	Milling spindle requires repair	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A27	03/05/2015	Leak in side B hydraulic line	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A79	18/01/2015	Accumulator inspection and charging required	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A48	26/09/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A55	27/03/2015	Milling spindle requires repair	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A95	01/07/2015	Hydraulic line leak on side B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A68	11/03/2015	Turret sections A & B showing leaks	Cristian Santos noted: No additional information provided.	cristian_santos
A71	22/08/2015	Spindle indexing error with overfeed	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A81	28/06/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A41	10/06/2015	Turret sections A & B showing leaks	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A17	19/09/2015	Hydraulic line leak on side B	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A82	25/02/2015	Power supply failure detected	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A42	01/02/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A14	21/12/2015	Accumulators need checking and charging	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A97	25/10/2015	Power supply failure detected	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A33	28/10/2015	Accumulator inspection and charging required	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A71	01/09/2015	Unit lost electrical power	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A76	08/02/2015	Leak in side B hydraulic line	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A53	21/09/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A34	10/04/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A25	26/12/2015	Unit lost electrical power	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A7	22/08/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A17	22/03/2015	Unit lost electrical power	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A87	27/06/2015	Maintenance on milling spindle needed	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A59	25/02/2015	Machine is unpowered	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A77	15/02/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A9	18/11/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A47	21/04/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A46	17/11/2015	Accumulators need checking and charging	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A28	02/08/2015	Machine is unpowered	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A73	30/01/2015	Spindle fails to index, overfeeding	Michele Williams noted: Detail not recorded.	michele_williams
A37	16/04/2015	Maintenance on milling spindle needed	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A83	29/08/2015	Leaks found at turrets A and B	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A34	29/11/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams

A67	23/06/2015	Leak in side B hydraulic line	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A91	01/10/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A99	15/01/2015	Accumulators need checking and charging	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A45	05/08/2015	Turret A and B are leaking	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A94	30/08/2015	Repair work needed on milling spindle	Michele Williams noted: Detail not recorded.	michele_williams
A25	20/09/2015	Turret A and B are leaking	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A45	13/05/2015	Turret sections A & B showing leaks	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A86	27/02/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A72	19/06/2015	Leaks found at turrets A and B	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A8	27/01/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A96	31/05/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A85	19/04/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A98	01/05/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A35	05/10/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A64	11/01/2016	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A65	11/02/2015	Milling spindle requires repair	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A81	30/01/2015	Leak in side B hydraulic line	Michele Williams noted: Repair completed.	michele_williams
A95	24/05/2015	Repair work needed on milling spindle	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A66	21/11/2015	Milling spindle requires repair	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A4	21/01/2015	Unit lost electrical power	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A60	17/11/2015	Hydraulic line leak on side B	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A48	28/09/2015	Spindle indexing error with overfeed	Cristian Santos noted: Fixed and tested.	cristian_santos
A29	14/02/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A31	21/11/2015	Machine is unpowered	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A77	10/09/2015	Leak in side B hydraulic line	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A18	23/02/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A72	10/12/2015	Power supply failure detected	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A40	25/04/2015	Leak in side B hydraulic line	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A15	08/09/2015	Turret sections A & B showing leaks	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A25	09/10/2015	Spindle indexing error with overfeed	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A18	28/06/2015	Inspect and recharge accumulators	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A64	04/10/2015	Accumulator inspection and charging required	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A40	25/06/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A8	14/09/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A54	10/04/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A6	26/07/2015	Milling spindle requires repair	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A48	24/02/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A80	06/02/2015	Milling spindle requires repair	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A90	27/01/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A67	23/07/2015	Spindle indexing error with overfeed	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A79	21/10/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A8	13/12/2015	Machine is unpowered	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A51	14/12/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A90	02/10/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A78	27/02/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A69	28/07/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A65	03/01/2016	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A14	25/04/2015	Turret A and B are leaking	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A19	04/11/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A65	01/11/2015	Milling spindle requires repair	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A70	19/11/2015	Hydraulic line leak on side B	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A67	13/03/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A48	06/10/2015	Spindle indexing error with overfeed	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A11	14/09/2015	Power supply failure detected	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A11	17/06/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: No further details.	nathan_maldonado
A51	27/05/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A34	09/07/2015	Leaks found at turrets A and B	Gina Moore noted: No further details.	gina_moore, dylan_miller
A16	04/07/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A99	27/04/2015	Leak in side B hydraulic line	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A43	20/11/2015	Spindle indexing error with overfeed	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A69	08/11/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A4	10/07/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A26	17/01/2015	Hydraulic line leak on side B	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A98	20/09/2015	Accumulators need checking and charging	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A88	15/02/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A86	03/03/2015	Power supply failure detected	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A57	07/01/2016	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A19	20/08/2015	Unit lost electrical power	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A75	16/09/2015	Machine is unpowered	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A7	19/02/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams

A72	20/02/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A64	28/09/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A48	16/07/2015	Machine is unpowered	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A67	27/02/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A64	22/12/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: No further details.	michele_williams
A26	07/10/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A24	21/02/2015	Maintenance on milling spindle needed	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A60	16/09/2015	Spindle indexing error with overfeed	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A9	09/02/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A62	16/07/2015	Repair work needed on milling spindle	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A16	19/07/2015	Turret sections A & B showing leaks	Cristian Santos noted: Repair completed.	cristian_santos
A89	30/05/2015	Leaks found at turrets A and B	Cristian Santos noted: Repair completed.	cristian_santos
A45	16/04/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A54	26/05/2015	Accumulator inspection and charging required	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A40	05/07/2015	Power supply failure detected	Michele Williams noted: No additional information provided.	michele_williams
A3	24/07/2015	Unit lost electrical power	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A18	13/06/2015	Leak in side B hydraulic line	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A90	26/04/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A54	09/04/2015	Spindle fails to index, overfeeding	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A49	14/08/2015	Turret A and B are leaking	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A99	08/07/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A26	23/05/2015	Turret A and B are leaking	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A83	13/04/2015	Unit lost electrical power	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A94	03/11/2015	Inspect and recharge accumulators	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A21	30/09/2015	Repair work needed on milling spindle	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A29	16/05/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: No further details.	nathan_maldonado
A40	04/04/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Detail not recorded.	cristian_santos
A50	19/06/2015	Maintenance on milling spindle needed	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A13	23/03/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A12	17/11/2015	Leak in side B hydraulic line	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A65	05/07/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A90	29/06/2015	Unit lost electrical power	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A31	06/02/2015	Power supply failure detected	Michele Williams noted: Detail not recorded.	michele_williams
A6	05/05/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A60	08/09/2015	Machine is unpowered	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A56	15/06/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A14	10/09/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A93	28/07/2015	Inspect and recharge accumulators	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A71	16/12/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Repair completed.	michele_williams
A3	05/12/2015	Power supply failure detected	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A31	01/08/2015	Hydraulic line leak on side B	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A44	28/03/2015	Maintenance on milling spindle needed	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A23	25/06/2015	Turret A and B are leaking	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A62	25/05/2015	Inspect and recharge accumulators	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A78	08/11/2015	Milling spindle requires repair	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A87	14/01/2015	Milling spindle requires repair	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A78	02/06/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A62	14/03/2015	Unit lost electrical power	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A10	11/01/2016	Leaks found at turrets A and B	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A11	09/01/2016	Machine is unpowered	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A11	12/06/2015	Turret sections A & B showing leaks	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A67	16/07/2015	Leak in side B hydraulic line	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A88	17/02/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Maintenance action successful.	michele_williams
A68	25/11/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A32	08/03/2015	Milling spindle requires repair	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A98	30/01/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A97	20/08/2015	Accumulator inspection and charging required	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A61	10/05/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A82	07/02/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A79	13/09/2015	Spindle indexing error with overfeed	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A51	02/05/2015	Machine is unpowered	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A77	09/08/2015	Accumulators need checking and charging	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A11	03/09/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A31	22/12/2015	Milling spindle requires repair	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A47	28/11/2015	Power supply failure detected	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A70	13/12/2015	Leak in side B hydraulic line	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A41	04/10/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A32	15/04/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A19	13/07/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A25	20/07/2015	Spindle indexing error with overfeed	Angie Henderson noted: No further details.	angie_henderson, michele_williams

A29	07/10/2015	Inspect and recharge accumulators	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A17	01/02/2015	Machine is unpowered	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A15	24/11/2015	Maintenance on milling spindle needed	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A39	22/04/2015	Power supply failure detected	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A49	03/07/2015	Hydraulic line leak on side B	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A15	17/07/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A79	10/12/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A59	24/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A43	05/09/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Repair completed.	cristian_santos
A45	22/04/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A43	09/08/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A65	10/07/2015	Turret sections A & B showing leaks	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A2	19/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A52	28/04/2015	Repair work needed on milling spindle	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A83	20/10/2015	Leaks found at turrets A and B	Cristian Santos noted: Repair completed.	cristian_santos
A59	06/11/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A70	27/07/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A84	07/02/2015	Unit lost electrical power	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A24	10/03/2015	Leaks found at turrets A and B	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A42	25/10/2015	Leak in side B hydraulic line	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A33	07/06/2015	Milling spindle requires repair	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A82	31/08/2015	Machine is unpowered	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A9	21/06/2015	Repair work needed on milling spindle	Cristian Santos noted: Fixed and tested.	cristian_santos
A5	09/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A14	02/07/2015	Machine is unpowered	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A65	09/08/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A67	08/10/2015	Accumulators need checking and charging	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A42	01/10/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A69	14/11/2015	Hydraulic line leak on side B	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A8	16/05/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A77	21/09/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A48	11/01/2016	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A78	24/11/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A87	24/04/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A88	09/10/2015	Turret A and B are leaking	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A91	02/07/2015	Power supply failure detected	Cristian Santos noted: No additional information provided.	cristian_santos
A47	16/08/2015	Spindle fails to index, overfeeding	Cristian Santos noted: No further details.	cristian_santos
A92	24/02/2015	Repair work needed on milling spindle	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A47	05/09/2015	Power supply failure detected	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A60	12/01/2016	Spindle indexing error with overfeed	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A75	20/01/2015	Accumulators need checking and charging	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A60	01/04/2015	Unit lost electrical power	Michele Williams noted: Detail not recorded.	michele_williams
A24	05/01/2016	Milling spindle requires repair	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A47	02/11/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A97	28/04/2015	Accumulators need checking and charging	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A9	09/01/2016	Grinding noise from tight gears on saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A48	08/08/2015	Spindle fails to index, overfeeding	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A6	06/02/2015	Unit lost electrical power	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A43	13/04/2015	Power supply failure detected	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A49	10/07/2015	Spindle indexing error with overfeed	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A79	13/04/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A68	01/04/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A64	28/12/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A2	18/02/2015	Turret sections A & B showing leaks	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A17	07/03/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A17	07/03/2015	Inspect and recharge accumulators	Gina Moore noted: No further details.	gina_moore, dylan_miller
A33	20/03/2015	Leak in side B hydraulic line	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A33	17/09/2015	Turret A and B are leaking	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A53	13/06/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A78	08/04/2015	Milling spindle requires repair	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A93	30/09/2015	Leaks found at turrets A and B	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A69	12/04/2015	Accumulators need checking and charging	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A67	19/02/2015	Hydraulic line leak on side B	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A20	06/07/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: No additional information provided.	cristian_santos
A99	05/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A92	22/09/2015	Repair work needed on milling spindle	Gina Moore noted: No further details.	gina_moore, dylan_miller
A39	26/02/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A85	05/01/2016	Accumulators need checking and charging	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A23	08/11/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A40	19/07/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams

A98	29/04/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A17	12/07/2015	Milling spindle requires repair	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A62	06/11/2015	Hydraulic line leak on side B	Cristian Santos noted: Detail not recorded.	cristian_santos
A4	17/03/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A96	25/10/2015	Hydraulic line leak on side B	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A54	26/06/2015	Hydraulic line leak on side B	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A95	18/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A33	15/08/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A9	11/12/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A8	09/09/2015	Leak in side B hydraulic line	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A21	05/07/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A22	24/06/2015	Unit lost electrical power	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A69	16/01/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A74	04/06/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A35	22/02/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A38	03/12/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A93	02/01/2016	Spindle indexing error with overfeed	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A4	11/09/2015	Inspect and recharge accumulators	Gina Moore noted: No further details.	gina_moore, dylan_miller
A33	04/02/2015	Spindle fails to index, overfeeding	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A48	27/08/2015	Unit lost electrical power	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A74	12/08/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A96	11/04/2015	Unit lost electrical power	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A38	28/04/2015	Turret sections A & B showing leaks	Cristian Santos noted: Fixed and tested.	cristian_santos
A21	04/12/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A58	26/10/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A9	29/08/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A76	24/06/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A21	06/01/2016	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A3	28/07/2015	Hydraulic line leak on side B	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A55	25/08/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A17	04/03/2015	Unit lost electrical power	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A1	22/07/2015	Hydraulic line leak on side B	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A79	30/04/2015	Repair work needed on milling spindle	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A41	27/08/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A67	25/12/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A37	09/11/2015	Accumulators need checking and charging	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A73	26/12/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A27	22/06/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A38	03/08/2015	Milling spindle requires repair	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A36	25/11/2015	Machine is unpowered	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A35	20/12/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Detail not recorded.	cristian_santos
A21	24/05/2015	Unit lost electrical power	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A59	09/04/2015	Unit lost electrical power	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A28	06/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A38	17/03/2015	Inspect and recharge accumulators	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A81	02/07/2015	Power supply failure detected	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A23	24/07/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A17	15/12/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A83	26/06/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A47	30/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A25	11/03/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A6	02/03/2015	Accumulator inspection and charging required	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A90	25/08/2015	Hydraulic line leak on side B	Michele Williams noted: System checked and accumulators charged.	michele_williams
A66	05/07/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A70	07/03/2015	Machine is unpowered	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A86	11/03/2015	Spindle indexing error with overfeed	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A22	06/03/2015	Hydraulic line leak on side B	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A58	17/03/2015	Machine is unpowered	Gina Moore noted: No further details.	gina_moore, dylan_miller
A50	25/02/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A58	02/01/2016	Repair work needed on milling spindle	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A88	30/04/2015	Turret sections A & B showing leaks	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A18	25/06/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A95	05/06/2015	Spindle fails to index, overfeeding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A44	23/10/2015	Machine is unpowered	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A13	31/07/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A64	31/05/2015	Inspect and recharge accumulators	Michele Williams noted: Maintenance action successful.	michele_williams
A78	28/12/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A55	02/11/2015	Accumulator inspection and charging required	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A55	30/12/2015	Unit lost electrical power	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A79	15/05/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams

A57	21/08/2015	Turret sections A & B showing leaks	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A99	29/04/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A28	29/05/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A54	27/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A12	29/11/2015	Unit lost electrical power	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A89	19/10/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A33	02/01/2016	Spindle fails to index, overfeeding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A58	03/04/2015	Machine is unpowered	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A31	09/02/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A13	20/11/2015	Milling spindle requires repair	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A2	15/01/2015	Hydraulic line leak on side B	Cristian Santos noted: Maintenance action successful.	cristian_santos
A86	03/06/2015	Repair work needed on milling spindle	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A71	19/01/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A72	27/06/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A2	19/10/2015	Leak in side B hydraulic line	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A64	27/10/2015	Accumulators need checking and charging	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A53	13/12/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A58	28/06/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A65	10/07/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A65	09/05/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A57	16/03/2015	Unit lost electrical power	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A8	15/06/2015	Accumulators need checking and charging	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A15	01/05/2015	Maintenance on milling spindle needed	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A47	17/07/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A55	12/11/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A94	03/10/2015	Leaks found at turrets A and B	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A11	20/10/2015	Accumulators need checking and charging	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A97	04/06/2015	Leaks found at turrets A and B	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A77	13/10/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A70	30/05/2015	Turret A and B are leaking	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A1	08/06/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A39	03/11/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A85	06/08/2015	Power supply failure detected	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A22	05/09/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A53	05/12/2015	Unit lost electrical power	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A39	31/12/2015	Power supply failure detected	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A14	28/11/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A7	15/03/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A84	24/02/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A56	08/12/2015	Unit lost electrical power	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A23	14/07/2015	Milling spindle requires repair	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A33	31/08/2015	Maintenance on milling spindle needed	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A21	08/12/2015	Milling spindle requires repair	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A18	17/04/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A26	07/12/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Repair completed.	cristian_santos
A27	22/04/2015	Machine is unpowered	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A27	01/04/2015	Hydraulic line leak on side B	Cristian Santos noted: Fixed and tested.	cristian_santos
A4	19/05/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A63	28/04/2015	Accumulator inspection and charging required	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A95	04/10/2015	Power supply failure detected	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A55	19/06/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A60	19/09/2015	Hydraulic line leak on side B	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A72	13/07/2015	Milling spindle requires repair	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A35	29/03/2015	Turret sections A & B showing leaks	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A93	17/06/2015	Accumulators need checking and charging	Cristian Santos noted: Maintenance action successful.	cristian_santos
A76	19/08/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A43	28/11/2015	Leak in side B hydraulic line	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A8	27/06/2015	Maintenance on milling spindle needed	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A97	19/10/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A93	18/11/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A99	29/06/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A70	01/09/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A65	07/02/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A43	13/09/2015	Milling spindle requires repair	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A77	27/08/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A81	20/04/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A37	06/10/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A65	26/10/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A77	12/01/2016	Repair work needed on milling spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A40	02/03/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado

A98	03/03/2015	Repair work needed on milling spindle	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A90	19/11/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A75	14/02/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A79	12/02/2015	Milling spindle requires repair	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A33	17/11/2015	Power supply failure detected	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A55	01/01/2016	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A53	15/08/2015	Machine is unpowered	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A2	15/10/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A94	05/06/2015	Repair work needed on milling spindle	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A11	15/03/2015	Maintenance on milling spindle needed	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A25	15/11/2015	Milling spindle requires repair	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A4	24/05/2015	Accumulators need checking and charging	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A98	22/08/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A61	05/09/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A55	03/11/2015	Power supply failure detected	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A73	08/11/2015	Spindle indexing error with overfeed	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A51	07/02/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Detail not recorded.	cristian_santos
A35	19/12/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A99	02/03/2015	Turret A and B are leaking	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A2	20/05/2015	Unit lost electrical power	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A83	09/01/2016	Power supply failure detected	Gina Moore noted: No further details.	gina_moore, dylan_miller
A81	25/01/2015	Inspect and recharge accumulators	Cristian Santos noted: Repair completed.	cristian_santos
A29	30/06/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A86	26/04/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A33	21/03/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A37	04/04/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A75	29/05/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A42	04/08/2015	Accumulator inspection and charging required	Michele Williams noted: No additional information provided.	michele_williams
A91	10/03/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A10	26/09/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A8	09/09/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A26	07/11/2015	Milling spindle requires repair	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A68	20/04/2015	Inspect and recharge accumulators	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A40	24/03/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Detail not recorded.	michele_williams
A87	19/08/2015	Leaks found at turrets A and B	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A29	15/06/2015	Hydraulic line leak on side B	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A6	06/02/2015	Turret A and B are leaking	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A57	28/05/2015	Repair work needed on milling spindle	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A4	13/07/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: No further details.	cristian_santos
A12	14/05/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A24	31/01/2015	Accumulator inspection and charging required	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A68	20/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A58	13/11/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A61	19/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A80	26/12/2015	Turret sections A & B showing leaks	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A55	25/09/2015	Hydraulic line leak on side B	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A88	15/10/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A91	05/11/2015	Power supply failure detected	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A40	18/05/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A95	16/01/2015	Machine is unpowered	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A69	17/06/2015	Turret sections A & B showing leaks	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A74	25/10/2015	Leak in side B hydraulic line	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A86	14/01/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Maintenance action successful.	cristian_santos
A27	05/01/2016	Maintenance on milling spindle needed	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A7	16/06/2015	Machine is unpowered	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A76	07/10/2015	Inspect and recharge accumulators	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A64	15/09/2015	Maintenance on milling spindle needed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A21	29/06/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A78	22/04/2015	Milling spindle requires repair	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A55	31/07/2015	Inspect and recharge accumulators	Michele Williams noted: No additional information provided.	michele_williams
A8	16/10/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A82	18/12/2015	Accumulators need checking and charging	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A82	05/03/2015	Leaks found at turrets A and B	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A20	18/08/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A37	02/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A15	28/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A9	22/05/2015	Machine is unpowered	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A92	08/03/2015	Unit lost electrical power	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A8	23/08/2015	Hydraulic line leak on side B	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A7	05/09/2015	Turret A and B are leaking	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams

A63	14/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A59	21/04/2015	Accumulators need checking and charging	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A19	22/12/2015	Machine is unpowered	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A10	11/01/2016	Saw attachment is leaking hydraulics	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A69	13/08/2015	Repair work needed on milling spindle	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A24	20/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A70	25/07/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A61	16/03/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Maintenance action successful.	michele_williams
A61	31/03/2015	Repair work needed on milling spindle	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A50	31/05/2015	Hydraulic line leak on side B	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A1	26/09/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A36	31/08/2015	Machine is unpowered	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A58	07/10/2015	Hydraulic line leak on side B	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A54	15/11/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A68	28/06/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: No additional information provided.	michele_williams
A63	23/11/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A8	08/12/2015	Turret sections A & B showing leaks	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A74	19/04/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A4	26/01/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A43	13/08/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A56	01/04/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A6	02/10/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A4	07/03/2015	Accumulator inspection and charging required	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A88	07/11/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A77	08/09/2015	Accumulator inspection and charging required	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A78	24/04/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A51	12/03/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A54	15/10/2015	Unit lost electrical power	Cristian Santos noted: Maintenance action successful.	cristian_santos
A80	27/07/2015	Machine is unpowered	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A15	02/07/2015	Turret A and B are leaking	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A73	05/04/2015	Spindle indexing error with overfeed	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A32	11/04/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A28	18/07/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A91	12/04/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A19	30/09/2015	Repair work needed on milling spindle	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A38	06/03/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A19	22/08/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A58	25/01/2015	Inspect and recharge accumulators	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A1	19/07/2015	Accumulator inspection and charging required	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A94	12/05/2015	Turret sections A & B showing leaks	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A73	24/07/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A61	16/08/2015	Saw attachment is leaking hydraulics	Michele Williams noted: System checked and accumulators charged.	michele_williams
A11	11/08/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A65	11/01/2016	Accumulator inspection and charging required	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A1	06/06/2015	Power supply failure detected	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A17	11/11/2015	Maintenance on milling spindle needed	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A60	26/04/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A42	23/11/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A38	18/05/2015	Machine is unpowered	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A49	11/12/2015	Spindle indexing error with overfeed	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A88	21/10/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A90	13/08/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Fixed and tested.	cristian_santos
A19	31/03/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A51	19/04/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A1	04/05/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A67	30/12/2015	Hydraulic line leak on side B	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A21	10/05/2015	Accumulators need checking and charging	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A40	25/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A36	07/08/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A28	19/02/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A10	08/12/2015	Accumulator inspection and charging required	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A36	05/08/2015	Accumulators need checking and charging	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A59	15/10/2015	Milling spindle requires repair	Cristian Santos noted: Detail not recorded.	cristian_santos
A14	28/11/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A86	29/05/2015	Maintenance on milling spindle needed	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A1	21/04/2015	Repair work needed on milling spindle	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A57	17/07/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A86	18/01/2015	Accumulators need checking and charging	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A68	01/10/2015	Inspect and recharge accumulators	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A25	26/12/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams

A49	22/03/2015	Milling spindle requires repair	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A5	04/07/2015	Power supply failure detected	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A15	14/09/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A13	05/02/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A28	17/07/2015	Maintenance on milling spindle needed	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A95	26/10/2015	Accumulator inspection and charging required	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A43	13/04/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A5	13/03/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A86	08/08/2015	Leaks found at turrets A and B	Michele Williams noted: Detail not recorded.	michele_williams
A57	30/01/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A30	01/04/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A54	31/01/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A57	15/09/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A94	01/12/2015	Spindle indexing error with overfeed	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A57	02/09/2015	Spindle fails to index, overfeeding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A56	08/12/2015	Milling spindle requires repair	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A34	20/07/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A31	16/01/2015	Leaks found at turrets A and B	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A98	26/07/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A27	27/12/2015	Turret sections A & B showing leaks	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A86	09/06/2015	Accumulator inspection and charging required	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A22	15/02/2015	Accumulator inspection and charging required	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A8	17/10/2015	Power supply failure detected	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A25	30/04/2015	Milling spindle requires repair	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A31	12/10/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A58	17/06/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A38	07/12/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A94	09/04/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A45	30/11/2015	Accumulator inspection and charging required	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A25	17/10/2015	Milling spindle requires repair	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A65	16/08/2015	Hydraulic line leak on side B	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A41	30/03/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A25	05/04/2015	Accumulators need checking and charging	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A39	15/08/2015	Accumulator inspection and charging required	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A85	12/05/2015	Turret A and B are leaking	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A73	26/03/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A47	16/03/2015	Leaks found at turrets A and B	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A76	23/08/2015	Unit lost electrical power	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A14	20/12/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A33	13/12/2015	Inspect and recharge accumulators	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A95	14/07/2015	Repair work needed on milling spindle	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A60	08/10/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A28	20/08/2015	Repair work needed on milling spindle	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A61	20/09/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A45	02/07/2015	Turret sections A & B showing leaks	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A75	05/09/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A72	29/10/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A48	01/04/2015	Unit lost electrical power	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A61	29/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A86	24/04/2015	Milling spindle requires repair	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A82	30/09/2015	Spindle indexing error with overfeed	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A49	11/01/2016	Grinding noise from tight gears on saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A31	10/06/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A41	22/12/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A52	20/01/2015	Turret A and B are leaking	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A32	27/01/2015	Accumulators need checking and charging	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A34	23/08/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Repair completed.	michele_williams
A55	31/01/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A18	19/07/2015	Repair work needed on milling spindle	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A44	08/06/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A61	19/11/2015	Spindle indexing error with overfeed	Michele Williams noted: No further details.	michele_williams
A29	06/10/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A40	08/06/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A55	01/05/2015	Milling spindle requires repair	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A13	31/10/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A47	11/11/2015	Milling spindle requires repair	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A89	17/10/2015	Spindle fails to index, overfeeding	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A37	01/09/2015	Spindle indexing error with overfeed	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A54	07/09/2015	Accumulators need checking and charging	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A51	11/09/2015	Repair work needed on milling spindle	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos

A8	29/04/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A58	04/06/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A81	12/02/2015	Leak in side B hydraulic line	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A20	03/07/2015	Repair work needed on milling spindle	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A49	16/05/2015	Accumulator inspection and charging required	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A61	07/03/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A94	15/12/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A7	11/02/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Detail not recorded.	cristian_santos
A69	09/11/2015	Machine is unpowered	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A77	09/03/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A7	10/12/2015	Power supply failure detected	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A46	02/03/2015	Inspect and recharge accumulators	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A38	21/10/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Detail not recorded.	cristian_santos
A64	24/11/2015	Power supply failure detected	Michele Williams noted: No additional information provided.	michele_williams
A78	28/07/2015	Unit lost electrical power	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A55	21/05/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A31	05/11/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A5	02/11/2015	Machine is unpowered	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A51	20/11/2015	Accumulator inspection and charging required	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A55	05/10/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A70	23/05/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A38	01/05/2015	Maintenance on milling spindle needed	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A40	18/10/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A52	02/12/2015	Milling spindle requires repair	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A28	04/03/2015	Turret sections A & B showing leaks	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A21	09/05/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A13	18/11/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A92	11/08/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A43	12/11/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A56	30/04/2015	Accumulator inspection and charging required	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A58	23/03/2015	Unit lost electrical power	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A8	21/11/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A11	11/10/2015	Unit lost electrical power	Gina Moore noted: No further details.	gina_moore, dylan_miller
A88	20/10/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A92	11/04/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A56	31/10/2015	Leaks found at turrets A and B	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A3	04/10/2015	Repair work needed on milling spindle	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A67	11/12/2015	Accumulator inspection and charging required	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A40	10/04/2015	Unit lost electrical power	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A33	20/08/2015	Maintenance on milling spindle needed	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A61	07/01/2016	Accumulator inspection and charging required	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A97	20/08/2015	Maintenance on milling spindle needed	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A19	07/05/2015	Leak in side B hydraulic line	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A95	05/09/2015	Hydraulic line leak on side B	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A12	26/03/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A28	03/04/2015	Unit lost electrical power	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A41	28/09/2015	Unit lost electrical power	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A81	18/06/2015	Turret sections A & B showing leaks	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A94	08/08/2015	Milling spindle requires repair	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A74	12/06/2015	Machine is unpowered	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A71	03/10/2015	Machine is unpowered	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A56	04/08/2015	Inspect and recharge accumulators	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A19	15/07/2015	Leaks found at turrets A and B	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A72	20/09/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A44	03/02/2015	Turret A and B are leaking	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A19	06/03/2015	Inspect and recharge accumulators	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A75	09/02/2015	Hydraulic line leak on side B	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A28	11/01/2016	Maintenance on milling spindle needed	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A76	15/05/2015	Power supply failure detected	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A1	06/08/2015	Unit lost electrical power	Michele Williams noted: No additional information provided.	michele_williams
A58	18/03/2015	Spindle indexing error with overfeed	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A79	15/11/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A29	12/01/2016	Accumulator inspection and charging required	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A70	17/11/2015	Hydraulic line leak on side B	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A64	21/12/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A77	17/12/2015	Unit lost electrical power	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A46	05/07/2015	Accumulators need checking and charging	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A34	11/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A85	07/02/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A24	27/01/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams

A53	17/10/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A15	22/01/2015	Turret sections A & B showing leaks	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A13	30/06/2015	Unit lost electrical power	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A72	29/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A48	01/08/2015	Accumulators need checking and charging	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A43	29/07/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A95	17/11/2015	Maintenance on milling spindle needed	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A27	16/04/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A88	03/09/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A96	29/07/2015	Turret A and B are leaking	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A61	24/05/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A49	16/07/2015	Machine is unpowered	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A44	02/05/2015	Leak in side B hydraulic line	Michele Williams noted: No further details.	michele_williams
A69	30/11/2015	Maintenance on milling spindle needed	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A58	07/10/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A11	21/05/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A69	06/08/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A22	18/11/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A60	22/04/2015	Turret sections A & B showing leaks	Michele Williams noted: Repair completed.	michele_williams
A20	18/10/2015	Turret A and B are leaking	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A1	07/01/2016	Inspect and recharge accumulators	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A99	17/04/2015	Accumulators need checking and charging	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A85	05/12/2015	Maintenance on milling spindle needed	Michele Williams noted: No additional information provided.	michele_williams
A19	24/06/2015	Milling spindle requires repair	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A90	12/02/2015	Unit lost electrical power	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A53	02/07/2015	Leak in side B hydraulic line	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A23	24/03/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A32	11/12/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A53	19/08/2015	Turret A and B are leaking	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A89	11/10/2015	Repair work needed on milling spindle	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A97	21/02/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A85	27/06/2015	Leak in side B hydraulic line	Cristian Santos noted: Fixed and tested.	cristian_santos
A78	16/03/2015	Turret A and B are leaking	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A74	18/01/2015	Inspect and recharge accumulators	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A75	19/10/2015	Unit lost electrical power	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A80	27/09/2015	Accumulators need checking and charging	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A13	18/10/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A20	24/10/2015	Spindle indexing error with overfeed	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A64	27/04/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A45	09/06/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A87	30/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A97	29/03/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A1	15/01/2015	Inspect and recharge accumulators	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A41	02/05/2015	Repair work needed on milling spindle	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A59	24/10/2015	Turret sections A & B showing leaks	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A67	14/08/2015	Machine is unpowered	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A86	29/01/2015	Repair work needed on milling spindle	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A72	16/11/2015	Leaks found at turrets A and B	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A58	04/11/2015	Leak in side B hydraulic line	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A13	16/05/2015	Milling spindle requires repair	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A43	05/09/2015	Machine is unpowered	Michele Williams noted: Maintenance action successful.	michele_williams
A86	06/04/2015	Maintenance on milling spindle needed	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A38	21/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A22	16/03/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A15	09/01/2016	Turret A and B are leaking	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A65	13/04/2015	Leaks found at turrets A and B	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A68	15/07/2015	Power supply failure detected	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A28	06/08/2015	Milling spindle requires repair	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A36	01/11/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A83	09/10/2015	Machine is unpowered	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A11	04/02/2015	Unit lost electrical power	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A94	13/04/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A44	11/02/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A58	13/09/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A67	10/03/2015	Turret A and B are leaking	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A36	13/05/2015	Unit lost electrical power	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A56	12/05/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A19	27/03/2015	Accumulator inspection and charging required	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A97	22/11/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A32	14/04/2015	Maintenance on milling spindle needed	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller

A66	14/02/2015	Machine is unpowered	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A9	14/09/2015	Unit lost electrical power	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A52	19/06/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A96	02/12/2015	Accumulator inspection and charging required	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A20	19/07/2015	Spindle indexing error with overfeed	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A20	01/09/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Repair completed.	michele_williams
A33	11/01/2016	Turret A and B are leaking	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A29	03/04/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A51	05/02/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A56	11/12/2015	Hydraulic line leak on side B	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A95	21/01/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A16	09/10/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A5	09/04/2015	Accumulators need checking and charging	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A13	06/02/2015	Power supply failure detected	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A46	07/07/2015	Machine is unpowered	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A24	07/01/2016	Grinding noise from tight gears on saw attachment	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A86	25/12/2015	Spindle indexing error with overfeed	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A38	12/08/2015	Hydraulic line leak on side B	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A97	23/07/2015	Unit lost electrical power	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A14	05/04/2015	Power supply failure detected	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A33	29/11/2015	Power supply failure detected	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A13	18/11/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A71	09/07/2015	Power supply failure detected	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A8	13/05/2015	Maintenance on milling spindle needed	Michele Williams noted: No further details.	michele_williams
A53	22/01/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A76	02/11/2015	Turret A and B are leaking	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A78	05/04/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A42	30/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A17	22/01/2015	Maintenance on milling spindle needed	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A11	21/03/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A86	12/02/2015	Turret A and B are leaking	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A50	17/07/2015	Turret sections A & B showing leaks	Michele Williams noted: Detail not recorded.	michele_williams
A75	01/02/2015	Spindle fails to index, overfeeding	Michele Williams noted: No further details.	michele_williams
A73	19/03/2015	Accumulators need checking and charging	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A30	16/04/2015	Accumulators need checking and charging	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A79	25/08/2015	Turret A and B are leaking	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A33	07/06/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A61	07/09/2015	Milling spindle requires repair	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A20	08/02/2015	Accumulators need checking and charging	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A91	22/08/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A73	27/06/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A63	07/07/2015	Unit lost electrical power	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A68	05/05/2015	Hydraulic line leak on side B	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A36	19/12/2015	Leaks found at turrets A and B	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A61	23/11/2015	Hydraulic line leak on side B	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A78	19/09/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A42	01/08/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A71	20/12/2015	Power supply failure detected	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A52	07/04/2015	Leaks found at turrets A and B	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A39	15/05/2015	Spindle indexing error with overfeed	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A31	10/08/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A53	04/08/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A16	22/08/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A98	23/06/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A41	15/07/2015	Repair work needed on milling spindle	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A22	23/11/2015	Turret sections A & B showing leaks	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A39	18/12/2015	Turret sections A & B showing leaks	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A86	19/12/2015	Turret sections A & B showing leaks	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A83	15/06/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A43	16/04/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A76	30/07/2015	Turret sections A & B showing leaks	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A74	27/06/2015	Turret A and B are leaking	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A6	04/09/2015	Hydraulic line leak on side B	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A39	25/04/2015	Power supply failure detected	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A51	25/06/2015	Inspect and recharge accumulators	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A83	30/07/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A53	20/09/2015	Accumulators need checking and charging	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A27	08/10/2015	Maintenance on milling spindle needed	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A92	27/03/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A34	27/08/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams

A82	10/07/2015	Leak in side B hydraulic line	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A36	20/02/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A90	06/05/2015	Accumulators need checking and charging	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A44	14/04/2015	Milling spindle requires repair	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A97	13/12/2015	Spindle indexing error with overfeed	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A1	05/12/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A85	11/02/2015	Power supply failure detected	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A77	26/04/2015	Inspect and recharge accumulators	Michele Williams noted: Repair completed.	michele_williams
A15	19/05/2015	Milling spindle requires repair	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A3	14/08/2015	Spindle indexing error with overfeed	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A43	20/01/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A77	08/05/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A97	14/02/2015	Turret sections A & B showing leaks	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A11	24/09/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A98	25/03/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A7	09/04/2015	Repair work needed on milling spindle	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A75	18/09/2015	Turret A and B are leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A30	22/09/2015	Maintenance on milling spindle needed	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A90	28/06/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A84	14/09/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A95	14/10/2015	Leaks found at turrets A and B	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A9	02/12/2015	Repair work needed on milling spindle	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A32	07/04/2015	Accumulator inspection and charging required	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A89	05/02/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A34	04/07/2015	Machine is unpowered	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A72	02/08/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A83	05/12/2015	Unit lost electrical power	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A7	05/05/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A14	01/12/2015	Leak in side B hydraulic line	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A71	21/05/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Detail not recorded.	cristian_santos
A9	01/07/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A32	14/03/2015	Hydraulic line leak on side B	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A11	04/12/2015	Hydraulic line leak on side B	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A92	18/06/2015	Hydraulic line leak on side B	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A44	09/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A64	09/05/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A46	30/12/2015	Inspect and recharge accumulators	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A42	04/05/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A75	07/05/2015	Machine is unpowered	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A87	02/10/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A3	13/09/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A87	25/01/2015	Unit lost electrical power	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A75	24/09/2015	Accumulators need checking and charging	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A54	28/07/2015	Milling spindle requires repair	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A50	06/04/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A71	02/07/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A68	06/01/2016	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A49	22/09/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A87	02/09/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: No further details.	cristian_santos
A14	31/12/2015	Hydraulic line leak on side B	Cristian Santos noted: Detail not recorded.	cristian_santos
A93	23/11/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A20	25/04/2015	Turret sections A & B showing leaks	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A57	04/04/2015	Milling spindle requires repair	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A61	08/06/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A69	29/09/2015	Milling spindle requires repair	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A79	29/03/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A68	15/01/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A25	18/11/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A15	08/02/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A48	26/05/2015	Turret sections A & B showing leaks	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A57	18/12/2015	Leak in side B hydraulic line	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A16	02/11/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A95	21/09/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A2	11/08/2015	Accumulator inspection and charging required	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A20	16/08/2015	Hydraulic line leak on side B	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A41	24/02/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A68	02/11/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A21	11/12/2015	Unit lost electrical power	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A65	11/07/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A67	01/05/2015	Turret sections A & B showing leaks	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos

A71	16/03/2015	Turret A and B are leaking	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A38	05/02/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: No further details.	nathan_maldonado
A50	10/06/2015	Machine is unpowered	Nathan Maldonado noted: No further details.	nathan_maldonado
A68	30/03/2015	Leaks found at turrets A and B	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A81	19/02/2015	Power supply failure detected	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A62	19/03/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A46	22/08/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A97	02/08/2015	Inspect and recharge accumulators	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A61	28/10/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A13	10/01/2016	Hydraulic line leak on side B	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A41	04/11/2015	Spindle indexing error with overfeed	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A23	15/06/2015	Accumulator inspection and charging required	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A69	23/12/2015	Inspect and recharge accumulators	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A21	26/12/2015	Accumulator inspection and charging required	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A62	01/11/2015	Spindle indexing error with overfeed	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A42	27/11/2015	Repair work needed on milling spindle	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A58	27/01/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A52	25/02/2015	Power supply failure detected	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A67	08/06/2015	Machine is unpowered	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A22	31/10/2015	Turret sections A & B showing leaks	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A21	25/02/2015	Machine is unpowered	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A63	23/08/2015	Inspect and recharge accumulators	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A71	26/04/2015	Accumulators need checking and charging	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A82	06/02/2015	Leaks found at turrets A and B	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A18	24/04/2015	Accumulator inspection and charging required	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A38	06/09/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A18	21/11/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A95	12/04/2015	Leak in side B hydraulic line	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A21	19/07/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A45	19/02/2015	Turret A and B are leaking	Gina Moore noted: No further details.	gina_moore, dylan_miller
A48	18/04/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A17	26/04/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A96	16/04/2015	Turret A and B are leaking	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A80	08/11/2015	Leak in side B hydraulic line	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A88	04/07/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A26	04/03/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A6	02/02/2015	Hydraulic line leak on side B	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A29	05/02/2015	Hydraulic line leak on side B	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A42	31/05/2015	Accumulator inspection and charging required	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A88	11/07/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Fixed and tested.	michele_williams
A29	23/08/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A71	01/05/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A27	26/05/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: No further details.	nathan_maldonado
A33	25/03/2015	Leaks found at turrets A and B	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A37	04/11/2015	Turret A and B are leaking	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A82	06/07/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A86	05/04/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A36	15/12/2015	Machine is unpowered	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A19	06/02/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A78	23/10/2015	Turret sections A & B showing leaks	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A53	11/11/2015	Accumulator inspection and charging required	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A58	22/05/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A13	04/03/2015	Accumulators need checking and charging	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A6	02/07/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A76	31/10/2015	Turret A and B are leaking	Michele Williams noted: Maintenance action successful.	michele_williams
A81	03/11/2015	Turret sections A & B showing leaks	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A76	07/03/2015	Spindle indexing error with overfeed	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A68	04/06/2015	Turret sections A & B showing leaks	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A23	31/12/2015	Hydraulic line leak on side B	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A37	16/08/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A10	19/05/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A9	29/09/2015	Repair work needed on milling spindle	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A63	10/04/2015	Maintenance on milling spindle needed	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A62	12/07/2015	Hydraulic line leak on side B	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A47	10/01/2016	Turret A and B are leaking	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A59	05/11/2015	Hydraulic line leak on side B	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A22	08/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A53	24/04/2015	Accumulator inspection and charging required	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A2	15/10/2015	Inspect and recharge accumulators	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A40	16/09/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams

A79	14/01/2015	Machine is unpowered	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A80	21/11/2015	Spindle fails to index, overfeeding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A23	01/12/2015	Leaks found at turrets A and B	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A61	15/01/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A94	04/06/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A96	02/03/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A34	05/07/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A25	28/11/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A63	26/06/2015	Accumulators need checking and charging	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A55	24/07/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A23	17/09/2015	Maintenance on milling spindle needed	Michele Williams noted: System checked and accumulators charged.	michele_williams
A62	30/05/2015	Unit lost electrical power	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A62	26/09/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A44	09/03/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A14	07/12/2015	Power supply failure detected	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A51	14/03/2015	Spindle indexing error with overfeed	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A47	05/12/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A26	30/01/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Fixed and tested.	michele_williams
A77	15/02/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A41	21/06/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A57	19/04/2015	Maintenance on milling spindle needed	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A73	12/10/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A51	23/02/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A28	26/02/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A52	20/11/2015	Repair work needed on milling spindle	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A71	23/03/2015	Machine is unpowered	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A67	12/01/2016	Machine is unpowered	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A83	27/06/2015	Accumulator inspection and charging required	Cristian Santos noted: Repair completed.	cristian_santos
A47	08/05/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A36	03/12/2015	Turret A and B are leaking	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A56	30/11/2015	Turret A and B are leaking	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A92	05/11/2015	Accumulators need checking and charging	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A80	02/05/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A31	09/10/2015	Machine is unpowered	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A40	01/01/2016	Repair work needed on milling spindle	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A63	15/04/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Fixed and tested.	cristian_santos
A56	18/03/2015	Unit lost electrical power	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A23	12/01/2016	Hydraulic fluid leak at saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A32	10/12/2015	Saw attachment is leaking hydraulics	Michele Williams noted: System checked and accumulators charged.	michele_williams
A88	13/07/2015	Milling spindle requires repair	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A59	21/09/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: No additional information provided.	cristian_santos
A27	24/08/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A94	26/02/2015	Milling spindle requires repair	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A76	21/07/2015	Leaks found at turrets A and B	Michele Williams noted: Fixed and tested.	michele_williams
A58	09/11/2015	Turret A and B are leaking	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A55	18/02/2015	Unit lost electrical power	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A58	24/12/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A42	05/05/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A5	11/10/2015	Turret A and B are leaking	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A18	12/10/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A62	05/11/2015	Accumulator inspection and charging required	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A41	10/10/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A38	18/06/2015	Machine is unpowered	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A20	28/03/2015	Accumulators need checking and charging	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A76	18/02/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A13	02/02/2015	Machine is unpowered	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A35	30/08/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A65	28/10/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A35	23/07/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A37	12/10/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A46	20/07/2015	Milling spindle requires repair	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A26	24/03/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A60	04/12/2015	Turret A and B are leaking	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A39	25/04/2015	Leaks found at turrets A and B	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A72	14/01/2015	Milling spindle requires repair	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A74	28/10/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A57	11/01/2016	Repair work needed on milling spindle	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A53	15/07/2015	Spindle fails to index, overfeeding	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A64	24/02/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A44	15/07/2015	Turret A and B are leaking	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller

A69	27/11/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A96	07/05/2015	Unit lost electrical power	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A32	21/09/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A83	17/03/2015	Spindle fails to index, overfeeding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A25	05/03/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A42	02/11/2015	Milling spindle requires repair	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A53	12/03/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A72	03/01/2016	Unit lost electrical power	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A46	04/06/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A29	23/04/2015	Unit lost electrical power	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A22	03/07/2015	Leaks found at turrets A and B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A60	24/03/2015	Hydraulic line leak on side B	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A19	26/02/2015	Maintenance on milling spindle needed	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A5	25/04/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A42	06/11/2015	Leak in side B hydraulic line	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A60	13/03/2015	Repair work needed on milling spindle	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A76	13/10/2015	Turret sections A & B showing leaks	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A76	30/06/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A11	25/07/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A60	25/12/2015	Unit lost electrical power	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A35	25/10/2015	Leaks found at turrets A and B	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A40	25/01/2015	Accumulator inspection and charging required	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A24	19/10/2015	Machine is unpowered	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A91	18/06/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A54	07/09/2015	Leak in side B hydraulic line	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A62	02/05/2015	Turret A and B are leaking	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A34	22/01/2015	Accumulator inspection and charging required	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A13	06/11/2015	Power supply failure detected	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A4	16/12/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A39	22/12/2015	Turret A and B are leaking	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A5	20/06/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A55	28/06/2015	Unit lost electrical power	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A48	06/09/2015	Turret sections A & B showing leaks	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A6	18/04/2015	Turret sections A & B showing leaks	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A36	23/05/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A43	12/05/2015	Power supply failure detected	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A13	18/06/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A79	01/12/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A82	01/12/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A35	11/04/2015	Milling spindle requires repair	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A25	21/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A96	11/10/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A2	14/03/2015	Machine is unpowered	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A98	02/05/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A81	15/07/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A37	13/04/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A17	22/06/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A25	24/06/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A64	11/01/2016	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A59	05/02/2015	Repair work needed on milling spindle	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A67	16/08/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A8	12/06/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A22	17/11/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A61	29/05/2015	Turret A and B are leaking	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A94	14/06/2015	Turret A and B are leaking	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A18	01/01/2016	Turret sections A & B showing leaks	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A26	02/01/2016	Maintenance on milling spindle needed	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A30	18/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A16	21/02/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A65	27/11/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A5	12/10/2015	Accumulators need checking and charging	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A20	03/07/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A70	12/08/2015	Leak in side B hydraulic line	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A79	30/07/2015	Spindle indexing error with overfeed	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A3	14/06/2015	Repair work needed on milling spindle	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A42	14/05/2015	Inspect and recharge accumulators	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A49	22/06/2015	Maintenance on milling spindle needed	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A8	21/01/2015	Turret A and B are leaking	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A17	22/01/2015	Leak in side B hydraulic line	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A89	05/10/2015	Power supply failure detected	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado

A76	02/02/2015	Unit lost electrical power	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A85	10/07/2015	Accumulator inspection and charging required	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A50	02/08/2015	Milling spindle requires repair	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A90	22/01/2015	Hydraulic line leak on side B	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A11	26/08/2015	Turret A and B are leaking	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A72	28/10/2015	Repair work needed on milling spindle	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A40	09/05/2015	Inspect and recharge accumulators	Michele Williams noted: No further details.	michele_williams
A58	26/05/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A21	18/01/2015	Repair work needed on milling spindle	Cristian Santos noted: Maintenance action successful.	cristian_santos
A90	24/07/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A4	10/09/2015	Accumulator inspection and charging required	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A74	18/08/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A44	03/04/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A5	16/02/2015	Accumulators need checking and charging	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A55	25/12/2015	Milling spindle requires repair	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A47	20/11/2015	Accumulators need checking and charging	Cristian Santos noted: Fixed and tested.	cristian_santos
A76	26/11/2015	Leak in side B hydraulic line	Michele Williams noted: Repair completed.	michele_williams
A1	25/12/2015	Turret sections A & B showing leaks	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A55	04/06/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A21	15/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A86	19/11/2015	Unit lost electrical power	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A41	02/06/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A11	16/02/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A76	06/08/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A30	02/01/2016	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A15	16/05/2015	Turret A and B are leaking	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A78	09/07/2015	Unit lost electrical power	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A91	20/11/2015	Machine is unpowered	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A96	13/02/2015	Accumulator inspection and charging required	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A26	13/05/2015	Repair work needed on milling spindle	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A54	24/11/2015	Maintenance on milling spindle needed	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A58	12/08/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A35	14/11/2015	Unit lost electrical power	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A79	24/10/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Repair completed.	cristian_santos
A62	11/01/2016	Machine is unpowered	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A86	25/04/2015	Machine is unpowered	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A64	21/02/2015	Turret A and B are leaking	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A29	13/09/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A49	14/05/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A66	16/02/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A47	06/01/2016	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A27	15/11/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A8	28/08/2015	Leaks found at turrets A and B	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A5	25/03/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A14	17/02/2015	Milling spindle requires repair	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A48	24/04/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A26	10/07/2015	Unit lost electrical power	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A72	11/11/2015	Unit lost electrical power	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A17	13/09/2015	Accumulators need checking and charging	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A54	08/01/2016	Power supply failure detected	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A9	28/11/2015	Turret sections A & B showing leaks	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A31	06/10/2015	Unit lost electrical power	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A49	26/10/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A1	21/10/2015	Leak in side B hydraulic line	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A85	12/05/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A74	31/08/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A22	31/10/2015	Milling spindle requires repair	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A33	01/02/2015	Accumulators need checking and charging	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A92	11/06/2015	Milling spindle requires repair	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A84	03/10/2015	Unit lost electrical power	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A2	20/07/2015	Power supply failure detected	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A32	28/01/2015	Hydraulic line leak on side B	Michele Williams noted: Fixed and tested.	michele_williams
A95	16/10/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A22	12/03/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A85	28/12/2015	Turret A and B are leaking	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A67	12/03/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A15	28/10/2015	Milling spindle requires repair	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A43	01/03/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A92	02/11/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A72	18/11/2015	Unit lost electrical power	Nathan Maldonado noted: No additional information provided.	nathan_maldonado

A20	05/11/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A96	16/10/2015	Hydraulic line leak on side B	Michele Williams noted: Detail not recorded.	michele_williams
A20	10/05/2015	Unit lost electrical power	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A16	31/03/2015	Milling spindle requires repair	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A95	23/03/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A81	23/08/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A33	06/02/2015	Unit lost electrical power	Cristian Santos noted: Fixed and tested.	cristian_santos
A24	21/05/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A60	01/06/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A4	01/04/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A70	08/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Detail not recorded.	cristian_santos
A10	15/01/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A70	21/09/2015	Leaks found at turrets A and B	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A50	15/04/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A59	12/05/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A94	08/03/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A36	01/07/2015	Hydraulic line leak on side B	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A40	03/12/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A57	23/01/2015	Power supply failure detected	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A69	21/03/2015	Unit lost electrical power	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A90	11/06/2015	Accumulator inspection and charging required	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A69	20/12/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A74	16/11/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A61	15/02/2015	Repair work needed on milling spindle	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A64	23/11/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A30	20/01/2015	Spindle indexing error with overfeed	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A26	12/05/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Maintenance action successful.	michele_williams
A83	19/11/2015	Accumulator inspection and charging required	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A40	10/03/2015	Turret sections A & B showing leaks	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A23	17/05/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A58	14/10/2015	Turret A and B are leaking	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A66	14/01/2015	Spindle fails to index, overfeeding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A61	28/10/2015	Unit lost electrical power	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A13	18/10/2015	Accumulators need checking and charging	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A9	28/03/2015	Machine is unpowered	Cristian Santos noted: Maintenance action successful.	cristian_santos
A53	23/12/2015	Accumulators need checking and charging	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A99	20/01/2015	Spindle fails to index, overfeeding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A26	18/02/2015	Machine is unpowered	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A14	19/03/2015	Machine is unpowered	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A4	25/07/2015	Unit lost electrical power	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A4	18/11/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A30	30/10/2015	Hydraulic line leak on side B	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A85	06/10/2015	Machine is unpowered	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A91	26/06/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A25	20/09/2015	Repair work needed on milling spindle	Gina Moore noted: No further details.	gina_moore, dylan_miller
A83	04/03/2015	Unit lost electrical power	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A49	16/08/2015	Hydraulic line leak on side B	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A11	25/10/2015	Spindle indexing error with overfeed	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A10	24/07/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A9	21/11/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A44	27/09/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A6	14/10/2015	Spindle indexing error with overfeed	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A40	26/04/2015	Hydraulic line leak on side B	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A78	10/10/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A77	03/03/2015	Milling spindle requires repair	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A29	24/02/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A80	22/12/2015	Accumulators need checking and charging	Michele Williams noted: Repair completed.	michele_williams
A27	17/09/2015	Turret sections A & B showing leaks	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A43	22/04/2015	Inspect and recharge accumulators	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A62	01/12/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A90	16/06/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A16	02/09/2015	Machine is unpowered	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A42	09/01/2016	Milling spindle requires repair	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A12	04/05/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A84	10/08/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A13	10/12/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A71	10/01/2016	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A65	09/12/2015	Maintenance on milling spindle needed	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A44	01/12/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A90	21/11/2015	Spindle indexing error with overfeed	Michele Williams noted: System checked and accumulators charged.	michele_williams

A3	30/04/2015	Spindle indexing error with overfeed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A24	21/03/2015	Milling spindle requires repair	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A56	10/07/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A88	20/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A66	14/03/2015	Maintenance on milling spindle needed	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A73	27/11/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Maintenance action successful.	michele_williams
A51	12/05/2015	Spindle fails to index, overfeeding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A24	18/10/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A38	27/11/2015	Leaks found at turrets A and B	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A33	17/07/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A9	01/06/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A48	21/03/2015	Milling spindle requires repair	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A52	31/10/2015	Hydraulic line leak on side B	Cristian Santos noted: Repair completed.	cristian_santos
A8	29/03/2015	Hydraulic line leak on side B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A87	08/08/2015	Power supply failure detected	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A9	25/04/2015	Spindle fails to index, overfeeding	Cristian Santos noted: No further details.	cristian_santos
A57	17/10/2015	Accumulators need checking and charging	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A6	04/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A7	28/07/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A54	14/05/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A12	26/05/2015	Machine is unpowered	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A22	23/05/2015	Repair work needed on milling spindle	Michele Williams noted: No additional information provided.	michele_williams
A57	18/10/2015	Milling spindle requires repair	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A11	21/04/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A17	09/10/2015	Turret A and B are leaking	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A31	15/06/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Maintenance action successful.	cristian_santos
A63	17/09/2015	Hydraulic line leak on side B	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A9	26/09/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A36	11/04/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: No additional information provided.	cristian_santos
A22	01/10/2015	Power supply failure detected	Cristian Santos noted: No further details.	cristian_santos
A7	03/06/2015	Leaks found at turrets A and B	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A23	05/12/2015	Milling spindle requires repair	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A10	10/06/2015	Accumulators need checking and charging	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A15	17/06/2015	Inspect and recharge accumulators	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A20	25/02/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A23	07/11/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A33	08/04/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A67	25/10/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A16	05/03/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A27	24/04/2015	Machine is unpowered	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A82	03/10/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A13	26/12/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A86	09/09/2015	Milling spindle requires repair	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A97	02/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A13	21/07/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A78	27/04/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A74	22/08/2015	Turret A and B are leaking	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A55	21/07/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A54	15/05/2015	Milling spindle requires repair	Michele Williams noted: Detail not recorded.	michele_williams
A78	05/04/2015	Accumulators need checking and charging	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A73	05/05/2015	Machine is unpowered	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A92	11/09/2015	Turret A and B are leaking	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A46	02/05/2015	Spindle fails to index, overfeeding	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A74	03/07/2015	Maintenance on milling spindle needed	Cristian Santos noted: No further details.	cristian_santos
A47	01/03/2015	Inspect and recharge accumulators	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A82	14/01/2015	Milling spindle requires repair	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A12	20/06/2015	Inspect and recharge accumulators	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A2	21/10/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A61	12/11/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A81	03/01/2016	Spindle indexing error with overfeed	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A41	31/01/2015	Hydraulic line leak on side B	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A41	11/02/2015	Leak in side B hydraulic line	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A94	19/06/2015	Unit lost electrical power	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A62	26/05/2015	Unit lost electrical power	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A96	17/09/2015	Unit lost electrical power	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A74	27/10/2015	Spindle indexing error with overfeed	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A92	10/07/2015	Unit lost electrical power	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A93	06/09/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A88	10/12/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A92	19/08/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams

A18	29/11/2015	Turret sections A & B showing leaks	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A11	08/07/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Fixed and tested.	cristian_santos
A55	30/12/2015	Inspect and recharge accumulators	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A45	24/07/2015	Milling spindle requires repair	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A70	31/12/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A55	24/04/2015	Leaks found at turrets A and B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A63	15/08/2015	Leaks found at turrets A and B	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A69	09/11/2015	Hydraulic line leak on side B	Michele Williams noted: Detail not recorded.	michele_williams
A21	09/10/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A65	07/01/2016	Indexing issue causing overfeed on spindle	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A83	02/02/2015	Milling spindle requires repair	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A61	17/08/2015	Accumulator inspection and charging required	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A23	13/04/2015	Repair work needed on milling spindle	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A57	03/05/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A87	24/11/2015	Hydraulic line leak on side B	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A58	24/11/2015	Saw attachment gears are binding and grinding	Michele Williams noted: No additional information provided.	michele_williams
A18	09/02/2015	Leak in side B hydraulic line	Cristian Santos noted: Repair completed.	cristian_santos
A65	08/06/2015	Unit lost electrical power	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A42	12/01/2016	Saw attachment gears are binding and grinding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A80	21/07/2015	Power supply failure detected	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A43	13/10/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A98	02/06/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A26	14/09/2015	Leaks found at turrets A and B	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A30	16/10/2015	Unit lost electrical power	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A61	03/03/2015	Inspect and recharge accumulators	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A74	30/03/2015	Inspect and recharge accumulators	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A53	21/04/2015	Accumulator inspection and charging required	Michele Williams noted: Repair completed.	michele_williams
A77	26/11/2015	Machine is unpowered	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A1	22/08/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A24	14/06/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A93	24/03/2015	Repair work needed on milling spindle	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A37	17/02/2015	Leaks found at turrets A and B	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A48	09/06/2015	Machine is unpowered	Michele Williams noted: System checked and accumulators charged.	michele_williams
A45	10/10/2015	Turret sections A & B showing leaks	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A48	04/01/2016	Turret sections A & B showing leaks	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A3	10/10/2015	Accumulator inspection and charging required	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A24	24/02/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A95	23/03/2015	Repair work needed on milling spindle	Gina Moore noted: No further details.	gina_moore, dylan_miller
A92	19/04/2015	Turret sections A & B showing leaks	Cristian Santos noted: Repair completed.	cristian_santos
A58	11/06/2015	Turret sections A & B showing leaks	Cristian Santos noted: Repair completed.	cristian_santos
A36	17/02/2015	Hydraulic line leak on side B	Cristian Santos noted: Maintenance action successful.	cristian_santos
A92	10/05/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A89	02/05/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A49	10/10/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A51	18/08/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A84	15/06/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A26	17/05/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A6	07/01/2016	Indexing issue causing overfeed on spindle	Michele Williams noted: Detail not recorded.	michele_williams
A89	30/06/2015	Spindle indexing error with overfeed	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A85	18/02/2015	Spindle fails to index, overfeeding	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A87	10/01/2016	Accumulators need checking and charging	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A63	14/07/2015	Leak in side B hydraulic line	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A40	13/04/2015	Turret sections A & B showing leaks	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A51	12/04/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A33	13/01/2016	Spindle indexing error with overfeed	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A96	13/12/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A64	22/01/2015	Machine is unpowered	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A6	28/10/2015	Milling spindle requires repair	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A60	23/07/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A59	09/10/2015	Turret A and B are leaking	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A83	23/01/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A36	16/01/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A90	19/10/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A11	27/05/2015	Inspect and recharge accumulators	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A19	16/05/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A80	17/01/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A46	18/07/2015	Turret sections A & B showing leaks	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A52	12/06/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A88	27/11/2015	Hydraulic line leak on side B	Michele Williams noted: Detail not recorded.	michele_williams
A67	31/01/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams

A91	23/02/2015	Accumulators need checking and charging	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A56	28/07/2015	Spindle indexing error with overfeed	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A10	03/07/2015	Turret sections A & B showing leaks	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A43	09/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A86	01/12/2015	Repair work needed on milling spindle	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A59	15/10/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A72	07/11/2015	Repair work needed on milling spindle	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A38	02/06/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A79	23/04/2015	Power supply failure detected	Cristian Santos noted: Fixed and tested.	cristian_santos
A78	21/06/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A72	14/09/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A39	28/09/2015	Turret sections A & B showing leaks	Cristian Santos noted: Fixed and tested.	cristian_santos
A89	14/03/2015	Leaks found at turrets A and B	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A39	06/07/2015	Turret sections A & B showing leaks	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A32	03/12/2015	Turret sections A & B showing leaks	Michele Williams noted: Detail not recorded.	michele_williams
A65	29/01/2015	Spindle fails to index, overfeeding	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A77	02/06/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A66	15/12/2015	Machine is unpowered	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A62	02/06/2015	Inspect and recharge accumulators	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A64	26/11/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A81	14/01/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A90	08/07/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A44	13/01/2016	Hydraulic fluid leak at saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A84	12/06/2015	Milling spindle requires repair	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A41	05/08/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A94	11/09/2015	Turret sections A & B showing leaks	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A84	06/10/2015	Turret A and B are leaking	Cristian Santos noted: Repair completed.	cristian_santos
A63	19/01/2015	Accumulator inspection and charging required	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A38	11/03/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A9	23/09/2015	Turret A and B are leaking	Nathan Maldonado noted: No further details.	nathan_maldonado
A53	10/01/2016	Leak in side B hydraulic line	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A78	27/10/2015	Repair work needed on milling spindle	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A76	03/05/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A92	13/06/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A94	17/11/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A63	08/01/2016	Machine is unpowered	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A13	29/11/2015	Unit lost electrical power	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A61	04/06/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A89	01/05/2015	Leak in side B hydraulic line	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A35	15/07/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A59	11/05/2015	Hydraulic line leak on side B	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A63	20/07/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A44	22/07/2015	Inspect and recharge accumulators	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A57	08/09/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A13	18/02/2015	Machine is unpowered	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A67	28/10/2015	Machine is unpowered	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A66	19/10/2015	Repair work needed on milling spindle	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A20	11/11/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A20	30/05/2015	Machine is unpowered	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A81	21/01/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A87	09/12/2015	Hydraulic line leak on side B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A53	19/01/2015	Inspect and recharge accumulators	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A67	11/08/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A26	02/01/2016	Machine is unpowered	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A42	06/02/2015	Maintenance on milling spindle needed	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A70	29/06/2015	Accumulators need checking and charging	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A57	18/09/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: No additional information provided.	cristian_santos
A33	20/03/2015	Spindle indexing error with overfeed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A53	15/03/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A12	24/08/2015	Accumulator inspection and charging required	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A34	25/10/2015	Milling spindle requires repair	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A75	08/05/2015	Turret A and B are leaking	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A39	11/06/2015	Accumulators need checking and charging	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A30	24/12/2015	Power supply failure detected	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A76	23/02/2015	Accumulator inspection and charging required	Michele Williams noted: Repair completed.	michele_williams
A63	03/08/2015	Power supply failure detected	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A18	28/07/2015	Accumulators need checking and charging	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A80	17/12/2015	Milling spindle requires repair	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A10	23/10/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A17	10/06/2015	Inspect and recharge accumulators	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller

A57	18/07/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A34	12/01/2016	Hydraulic hose on side B is leaking	Michele Williams noted: Fixed and tested.	michele_williams
A81	14/08/2015	Maintenance on milling spindle needed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A64	01/09/2015	Spindle indexing error with overfeed	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A78	05/10/2015	Turret A and B are leaking	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A49	30/05/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A11	12/07/2015	Accumulators need checking and charging	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A61	15/06/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A10	07/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A85	04/12/2015	Machine is unpowered	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A78	03/10/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A7	05/04/2015	Milling spindle requires repair	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A81	21/12/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A19	30/07/2015	Power supply failure detected	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A52	21/12/2015	Turret A and B are leaking	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A71	01/01/2016	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A27	15/04/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A70	24/09/2015	Leaks found at turrets A and B	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A69	22/11/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A11	27/02/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A21	15/11/2015	Machine is unpowered	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A24	22/01/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A59	04/05/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A55	06/11/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A35	16/09/2015	Machine is unpowered	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A94	25/04/2015	Turret sections A & B showing leaks	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A9	06/09/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A49	07/10/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A28	09/03/2015	Power supply failure detected	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A25	26/03/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A28	23/03/2015	Milling spindle requires repair	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A62	28/01/2015	Machine is unpowered	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A58	25/07/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A34	25/03/2015	Unit lost electrical power	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A46	06/05/2015	Unit lost electrical power	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A37	14/05/2015	Inspect and recharge accumulators	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A53	24/05/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A76	30/11/2015	Accumulator inspection and charging required	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A97	17/03/2015	Hydraulic line leak on side B	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A44	23/05/2015	Accumulators need checking and charging	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A19	19/07/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Detail not recorded.	cristian_santos
A64	08/06/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A54	18/10/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A67	03/04/2015	Turret A and B are leaking	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A14	26/02/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A25	31/08/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A47	28/05/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A39	27/10/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A38	19/03/2015	Repair work needed on milling spindle	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A90	14/04/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A64	29/03/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A57	25/07/2015	Unit lost electrical power	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A10	07/02/2015	Turret sections A & B showing leaks	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A77	07/11/2015	Repair work needed on milling spindle	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A24	16/09/2015	Turret A and B are leaking	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A27	19/10/2015	Machine is unpowered	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A74	16/03/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A4	18/07/2015	Maintenance on milling spindle needed	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A96	11/05/2015	Inspect and recharge accumulators	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A76	26/03/2015	Accumulators need checking and charging	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A54	28/11/2015	Accumulator inspection and charging required	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A20	01/06/2015	Milling spindle requires repair	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A20	24/10/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A60	07/02/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A90	04/11/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A95	24/09/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A88	28/11/2015	Turret sections A & B showing leaks	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A50	20/02/2015	Turret sections A & B showing leaks	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A59	09/12/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A26	02/02/2015	Leak in side B hydraulic line	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams

A48	11/10/2015	Repair work needed on milling spindle	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A54	30/10/2015	Turret A and B are leaking	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A59	09/12/2015	Power supply failure detected	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A88	11/03/2015	Turret A and B are leaking	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A6	25/04/2015	Hydraulic line leak on side B	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A61	29/11/2015	Inspect and recharge accumulators	Michele Williams noted: Maintenance action successful.	michele_williams
A76	12/05/2015	Machine is unpowered	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A8	02/01/2016	Maintenance on milling spindle needed	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A96	24/08/2015	Turret A and B are leaking	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A71	02/07/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A14	31/12/2015	Inspect and recharge accumulators	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A58	26/04/2015	Machine is unpowered	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A18	09/06/2015	Repair work needed on milling spindle	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A10	10/08/2015	Hydraulic line leak on side B	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A28	16/07/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A38	24/12/2015	Accumulator inspection and charging required	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A3	24/12/2015	Power supply failure detected	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A90	19/04/2015	Leak in side B hydraulic line	Cristian Santos noted: Repair completed.	cristian_santos
A13	21/08/2015	Hydraulic line leak on side B	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A61	14/12/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A67	17/01/2015	Turret A and B are leaking	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A68	14/01/2015	Inspect and recharge accumulators	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A20	11/02/2015	Leak in side B hydraulic line	Michele Williams noted: No further details.	michele_williams
A19	19/12/2015	Hydraulic line leak on side B	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A65	16/05/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Maintenance action successful.	cristian_santos
A8	10/07/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A58	09/01/2016	Milling spindle requires repair	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A59	15/01/2015	Maintenance on milling spindle needed	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A77	15/11/2015	Turret A and B are leaking	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A62	25/05/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A41	12/05/2015	Spindle indexing error with overfeed	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A96	08/12/2015	Leaks found at turrets A and B	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A33	07/12/2015	Maintenance on milling spindle needed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A20	29/05/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Repair completed.	cristian_santos
A79	09/02/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A15	18/04/2015	Turret A and B are leaking	Cristian Santos noted: Fixed and tested.	cristian_santos
A12	24/01/2015	Repair work needed on milling spindle	Cristian Santos noted: Detail not recorded.	cristian_santos
A11	23/05/2015	Turret sections A & B showing leaks	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A88	10/08/2015	Machine is unpowered	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A95	03/01/2016	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A60	14/10/2015	Machine is unpowered	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A94	30/09/2015	Leak in side B hydraulic line	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A69	09/08/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A90	24/08/2015	Milling spindle requires repair	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A19	17/03/2015	Turret A and B are leaking	Cristian Santos noted: No further details.	cristian_santos
A60	02/07/2015	Leak in side B hydraulic line	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A84	02/08/2015	Turret A and B are leaking	Cristian Santos noted: No further details.	cristian_santos
A52	31/10/2015	Inspect and recharge accumulators	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A32	21/04/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A74	23/10/2015	Unit lost electrical power	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A13	26/01/2015	Power supply failure detected	Michele Williams noted: Repair completed.	michele_williams
A14	13/01/2016	Leaks found at turrets A and B	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A94	16/10/2015	Accumulator inspection and charging required	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A52	12/02/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A15	07/09/2015	Accumulators need checking and charging	Cristian Santos noted: Maintenance action successful.	cristian_santos
A63	02/08/2015	Unit lost electrical power	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A15	04/12/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A53	23/04/2015	Accumulator inspection and charging required	Cristian Santos noted: No further details.	cristian_santos
A56	09/07/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A4	15/06/2015	Leaks found at turrets A and B	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A55	06/12/2015	Unit lost electrical power	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A41	18/11/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: No further details.	nathan_maldonado
A28	13/05/2015	Leaks found at turrets A and B	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A94	20/09/2015	Repair work needed on milling spindle	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A51	08/10/2015	Unit lost electrical power	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A16	24/02/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A20	26/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A31	02/04/2015	Spindle indexing error with overfeed	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A67	28/10/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A1	22/05/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado

A14	24/02/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A40	13/07/2015	Turret A and B are leaking	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A57	07/03/2015	Unit lost electrical power	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A46	21/04/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A82	01/01/2016	Saw attachment gears are binding and grinding	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A15	01/03/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A17	18/01/2015	Inspect and recharge accumulators	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A68	27/06/2015	Milling spindle requires repair	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A21	26/01/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A98	16/05/2015	Turret sections A & B showing leaks	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A12	09/05/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Repair completed.	cristian_santos
A78	06/01/2016	Inspect and recharge accumulators	Cristian Santos noted: No further details.	cristian_santos
A42	27/01/2015	Power supply failure detected	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A35	30/10/2015	Accumulators need checking and charging	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A77	02/04/2015	Turret A and B are leaking	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A13	04/01/2016	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Repair completed.	michele_williams
A24	01/03/2015	Inspect and recharge accumulators	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A66	06/02/2015	Accumulators need checking and charging	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A92	31/07/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A94	12/02/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A8	24/04/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A90	23/06/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Repair completed.	michele_williams
A80	10/04/2015	Spindle fails to index, overfeeding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A26	13/12/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A2	21/11/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A38	19/12/2015	Unit lost electrical power	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A65	23/05/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A35	27/06/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A27	09/02/2015	Leaks found at turrets A and B	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A44	11/02/2015	Repair work needed on milling spindle	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A6	25/01/2015	Spindle fails to index, overfeeding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A95	26/10/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A69	02/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A40	31/10/2015	Leak in side B hydraulic line	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A10	21/12/2015	Unit lost electrical power	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A45	21/08/2015	Leaks found at turrets A and B	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A52	02/11/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A68	04/10/2015	Inspect and recharge accumulators	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A84	16/01/2015	Inspect and recharge accumulators	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A58	24/11/2015	Milling spindle requires repair	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A99	24/09/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A67	20/10/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A33	23/09/2015	Inspect and recharge accumulators	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A38	15/11/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A6	02/03/2015	Milling spindle requires repair	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A82	12/06/2015	Spindle fails to index, overfeeding	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A35	10/11/2015	Unit lost electrical power	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A96	18/11/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A30	26/11/2015	Repair work needed on milling spindle	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A60	05/05/2015	Hydraulic line leak on side B	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A12	16/05/2015	Machine is unpowered	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A29	16/07/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A51	07/05/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A22	15/06/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A98	22/08/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A99	06/07/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A71	14/12/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A33	03/02/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A21	08/01/2016	Inspect and recharge accumulators	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A31	25/04/2015	Leak in side B hydraulic line	Michele Williams noted: System checked and accumulators charged.	michele_williams
A1	05/10/2015	Machine is unpowered	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A69	14/02/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A83	25/11/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A84	13/08/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A88	06/02/2015	Machine is unpowered	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A99	07/12/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A90	30/04/2015	Turret sections A & B showing leaks	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A53	22/10/2015	Spindle indexing error with overfeed	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A33	20/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: No further details.	michele_williams
A59	31/08/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams

A92	05/06/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Detail not recorded.	cristian_santos
A19	18/11/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A27	04/02/2015	Maintenance on milling spindle needed	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A91	29/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A76	28/10/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A62	28/07/2015	Spindle fails to index, overfeeding	Michele Williams noted: Detail not recorded.	michele_williams
A11	25/11/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A56	02/10/2015	Turret sections A & B showing leaks	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A14	11/05/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A65	28/07/2015	Power supply failure detected	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A13	06/06/2015	Accumulator inspection and charging required	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A24	07/04/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A97	30/10/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A71	19/05/2015	Spindle fails to index, overfeeding	Michele Williams noted: Repair completed.	michele_williams
A66	17/03/2015	Turret A and B are leaking	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A76	26/08/2015	Inspect and recharge accumulators	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A87	18/01/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A18	14/04/2015	Leak in side B hydraulic line	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A53	21/01/2015	Power supply failure detected	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A47	12/11/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A33	18/04/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A48	23/07/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Repair completed.	michele_williams
A42	10/11/2015	Turret A and B are leaking	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A75	21/05/2015	Leak in side B hydraulic line	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A46	03/12/2015	Turret A and B are leaking	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A83	01/07/2015	Leaks found at turrets A and B	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A21	11/04/2015	Leaks found at turrets A and B	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A25	30/12/2015	Spindle indexing error with overfeed	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A49	25/11/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A14	29/10/2015	Maintenance on milling spindle needed	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A60	25/05/2015	Milling spindle requires repair	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A36	26/07/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Maintenance action successful.	michele_williams
A89	14/03/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A24	19/06/2015	Leak in side B hydraulic line	Michele Williams noted: No additional information provided.	michele_williams
A48	04/02/2015	Power supply failure detected	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A87	03/05/2015	Turret A and B are leaking	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A66	02/09/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A45	06/06/2015	Power supply failure detected	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A52	20/03/2015	Machine is unpowered	Cristian Santos noted: Repair completed.	cristian_santos
A10	23/03/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A81	12/01/2016	Accumulator inspection and charging required	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A85	07/05/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A12	09/09/2015	Power supply failure detected	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A11	21/10/2015	Power supply failure detected	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A6	28/04/2015	Spindle indexing error with overfeed	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A77	10/02/2015	Accumulators need checking and charging	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A11	22/10/2015	Spindle indexing error with overfeed	Michele Williams noted: Fixed and tested.	michele_williams
A80	09/09/2015	Leaks found at turrets A and B	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A69	11/08/2015	Unit lost electrical power	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A41	25/01/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A44	02/07/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A67	13/03/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A51	18/07/2015	Leak in side B hydraulic line	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A65	03/02/2015	Spindle fails to index, overfeeding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A69	03/09/2015	Power supply failure detected	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A52	12/07/2015	Maintenance on milling spindle needed	Cristian Santos noted: No additional information provided.	cristian_santos
A90	15/08/2015	Maintenance on milling spindle needed	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A60	22/07/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A34	16/09/2015	Leak in side B hydraulic line	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A47	18/02/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A58	03/07/2015	Accumulators need checking and charging	Michele Williams noted: No additional information provided.	michele_williams
A63	09/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A6	13/11/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A32	15/02/2015	Leaks found at turrets A and B	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A51	15/10/2015	Milling spindle requires repair	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A28	12/09/2015	Accumulator inspection and charging required	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A61	27/01/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A40	11/07/2015	Turret A and B are leaking	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A7	13/08/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A80	26/08/2015	Turret sections A & B showing leaks	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller

A79	22/07/2015	Leaks found at turrets A and B	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A21	17/10/2015	Turret A and B are leaking	Michele Williams noted: Fixed and tested.	michele_williams
A53	23/02/2015	Repair work needed on milling spindle	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A6	16/01/2015	Maintenance on milling spindle needed	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A97	21/02/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A70	06/05/2015	Accumulator inspection and charging required	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A84	05/02/2015	Accumulator inspection and charging required	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A16	27/05/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A80	23/08/2015	Accumulators need checking and charging	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A66	23/03/2015	Unit lost electrical power	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A47	12/08/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A66	05/06/2015	Spindle indexing error with overfeed	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A96	31/01/2015	Turret A and B are leaking	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A24	15/05/2015	Inspect and recharge accumulators	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A20	19/06/2015	Unit lost electrical power	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A26	24/11/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A4	26/02/2015	Accumulators need checking and charging	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A51	30/09/2015	Unit lost electrical power	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A80	12/09/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A65	12/06/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A39	15/03/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A84	09/09/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A56	06/09/2015	Spindle fails to index, overfeeding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A11	19/12/2015	Maintenance on milling spindle needed	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A88	12/08/2015	Milling spindle requires repair	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A6	16/01/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A42	07/04/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A41	17/02/2015	Inspect and recharge accumulators	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A28	02/03/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A53	04/02/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A58	21/08/2015	Turret A and B are leaking	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A3	14/11/2015	Inspect and recharge accumulators	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A33	06/08/2015	Turret A and B are leaking	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A68	19/10/2015	Leak in side B hydraulic line	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A24	01/02/2015	Turret A and B are leaking	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A95	15/05/2015	Maintenance on milling spindle needed	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A95	18/03/2015	Accumulator inspection and charging required	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A4	30/10/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A14	24/09/2015	Accumulators need checking and charging	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A1	30/09/2015	Turret A and B are leaking	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A12	02/11/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A77	26/03/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A66	19/08/2015	Repair work needed on milling spindle	Nathan Maldonado noted: No further details.	nathan_maldonado
A15	22/10/2015	Maintenance on milling spindle needed	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A73	26/05/2015	Power supply failure detected	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A53	13/08/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A94	22/08/2015	Turret A and B are leaking	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A54	15/07/2015	Unit lost electrical power	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A18	28/12/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A3	11/09/2015	Turret A and B are leaking	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A17	06/06/2015	Accumulator inspection and charging required	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A23	22/01/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Maintenance action successful.	michele_williams
A54	25/06/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A12	15/02/2015	Turret sections A & B showing leaks	Michele Williams noted: Detail not recorded.	michele_williams
A33	18/12/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A37	18/05/2015	Turret A and B are leaking	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A56	19/09/2015	Turret A and B are leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A63	31/08/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A58	29/11/2015	Power supply failure detected	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A13	17/02/2015	Leak in side B hydraulic line	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A9	28/02/2015	Milling spindle requires repair	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A1	25/11/2015	Maintenance on milling spindle needed	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A34	10/12/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A74	17/02/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A98	26/06/2015	Inspect and recharge accumulators	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A22	17/05/2015	Spindle indexing error with overfeed	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A19	27/06/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A25	27/02/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A86	08/09/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A29	31/03/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado

A63	14/02/2015	Hydraulic line leak on side B	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A5	24/01/2015	Leak in side B hydraulic line	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A29	19/10/2015	Milling spindle requires repair	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A37	27/08/2015	Turret sections A & B showing leaks	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A78	12/07/2015	Leaks found at turrets A and B	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A39	01/12/2015	Leak in side B hydraulic line	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A50	19/08/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A29	27/06/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A21	19/09/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A50	31/01/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A8	22/09/2015	Leaks found at turrets A and B	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A97	04/06/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A5	16/08/2015	Turret sections A & B showing leaks	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A68	11/02/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A50	01/10/2015	Machine is unpowered	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A12	02/03/2015	Accumulators need checking and charging	Cristian Santos noted: No additional information provided.	cristian_santos
A73	28/05/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A64	25/12/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A16	16/01/2015	Maintenance on milling spindle needed	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A62	09/02/2015	Spindle indexing error with overfeed	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A6	24/08/2015	Hydraulic line leak on side B	Cristian Santos noted: Repair completed.	cristian_santos
A15	10/08/2015	Accumulators need checking and charging	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A40	08/06/2015	Machine is unpowered	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A58	22/05/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A32	15/03/2015	Maintenance on milling spindle needed	Michele Williams noted: Fixed and tested.	michele_williams
A36	20/05/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A94	27/10/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A45	12/02/2015	Maintenance on milling spindle needed	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A27	01/03/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A38	29/05/2015	Unit lost electrical power	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A29	02/08/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A10	01/09/2015	Repair work needed on milling spindle	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A51	23/08/2015	Inspect and recharge accumulators	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A18	25/03/2015	Turret A and B are leaking	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A79	26/04/2015	Repair work needed on milling spindle	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A5	08/04/2015	Spindle indexing error with overfeed	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A7	22/07/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A45	22/01/2015	Leaks found at turrets A and B	Michele Williams noted: Detail not recorded.	michele_williams
A98	05/11/2015	Milling spindle requires repair	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A89	11/09/2015	Unit lost electrical power	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A77	17/04/2015	Turret A and B are leaking	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A88	09/10/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A38	03/05/2015	Power supply failure detected	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A15	09/05/2015	Milling spindle requires repair	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A98	25/04/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A49	24/12/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A81	04/06/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A23	10/03/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A1	07/04/2015	Unit lost electrical power	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A17	12/07/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A33	27/10/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A38	18/02/2015	Inspect and recharge accumulators	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A4	31/01/2015	Spindle indexing error with overfeed	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A1	24/05/2015	Accumulator inspection and charging required	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A17	20/06/2015	Inspect and recharge accumulators	Michele Williams noted: System checked and accumulators charged.	michele_williams
A25	09/09/2015	Maintenance on milling spindle needed	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A45	09/09/2015	Power supply failure detected	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A29	10/05/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A71	10/05/2015	Turret A and B are leaking	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A24	29/08/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A49	01/12/2015	Leaks found at turrets A and B	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A54	25/02/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A62	19/08/2015	Leaks found at turrets A and B	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A73	21/01/2015	Accumulators need checking and charging	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A40	14/10/2015	Power supply failure detected	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A6	15/08/2015	Milling spindle requires repair	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A31	13/09/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A80	13/04/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A62	12/02/2015	Leaks found at turrets A and B	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A95	21/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams

A95	27/02/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A4	24/02/2015	Leaks found at turrets A and B	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A9	08/09/2015	Spindle indexing error with overfeed	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A99	17/01/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A29	30/01/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A49	23/02/2015	Unit lost electrical power	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A50	03/09/2015	Leaks found at turrets A and B	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A25	11/03/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A52	28/01/2015	Spindle indexing error with overfeed	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A3	31/10/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A88	13/01/2016	Repair work needed on milling spindle	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A16	07/03/2015	Power supply failure detected	Michele Williams noted: System checked and accumulators charged.	michele_williams
A16	12/10/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A23	12/12/2015	Milling spindle requires repair	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A68	07/12/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A26	04/04/2015	Turret sections A & B showing leaks	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A43	03/09/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A4	20/08/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A9	18/03/2015	Leak in side B hydraulic line	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A15	29/12/2015	Repair work needed on milling spindle	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A42	01/07/2015	Spindle fails to index, overfeeding	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A82	11/02/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A79	02/03/2015	Hydraulic line leak on side B	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A58	01/07/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Fixed and tested.	cristian_santos
A46	16/08/2015	Accumulators need checking and charging	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A65	23/03/2015	Repair work needed on milling spindle	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A26	26/03/2015	Machine is unpowered	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A41	01/10/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A56	05/10/2015	Inspect and recharge accumulators	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A35	17/08/2015	Spindle indexing error with overfeed	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A98	11/07/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A79	25/05/2015	Leaks found at turrets A and B	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A11	18/04/2015	Unit lost electrical power	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A94	07/08/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A3	22/04/2015	Accumulators need checking and charging	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A89	09/11/2015	Turret A and B are leaking	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A35	07/10/2015	Unit lost electrical power	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A62	24/05/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A53	18/12/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A59	29/03/2015	Repair work needed on milling spindle	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A35	04/10/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A37	10/08/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A38	31/12/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A25	12/03/2015	Milling spindle requires repair	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A77	13/11/2015	Inspect and recharge accumulators	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A24	22/09/2015	Spindle indexing error with overfeed	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A97	06/06/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A25	14/06/2015	Leaks found at turrets A and B	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A12	02/02/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A22	17/06/2015	Unit lost electrical power	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A85	05/02/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A9	20/12/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A55	03/02/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A90	29/05/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Repair completed.	michele_williams
A7	21/03/2015	Maintenance on milling spindle needed	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A28	29/12/2015	Machine is unpowered	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A38	23/06/2015	Machine is unpowered	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A34	18/01/2015	Power supply failure detected	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A43	20/03/2015	Maintenance on milling spindle needed	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A35	15/01/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A34	20/11/2015	Machine is unpowered	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A22	15/02/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A45	21/10/2015	Leaks found at turrets A and B	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A33	18/09/2015	Unit lost electrical power	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A76	11/08/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A43	18/02/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A76	23/02/2015	Hydraulic line leak on side B	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A25	15/12/2015	Accumulators need checking and charging	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A82	20/01/2015	Leak in side B hydraulic line	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A19	01/01/2016	Inspect and recharge accumulators	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams

A31	01/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A66	29/03/2015	Power supply failure detected	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A61	17/01/2015	Leak in side B hydraulic line	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A3	11/09/2015	Repair work needed on milling spindle	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A45	30/06/2015	Hydraulic line leak on side B	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A28	21/11/2015	Turret sections A & B showing leaks	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A92	02/08/2015	Hydraulic line leak on side B	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A21	20/11/2015	Maintenance on milling spindle needed	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A34	29/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A52	04/04/2015	Accumulators need checking and charging	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A28	22/01/2015	Machine is unpowered	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A19	29/08/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A43	07/03/2015	Milling spindle requires repair	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A84	05/10/2015	Spindle indexing error with overfeed	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A3	16/08/2015	Unit lost electrical power	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A76	30/04/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Detail not recorded.	cristian_santos
A42	23/08/2015	Maintenance on milling spindle needed	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A31	23/04/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Maintenance action successful.	michele_williams
A52	11/12/2015	Leaks found at turrets A and B	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A83	27/10/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A79	29/01/2015	Turret A and B are leaking	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A64	04/01/2016	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A20	12/11/2015	Inspect and recharge accumulators	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A80	07/05/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A7	21/02/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A38	20/08/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Maintenance action successful.	michele_williams
A33	11/10/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A87	04/12/2015	Machine is unpowered	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A77	12/07/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A89	13/02/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A27	27/02/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A24	22/01/2015	Spindle indexing error with overfeed	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A45	29/06/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A50	12/06/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A67	19/08/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A57	22/12/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A91	19/02/2015	Machine is unpowered	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A44	24/02/2015	Accumulators need checking and charging	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A3	04/10/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Detail not recorded.	cristian_santos
A45	07/08/2015	Leaks found at turrets A and B	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A66	21/10/2015	Inspect and recharge accumulators	Cristian Santos noted: Maintenance action successful.	cristian_santos
A66	21/11/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Fixed and tested.	michele_williams
A89	25/07/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A84	26/10/2015	Leak in side B hydraulic line	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A55	14/11/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A2	10/07/2015	Machine is unpowered	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A74	08/05/2015	Inspect and recharge accumulators	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A16	26/07/2015	Accumulators need checking and charging	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A31	24/02/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: No further details.	cristian_santos
A84	30/08/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A10	04/02/2015	Leaks found at turrets A and B	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A77	10/03/2015	Accumulators need checking and charging	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A22	21/03/2015	Turret A and B are leaking	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A45	02/05/2015	Leak in side B hydraulic line	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A9	06/10/2015	Inspect and recharge accumulators	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A40	20/11/2015	Leak in side B hydraulic line	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A16	22/10/2015	Unit lost electrical power	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A9	29/08/2015	Turret sections A & B showing leaks	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A5	20/12/2015	Unit lost electrical power	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A31	08/12/2015	Turret sections A & B showing leaks	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A56	26/04/2015	Milling spindle requires repair	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A30	09/12/2015	Leak in side B hydraulic line	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A29	18/10/2015	Accumulators need checking and charging	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A90	20/08/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A88	11/12/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A79	04/10/2015	Hydraulic line leak on side B	Michele Williams noted: Repair completed.	michele_williams
A74	28/01/2015	Accumulator inspection and charging required	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A73	11/06/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A24	25/03/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A81	07/10/2015	Leaks found at turrets A and B	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams

A58	18/06/2015	Turret A and B are leaking	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A22	19/11/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A13	31/05/2015	Machine is unpowered	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A32	07/11/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A91	22/01/2015	Turret sections A & B showing leaks	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A22	05/05/2015	Saw attachment gears are binding and grinding	Michele Williams noted: No additional information provided.	michele_williams
A63	28/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A97	19/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A29	17/04/2015	Leak in side B hydraulic line	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A55	05/10/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A69	12/01/2016	Hydraulic line leak on side B	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A69	09/11/2015	Inspect and recharge accumulators	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A85	19/02/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A22	01/01/2016	Repair work needed on milling spindle	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A78	30/08/2015	Spindle indexing error with overfeed	Cristian Santos noted: Repair completed.	cristian_santos
A9	17/11/2015	Machine is unpowered	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A52	12/09/2015	Leaks found at turrets A and B	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A58	18/11/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A12	14/05/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A44	28/05/2015	Turret sections A & B showing leaks	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A39	11/04/2015	Spindle indexing error with overfeed	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A44	03/06/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Repair completed.	michele_williams
A31	03/12/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A24	27/06/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A10	10/12/2015	Leaks found at turrets A and B	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A45	11/05/2015	Repair work needed on milling spindle	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A63	30/04/2015	Spindle indexing error with overfeed	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A18	25/05/2015	Milling spindle requires repair	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A3	25/04/2015	Hydraulic line leak on side B	Michele Williams noted: No further details.	michele_williams
A79	14/11/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A71	16/03/2015	Machine is unpowered	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A18	20/11/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A15	21/11/2015	Turret sections A & B showing leaks	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A22	01/04/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A56	09/05/2015	Milling spindle requires repair	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A74	18/06/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A88	19/03/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A75	16/12/2015	Inspect and recharge accumulators	Cristian Santos noted: No further details.	cristian_santos
A69	21/05/2015	Power supply failure detected	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A76	23/03/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A12	30/11/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A75	13/08/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A28	06/03/2015	Inspect and recharge accumulators	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A63	05/09/2015	Milling spindle requires repair	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A7	15/01/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A46	22/04/2015	Turret sections A & B showing leaks	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A77	11/06/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A53	14/03/2015	Accumulators need checking and charging	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A10	07/08/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A3	19/11/2015	Leak in side B hydraulic line	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A55	11/12/2015	Milling spindle requires repair	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A67	18/04/2015	Inspect and recharge accumulators	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A61	03/07/2015	Leak in side B hydraulic line	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A39	20/04/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A29	02/02/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A68	06/06/2015	Turret A and B are leaking	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A43	21/08/2015	Maintenance on milling spindle needed	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A77	25/10/2015	Unit lost electrical power	Cristian Santos noted: No additional information provided.	cristian_santos
A2	05/03/2015	Saw attachment gears are binding and grinding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A3	25/07/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A35	28/08/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A95	19/04/2015	Leaks found at turrets A and B	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A35	19/05/2015	Unit lost electrical power	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A26	05/03/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A45	27/02/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A26	17/01/2015	Maintenance on milling spindle needed	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A50	18/02/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A1	15/11/2015	Spindle fails to index, overfeeding	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A65	12/08/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A89	19/05/2015	Repair work needed on milling spindle	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller

A59	17/12/2015	Milling spindle requires repair	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A35	21/03/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A79	15/12/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A37	22/10/2015	Turret sections A & B showing leaks	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A60	06/12/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A34	10/11/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A38	21/08/2015	Milling spindle requires repair	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A23	12/06/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A59	17/01/2015	Power supply failure detected	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A93	20/04/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A91	11/02/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A41	23/09/2015	Milling spindle requires repair	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A57	26/12/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A38	27/10/2015	Leak in side B hydraulic line	Cristian Santos noted: Maintenance action successful.	cristian_santos
A20	08/06/2015	Repair work needed on milling spindle	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A2	07/10/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A53	03/12/2015	Accumulator inspection and charging required	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A52	13/06/2015	Power supply failure detected	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A37	20/07/2015	Turret sections A & B showing leaks	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A87	10/11/2015	Leak in side B hydraulic line	Michele Williams noted: Maintenance action successful.	michele_williams
A32	15/07/2015	Power supply failure detected	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A66	14/09/2015	Spindle fails to index, overfeeding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A74	25/03/2015	Turret sections A & B showing leaks	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A76	23/03/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Maintenance action successful.	cristian_santos
A54	15/09/2015	Maintenance on milling spindle needed	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A14	13/01/2016	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A2	23/12/2015	Hydraulic line leak on side B	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A47	16/09/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A5	14/10/2015	Hydraulic line leak on side B	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A22	15/04/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A52	24/06/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A76	10/01/2016	Hydraulic hose on side B is leaking	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A25	12/08/2015	Saw attachment is leaking hydraulics	Michele Williams noted: System checked and accumulators charged.	michele_williams
A57	28/09/2015	Machine is unpowered	Cristian Santos noted: No further details.	cristian_santos
A26	30/08/2015	Turret sections A & B showing leaks	Cristian Santos noted: Fixed and tested.	cristian_santos
A63	10/04/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A36	25/10/2015	Power supply failure detected	Michele Williams noted: No additional information provided.	michele_williams
A59	25/06/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A20	06/02/2015	Inspect and recharge accumulators	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A44	20/03/2015	Turret sections A & B showing leaks	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A13	26/06/2015	Accumulators need checking and charging	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A28	24/05/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A70	01/01/2016	Machine is unpowered	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A37	19/08/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A29	30/05/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A94	14/12/2015	Repair work needed on milling spindle	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A17	11/12/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A43	27/08/2015	Hydraulic line leak on side B	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A86	19/09/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: No additional information provided.	cristian_santos
A18	08/06/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A27	28/12/2015	Leaks found at turrets A and B	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A3	06/04/2015	Turret A and B are leaking	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A75	22/04/2015	Turret A and B are leaking	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A81	18/08/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A20	02/03/2015	Power supply failure detected	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A66	07/11/2015	Spindle indexing error with overfeed	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A62	16/01/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A94	02/06/2015	Milling spindle requires repair	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A13	29/06/2015	Unit lost electrical power	Michele Williams noted: Detail not recorded.	michele_williams
A83	28/04/2015	Accumulators need checking and charging	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A66	24/05/2015	Turret sections A & B showing leaks	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A57	25/08/2015	Leak in side B hydraulic line	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A89	21/12/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A6	05/11/2015	Unit lost electrical power	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A32	13/09/2015	Machine is unpowered	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A90	20/03/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A44	28/07/2015	Spindle indexing error with overfeed	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A53	26/08/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: No further details.	nathan_maldonado
A20	22/07/2015	Machine is unpowered	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A61	15/09/2015	Inspect and recharge accumulators	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams

A61	19/03/2015	Maintenance on milling spindle needed	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A41	10/08/2015	Machine is unpowered	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A51	14/01/2015	Power supply failure detected	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A87	01/03/2015	Maintenance on milling spindle needed	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A31	27/12/2015	Hydraulic line leak on side B	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A70	15/10/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A5	31/03/2015	Leaks found at turrets A and B	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A24	06/12/2015	Hydraulic line leak on side B	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A31	25/10/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A51	22/04/2015	Maintenance on milling spindle needed	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A53	11/07/2015	Spindle indexing error with overfeed	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A1	29/05/2015	Inspect and recharge accumulators	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A28	13/11/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A80	22/04/2015	Leak in side B hydraulic line	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A90	26/09/2015	Maintenance on milling spindle needed	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A69	30/12/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: No further details.	nathan_maldonado
A29	11/10/2015	Inspect and recharge accumulators	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A82	26/11/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A82	17/05/2015	Turret A and B are leaking	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A59	29/04/2015	Accumulator inspection and charging required	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A97	16/08/2015	Leaks found at turrets A and B	Cristian Santos noted: No additional information provided.	cristian_santos
A53	25/12/2015	Repair work needed on milling spindle	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A58	25/04/2015	Accumulators need checking and charging	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A70	05/10/2015	Leak in side B hydraulic line	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A85	16/08/2015	Milling spindle requires repair	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A32	14/11/2015	Machine is unpowered	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A87	29/06/2015	Hydraulic line leak on side B	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A99	26/05/2015	Turret sections A & B showing leaks	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A37	08/07/2015	Turret sections A & B showing leaks	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A58	21/05/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A86	30/03/2015	Hydraulic hose on side B is leaking	Michele Williams noted: No further details.	michele_williams
A78	28/08/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A41	31/08/2015	Accumulators need checking and charging	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A22	16/01/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A51	01/07/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A57	30/03/2015	Leaks found at turrets A and B	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A87	21/01/2015	Repair work needed on milling spindle	Michele Williams noted: Detail not recorded.	michele_williams
A28	08/07/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A26	18/12/2015	Accumulator inspection and charging required	Michele Williams noted: No further details.	michele_williams
A99	03/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A50	23/04/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A73	17/10/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A66	19/08/2015	Spindle indexing error with overfeed	Cristian Santos noted: Detail not recorded.	cristian_santos
A20	28/08/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Detail not recorded.	cristian_santos
A25	29/01/2015	Spindle indexing error with overfeed	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A99	27/12/2015	Milling spindle requires repair	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A89	02/05/2015	Turret A and B are leaking	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A20	06/12/2015	Accumulator inspection and charging required	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A92	19/08/2015	Turret A and B are leaking	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A61	03/03/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A4	29/06/2015	Milling spindle requires repair	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A21	27/08/2015	Machine is unpowered	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A91	09/01/2016	Power supply failure detected	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A33	17/11/2015	Turret sections A & B showing leaks	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A9	02/06/2015	Turret A and B are leaking	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A56	26/02/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A40	08/03/2015	Machine is unpowered	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A28	30/08/2015	Leak in side B hydraulic line	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A98	18/08/2015	Unit lost electrical power	Michele Williams noted: Repair completed.	michele_williams
A87	15/01/2015	Leaks found at turrets A and B	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A32	28/07/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A97	13/04/2015	Turret sections A & B showing leaks	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A77	08/06/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A57	01/10/2015	Accumulators need checking and charging	Cristian Santos noted: Repair completed.	cristian_santos
A56	18/10/2015	Leak in side B hydraulic line	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A60	02/03/2015	Power supply failure detected	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A47	29/07/2015	Turret A and B are leaking	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A75	01/10/2015	Leak in side B hydraulic line	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A6	09/05/2015	Accumulator inspection and charging required	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A63	21/07/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: No additional information provided.	nathan_maldonado

A83	07/07/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A65	13/11/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A6	24/12/2015	Power supply failure detected	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A35	16/05/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A39	15/05/2015	Spindle fails to index, overfeeding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A65	07/11/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A16	21/02/2015	Accumulators need checking and charging	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A38	18/05/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A79	03/03/2015	Machine is unpowered	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A33	12/02/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A98	28/08/2015	Accumulator inspection and charging required	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A18	07/02/2015	Power supply failure detected	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A21	15/05/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A68	16/05/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A74	21/07/2015	Machine is unpowered	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A44	16/05/2015	Accumulators need checking and charging	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A45	31/08/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A18	21/09/2015	Milling spindle requires repair	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A68	13/05/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A28	05/06/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A39	20/09/2015	Machine is unpowered	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A49	28/12/2015	Milling spindle requires repair	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A74	28/06/2015	Milling spindle requires repair	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A81	27/05/2015	Leak in side B hydraulic line	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A80	19/02/2015	Power supply failure detected	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A69	03/10/2015	Accumulator inspection and charging required	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A93	25/03/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A71	27/08/2015	Repair work needed on milling spindle	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A29	15/12/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A9	27/08/2015	Unit lost electrical power	Michele Williams noted: Maintenance action successful.	michele_williams
A12	22/05/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A50	14/02/2015	Leaks found at turrets A and B	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A86	13/10/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A64	02/09/2015	Turret A and B are leaking	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A7	29/05/2015	Leak in side B hydraulic line	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A95	08/12/2015	Milling spindle requires repair	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A14	07/06/2015	Unit lost electrical power	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A72	01/01/2016	Machine is unpowered	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A77	05/12/2015	Unit lost electrical power	Michele Williams noted: No additional information provided.	michele_williams
A53	22/09/2015	Power supply failure detected	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A21	07/05/2015	Turret sections A & B showing leaks	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A55	31/12/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A71	10/04/2015	Leaks found at turrets A and B	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A40	12/07/2015	Hydraulic line leak on side B	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A39	27/11/2015	Turret A and B are leaking	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A98	01/09/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A84	20/08/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A86	30/06/2015	Machine is unpowered	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A84	14/10/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A48	23/11/2015	Turret A and B are leaking	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A83	15/01/2015	Machine is unpowered	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A89	01/03/2015	Leak in side B hydraulic line	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A90	01/12/2015	Spindle indexing error with overfeed	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A7	21/08/2015	Turret A and B are leaking	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A28	25/07/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A26	19/02/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A70	14/07/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A40	15/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A22	07/03/2015	Turret sections A & B showing leaks	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A16	24/05/2015	Hydraulic line leak on side B	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A60	16/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A27	14/06/2015	Machine is unpowered	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A87	24/02/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A15	07/07/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A5	22/05/2015	Power supply failure detected	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A26	23/06/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A42	17/05/2015	Accumulators need checking and charging	Michele Williams noted: No additional information provided.	michele_williams
A96	05/09/2015	Turret A and B are leaking	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A79	11/09/2015	Leak in side B hydraulic line	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A97	04/06/2015	Turret sections A & B showing leaks	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams

A14	26/09/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A39	03/03/2015	Leak in side B hydraulic line	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A8	27/09/2015	Spindle fails to index, overfeeding	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A90	04/05/2015	Maintenance on milling spindle needed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A82	14/04/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A61	24/03/2015	Repair work needed on milling spindle	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A50	14/05/2015	Spindle indexing error with overfeed	Michele Williams noted: Fixed and tested.	michele_williams
A56	27/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A77	13/09/2015	Maintenance on milling spindle needed	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A63	30/08/2015	Inspect and recharge accumulators	Cristian Santos noted: Detail not recorded.	cristian_santos
A67	05/01/2016	Accumulators need checking and charging	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A75	24/04/2015	Leak in side B hydraulic line	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A45	12/10/2015	Leak in side B hydraulic line	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A74	20/11/2015	Milling spindle requires repair	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A37	22/05/2015	Inspect and recharge accumulators	Michele Williams noted: No further details.	michele_williams
A91	11/08/2015	Inspect and recharge accumulators	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A32	05/01/2016	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A92	03/05/2015	Turret A and B are leaking	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A31	31/05/2015	Turret sections A & B showing leaks	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A90	11/05/2015	Unit lost electrical power	Michele Williams noted: Repair completed.	michele_williams
A41	16/08/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A72	14/07/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A63	03/04/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A17	19/03/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A36	19/06/2015	Unit lost electrical power	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A18	17/04/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A40	01/11/2015	Leak in side B hydraulic line	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A88	16/12/2015	Hydraulic line leak on side B	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A8	01/11/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A64	13/05/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: No additional information provided.	cristian_santos
A80	16/05/2015	Hydraulic line leak on side B	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A98	13/05/2015	Repair work needed on milling spindle	Michele Williams noted: Fixed and tested.	michele_williams
A73	10/05/2015	Turret A and B are leaking	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A34	03/01/2016	Milling spindle requires repair	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A68	17/01/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A46	16/01/2015	Unit lost electrical power	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A89	08/12/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A4	28/12/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A42	01/09/2015	Turret A and B are leaking	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A98	03/09/2015	Unit lost electrical power	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A85	06/04/2015	Spindle indexing error with overfeed	Michele Williams noted: Maintenance action successful.	michele_williams
A86	13/03/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A22	17/06/2015	Maintenance on milling spindle needed	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A3	01/02/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A27	06/07/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A68	11/05/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A18	21/03/2015	Machine is unpowered	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A97	21/01/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A11	10/06/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A95	13/12/2015	Spindle fails to index, overfeeding	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A78	29/11/2015	Unit lost electrical power	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A33	27/12/2015	Unit lost electrical power	Cristian Santos noted: Detail not recorded.	cristian_santos
A51	06/06/2015	Maintenance on milling spindle needed	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A13	16/11/2015	Accumulator inspection and charging required	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A42	07/07/2015	Repair work needed on milling spindle	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A12	16/06/2015	Repair work needed on milling spindle	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A31	03/09/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A66	23/07/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A60	28/03/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A20	25/03/2015	Turret A and B are leaking	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A90	28/12/2015	Turret sections A & B showing leaks	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A81	07/12/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: No further details.	cristian_santos
A2	21/10/2015	Accumulator inspection and charging required	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A12	30/08/2015	Spindle indexing error with overfeed	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A31	17/05/2015	Accumulators need checking and charging	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A96	02/04/2015	Accumulator inspection and charging required	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A88	22/11/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A15	09/09/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A89	28/08/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: No further details.	michele_williams
A85	14/08/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Maintenance action successful.	cristian_santos

A3	09/01/2016	Turret A and B are leaking	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A45	23/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A91	08/10/2015	Milling spindle requires repair	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A44	20/07/2015	Milling spindle requires repair	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A15	25/12/2015	Turret A and B are leaking	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A74	27/12/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A97	15/09/2015	Accumulator inspection and charging required	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A22	21/09/2015	Turret sections A & B showing leaks	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A40	22/04/2015	Repair work needed on milling spindle	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A57	24/05/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A62	28/07/2015	Hydraulic line leak on side B	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A72	08/08/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A82	28/12/2015	Turret A and B are leaking	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A62	11/01/2016	Maintenance on milling spindle needed	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A28	24/04/2015	Inspect and recharge accumulators	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A40	19/02/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A1	21/02/2015	Accumulators need checking and charging	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A26	21/04/2015	Hydraulic line leak on side B	Michele Williams noted: No additional information provided.	michele_williams
A34	26/03/2015	Unit lost electrical power	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A65	02/01/2016	Accumulator inspection and charging required	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A27	26/10/2015	Maintenance on milling spindle needed	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A53	06/10/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A55	13/01/2016	Repair work needed on milling spindle	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A5	16/01/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A63	31/01/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Repair completed.	cristian_santos
A12	01/09/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A99	23/11/2015	Leaks found at turrets A and B	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A15	04/11/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A20	06/04/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A53	19/09/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A88	23/02/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A14	31/07/2015	Inspect and recharge accumulators	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A75	19/11/2015	Power supply failure detected	Cristian Santos noted: No additional information provided.	cristian_santos
A22	28/06/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A67	03/04/2015	Unit lost electrical power	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A90	25/04/2015	Accumulator inspection and charging required	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A4	13/05/2015	Power supply failure detected	Michele Williams noted: Maintenance action successful.	michele_williams
A66	04/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A95	21/10/2015	Hydraulic line leak on side B	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A92	29/04/2015	Power supply failure detected	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A90	09/07/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A22	03/12/2015	Machine is unpowered	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A71	22/03/2015	Repair work needed on milling spindle	Michele Williams noted: Maintenance action successful.	michele_williams
A84	20/09/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A13	22/06/2015	Saw attachment gears are binding and grinding	Michele Williams noted: No further details.	michele_williams
A95	29/05/2015	Turret A and B are leaking	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A2	15/04/2015	Milling spindle requires repair	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A20	15/10/2015	Accumulators need checking and charging	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A52	19/06/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A40	08/05/2015	Leak in side B hydraulic line	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A89	12/06/2015	Maintenance on milling spindle needed	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A12	09/10/2015	Turret sections A & B showing leaks	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A90	28/11/2015	Power supply failure detected	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A35	06/05/2015	Machine is unpowered	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A17	05/02/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A76	22/07/2015	Maintenance on milling spindle needed	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A27	19/04/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A1	31/10/2015	Unit lost electrical power	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A28	14/05/2015	Power supply failure detected	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A81	29/10/2015	Spindle fails to index, overfeeding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A8	17/07/2015	Spindle indexing error with overfeed	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A56	24/02/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Detail not recorded.	cristian_santos
A28	01/07/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: System checked and accumulators charged.	michele_williams
A38	27/07/2015	Accumulators need checking and charging	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A68	12/11/2015	Inspect and recharge accumulators	Michele Williams noted: Fixed and tested.	michele_williams
A50	31/05/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A78	04/12/2015	Machine is unpowered	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A9	19/06/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A42	12/08/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A72	08/02/2015	Maintenance on milling spindle needed	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos

A96	13/03/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A80	24/06/2015	Power supply failure detected	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A30	26/04/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A95	11/09/2015	Maintenance on milling spindle needed	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A61	25/08/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A43	29/11/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A66	22/04/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A36	17/04/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A1	07/10/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Detail not recorded.	cristian_santos
A50	05/03/2015	Leaks found at turrets A and B	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A81	18/06/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A38	20/12/2015	Repair work needed on milling spindle	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A22	20/01/2015	Milling spindle requires repair	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A95	30/08/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A24	22/04/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A35	02/07/2015	Accumulator inspection and charging required	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A31	10/06/2015	Milling spindle requires repair	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A88	11/03/2015	Turret sections A & B showing leaks	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A35	03/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A92	09/06/2015	Hydraulic line leak on side B	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A7	25/02/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Maintenance action successful.	michele_williams
A14	26/03/2015	Hydraulic line leak on side B	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A51	04/03/2015	Machine is unpowered	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A55	17/10/2015	Power supply failure detected	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A68	20/07/2015	Spindle indexing error with overfeed	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A22	02/02/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A22	04/05/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A57	10/07/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A60	24/05/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A57	12/12/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A26	19/09/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A10	20/08/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A83	01/12/2015	Spindle indexing error with overfeed	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A34	18/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A79	06/08/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A39	31/10/2015	Spindle indexing error with overfeed	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A11	18/09/2015	Spindle indexing error with overfeed	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A15	19/04/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A82	01/03/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A74	01/04/2015	Unit lost electrical power	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A91	23/04/2015	Maintenance on milling spindle needed	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A43	30/03/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A90	21/02/2015	Turret sections A & B showing leaks	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A3	30/09/2015	Turret A and B are leaking	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A9	20/09/2015	Repair work needed on milling spindle	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A38	02/03/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A93	21/05/2015	Hydraulic line leak on side B	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A61	30/01/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A26	24/02/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: System checked and accumulators charged.	michele_williams
A92	03/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A47	12/03/2015	Turret A and B are leaking	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A21	16/07/2015	Accumulators need checking and charging	Cristian Santos noted: No further details.	cristian_santos
A94	09/08/2015	Milling spindle requires repair	Michele Williams noted: System checked and accumulators charged.	michele_williams
A69	05/07/2015	Accumulators need checking and charging	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A72	11/03/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A47	27/02/2015	Hydraulic line leak on side B	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A65	24/09/2015	Leaks found at turrets A and B	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A20	28/02/2015	Maintenance on milling spindle needed	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A17	25/05/2015	Turret sections A & B showing leaks	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A18	27/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A8	05/08/2015	Turret sections A & B showing leaks	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A58	24/03/2015	Spindle fails to index, overfeeding	Cristian Santos noted: No further details.	cristian_santos
A23	26/06/2015	Power supply failure detected	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A54	30/12/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A40	01/02/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A97	11/07/2015	Maintenance on milling spindle needed	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A36	25/06/2015	Spindle indexing error with overfeed	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A92	05/06/2015	Leaks found at turrets A and B	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A96	09/11/2015	Accumulator inspection and charging required	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A88	02/11/2015	Maintenance on milling spindle needed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams

A88	22/10/2015	Repair work needed on milling spindle	Michele Williams noted: Fixed and tested.	michele_williams
A29	13/06/2015	Turret sections A & B showing leaks	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A85	27/08/2015	Inspect and recharge accumulators	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A38	07/03/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A22	03/11/2015	Leak in side B hydraulic line	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A37	16/07/2015	Leak in side B hydraulic line	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A8	21/04/2015	Spindle fails to index, overfeeding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A99	23/10/2015	Turret A and B are leaking	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A77	05/03/2015	Power supply failure detected	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A20	04/03/2015	Repair work needed on milling spindle	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A26	19/12/2015	Hydraulic line leak on side B	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A70	09/03/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A63	18/03/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A9	31/05/2015	Accumulators need checking and charging	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A35	14/08/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A33	03/04/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A61	23/08/2015	Leaks found at turrets A and B	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A43	03/09/2015	Leak in side B hydraulic line	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A69	23/04/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A20	29/06/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A60	21/06/2015	Leaks found at turrets A and B	Michele Williams noted: Fixed and tested.	michele_williams
A43	12/10/2015	Leak in side B hydraulic line	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A93	17/02/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Detail not recorded.	cristian_santos
A22	29/01/2015	Hydraulic line leak on side B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A74	22/03/2015	Inspect and recharge accumulators	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A14	25/03/2015	Inspect and recharge accumulators	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A45	31/07/2015	Unit lost electrical power	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A10	27/08/2015	Hydraulic line leak on side B	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A31	15/05/2015	Spindle fails to index, overfeeding	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A25	08/05/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A68	22/06/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A77	02/04/2015	Machine is unpowered	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A31	16/12/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A69	30/04/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A35	07/05/2015	Accumulators need checking and charging	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A64	12/10/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A54	17/01/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A11	08/02/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A28	09/04/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A83	21/05/2015	Hydraulic line leak on side B	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A95	28/01/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A59	30/07/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A21	07/10/2015	Milling spindle requires repair	Cristian Santos noted: Fixed and tested.	cristian_santos
A57	09/08/2015	Turret sections A & B showing leaks	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A56	15/05/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A50	10/03/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Repair completed.	michele_williams
A68	15/07/2015	Accumulator inspection and charging required	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A66	12/08/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A43	26/12/2015	Leak in side B hydraulic line	Michele Williams noted: No additional information provided.	michele_williams
A55	11/04/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A86	30/05/2015	Spindle fails to index, overfeeding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A64	05/10/2015	Leak in side B hydraulic line	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A97	17/07/2015	Milling spindle requires repair	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A61	28/01/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A65	18/08/2015	Accumulators need checking and charging	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A21	07/11/2015	Hydraulic line leak on side B	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A27	23/03/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A32	04/11/2015	Machine is unpowered	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A86	14/03/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A78	07/02/2015	Power supply failure detected	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A39	10/02/2015	Inspect and recharge accumulators	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A38	19/08/2015	Machine is unpowered	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A22	21/03/2015	Turret A and B are leaking	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A19	02/05/2015	Leak in side B hydraulic line	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A81	20/04/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A76	01/05/2015	Inspect and recharge accumulators	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A25	08/06/2015	Power supply failure detected	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A98	12/08/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A54	24/09/2015	Hydraulic line leak on side B	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A8	14/04/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams

A2	18/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A86	07/01/2016	Repair work needed on milling spindle	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A34	30/08/2015	Power supply failure detected	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A74	02/09/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A57	13/12/2015	Inspect and recharge accumulators	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A45	18/08/2015	Turret sections A & B showing leaks	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A58	10/06/2015	Milling spindle requires repair	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A93	25/12/2015	Accumulator inspection and charging required	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A11	05/04/2015	Machine is unpowered	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A17	23/07/2015	Spindle indexing error with overfeed	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A49	31/08/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Repair completed.	michele_williams
A22	05/04/2015	Accumulator inspection and charging required	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A90	08/08/2015	Repair work needed on milling spindle	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A31	06/02/2015	Unit lost electrical power	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A85	25/07/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A9	11/06/2015	Maintenance on milling spindle needed	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A19	01/09/2015	Hydraulic line leak on side B	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A31	12/09/2015	Power supply failure detected	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A91	01/09/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A91	03/10/2015	Accumulators need checking and charging	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A90	22/05/2015	Accumulators need checking and charging	Michele Williams noted: Maintenance action successful.	michele_williams
A14	07/10/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A38	23/04/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A86	09/12/2015	Accumulators need checking and charging	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A89	17/08/2015	Turret sections A & B showing leaks	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A57	08/09/2015	Machine is unpowered	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A82	04/06/2015	Hydraulic line leak on side B	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A62	25/10/2015	Inspect and recharge accumulators	Cristian Santos noted: Repair completed.	cristian_santos
A63	20/03/2015	Turret sections A & B showing leaks	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A29	18/03/2015	Hydraulic line leak on side B	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A3	18/07/2015	Milling spindle requires repair	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A43	21/09/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A2	02/09/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A70	08/05/2015	Turret sections A & B showing leaks	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A72	10/01/2016	Milling spindle requires repair	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A24	28/01/2015	Accumulators need checking and charging	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A16	12/06/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A61	12/10/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A26	06/11/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A63	08/11/2015	Accumulator inspection and charging required	Michele Williams noted: Maintenance action successful.	michele_williams
A3	11/07/2015	Accumulators need checking and charging	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A6	20/04/2015	Machine is unpowered	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A43	31/03/2015	Turret sections A & B showing leaks	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A5	23/08/2015	Leak in side B hydraulic line	Cristian Santos noted: Maintenance action successful.	cristian_santos
A8	01/07/2015	Maintenance on milling spindle needed	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A46	21/04/2015	Turret sections A & B showing leaks	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A94	28/04/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A91	19/10/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A73	02/10/2015	Power supply failure detected	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A86	06/07/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Detail not recorded.	cristian_santos
A69	17/04/2015	Accumulators need checking and charging	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A65	02/02/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A2	10/09/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A56	11/10/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A37	16/07/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A44	28/03/2015	Turret sections A & B showing leaks	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A24	19/11/2015	Repair work needed on milling spindle	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A98	15/10/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A8	19/07/2015	Milling spindle requires repair	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A17	08/10/2015	Milling spindle requires repair	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A76	14/05/2015	Power supply failure detected	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A39	14/02/2015	Repair work needed on milling spindle	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A50	22/01/2015	Inspect and recharge accumulators	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A52	04/08/2015	Milling spindle requires repair	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A27	18/07/2015	Hydraulic line leak on side B	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A87	08/03/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A78	29/06/2015	Power supply failure detected	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A72	22/02/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A48	17/12/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A47	06/11/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos

A8	08/04/2015	Unit lost electrical power	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A17	27/10/2015	Milling spindle requires repair	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A47	13/05/2015	Leaks found at turrets A and B	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A60	27/05/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A7	05/07/2015	Spindle indexing error with overfeed	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A32	22/10/2015	Turret A and B are leaking	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A65	16/11/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A38	04/07/2015	Accumulators need checking and charging	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A85	27/05/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A67	28/05/2015	Repair work needed on milling spindle	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A5	07/12/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A85	16/03/2015	Hydraulic line leak on side B	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A23	24/10/2015	Inspect and recharge accumulators	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A88	30/03/2015	Inspect and recharge accumulators	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A62	01/11/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A88	03/02/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A74	06/02/2015	Inspect and recharge accumulators	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A78	20/08/2015	Hydraulic line leak on side B	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A71	23/03/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A61	15/08/2015	Accumulator inspection and charging required	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A90	11/03/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A12	06/01/2016	Unit lost electrical power	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A47	22/08/2015	Milling spindle requires repair	Michele Williams noted: Detail not recorded.	michele_williams
A40	30/10/2015	Spindle fails to index, overfeeding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A28	06/12/2015	Machine is unpowered	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A24	31/05/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: No additional information provided.	michele_williams
A44	15/11/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A46	02/02/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A77	03/02/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: No further details.	cristian_santos
A33	07/10/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A28	29/10/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A69	25/07/2015	Inspect and recharge accumulators	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A41	25/02/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A56	07/09/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A83	22/10/2015	Spindle indexing error with overfeed	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A42	09/01/2016	Milling spindle requires repair	Michele Williams noted: Repair completed.	michele_williams
A5	10/06/2015	Spindle fails to index, overfeeding	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A54	30/01/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A74	23/03/2015	Turret A and B are leaking	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A1	19/02/2015	Hydraulic line leak on side B	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A20	08/10/2015	Milling spindle requires repair	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A88	22/05/2015	Unit lost electrical power	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A16	02/07/2015	Power supply failure detected	Gina Moore noted: No further details.	gina_moore, dylan_miller
A97	18/05/2015	Leaks found at turrets A and B	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A51	19/07/2015	Inspect and recharge accumulators	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A41	04/09/2015	Milling spindle requires repair	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A99	23/05/2015	Unit lost electrical power	Cristian Santos noted: Maintenance action successful.	cristian_santos
A69	08/04/2015	Milling spindle requires repair	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A70	03/08/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A82	30/08/2015	Maintenance on milling spindle needed	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A41	22/07/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A45	15/03/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A1	26/05/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A82	26/12/2015	Leaks found at turrets A and B	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A17	20/09/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A18	02/02/2015	Repair work needed on milling spindle	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A72	17/11/2015	Hydraulic line leak on side B	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A19	16/10/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A47	25/09/2015	Hydraulic line leak on side B	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A29	21/08/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A43	04/10/2015	Unit lost electrical power	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A31	30/03/2015	Hydraulic line leak on side B	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A35	06/01/2016	Power supply failure detected	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A99	10/01/2016	Maintenance on milling spindle needed	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A26	21/12/2015	Spindle indexing error with overfeed	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A11	12/11/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A88	04/03/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A99	16/10/2015	Spindle indexing error with overfeed	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A76	22/10/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A19	06/01/2016	Turret A and B are leaking	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams

A35	04/02/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A78	28/04/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A56	04/08/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A79	04/03/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A58	06/04/2015	Inspect and recharge accumulators	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A70	23/05/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A27	18/04/2015	Maintenance on milling spindle needed	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A45	19/09/2015	Maintenance on milling spindle needed	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A15	02/09/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A57	16/02/2015	Repair work needed on milling spindle	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A32	04/01/2016	Power supply failure detected	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A68	05/10/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A4	04/06/2015	Accumulators need checking and charging	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A26	05/09/2015	Milling spindle requires repair	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A93	21/09/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A55	23/07/2015	Spindle indexing error with overfeed	Gina Moore noted: No further details.	gina_moore, dylan_miller
A71	04/04/2015	Accumulators need checking and charging	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A62	25/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A71	08/01/2016	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A31	10/05/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A84	02/09/2015	Leaks found at turrets A and B	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A37	14/04/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A44	07/10/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A48	28/11/2015	Milling spindle requires repair	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A11	01/12/2015	Milling spindle requires repair	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A65	02/05/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A52	21/08/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A98	22/01/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A16	26/10/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A13	05/09/2015	Hydraulic line leak on side B	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A30	29/07/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A39	06/04/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A51	21/08/2015	Milling spindle requires repair	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A32	13/03/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A81	22/04/2015	Machine is unpowered	Michele Williams noted: Fixed and tested.	michele_williams
A24	02/02/2015	Turret sections A & B showing leaks	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A70	06/07/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A41	27/03/2015	Spindle indexing error with overfeed	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A33	13/11/2015	Accumulators need checking and charging	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A58	13/02/2015	Spindle indexing error with overfeed	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A58	20/10/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A33	03/06/2015	Repair work needed on milling spindle	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A89	18/08/2015	Spindle indexing error with overfeed	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A78	30/06/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A53	11/12/2015	Turret A and B are leaking	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A49	28/10/2015	Turret sections A & B showing leaks	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A86	10/05/2015	Milling spindle requires repair	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A77	29/07/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A16	24/06/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A71	01/01/2016	Spindle fails to index, overfeeding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A74	31/10/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A3	18/02/2015	Machine is unpowered	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A69	04/08/2015	Spindle indexing error with overfeed	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A41	26/08/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A48	03/02/2015	Machine is unpowered	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A93	19/09/2015	Machine is unpowered	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A69	14/09/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A98	13/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A3	20/12/2015	Unit lost electrical power	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A55	21/07/2015	Power supply failure detected	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A9	29/09/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A34	24/08/2015	Power supply failure detected	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A40	27/10/2015	Accumulator inspection and charging required	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A30	13/06/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A7	26/10/2015	Power supply failure detected	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A26	09/12/2015	Maintenance on milling spindle needed	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A32	10/01/2016	Saw attachment gears are binding and grinding	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A19	08/01/2016	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A19	01/05/2015	Hydraulic line leak on side B	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A89	03/06/2015	Spindle indexing error with overfeed	Cristian Santos noted: No further details.	cristian_santos

A12	20/12/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A68	20/08/2015	Hydraulic line leak on side B	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A45	30/10/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A44	26/04/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A1	12/03/2015	Milling spindle requires repair	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A55	21/06/2015	Unit lost electrical power	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A87	30/07/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A29	03/11/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A67	12/02/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A99	18/01/2015	Turret A and B are leaking	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A10	14/11/2015	Maintenance on milling spindle needed	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A88	30/12/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A75	29/12/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A37	12/09/2015	Spindle indexing error with overfeed	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A7	19/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A21	31/08/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A83	07/03/2015	Machine is unpowered	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A80	19/07/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A70	25/10/2015	Power supply failure detected	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A11	31/10/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A61	12/06/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A95	04/02/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A8	23/12/2015	Milling spindle requires repair	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A68	15/07/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A96	31/03/2015	Accumulators need checking and charging	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A94	13/02/2015	Maintenance on milling spindle needed	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A3	09/12/2015	Unit lost electrical power	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A25	15/03/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A48	04/06/2015	Spindle indexing error with overfeed	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A49	09/11/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A51	09/08/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A83	09/01/2016	Inspect and recharge accumulators	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A86	04/04/2015	Accumulators need checking and charging	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A68	20/01/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A14	03/01/2016	Repair work needed on milling spindle	Gina Moore noted: No further details.	gina_moore, dylan_miller
A47	18/10/2015	Turret sections A & B showing leaks	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A70	24/09/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A79	14/12/2015	Inspect and recharge accumulators	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A70	06/01/2016	Saw attachment is leaking hydraulics	Cristian Santos noted: Repair completed.	cristian_santos
A77	20/08/2015	Machine is unpowered	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A95	04/04/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A28	14/04/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A16	02/02/2015	Leak in side B hydraulic line	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A28	02/06/2015	Accumulator inspection and charging required	Michele Williams noted: No additional information provided.	michele_williams
A73	29/08/2015	Machine is unpowered	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A37	12/02/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A22	08/09/2015	Accumulators need checking and charging	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A95	13/11/2015	Leaks found at turrets A and B	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A32	20/05/2015	Machine is unpowered	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A54	17/04/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A44	26/10/2015	Hydraulic line leak on side B	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A12	23/09/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A72	16/02/2015	Power supply failure detected	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A95	15/07/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A49	12/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A85	27/07/2015	Repair work needed on milling spindle	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A79	13/10/2015	Milling spindle requires repair	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A6	07/01/2016	Milling spindle requires repair	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A58	15/09/2015	Spindle indexing error with overfeed	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A57	01/09/2015	Machine is unpowered	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A97	31/07/2015	Leaks found at turrets A and B	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A34	08/12/2015	Milling spindle requires repair	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A81	11/12/2015	Machine is unpowered	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A65	12/10/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A13	05/08/2015	Repair work needed on milling spindle	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A85	16/06/2015	Machine is unpowered	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A79	16/06/2015	Inspect and recharge accumulators	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A79	06/05/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A47	26/07/2015	Milling spindle requires repair	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A29	26/01/2015	Spindle indexing error with overfeed	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams

A73	04/11/2015	Leak in side B hydraulic line	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A9	13/01/2016	Hydraulic hose on side B is leaking	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A69	31/05/2015	Turret A and B are leaking	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A2	18/12/2015	Power supply failure detected	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A68	24/09/2015	Turret A and B are leaking	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A48	03/07/2015	Power supply failure detected	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A72	18/06/2015	Accumulators need checking and charging	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A65	21/08/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A84	18/02/2015	Machine is unpowered	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A81	04/12/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A23	17/07/2015	Milling spindle requires repair	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A88	26/12/2015	Spindle fails to index, overfeeding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A19	09/05/2015	Hydraulic line leak on side B	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A76	25/07/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A48	13/11/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A39	17/07/2015	Repair work needed on milling spindle	Michele Williams noted: Repair completed.	michele_williams
A85	30/11/2015	Inspect and recharge accumulators	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A15	03/05/2015	Power supply failure detected	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A76	05/07/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A55	17/01/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: No further details.	michele_williams
A6	07/10/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A57	09/02/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A88	17/10/2015	Unit lost electrical power	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A50	05/09/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A15	28/03/2015	Unit lost electrical power	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A72	01/05/2015	Accumulator inspection and charging required	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A23	07/11/2015	Unit lost electrical power	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A31	12/05/2015	Machine is unpowered	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A16	26/05/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A2	04/06/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A8	28/01/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A57	24/10/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A69	22/11/2015	Accumulator inspection and charging required	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A54	25/01/2015	Inspect and recharge accumulators	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A27	04/02/2015	Turret A and B are leaking	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A63	20/01/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A29	12/02/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A96	15/09/2015	Spindle fails to index, overfeeding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A3	30/08/2015	Machine is unpowered	Gina Moore noted: No further details.	gina_moore, dylan_miller
A38	26/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A38	09/02/2015	Repair work needed on milling spindle	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A92	25/10/2015	Maintenance on milling spindle needed	Michele Williams noted: Detail not recorded.	michele_williams
A91	25/02/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A45	19/04/2015	Milling spindle requires repair	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A30	27/02/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A93	13/08/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A85	22/05/2015	Unit lost electrical power	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A42	11/06/2015	Power supply failure detected	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A28	24/05/2015	Repair work needed on milling spindle	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A32	25/05/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A12	22/07/2015	Accumulator inspection and charging required	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A24	19/11/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A49	03/05/2015	Turret A and B are leaking	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A2	01/06/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A49	21/08/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A61	30/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A27	26/04/2015	Power supply failure detected	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A95	26/08/2015	Accumulators need checking and charging	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A16	11/03/2015	Repair work needed on milling spindle	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A57	06/12/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A18	20/11/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A71	14/02/2015	Repair work needed on milling spindle	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A45	06/08/2015	Accumulator inspection and charging required	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A68	08/01/2016	Inspect and recharge accumulators	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A79	07/01/2016	Accumulators need checking and charging	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A1	08/10/2015	Leak in side B hydraulic line	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A67	04/09/2015	Accumulators need checking and charging	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A84	29/09/2015	Accumulator inspection and charging required	Cristian Santos noted: No further details.	cristian_santos
A92	03/12/2015	Milling spindle requires repair	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A16	13/09/2015	Unit lost electrical power	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller

A45	05/03/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A37	24/05/2015	Turret A and B are leaking	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A69	22/09/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A89	18/12/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A10	08/08/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A43	26/11/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A69	05/07/2015	Machine is unpowered	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A93	26/10/2015	Machine is unpowered	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A38	29/07/2015	Spindle indexing error with overfeed	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A33	14/06/2015	Unit lost electrical power	Cristian Santos noted: No additional information provided.	cristian_santos
A5	19/03/2015	Accumulators need checking and charging	Michele Williams noted: Fixed and tested.	michele_williams
A45	06/08/2015	Turret A and B are leaking	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A5	10/01/2016	Indexing issue causing overfeed on spindle	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A41	19/05/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A75	06/05/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A59	28/03/2015	Milling spindle requires repair	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A72	30/10/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A71	07/05/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A60	15/10/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A7	11/01/2016	Accumulator inspection and charging required	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A79	01/07/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A53	02/07/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A41	05/07/2015	Spindle indexing error with overfeed	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A13	03/08/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A88	26/12/2015	Saw attachment gears are binding and grinding	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A50	25/08/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A7	13/03/2015	Accumulators need checking and charging	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A31	01/02/2015	Leak in side B hydraulic line	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A98	19/08/2015	Accumulators need checking and charging	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A12	16/03/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A84	09/04/2015	Unit lost electrical power	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A46	21/07/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A50	30/04/2015	Hydraulic line leak on side B	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A55	19/08/2015	Machine is unpowered	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A4	04/10/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A61	05/08/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A9	20/07/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A90	06/05/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A33	02/12/2015	Inspect and recharge accumulators	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A34	03/10/2015	Spindle indexing error with overfeed	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A65	29/04/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A91	16/05/2015	Turret A and B are leaking	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A45	06/01/2016	Saw attachment gears are binding and grinding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A22	13/10/2015	Turret A and B are leaking	Cristian Santos noted: Maintenance action successful.	cristian_santos
A61	22/02/2015	Turret A and B are leaking	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A26	16/01/2015	Repair work needed on milling spindle	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A10	01/08/2015	Turret sections A & B showing leaks	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A39	03/10/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A66	19/11/2015	Hydraulic line leak on side B	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A6	11/01/2016	Turret A and B are leaking	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A34	23/01/2015	Machine is unpowered	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A93	24/07/2015	Spindle fails to index, overfeeding	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A90	14/11/2015	Machine is unpowered	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A25	29/10/2015	Milling spindle requires repair	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A25	14/05/2015	Accumulator inspection and charging required	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A20	19/10/2015	Milling spindle requires repair	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A36	13/02/2015	Accumulator inspection and charging required	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A32	09/08/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A74	13/01/2016	Hydraulic line leak on side B	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A27	24/11/2015	Inspect and recharge accumulators	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A58	19/04/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A42	06/12/2015	Unit lost electrical power	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A9	01/06/2015	Unit lost electrical power	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A67	20/09/2015	Milling spindle requires repair	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A56	22/07/2015	Spindle indexing error with overfeed	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A28	08/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A42	28/10/2015	Unit lost electrical power	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A11	30/01/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A18	03/04/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A69	17/07/2015	Accumulators need checking and charging	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams

A57	08/10/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A38	05/09/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A6	19/06/2015	Leak in side B hydraulic line	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A29	16/06/2015	Accumulator inspection and charging required	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A94	04/07/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A77	06/07/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A13	23/01/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A67	12/11/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A8	17/08/2015	Leak in side B hydraulic line	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A33	19/02/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A32	07/03/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A75	10/09/2015	Accumulator inspection and charging required	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A27	12/07/2015	Accumulator inspection and charging required	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A22	15/05/2015	Repair work needed on milling spindle	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A13	15/07/2015	Unit lost electrical power	Michele Williams noted: Detail not recorded.	michele_williams
A25	02/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A37	27/10/2015	Hydraulic line leak on side B	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A40	02/08/2015	Inspect and recharge accumulators	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A76	02/05/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A1	04/11/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A36	25/04/2015	Leaks found at turrets A and B	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A3	19/11/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A78	16/04/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A35	15/11/2015	Accumulator inspection and charging required	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A33	17/06/2015	Milling spindle requires repair	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A48	28/08/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A62	28/01/2015	Inspect and recharge accumulators	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A72	17/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A37	02/04/2015	Unit lost electrical power	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A27	10/07/2015	Accumulator inspection and charging required	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A36	24/01/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A71	24/12/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A49	02/12/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A83	01/12/2015	Turret A and B are leaking	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A73	03/05/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A58	11/09/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A51	29/01/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A2	13/06/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A10	18/01/2015	Leaks found at turrets A and B	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A46	27/05/2015	Accumulator inspection and charging required	Michele Williams noted: System checked and accumulators charged.	michele_williams
A88	28/01/2015	Spindle fails to index, overfeeding	Michele Williams noted: Fixed and tested.	michele_williams
A87	26/04/2015	Inspect and recharge accumulators	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A19	05/05/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A59	29/09/2015	Leaks found at turrets A and B	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A92	11/08/2015	Inspect and recharge accumulators	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A88	09/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A49	01/08/2015	Hydraulic line leak on side B	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A41	15/02/2015	Hydraulic line leak on side B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A52	12/11/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A26	25/05/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A57	28/08/2015	Power supply failure detected	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A20	21/09/2015	Power supply failure detected	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A26	23/10/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A14	27/07/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A13	02/03/2015	Machine is unpowered	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A24	15/07/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A62	28/03/2015	Unit lost electrical power	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A73	13/12/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A26	08/02/2015	Turret sections A & B showing leaks	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A75	26/02/2015	Leaks found at turrets A and B	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A27	21/04/2015	Leak in side B hydraulic line	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A69	13/04/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A60	07/11/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A93	23/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A71	17/06/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A84	17/04/2015	Accumulator inspection and charging required	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A11	31/10/2015	Machine is unpowered	Cristian Santos noted: Repair completed.	cristian_santos
A34	23/05/2015	Saw attachment gears are binding and grinding	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A13	28/09/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A18	19/07/2015	Machine is unpowered	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos

A21	25/07/2015	Power supply failure detected	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A70	23/09/2015	Power supply failure detected	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A65	09/12/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A78	14/05/2015	Leak in side B hydraulic line	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A33	23/07/2015	Power supply failure detected	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A64	20/01/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A51	27/08/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A87	22/04/2015	Inspect and recharge accumulators	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A31	21/06/2015	Accumulators need checking and charging	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A84	07/02/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A55	31/12/2015	Spindle indexing error with overfeed	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A73	02/04/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A9	28/05/2015	Leaks found at turrets A and B	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A14	21/07/2015	Inspect and recharge accumulators	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A94	20/04/2015	Power supply failure detected	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A59	10/03/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A28	14/08/2015	Unit lost electrical power	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A76	05/03/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A35	17/08/2015	Maintenance on milling spindle needed	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A34	22/11/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A2	29/05/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A87	12/02/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A38	29/11/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A54	07/01/2016	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A17	11/12/2015	Power supply failure detected	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A32	16/02/2015	Spindle indexing error with overfeed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A11	07/05/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A72	16/08/2015	Power supply failure detected	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A90	10/08/2015	Turret sections A & B showing leaks	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A37	05/06/2015	Leak in side B hydraulic line	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A42	06/03/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A16	20/06/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A94	13/11/2015	Accumulator inspection and charging required	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A97	09/06/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A1	02/01/2016	Machine is unpowered	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A80	27/06/2015	Power supply failure detected	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A75	04/06/2015	Unit lost electrical power	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A43	13/08/2015	Turret sections A & B showing leaks	Michele Williams noted: System checked and accumulators charged.	michele_williams
A90	07/02/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A76	16/04/2015	Milling spindle requires repair	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A55	08/12/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A49	27/08/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A48	22/02/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A92	29/10/2015	Inspect and recharge accumulators	Michele Williams noted: System checked and accumulators charged.	michele_williams
A77	13/06/2015	Accumulators need checking and charging	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A14	31/12/2015	Spindle indexing error with overfeed	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A51	19/01/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Repair completed.	cristian_santos
A27	24/01/2015	Repair work needed on milling spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A12	18/06/2015	Hydraulic line leak on side B	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A74	02/05/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A78	26/04/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A95	17/06/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A58	12/07/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A88	10/12/2015	Leak in side B hydraulic line	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A92	22/10/2015	Accumulator inspection and charging required	Cristian Santos noted: Fixed and tested.	cristian_santos
A57	23/11/2015	Spindle indexing error with overfeed	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A89	01/01/2016	Spindle indexing error with overfeed	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A76	21/12/2015	Leak in side B hydraulic line	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A83	08/11/2015	Leaks found at turrets A and B	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A69	25/06/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: No further details.	gina_moore, dylan_miller
A28	24/07/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A23	12/09/2015	Leak in side B hydraulic line	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A74	27/09/2015	Inspect and recharge accumulators	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A40	19/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A21	18/05/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A51	20/10/2015	Accumulator inspection and charging required	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A38	30/12/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A25	16/01/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A63	07/11/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A12	22/07/2015	Milling spindle requires repair	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos

A66	17/07/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A2	26/09/2015	Accumulator inspection and charging required	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A53	03/04/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A18	23/04/2015	Accumulator inspection and charging required	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A29	16/08/2015	Turret sections A & B showing leaks	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A70	05/05/2015	Unit lost electrical power	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A29	18/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A73	24/09/2015	Spindle indexing error with overfeed	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A15	06/10/2015	Leak in side B hydraulic line	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A7	08/12/2015	Spindle indexing error with overfeed	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A2	09/12/2015	Accumulator inspection and charging required	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A57	21/08/2015	Unit lost electrical power	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A53	09/11/2015	Maintenance on milling spindle needed	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A16	28/08/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A38	25/07/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A10	17/10/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A78	02/03/2015	Unit lost electrical power	Michele Williams noted: Fixed and tested.	michele_williams
A42	12/12/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A71	02/05/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: No further details.	nathan_maldonado
A35	18/05/2015	Hydraulic line leak on side B	Cristian Santos noted: No additional information provided.	cristian_santos
A27	13/03/2015	Leaks found at turrets A and B	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A29	01/05/2015	Accumulators need checking and charging	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A26	04/08/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A52	27/04/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: No further details.	cristian_santos
A15	09/06/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: No further details.	nathan_maldonado
A40	30/01/2015	Accumulators need checking and charging	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A1	25/07/2015	Hydraulic line leak on side B	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A78	18/02/2015	Spindle indexing error with overfeed	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A53	01/07/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A65	25/12/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A44	16/10/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A87	23/01/2015	Unit lost electrical power	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A98	24/03/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A27	22/11/2015	Hydraulic line leak on side B	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A67	01/01/2016	Spindle indexing error with overfeed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A82	25/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A61	09/09/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A96	03/01/2016	Grinding noise from tight gears on saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A61	15/08/2015	Turret sections A & B showing leaks	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A21	14/07/2015	Machine is unpowered	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A21	15/10/2015	Maintenance on milling spindle needed	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A48	30/07/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A35	26/10/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A79	17/11/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A10	03/12/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A14	14/11/2015	Accumulators need checking and charging	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A21	12/12/2015	Accumulators need checking and charging	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A99	01/12/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A7	22/06/2015	Unit lost electrical power	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A3	12/06/2015	Accumulators need checking and charging	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A60	28/03/2015	Repair work needed on milling spindle	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A66	19/02/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A6	16/01/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A59	05/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A54	19/01/2015	Leak in side B hydraulic line	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A23	21/02/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Fixed and tested.	michele_williams
A49	28/12/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A74	09/11/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A84	03/07/2015	Unit lost electrical power	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A3	03/10/2015	Power supply failure detected	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A15	27/10/2015	Turret sections A & B showing leaks	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A66	24/09/2015	Maintenance on milling spindle needed	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A34	17/10/2015	Maintenance on milling spindle needed	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A38	16/01/2015	Hydraulic line leak on side B	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A77	17/06/2015	Maintenance on milling spindle needed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A7	13/10/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A37	18/09/2015	Leaks found at turrets A and B	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A17	01/01/2016	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A93	31/07/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A70	05/07/2015	Turret sections A & B showing leaks	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams

A7	04/04/2015	Inspect and recharge accumulators	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A25	30/06/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A99	10/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A47	25/07/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: System checked and accumulators charged.	michele_williams
A85	04/08/2015	Turret A and B are leaking	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A49	12/01/2016	Inspect and recharge accumulators	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A21	05/04/2015	Inspect and recharge accumulators	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A67	10/07/2015	Repair work needed on milling spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A98	25/03/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A29	29/03/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A99	28/09/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A9	02/04/2015	Accumulators need checking and charging	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A83	06/04/2015	Turret sections A & B showing leaks	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A31	07/01/2016	Saw attachment gears are binding and grinding	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A28	30/03/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A72	11/05/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A9	10/03/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A74	21/09/2015	Accumulator inspection and charging required	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A12	28/04/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A6	18/01/2015	Turret sections A & B showing leaks	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A18	25/09/2015	Spindle indexing error with overfeed	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A63	25/12/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A48	21/04/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A22	15/12/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A83	16/09/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A44	08/06/2015	Hydraulic line leak on side B	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A18	30/04/2015	Turret sections A & B showing leaks	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A14	10/04/2015	Unit lost electrical power	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A18	15/07/2015	Inspect and recharge accumulators	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A84	06/09/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A23	02/08/2015	Leak in side B hydraulic line	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A85	09/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A55	21/03/2015	Machine is unpowered	Cristian Santos noted: Fixed and tested.	cristian_santos
A10	02/03/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: No additional information provided.	michele_williams
A58	06/10/2015	Milling spindle requires repair	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A25	06/10/2015	Accumulators need checking and charging	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A49	17/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A98	11/12/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A74	04/02/2015	Accumulators need checking and charging	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A19	27/01/2015	Leak in side B hydraulic line	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A82	25/03/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A95	13/05/2015	Accumulator inspection and charging required	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A50	05/12/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A20	15/03/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A41	20/02/2015	Unit lost electrical power	Michele Williams noted: Fixed and tested.	michele_williams
A43	07/02/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A96	16/09/2015	Power supply failure detected	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A92	02/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A63	30/10/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A31	05/03/2015	Accumulators need checking and charging	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A24	09/08/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A14	30/11/2015	Spindle indexing error with overfeed	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A5	06/05/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A62	19/10/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A52	18/05/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A55	16/07/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A28	09/04/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Repair completed.	cristian_santos
A5	06/04/2015	Accumulators need checking and charging	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A9	21/02/2015	Maintenance on milling spindle needed	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A81	01/01/2016	Milling spindle requires repair	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A91	23/02/2015	Milling spindle requires repair	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A46	13/01/2016	Accumulator inspection and charging required	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A55	21/12/2015	Turret A and B are leaking	Cristian Santos noted: Fixed and tested.	cristian_santos
A98	08/02/2015	Turret A and B are leaking	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A26	06/04/2015	Maintenance on milling spindle needed	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A5	11/06/2015	Power supply failure detected	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A40	12/03/2015	Turret A and B are leaking	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A37	13/01/2016	Milling spindle requires repair	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A94	01/12/2015	Repair work needed on milling spindle	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A90	14/12/2015	Spindle indexing error with overfeed	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams

A7	19/06/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A63	13/03/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A94	23/03/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Fixed and tested.	michele_williams
A32	03/03/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A19	19/01/2015	Spindle indexing error with overfeed	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A93	16/08/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A1	28/08/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A22	06/04/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A19	23/06/2015	Hydraulic hose on side B is leaking	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A81	14/02/2015	Milling spindle requires repair	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A64	31/08/2015	Machine is unpowered	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A76	01/05/2015	Machine is unpowered	Cristian Santos noted: Detail not recorded.	cristian_santos
A37	29/06/2015	Inspect and recharge accumulators	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A75	06/03/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A54	30/12/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A20	31/08/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A55	10/02/2015	Accumulator inspection and charging required	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A1	26/03/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A83	25/11/2015	Power supply failure detected	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A56	09/08/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A52	08/09/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A13	03/08/2015	Leak in side B hydraulic line	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A58	20/06/2015	Leak in side B hydraulic line	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A15	16/05/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A42	26/02/2015	Turret sections A & B showing leaks	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A20	05/01/2016	Maintenance on milling spindle needed	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A59	04/11/2015	Milling spindle requires repair	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A18	03/07/2015	Milling spindle requires repair	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A35	15/06/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Maintenance action successful.	cristian_santos
A80	27/09/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A20	10/08/2015	Turret A and B are leaking	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A11	16/04/2015	Leaks found at turrets A and B	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A88	03/09/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A39	11/06/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A27	20/12/2015	Leaks found at turrets A and B	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A35	26/01/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A52	27/11/2015	Power supply failure detected	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A54	24/07/2015	Leak in side B hydraulic line	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A53	20/01/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A77	17/06/2015	Leak in side B hydraulic line	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A63	11/10/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A12	15/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Detail not recorded.	michele_williams
A59	14/06/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A35	28/03/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A10	17/07/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A87	22/05/2015	Unit lost electrical power	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A9	31/07/2015	Turret sections A & B showing leaks	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A11	16/05/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A60	08/07/2015	Spindle indexing error with overfeed	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A86	16/12/2015	Repair work needed on milling spindle	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A58	04/12/2015	Spindle indexing error with overfeed	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A10	26/02/2015	Milling spindle requires repair	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A35	12/09/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A74	05/08/2015	Leak in side B hydraulic line	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A23	01/01/2016	Hydraulic fluid leak at saw attachment	Michele Williams noted: System checked and accumulators charged.	michele_williams
A72	25/01/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A75	16/06/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A46	31/01/2015	Machine is unpowered	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A56	02/05/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A41	14/01/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A32	20/01/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A31	15/12/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A18	30/05/2015	Machine is unpowered	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A57	02/08/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A73	22/10/2015	Leak in side B hydraulic line	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A76	30/04/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A85	09/02/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A45	21/07/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A73	27/03/2015	Leaks found at turrets A and B	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A4	17/08/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller

A18	14/11/2015	Unit lost electrical power	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A49	14/12/2015	Maintenance on milling spindle needed	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A80	12/10/2015	Milling spindle requires repair	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A59	17/09/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A90	26/01/2015	Accumulator inspection and charging required	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A15	30/03/2015	Hydraulic line leak on side B	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A14	12/03/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A13	28/06/2015	Leak in side B hydraulic line	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A68	25/10/2015	Repair work needed on milling spindle	Cristian Santos noted: Repair completed.	cristian_santos
A44	14/12/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A77	17/04/2015	Inspect and recharge accumulators	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A33	01/01/2016	Indexing issue causing overfeed on spindle	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A65	20/04/2015	Spindle fails to index, overfeeding	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A5	10/06/2015	Power supply failure detected	Michele Williams noted: Maintenance action successful.	michele_williams
A46	03/08/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A22	15/03/2015	Leak in side B hydraulic line	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A97	26/10/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A38	25/03/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A8	18/07/2015	Turret A and B are leaking	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A82	07/05/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A31	20/06/2015	Power supply failure detected	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A78	28/01/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A48	23/01/2015	Accumulators need checking and charging	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A96	15/07/2015	Turret sections A & B showing leaks	Cristian Santos noted: Fixed and tested.	cristian_santos
A96	03/10/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A15	17/02/2015	Turret A and B are leaking	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A70	25/10/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A21	01/09/2015	Inspect and recharge accumulators	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A69	24/02/2015	Power supply failure detected	Michele Williams noted: Detail not recorded.	michele_williams
A26	31/10/2015	Milling spindle requires repair	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A47	19/05/2015	Repair work needed on milling spindle	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A16	16/04/2015	Machine is unpowered	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A47	09/05/2015	Turret sections A & B showing leaks	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A46	12/04/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A26	05/08/2015	Power supply failure detected	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A19	21/01/2015	Spindle fails to index, overfeeding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A83	21/03/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A15	04/10/2015	Unit lost electrical power	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A21	03/09/2015	Power supply failure detected	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A64	26/05/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A63	21/06/2015	Leaks found at turrets A and B	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A39	18/05/2015	Turret A and B are leaking	Michele Williams noted: Maintenance action successful.	michele_williams
A63	06/01/2016	Inspect and recharge accumulators	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A79	06/01/2016	Repair work needed on milling spindle	Michele Williams noted: No additional information provided.	michele_williams
A61	01/06/2015	Spindle indexing error with overfeed	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A13	21/03/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A44	08/06/2015	Unit lost electrical power	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A58	20/11/2015	Unit lost electrical power	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A78	07/07/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A63	15/08/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A30	26/10/2015	Machine is unpowered	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A13	27/06/2015	Power supply failure detected	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A4	10/06/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A14	23/12/2015	Hydraulic line leak on side B	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A50	18/01/2015	Maintenance on milling spindle needed	Michele Williams noted: No additional information provided.	michele_williams
A73	13/07/2015	Accumulators need checking and charging	Michele Williams noted: Maintenance action successful.	michele_williams
A91	03/07/2015	Accumulator inspection and charging required	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A12	16/08/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A51	26/05/2015	Hydraulic line leak on side B	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A26	02/11/2015	Turret A and B are leaking	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A61	24/06/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A23	12/02/2015	Accumulator inspection and charging required	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A21	15/10/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A22	18/06/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A99	22/08/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A70	01/11/2015	Power supply failure detected	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A48	21/10/2015	Power supply failure detected	Cristian Santos noted: Maintenance action successful.	cristian_santos
A43	20/06/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A47	08/02/2015	Spindle indexing error with overfeed	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A96	19/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos

A35	19/07/2015	Accumulator inspection and charging required	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A61	29/09/2015	Milling spindle requires repair	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A78	27/06/2015	Leaks found at turrets A and B	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A7	26/08/2015	Machine is unpowered	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A3	20/08/2015	Spindle indexing error with overfeed	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A58	18/06/2015	Spindle indexing error with overfeed	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A27	30/05/2015	Unit lost electrical power	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A53	16/01/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A81	10/01/2016	Spindle fails to index, overfeeding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A54	31/10/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A43	30/12/2015	Repair work needed on milling spindle	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A36	20/05/2015	Machine is unpowered	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A71	02/07/2015	Turret sections A & B showing leaks	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A77	27/05/2015	Spindle fails to index, overfeeding	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A10	22/07/2015	Leaks found at turrets A and B	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A65	27/09/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A3	28/07/2015	Unit lost electrical power	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A72	26/11/2015	Milling spindle requires repair	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A76	14/04/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A7	10/11/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A18	09/07/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: No further details.	cristian_santos
A28	20/06/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A59	21/02/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A97	09/02/2015	Turret A and B are leaking	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A30	28/03/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A49	22/08/2015	Unit lost electrical power	Gina Moore noted: No further details.	gina_moore, dylan_miller
A21	08/07/2015	Accumulators need checking and charging	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A38	17/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A68	09/11/2015	Inspect and recharge accumulators	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A93	28/08/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A12	09/01/2016	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A69	04/07/2015	Machine is unpowered	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A61	27/05/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A75	23/05/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A49	18/07/2015	Spindle indexing error with overfeed	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A26	12/05/2015	Repair work needed on milling spindle	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A71	25/01/2015	Hydraulic line leak on side B	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A35	08/03/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: No further details.	gina_moore, dylan_miller
A88	30/04/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A57	08/11/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: No further details.	michele_williams
A24	11/03/2015	Milling spindle requires repair	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A98	03/04/2015	Accumulators need checking and charging	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A84	14/11/2015	Accumulators need checking and charging	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A96	07/01/2016	Leaks found at turrets A and B	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A53	28/12/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A16	03/04/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A87	17/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A49	17/07/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A68	01/11/2015	Accumulators need checking and charging	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A89	06/09/2015	Turret A and B are leaking	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A45	14/04/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A36	14/07/2015	Hydraulic line leak on side B	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A29	03/08/2015	Spindle indexing error with overfeed	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A82	29/03/2015	Hydraulic line leak on side B	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A22	08/10/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A82	25/09/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A67	22/08/2015	Inspect and recharge accumulators	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A46	20/02/2015	Repair work needed on milling spindle	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A64	31/08/2015	Leak in side B hydraulic line	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A19	22/09/2015	Leaks found at turrets A and B	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A77	09/11/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A36	08/10/2015	Accumulator inspection and charging required	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A88	23/08/2015	Unit lost electrical power	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A23	19/01/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A6	15/12/2015	Turret A and B are leaking	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A47	15/12/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A42	01/02/2015	Maintenance on milling spindle needed	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A73	30/01/2015	Leaks found at turrets A and B	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A75	01/01/2016	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A6	12/01/2016	Inspect and recharge accumulators	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller

A1	23/07/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A86	12/01/2016	Unit lost electrical power	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A58	26/10/2015	Hydraulic line leak on side B	Michele Williams noted: Detail not recorded.	michele_williams
A77	11/09/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A93	13/10/2015	Unit lost electrical power	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A4	11/06/2015	Repair work needed on milling spindle	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A97	21/10/2015	Repair work needed on milling spindle	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A71	17/08/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A44	30/06/2015	Accumulators need checking and charging	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A45	05/02/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A71	17/09/2015	Turret A and B are leaking	Gina Moore noted: No further details.	gina_moore, dylan_miller
A70	06/01/2016	Saw attachment gears are binding and grinding	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A18	09/08/2015	Milling spindle requires repair	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A81	19/12/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A46	23/12/2015	Milling spindle requires repair	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A2	06/09/2015	Unit lost electrical power	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A37	26/03/2015	Turret A and B are leaking	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A30	01/10/2015	Leaks found at turrets A and B	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A81	09/10/2015	Machine is unpowered	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A58	13/03/2015	Maintenance on milling spindle needed	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A3	26/03/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A68	11/09/2015	Leaks found at turrets A and B	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A16	31/07/2015	Inspect and recharge accumulators	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A87	11/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A79	20/09/2015	Leaks found at turrets A and B	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A23	30/01/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A34	02/07/2015	Leaks found at turrets A and B	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A16	02/10/2015	Machine is unpowered	Cristian Santos noted: No further details.	cristian_santos
A97	28/01/2015	Accumulators need checking and charging	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A82	20/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A35	02/06/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A48	02/04/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A10	04/06/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A49	06/08/2015	Power supply failure detected	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A63	20/06/2015	Unit lost electrical power	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A29	09/06/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A93	23/08/2015	Turret sections A & B showing leaks	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A66	28/05/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A91	04/01/2016	Inspect and recharge accumulators	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A23	05/10/2015	Spindle fails to index, overfeeding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A60	21/02/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A53	18/08/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A75	26/04/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A44	17/02/2015	Turret A and B are leaking	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A17	08/12/2015	Inspect and recharge accumulators	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A39	25/04/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A32	28/02/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A19	01/11/2015	Unit lost electrical power	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A91	04/10/2015	Accumulator inspection and charging required	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A79	07/05/2015	Unit lost electrical power	Cristian Santos noted: Repair completed.	cristian_santos
A34	27/08/2015	Accumulator inspection and charging required	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A51	23/11/2015	Milling spindle requires repair	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A93	07/12/2015	Machine is unpowered	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A94	05/11/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A33	03/08/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A35	21/07/2015	Leak in side B hydraulic line	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A75	16/01/2015	Leak in side B hydraulic line	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A17	18/04/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A6	21/09/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A74	25/02/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A5	22/02/2015	Leak in side B hydraulic line	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A44	15/12/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A93	16/09/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A32	09/05/2015	Accumulators need checking and charging	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A18	26/12/2015	Repair work needed on milling spindle	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A5	17/02/2015	Hydraulic line leak on side B	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A86	12/02/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Fixed and tested.	michele_williams
A41	16/12/2015	Accumulator inspection and charging required	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A32	04/02/2015	Spindle fails to index, overfeeding	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A44	04/03/2015	Inspect and recharge accumulators	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams

A79	09/09/2015	Hydraulic line leak on side B	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A64	01/10/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A47	08/07/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A23	21/03/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A94	02/10/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A13	23/04/2015	Power supply failure detected	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A22	21/01/2015	Turret A and B are leaking	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A73	09/02/2015	Repair work needed on milling spindle	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A41	30/12/2015	Milling spindle requires repair	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A30	15/09/2015	Milling spindle requires repair	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A48	31/12/2015	Turret sections A & B showing leaks	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A44	31/03/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A21	12/11/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A96	28/11/2015	Leak in side B hydraulic line	Michele Williams noted: No further details.	michele_williams
A19	10/05/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A25	27/02/2015	Accumulators need checking and charging	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A18	01/08/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A21	14/03/2015	Accumulator inspection and charging required	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A84	09/03/2015	Power supply failure detected	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A48	15/11/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A69	17/08/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A85	21/11/2015	Turret sections A & B showing leaks	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A74	27/09/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A23	03/03/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A42	25/01/2015	Power supply failure detected	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A7	02/01/2016	Unit lost electrical power	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A25	28/03/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A12	28/11/2015	Unit lost electrical power	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A44	23/08/2015	Leak in side B hydraulic line	Michele Williams noted: Fixed and tested.	michele_williams
A49	30/08/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A53	21/05/2015	Unit lost electrical power	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A5	30/08/2015	Repair work needed on milling spindle	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A94	18/10/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A83	14/12/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A21	25/12/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Repair completed.	cristian_santos
A92	21/01/2015	Power supply failure detected	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A35	22/12/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A97	18/02/2015	Accumulator inspection and charging required	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A37	03/05/2015	Machine is unpowered	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A33	26/11/2015	Spindle indexing error with overfeed	Michele Williams noted: No further details.	michele_williams
A52	30/03/2015	Accumulator inspection and charging required	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A15	12/02/2015	Maintenance on milling spindle needed	Michele Williams noted: Detail not recorded.	michele_williams
A15	12/10/2015	Power supply failure detected	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A80	24/03/2015	Accumulator inspection and charging required	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A58	23/11/2015	Maintenance on milling spindle needed	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A75	30/01/2015	Accumulators need checking and charging	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A64	10/02/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A98	24/12/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A70	20/10/2015	Turret sections A & B showing leaks	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A24	27/04/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A42	12/01/2016	Maintenance on milling spindle needed	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A7	29/12/2015	Repair work needed on milling spindle	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A33	08/01/2016	Milling spindle requires repair	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A32	02/01/2016	Power supply failure detected	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A4	26/04/2015	Accumulators need checking and charging	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A83	27/05/2015	Unit lost electrical power	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A20	05/08/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A88	18/09/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A53	13/06/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A82	31/01/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A91	24/03/2015	Hydraulic line leak on side B	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A73	21/11/2015	Turret A and B are leaking	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A76	16/03/2015	Turret sections A & B showing leaks	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A83	09/05/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A31	15/09/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A68	26/08/2015	Repair work needed on milling spindle	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A69	19/12/2015	Turret A and B are leaking	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A97	19/04/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A46	09/07/2015	Unit lost electrical power	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A66	18/02/2015	Power supply failure detected	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams

A73	28/10/2015	Spindle indexing error with overfeed	Michele Williams noted: Fixed and tested.	michele_williams
A31	08/09/2015	Milling spindle requires repair	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A98	06/01/2016	Spindle fails to index, overfeeding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A75	14/03/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A57	04/08/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A82	04/09/2015	Machine is unpowered	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A61	28/06/2015	Machine is unpowered	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A8	04/06/2015	Leak in side B hydraulic line	Cristian Santos noted: No additional information provided.	cristian_santos
A66	22/12/2015	Turret sections A & B showing leaks	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A79	03/06/2015	Machine is unpowered	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A26	21/09/2015	Leak in side B hydraulic line	Gina Moore noted: No further details.	gina_moore, dylan_miller
A26	05/08/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A59	25/09/2015	Inspect and recharge accumulators	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A30	27/03/2015	Accumulators need checking and charging	Cristian Santos noted: No additional information provided.	cristian_santos
A16	07/10/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A74	21/05/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: No further details.	nathan_maldonado
A30	01/09/2015	Spindle indexing error with overfeed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A10	18/06/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A29	05/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A86	21/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A90	09/08/2015	Accumulators need checking and charging	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A63	05/02/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A82	17/01/2015	Unit lost electrical power	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A36	11/06/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Fixed and tested.	cristian_santos
A30	22/11/2015	Accumulators need checking and charging	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A10	31/08/2015	Unit lost electrical power	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A34	11/05/2015	Hydraulic line leak on side B	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A73	24/01/2015	Machine is unpowered	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A36	13/09/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A23	18/04/2015	Turret A and B are leaking	Michele Williams noted: Maintenance action successful.	michele_williams
A86	25/03/2015	Maintenance on milling spindle needed	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A58	06/09/2015	Unit lost electrical power	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A71	16/09/2015	Milling spindle requires repair	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A43	11/08/2015	Maintenance on milling spindle needed	Michele Williams noted: No additional information provided.	michele_williams
A48	04/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A48	21/04/2015	Repair work needed on milling spindle	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A31	07/01/2016	Machine is unpowered	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A80	20/09/2015	Hydraulic line leak on side B	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A44	18/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A38	03/05/2015	Repair work needed on milling spindle	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A26	06/01/2016	Machine is unpowered	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A70	06/06/2015	Spindle indexing error with overfeed	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A23	17/01/2015	Leak in side B hydraulic line	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A27	12/09/2015	Maintenance on milling spindle needed	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A35	27/10/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Repair completed.	michele_williams
A36	30/09/2015	Accumulators need checking and charging	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A61	12/10/2015	Inspect and recharge accumulators	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A45	07/12/2015	Accumulator inspection and charging required	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A39	11/08/2015	Milling spindle requires repair	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A6	05/05/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A70	15/06/2015	Spindle indexing error with overfeed	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A62	04/10/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A40	30/10/2015	Unit lost electrical power	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A92	16/10/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A54	21/12/2015	Turret sections A & B showing leaks	Cristian Santos noted: No further details.	cristian_santos
A29	20/09/2015	Milling spindle requires repair	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A7	23/07/2015	Turret sections A & B showing leaks	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A7	05/02/2015	Repair work needed on milling spindle	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A30	20/12/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A46	22/04/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A68	04/12/2015	Repair work needed on milling spindle	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A41	18/06/2015	Milling spindle requires repair	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A95	22/02/2015	Leaks found at turrets A and B	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A59	22/11/2015	Spindle indexing error with overfeed	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A31	08/02/2015	Power supply failure detected	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A9	31/10/2015	Leak in side B hydraulic line	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A91	07/01/2016	Milling spindle requires repair	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A52	20/03/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A42	15/11/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A82	12/06/2015	Repair work needed on milling spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams

A70	21/02/2015	Turret sections A & B showing leaks	Michele Williams noted: System checked and accumulators charged.	michele_williams
A54	19/04/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A95	29/07/2015	Unit lost electrical power	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A47	06/09/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A23	26/07/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Maintenance action successful.	cristian_santos
A76	04/03/2015	Machine is unpowered	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A67	18/02/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A1	18/11/2015	Maintenance on milling spindle needed	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A58	08/10/2015	Machine is unpowered	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A95	25/01/2015	Hydraulic line leak on side B	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A44	06/12/2015	Accumulators need checking and charging	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A35	12/12/2015	Hydraulic line leak on side B	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A15	07/02/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A63	02/04/2015	Turret A and B are leaking	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A77	31/10/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A58	22/11/2015	Turret A and B are leaking	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A4	25/08/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A97	02/05/2015	Machine is unpowered	Michele Williams noted: No additional information provided.	michele_williams
A86	17/12/2015	Leak in side B hydraulic line	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A27	27/06/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A2	17/06/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A51	04/07/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A39	05/07/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A28	01/12/2015	Accumulator inspection and charging required	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A27	04/01/2016	Inspect and recharge accumulators	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A81	23/03/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A83	14/11/2015	Repair work needed on milling spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A63	08/06/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Fixed and tested.	cristian_santos
A19	09/08/2015	Power supply failure detected	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A1	13/09/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A60	24/03/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A59	28/12/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Fixed and tested.	cristian_santos
A79	27/07/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A31	15/02/2015	Milling spindle requires repair	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A4	07/05/2015	Accumulators need checking and charging	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A43	14/05/2015	Leak in side B hydraulic line	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A5	16/08/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A95	16/08/2015	Spindle indexing error with overfeed	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A22	07/11/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A44	07/06/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A95	24/07/2015	Milling spindle requires repair	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A73	09/06/2015	Leaks found at turrets A and B	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A86	07/01/2016	Inspect and recharge accumulators	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A41	18/05/2015	Power supply failure detected	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A99	14/07/2015	Machine is unpowered	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A18	16/09/2015	Accumulator inspection and charging required	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A97	19/06/2015	Accumulators need checking and charging	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A6	31/07/2015	Leaks found at turrets A and B	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A3	16/12/2015	Machine is unpowered	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A87	27/05/2015	Repair work needed on milling spindle	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A45	01/10/2015	Inspect and recharge accumulators	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A70	27/09/2015	Spindle indexing error with overfeed	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A30	19/06/2015	Turret A and B are leaking	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A4	31/12/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A85	12/06/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A91	23/02/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A23	21/08/2015	Unit lost electrical power	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A49	25/10/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A48	20/03/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A7	28/08/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A83	05/07/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A81	30/10/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A1	08/10/2015	Turret sections A & B showing leaks	Cristian Santos noted: No further details.	cristian_santos
A68	11/10/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A22	07/06/2015	Inspect and recharge accumulators	Cristian Santos noted: Maintenance action successful.	cristian_santos
A23	10/07/2015	Accumulators need checking and charging	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A79	08/10/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A16	13/10/2015	Inspect and recharge accumulators	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A54	19/03/2015	Leak in side B hydraulic line	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A63	28/05/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams

A72	19/12/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A74	08/09/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A98	10/03/2015	Milling spindle requires repair	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A77	14/05/2015	Turret sections A & B showing leaks	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A64	10/06/2015	Power supply failure detected	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A66	11/09/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A3	08/11/2015	Maintenance on milling spindle needed	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A82	26/02/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A59	03/09/2015	Maintenance on milling spindle needed	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A8	16/05/2015	Spindle indexing error with overfeed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A61	17/08/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A72	31/05/2015	Unit lost electrical power	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A24	01/05/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A11	04/11/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A10	01/01/2016	Inspect and recharge accumulators	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A38	19/09/2015	Spindle indexing error with overfeed	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A89	31/08/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A78	14/10/2015	Unit lost electrical power	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A19	11/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A23	07/10/2015	Spindle indexing error with overfeed	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A96	18/08/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A84	06/03/2015	Unit lost electrical power	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A42	31/10/2015	Accumulator inspection and charging required	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A62	21/08/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A99	01/07/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A27	26/06/2015	Leaks found at turrets A and B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A34	24/11/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Fixed and tested.	cristian_santos
A41	10/04/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A61	28/07/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A91	05/05/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A38	12/06/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A1	18/07/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A72	30/08/2015	Leak in side B hydraulic line	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A79	05/03/2015	Leaks found at turrets A and B	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A80	22/06/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A2	29/11/2015	Spindle indexing error with overfeed	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A29	02/06/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A45	15/10/2015	Maintenance on milling spindle needed	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A99	17/10/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A30	18/04/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A20	11/01/2016	Leaks found at turrets A and B	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A38	01/03/2015	Milling spindle requires repair	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A88	22/05/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A94	07/12/2015	Repair work needed on milling spindle	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A14	07/10/2015	Hydraulic line leak on side B	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A44	08/05/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A3	28/08/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A42	13/11/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A62	07/04/2015	Accumulators need checking and charging	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A20	12/02/2015	Spindle fails to index, overfeeding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A90	15/09/2015	Unit lost electrical power	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A26	01/10/2015	Machine is unpowered	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A65	25/07/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A73	30/09/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A8	13/12/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A20	13/05/2015	Power supply failure detected	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A17	11/09/2015	Spindle fails to index, overfeeding	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A29	07/03/2015	Leak in side B hydraulic line	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A7	16/07/2015	Leaks found at turrets A and B	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A76	13/01/2016	Accumulators need checking and charging	Michele Williams noted: Maintenance action successful.	michele_williams
A7	05/08/2015	Machine is unpowered	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A12	27/07/2015	Accumulators need checking and charging	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A99	20/06/2015	Machine is unpowered	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A83	03/10/2015	Milling spindle requires repair	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A21	14/08/2015	Milling spindle requires repair	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A92	30/04/2015	Power supply failure detected	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A59	02/06/2015	Milling spindle requires repair	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A58	07/09/2015	Machine is unpowered	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A53	03/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A22	11/02/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams

A4	19/10/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A46	04/02/2015	Hydraulic line leak on side B	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A26	17/01/2015	Accumulators need checking and charging	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A1	19/09/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A94	11/04/2015	Inspect and recharge accumulators	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A16	16/08/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A54	22/04/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A88	23/09/2015	Inspect and recharge accumulators	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A45	07/04/2015	Repair work needed on milling spindle	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A1	17/04/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A45	13/04/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A37	06/06/2015	Unit lost electrical power	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A47	01/02/2015	Maintenance on milling spindle needed	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A26	07/05/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A5	02/02/2015	Unit lost electrical power	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A93	19/05/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A99	09/07/2015	Turret A and B are leaking	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A99	03/03/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A93	08/10/2015	Inspect and recharge accumulators	Cristian Santos noted: No further details.	cristian_santos
A69	08/04/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A4	21/04/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A95	04/02/2015	Leak in side B hydraulic line	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A46	15/10/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A85	29/12/2015	Accumulators need checking and charging	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A51	06/10/2015	Turret sections A & B showing leaks	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A16	12/09/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A82	27/12/2015	Accumulator inspection and charging required	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A59	26/09/2015	Accumulators need checking and charging	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A35	13/02/2015	Maintenance on milling spindle needed	Michele Williams noted: Fixed and tested.	michele_williams
A14	17/11/2015	Power supply failure detected	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A1	30/01/2015	Spindle indexing error with overfeed	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A61	13/11/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A60	18/11/2015	Unit lost electrical power	Michele Williams noted: Fixed and tested.	michele_williams
A2	21/12/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A17	30/12/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: System checked and accumulators charged.	michele_williams
A76	23/10/2015	Turret A and B are leaking	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A35	18/01/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A73	05/05/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A63	29/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A3	22/04/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A70	18/09/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A51	30/03/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A5	24/01/2015	Turret sections A & B showing leaks	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A43	26/10/2015	Leaks found at turrets A and B	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A7	09/12/2015	Leak in side B hydraulic line	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A36	15/09/2015	Inspect and recharge accumulators	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A93	21/03/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A85	19/12/2015	Spindle indexing error with overfeed	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A42	23/08/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A43	05/02/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A32	03/12/2015	Repair work needed on milling spindle	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A46	31/10/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A59	13/08/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A60	31/01/2015	Unit lost electrical power	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A9	21/05/2015	Accumulators need checking and charging	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A56	29/08/2015	Machine is unpowered	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A1	25/01/2015	Machine is unpowered	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A23	07/11/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A97	27/10/2015	Unit lost electrical power	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A29	05/08/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A62	12/06/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A63	10/11/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A14	09/04/2015	Accumulator inspection and charging required	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A13	01/03/2015	Spindle indexing error with overfeed	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A18	26/08/2015	Power supply failure detected	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A72	26/07/2015	Inspect and recharge accumulators	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A35	12/03/2015	Hydraulic line leak on side B	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A55	18/10/2015	Accumulator inspection and charging required	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A89	27/12/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Repair completed.	michele_williams
A27	15/12/2015	Hydraulic hose on side B is leaking	Michele Williams noted: No additional information provided.	michele_williams

A69	16/06/2015	Power supply failure detected	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A86	20/08/2015	Milling spindle requires repair	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A35	06/08/2015	Power supply failure detected	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A19	30/10/2015	Milling spindle requires repair	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A66	20/05/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A66	05/12/2015	Accumulators need checking and charging	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A32	22/09/2015	Unit lost electrical power	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A23	28/02/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A84	23/10/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A4	29/05/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A65	26/07/2015	Milling spindle requires repair	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A52	20/08/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A45	31/12/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A74	25/10/2015	Milling spindle requires repair	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A32	13/02/2015	Unit lost electrical power	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A77	27/07/2015	Hydraulic line leak on side B	Gina Moore noted: No further details.	gina_moore, dylan_miller
A93	05/05/2015	Machine is unpowered	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A80	19/01/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A6	27/10/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A16	28/02/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A93	19/08/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A57	26/06/2015	Leaks found at turrets A and B	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A36	08/01/2016	Spindle fails to index, overfeeding	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A27	07/10/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A71	11/06/2015	Repair work needed on milling spindle	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A82	27/06/2015	Milling spindle requires repair	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A65	05/02/2015	Accumulators need checking and charging	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A95	03/06/2015	Unit lost electrical power	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A78	18/05/2015	Leaks found at turrets A and B	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A24	13/11/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A78	27/09/2015	Spindle fails to index, overfeeding	Michele Williams noted: No further details.	michele_williams
A43	13/11/2015	Milling spindle requires repair	Cristian Santos noted: Detail not recorded.	cristian_santos
A73	02/06/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A5	15/04/2015	Turret sections A & B showing leaks	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A77	07/03/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A76	13/01/2016	Turret A and B are leaking	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A92	27/11/2015	Accumulator inspection and charging required	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A12	27/11/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: No further details.	cristian_santos
A24	23/05/2015	Turret A and B are leaking	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A80	30/01/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A88	26/08/2015	Accumulators need checking and charging	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A51	04/01/2016	Leaks found at turrets A and B	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A44	18/09/2015	Milling spindle requires repair	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A23	25/02/2015	Spindle fails to index, overfeeding	Cristian Santos noted: No additional information provided.	cristian_santos
A76	17/11/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A77	22/05/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A40	23/05/2015	Turret A and B are leaking	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A35	07/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A98	29/05/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A54	24/01/2015	Power supply failure detected	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A41	03/03/2015	Inspect and recharge accumulators	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A14	02/11/2015	Turret sections A & B showing leaks	Cristian Santos noted: Maintenance action successful.	cristian_santos
A22	24/02/2015	Power supply failure detected	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A46	24/07/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A18	25/07/2015	Power supply failure detected	Nathan Maldonado noted: No further details.	nathan_maldonado
A66	02/12/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A70	11/09/2015	Accumulators need checking and charging	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A71	21/07/2015	Spindle indexing error with overfeed	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A41	25/02/2015	Power supply failure detected	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A52	11/05/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A65	27/07/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A88	08/04/2015	Power supply failure detected	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A75	16/04/2015	Milling spindle requires repair	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A81	19/03/2015	Spindle indexing error with overfeed	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A24	20/06/2015	Leak in side B hydraulic line	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A97	13/07/2015	Leak in side B hydraulic line	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A21	14/11/2015	Accumulator inspection and charging required	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A58	13/12/2015	Unit lost electrical power	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A61	05/10/2015	Accumulator inspection and charging required	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A55	14/04/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos

A83	25/02/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A88	21/07/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A17	04/09/2015	Milling spindle requires repair	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A95	28/06/2015	Unit lost electrical power	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A5	30/04/2015	Repair work needed on milling spindle	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A45	27/03/2015	Turret sections A & B showing leaks	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A14	17/11/2015	Unit lost electrical power	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A82	19/01/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A24	30/07/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A98	12/05/2015	Accumulators need checking and charging	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A60	16/06/2015	Spindle indexing error with overfeed	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A37	14/12/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A21	16/11/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A62	23/01/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A82	26/10/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A33	16/05/2015	Spindle indexing error with overfeed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A95	17/06/2015	Repair work needed on milling spindle	Michele Williams noted: Repair completed.	michele_williams
A30	11/07/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A89	28/04/2015	Milling spindle requires repair	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A44	22/04/2015	Turret A and B are leaking	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A4	04/04/2015	Milling spindle requires repair	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A32	02/11/2015	Milling spindle requires repair	Cristian Santos noted: No further details.	cristian_santos
A67	24/08/2015	Leaks found at turrets A and B	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A26	21/09/2015	Leaks found at turrets A and B	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A57	01/02/2015	Turret A and B are leaking	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A81	13/01/2016	Hydraulic fluid leak at saw attachment	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A70	17/06/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A86	05/09/2015	Repair work needed on milling spindle	Cristian Santos noted: Fixed and tested.	cristian_santos
A46	30/09/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A71	12/07/2015	Accumulator inspection and charging required	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A45	27/03/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A13	19/04/2015	Spindle indexing error with overfeed	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A45	26/09/2015	Maintenance on milling spindle needed	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A30	29/07/2015	Spindle indexing error with overfeed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A31	12/08/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A60	28/03/2015	Hydraulic line leak on side B	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A89	23/06/2015	Unit lost electrical power	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A70	29/05/2015	Hydraulic line leak on side B	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A42	17/05/2015	Hydraulic line leak on side B	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A66	08/05/2015	Repair work needed on milling spindle	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A83	20/02/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A72	16/11/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: System checked and accumulators charged.	michele_williams
A71	24/09/2015	Turret A and B are leaking	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A10	14/08/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A90	16/12/2015	Spindle indexing error with overfeed	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A78	07/11/2015	Saw attachment is leaking hydraulics	Gina Moore noted: No further details.	gina_moore, dylan_miller
A58	30/05/2015	Accumulator inspection and charging required	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A90	07/01/2016	Leaks found at turrets A and B	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A46	07/07/2015	Machine is unpowered	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A22	03/12/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A22	16/01/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A96	09/03/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A9	10/06/2015	Turret sections A & B showing leaks	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A59	03/11/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A62	31/10/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A90	20/11/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A82	23/02/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A97	26/09/2015	Accumulators need checking and charging	Cristian Santos noted: Detail not recorded.	cristian_santos
A68	25/02/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A85	23/11/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A45	29/08/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A53	22/05/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A68	16/10/2015	Turret A and B are leaking	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A1	03/02/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A10	08/02/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A7	25/11/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A68	17/04/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A56	07/01/2016	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A55	30/08/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A14	20/01/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado

A2	21/12/2015	Unit lost electrical power	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A16	25/04/2015	Milling spindle requires repair	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A17	15/07/2015	Milling spindle requires repair	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A87	18/03/2015	Turret sections A & B showing leaks	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A97	29/03/2015	Unit lost electrical power	Cristian Santos noted: Maintenance action successful.	cristian_santos
A39	11/06/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Repair completed.	michele_williams
A6	06/04/2015	Accumulators need checking and charging	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A36	19/02/2015	Machine is unpowered	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A83	27/05/2015	Hydraulic line leak on side B	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A86	04/11/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A70	19/11/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A48	09/05/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Repair completed.	michele_williams
A67	14/03/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A84	16/07/2015	Maintenance on milling spindle needed	Michele Williams noted: System checked and accumulators charged.	michele_williams
A38	31/08/2015	Unit lost electrical power	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A96	30/12/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A88	01/07/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A46	18/07/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A5	29/08/2015	Repair work needed on milling spindle	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A7	05/05/2015	Inspect and recharge accumulators	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A53	10/02/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A19	05/11/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A25	21/03/2015	Unit lost electrical power	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A63	16/01/2015	Machine is unpowered	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A87	29/09/2015	Accumulator inspection and charging required	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A4	08/06/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A59	08/02/2015	Turret A and B are leaking	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A71	07/01/2016	Indexing issue causing overfeed on spindle	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A9	18/04/2015	Leaks found at turrets A and B	Nathan Maldonado noted: No further details.	nathan_maldonado
A55	01/02/2015	Spindle indexing error with overfeed	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A76	29/08/2015	Unit lost electrical power	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A33	14/07/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A21	16/09/2015	Leaks found at turrets A and B	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A20	17/11/2015	Hydraulic line leak on side B	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A9	29/05/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A19	30/05/2015	Accumulator inspection and charging required	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A17	04/05/2015	Milling spindle requires repair	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A75	21/05/2015	Power supply failure detected	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A11	11/11/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A46	07/09/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A94	24/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A34	15/03/2015	Leak in side B hydraulic line	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A9	23/10/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A70	21/03/2015	Milling spindle requires repair	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A79	24/03/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A27	20/05/2015	Milling spindle requires repair	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A39	29/12/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A72	10/09/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Detail not recorded.	cristian_santos
A80	21/03/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A85	25/05/2015	Turret sections A & B showing leaks	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A27	02/05/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A58	26/02/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A6	12/06/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A47	14/06/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A15	04/01/2016	Spindle fails to index, overfeeding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A68	09/04/2015	Milling spindle requires repair	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A6	21/02/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A25	18/08/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A44	18/07/2015	Maintenance on milling spindle needed	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A10	08/10/2015	Machine is unpowered	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A37	05/10/2015	Unit lost electrical power	Michele Williams noted: No further details.	michele_williams
A28	26/01/2015	Unit lost electrical power	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A40	14/03/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A74	13/08/2015	Turret A and B are leaking	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A88	29/09/2015	Maintenance on milling spindle needed	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A48	02/09/2015	Machine is unpowered	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A69	03/11/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A10	28/01/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A78	27/09/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A70	25/03/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams

A31	23/10/2015	Turret A and B are leaking	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A13	21/07/2015	Milling spindle requires repair	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A57	07/11/2015	Machine is unpowered	Cristian Santos noted: No additional information provided.	cristian_santos
A92	28/12/2015	Maintenance on milling spindle needed	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A16	15/08/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A20	10/06/2015	Spindle indexing error with overfeed	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A83	20/10/2015	Accumulator inspection and charging required	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A68	15/12/2015	Turret A and B are leaking	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A32	17/09/2015	Inspect and recharge accumulators	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A45	16/07/2015	Machine is unpowered	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A65	14/07/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A22	25/05/2015	Machine is unpowered	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A40	02/09/2015	Unit lost electrical power	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A68	10/08/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A19	24/07/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A67	20/04/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A10	29/01/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A66	10/03/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A10	14/11/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A32	06/05/2015	Accumulator inspection and charging required	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A28	06/01/2016	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A33	10/07/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A36	18/06/2015	Power supply failure detected	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A49	01/12/2015	Unit lost electrical power	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A53	15/07/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A99	21/10/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A81	07/07/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A21	22/01/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A93	20/12/2015	Power supply failure detected	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A20	02/10/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A20	19/12/2015	Repair work needed on milling spindle	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A31	20/09/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A60	23/01/2015	Maintenance on milling spindle needed	Cristian Santos noted: Fixed and tested.	cristian_santos
A85	17/11/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A53	08/04/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A59	14/06/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A71	09/12/2015	Maintenance on milling spindle needed	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A99	28/06/2015	Repair work needed on milling spindle	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A26	08/05/2015	Machine is unpowered	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A81	10/09/2015	Leaks found at turrets A and B	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A96	16/10/2015	Spindle indexing error with overfeed	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A65	25/11/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Repair completed.	michele_williams
A28	25/09/2015	Unit lost electrical power	Cristian Santos noted: Repair completed.	cristian_santos
A3	24/01/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A55	20/05/2015	Leak in side B hydraulic line	Michele Williams noted: No further details.	michele_williams
A11	26/11/2015	Inspect and recharge accumulators	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A38	23/02/2015	Inspect and recharge accumulators	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A30	17/10/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A46	02/12/2015	Maintenance on milling spindle needed	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A67	15/02/2015	Accumulator inspection and charging required	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A72	29/04/2015	Milling spindle requires repair	Cristian Santos noted: No further details.	cristian_santos
A79	08/10/2015	Unit lost electrical power	Michele Williams noted: System checked and accumulators charged.	michele_williams
A13	29/07/2015	Turret A and B are leaking	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A91	20/06/2015	Power supply failure detected	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A51	30/12/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A91	14/08/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A22	13/06/2015	Turret A and B are leaking	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A21	14/09/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A86	14/05/2015	Power supply failure detected	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A20	14/07/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A72	17/08/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A19	25/01/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A72	26/02/2015	Milling spindle requires repair	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A72	02/04/2015	Machine is unpowered	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A65	03/08/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A62	24/06/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: No further details.	nathan_maldonado
A66	24/07/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A38	11/09/2015	Accumulator inspection and charging required	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A82	24/03/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A77	12/04/2015	Turret A and B are leaking	Cristian Santos noted: Detail not recorded.	cristian_santos

A31	14/07/2015	Leaks found at turrets A and B	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A32	09/05/2015	Leak in side B hydraulic line	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A12	19/09/2015	Spindle fails to index, overfeeding	Michele Williams noted: Detail not recorded.	michele_williams
A21	12/09/2015	Leaks found at turrets A and B	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A13	25/07/2015	Accumulators need checking and charging	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A35	21/11/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A17	21/06/2015	Machine is unpowered	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A72	01/01/2016	Power supply failure detected	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A16	03/11/2015	Turret A and B are leaking	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A31	30/09/2015	Leaks found at turrets A and B	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A10	15/04/2015	Accumulator inspection and charging required	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A3	17/08/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A2	29/04/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A24	27/05/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A21	27/08/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A84	06/09/2015	Milling spindle requires repair	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A23	21/02/2015	Unit lost electrical power	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A73	22/12/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A38	28/01/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A22	05/01/2016	Unit lost electrical power	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A85	14/10/2015	Leak in side B hydraulic line	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A47	24/10/2015	Spindle indexing error with overfeed	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A88	01/11/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A8	11/12/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A53	23/04/2015	Accumulators need checking and charging	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A69	02/09/2015	Accumulator inspection and charging required	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A82	11/07/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A5	24/11/2015	Spindle indexing error with overfeed	Michele Williams noted: Repair completed.	michele_williams
A54	25/07/2015	Machine is unpowered	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A6	07/03/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Detail not recorded.	cristian_santos
A44	07/07/2015	Repair work needed on milling spindle	Cristian Santos noted: Detail not recorded.	cristian_santos
A21	25/11/2015	Accumulator inspection and charging required	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A44	13/01/2016	Inspect and recharge accumulators	Michele Williams noted: Repair completed.	michele_williams
A37	02/08/2015	Hydraulic line leak on side B	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A39	31/12/2015	Leaks found at turrets A and B	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A52	28/11/2015	Power supply failure detected	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A87	15/07/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A47	28/08/2015	Repair work needed on milling spindle	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A6	03/08/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A62	07/02/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Maintenance action successful.	cristian_santos
A14	17/06/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A29	10/06/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A49	05/05/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A73	25/03/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: No further details.	nathan_maldonado
A25	09/02/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A66	02/09/2015	Milling spindle requires repair	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A49	23/03/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A78	24/08/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A99	27/04/2015	Unit lost electrical power	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A45	02/06/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A23	19/06/2015	Milling spindle requires repair	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A36	15/03/2015	Unit lost electrical power	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A79	30/08/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A61	13/06/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A44	31/10/2015	Turret A and B are leaking	Michele Williams noted: Detail not recorded.	michele_williams
A19	13/07/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A17	02/05/2015	Power supply failure detected	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A61	03/06/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A68	30/06/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A96	05/10/2015	Unit lost electrical power	Cristian Santos noted: No additional information provided.	cristian_santos
A60	16/09/2015	Machine is unpowered	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A10	04/12/2015	Accumulators need checking and charging	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A57	18/10/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A24	10/06/2015	Milling spindle requires repair	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A40	16/10/2015	Repair work needed on milling spindle	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A4	14/06/2015	Accumulators need checking and charging	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A34	29/01/2015	Maintenance on milling spindle needed	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A38	14/03/2015	Leaks found at turrets A and B	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A41	18/04/2015	Leaks found at turrets A and B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A69	15/10/2015	Turret A and B are leaking	Cristian Santos noted: Maintenance action successful.	cristian_santos

A98	24/10/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A53	30/01/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A46	22/04/2015	Machine is unpowered	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A74	12/04/2015	Accumulator inspection and charging required	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A92	04/08/2015	Leaks found at turrets A and B	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A63	01/10/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A30	02/03/2015	Power supply failure detected	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A75	23/12/2015	Maintenance on milling spindle needed	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A43	12/04/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A72	16/03/2015	Accumulators need checking and charging	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A1	10/12/2015	Power supply failure detected	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A30	21/07/2015	Turret A and B are leaking	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A59	29/04/2015	Milling spindle requires repair	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A43	17/06/2015	Maintenance on milling spindle needed	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A7	15/06/2015	Hydraulic line leak on side B	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A28	26/07/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A25	26/07/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A47	11/02/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A87	05/12/2015	Repair work needed on milling spindle	Michele Williams noted: Maintenance action successful.	michele_williams
A14	09/08/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A21	27/05/2015	Turret A and B are leaking	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A25	08/10/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A87	22/12/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A94	04/07/2015	Accumulators need checking and charging	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A38	17/07/2015	Milling spindle requires repair	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A68	18/10/2015	Spindle indexing error with overfeed	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A88	26/06/2015	Repair work needed on milling spindle	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A20	21/08/2015	Spindle indexing error with overfeed	Michele Williams noted: No additional information provided.	michele_williams
A73	11/04/2015	Accumulators need checking and charging	Cristian Santos noted: Detail not recorded.	cristian_santos
A7	29/07/2015	Turret A and B are leaking	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A96	27/04/2015	Hydraulic line leak on side B	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A50	04/02/2015	Leaks found at turrets A and B	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A55	04/09/2015	Turret sections A & B showing leaks	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A32	18/05/2015	Inspect and recharge accumulators	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A93	19/04/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A48	09/10/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A43	12/02/2015	Machine is unpowered	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A29	24/08/2015	Power supply failure detected	Nathan Maldonado noted: No further details.	nathan_maldonado
A86	22/11/2015	Repair work needed on milling spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A19	08/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A91	04/02/2015	Unit lost electrical power	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A80	12/05/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A80	23/02/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A46	17/03/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A41	17/07/2015	Accumulator inspection and charging required	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A7	28/10/2015	Milling spindle requires repair	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A17	19/12/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A69	30/06/2015	Accumulator inspection and charging required	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A26	28/01/2015	Maintenance on milling spindle needed	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A99	06/08/2015	Maintenance on milling spindle needed	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A20	30/06/2015	Spindle fails to index, overfeeding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A97	06/09/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A88	18/06/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A56	18/07/2015	Machine is unpowered	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A84	16/12/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A42	11/05/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A48	26/02/2015	Leaks found at turrets A and B	Michele Williams noted: Maintenance action successful.	michele_williams
A59	10/07/2015	Unit lost electrical power	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A97	05/01/2016	Leak in side B hydraulic line	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A72	05/12/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A90	05/12/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A67	30/05/2015	Leaks found at turrets A and B	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A96	08/08/2015	Unit lost electrical power	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A96	05/09/2015	Leaks found at turrets A and B	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A68	27/11/2015	Repair work needed on milling spindle	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A37	27/02/2015	Saw attachment gears are binding and grinding	Michele Williams noted: No further details.	michele_williams
A29	23/08/2015	Leaks found at turrets A and B	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A67	23/02/2015	Milling spindle requires repair	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A71	27/11/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A22	02/02/2015	Maintenance on milling spindle needed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos

A68	27/11/2015	Maintenance on milling spindle needed	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A56	09/06/2015	Inspect and recharge accumulators	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A46	25/11/2015	Inspect and recharge accumulators	Cristian Santos noted: Maintenance action successful.	cristian_santos
A87	01/11/2015	Leak in side B hydraulic line	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A78	04/03/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A2	16/02/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A6	08/05/2015	Turret sections A & B showing leaks	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A59	07/05/2015	Accumulator inspection and charging required	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A23	10/09/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A24	26/09/2015	Unit lost electrical power	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A88	08/11/2015	Maintenance on milling spindle needed	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A74	03/09/2015	Inspect and recharge accumulators	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A90	07/02/2015	Unit lost electrical power	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A47	19/07/2015	Leaks found at turrets A and B	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A40	30/06/2015	Power supply failure detected	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A89	16/10/2015	Repair work needed on milling spindle	Cristian Santos noted: Detail not recorded.	cristian_santos
A93	22/09/2015	Turret sections A & B showing leaks	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A59	07/01/2016	Power supply failure detected	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A27	15/09/2015	Maintenance on milling spindle needed	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A54	17/05/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A98	15/09/2015	Leak in side B hydraulic line	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A52	22/10/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A16	31/03/2015	Spindle indexing error with overfeed	Cristian Santos noted: No additional information provided.	cristian_santos
A6	16/02/2015	Accumulator inspection and charging required	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A79	27/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A50	15/12/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A59	24/09/2015	Leak in side B hydraulic line	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A39	09/11/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A13	15/05/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A86	25/07/2015	Hydraulic line leak on side B	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A26	17/02/2015	Turret sections A & B showing leaks	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A50	18/05/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A22	14/01/2015	Accumulator inspection and charging required	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A45	07/02/2015	Machine is unpowered	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A40	11/05/2015	Repair work needed on milling spindle	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A72	03/05/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A19	14/09/2015	Spindle indexing error with overfeed	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A41	19/11/2015	Spindle indexing error with overfeed	Michele Williams noted: Fixed and tested.	michele_williams
A14	08/07/2015	Machine is unpowered	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A63	22/07/2015	Spindle indexing error with overfeed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A80	17/10/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A66	03/07/2015	Hydraulic line leak on side B	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A90	01/11/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A36	08/05/2015	Maintenance on milling spindle needed	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A42	31/12/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A33	26/06/2015	Hydraulic hose on side B is leaking	Michele Williams noted: No further details.	michele_williams
A48	29/10/2015	Accumulator inspection and charging required	Cristian Santos noted: No further details.	cristian_santos
A3	10/06/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A60	11/08/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A5	12/06/2015	Machine is unpowered	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A25	10/09/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A18	15/03/2015	Accumulators need checking and charging	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A74	18/11/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A99	11/06/2015	Power supply failure detected	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A50	21/04/2015	Turret sections A & B showing leaks	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A22	27/04/2015	Unit lost electrical power	Cristian Santos noted: Fixed and tested.	cristian_santos
A38	26/05/2015	Machine is unpowered	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A53	25/08/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: No additional information provided.	cristian_santos
A80	16/07/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A92	19/05/2015	Machine is unpowered	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A16	29/06/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A33	17/05/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A9	11/10/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A94	25/10/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A72	22/10/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A76	04/12/2015	Machine is unpowered	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A11	19/03/2015	Leaks found at turrets A and B	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A72	12/06/2015	Milling spindle requires repair	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A32	27/05/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A74	06/07/2015	Unit lost electrical power	Ethan Adams noted: No further details.	ethan_adams, michele_williams

A57	08/01/2016	Saw attachment is leaking hydraulics	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A95	13/05/2015	Hydraulic line leak on side B	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A17	21/08/2015	Turret A and B are leaking	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A28	19/02/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A19	01/09/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A94	14/03/2015	Turret A and B are leaking	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A41	26/08/2015	Hydraulic line leak on side B	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A15	07/09/2015	Hydraulic line leak on side B	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A36	03/05/2015	Milling spindle requires repair	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A28	16/03/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A52	24/10/2015	Power supply failure detected	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A85	25/11/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A46	14/09/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A72	17/07/2015	Machine is unpowered	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A17	13/11/2015	Turret sections A & B showing leaks	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A95	14/10/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A79	18/08/2015	Milling spindle requires repair	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A29	27/10/2015	Turret A and B are leaking	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A14	31/03/2015	Turret A and B are leaking	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A12	31/08/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A16	28/05/2015	Machine is unpowered	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A14	27/01/2015	Spindle indexing error with overfeed	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A91	21/08/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A9	16/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A8	20/12/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A19	04/12/2015	Accumulator inspection and charging required	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A78	28/09/2015	Repair work needed on milling spindle	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A17	22/10/2015	Leaks found at turrets A and B	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A13	12/01/2016	Hydraulic hose on side B is leaking	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A42	19/08/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A67	29/08/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A53	26/05/2015	Leak in side B hydraulic line	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A19	11/05/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A80	09/08/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A81	12/02/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A14	29/08/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A41	12/12/2015	Accumulators need checking and charging	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A25	09/11/2015	Inspect and recharge accumulators	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A34	24/05/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A28	06/02/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A75	19/05/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A70	14/04/2015	Spindle fails to index, overfeeding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A53	26/05/2015	Accumulator inspection and charging required	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A68	05/12/2015	Hydraulic line leak on side B	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A86	26/12/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A38	13/06/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: No further details.	cristian_santos
A59	24/12/2015	Leak in side B hydraulic line	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A55	08/03/2015	Leaks found at turrets A and B	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A84	20/06/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A39	15/02/2015	Leaks found at turrets A and B	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A15	02/02/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A70	07/01/2016	Accumulator inspection and charging required	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A69	25/05/2015	Unit lost electrical power	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A45	17/11/2015	Machine is unpowered	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A32	21/09/2015	Power supply failure detected	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A13	27/03/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A41	07/07/2015	Accumulators need checking and charging	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A38	23/08/2015	Inspect and recharge accumulators	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A6	21/07/2015	Machine is unpowered	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A86	19/04/2015	Inspect and recharge accumulators	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A70	30/06/2015	Inspect and recharge accumulators	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A50	17/09/2015	Leak in side B hydraulic line	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A96	18/05/2015	Accumulators need checking and charging	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A26	28/12/2015	Turret sections A & B showing leaks	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A44	06/08/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A14	19/04/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A99	13/06/2015	Saw attachment gears are binding and grinding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A33	20/04/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A25	17/07/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A93	07/10/2015	Milling spindle requires repair	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller

A71	07/11/2015	Turret A and B are leaking	Michele Williams noted: System checked and accumulators charged.	michele_williams
A56	20/10/2015	Milling spindle requires repair	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A37	12/12/2015	Machine is unpowered	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A3	30/05/2015	Power supply failure detected	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A66	05/10/2015	Milling spindle requires repair	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A52	04/10/2015	Turret sections A & B showing leaks	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A93	25/03/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A55	04/08/2015	Machine is unpowered	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A60	08/06/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A76	12/11/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A64	13/12/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A63	14/04/2015	Maintenance on milling spindle needed	Gina Moore noted: No further details.	gina_moore, dylan_miller
A65	18/08/2015	Leak in side B hydraulic line	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A54	31/08/2015	Leaks found at turrets A and B	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A60	21/04/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A22	17/11/2015	Maintenance on milling spindle needed	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A17	28/04/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A97	02/03/2015	Unit lost electrical power	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A83	02/10/2015	Accumulators need checking and charging	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A63	28/09/2015	Hydraulic line leak on side B	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A18	01/08/2015	Milling spindle requires repair	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A68	08/01/2016	Saw attachment is leaking hydraulics	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A76	24/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A83	18/07/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A41	01/03/2015	Turret A and B are leaking	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A29	01/03/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A42	20/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A21	26/07/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A93	04/12/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A74	18/08/2015	Spindle indexing error with overfeed	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A31	29/11/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A24	21/09/2015	Machine is unpowered	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A58	21/02/2015	Hydraulic line leak on side B	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A8	27/08/2015	Inspect and recharge accumulators	Michele Williams noted: Maintenance action successful.	michele_williams
A96	16/05/2015	Milling spindle requires repair	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A54	31/10/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A84	23/07/2015	Turret A and B are leaking	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A49	17/01/2015	Milling spindle requires repair	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A10	26/05/2015	Power supply failure detected	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A63	25/07/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A88	01/10/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A62	16/10/2015	Machine is unpowered	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A47	16/01/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A66	17/03/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A51	21/08/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: No additional information provided.	michele_williams
A63	31/08/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A78	16/09/2015	Maintenance on milling spindle needed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A99	01/08/2015	Hydraulic line leak on side B	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A50	07/08/2015	Repair work needed on milling spindle	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A6	04/04/2015	Leaks found at turrets A and B	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A4	16/10/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A69	20/05/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A19	11/12/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A50	12/10/2015	Maintenance on milling spindle needed	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A43	19/08/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: No further details.	cristian_santos
A42	03/06/2015	Machine is unpowered	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A73	11/03/2015	Turret A and B are leaking	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A9	19/12/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: System checked and accumulators charged.	michele_williams
A11	24/08/2015	Turret A and B are leaking	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A86	08/07/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A25	02/03/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A42	04/05/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: No additional information provided.	michele_williams
A57	31/03/2015	Repair work needed on milling spindle	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A36	20/01/2015	Milling spindle requires repair	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A25	01/07/2015	Machine is unpowered	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A84	08/11/2015	Leaks found at turrets A and B	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A66	17/09/2015	Accumulator inspection and charging required	Cristian Santos noted: Repair completed.	cristian_santos
A46	04/01/2016	Spindle fails to index, overfeeding	Michele Williams noted: Fixed and tested.	michele_williams
A39	07/05/2015	Spindle indexing error with overfeed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A99	17/07/2015	Accumulators need checking and charging	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams

A99	20/02/2015	Machine is unpowered	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A3	13/06/2015	Turret sections A & B showing leaks	Cristian Santos noted: Repair completed.	cristian_santos
A99	10/04/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A14	29/03/2015	Power supply failure detected	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A56	28/03/2015	Machine is unpowered	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A34	01/07/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A14	08/05/2015	Accumulators need checking and charging	Michele Williams noted: Repair completed.	michele_williams
A5	11/12/2015	Turret sections A & B showing leaks	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A68	29/03/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A7	01/10/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A93	01/11/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A49	08/02/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A82	20/08/2015	Hydraulic line leak on side B	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A71	17/06/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A53	16/06/2015	Leak in side B hydraulic line	Cristian Santos noted: Maintenance action successful.	cristian_santos
A94	26/09/2015	Maintenance on milling spindle needed	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A1	14/03/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A62	13/05/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A49	24/07/2015	Leak in side B hydraulic line	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A55	16/02/2015	Unit lost electrical power	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A43	24/02/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A88	29/12/2015	Machine is unpowered	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A78	31/05/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A68	06/02/2015	Turret A and B are leaking	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A59	28/11/2015	Accumulator inspection and charging required	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A57	05/08/2015	Leak in side B hydraulic line	Michele Williams noted: Fixed and tested.	michele_williams
A58	04/11/2015	Leaks found at turrets A and B	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A59	07/09/2015	Spindle indexing error with overfeed	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A34	29/04/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A65	08/06/2015	Repair work needed on milling spindle	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A96	31/01/2015	Turret A and B are leaking	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A46	15/03/2015	Turret sections A & B showing leaks	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A91	01/11/2015	Turret sections A & B showing leaks	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A49	20/09/2015	Power supply failure detected	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A95	11/12/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A41	02/06/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A56	01/10/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A37	03/06/2015	Leaks found at turrets A and B	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A90	24/02/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A19	23/05/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A14	21/09/2015	Turret sections A & B showing leaks	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A33	30/07/2015	Milling spindle requires repair	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A3	30/11/2015	Machine is unpowered	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A89	30/12/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A90	11/09/2015	Machine is unpowered	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A90	12/05/2015	Accumulators need checking and charging	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A1	15/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A31	15/09/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A33	07/05/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A97	20/12/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A85	09/10/2015	Power supply failure detected	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A42	05/03/2015	Turret sections A & B showing leaks	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A67	23/06/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A4	08/08/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A97	02/09/2015	Machine is unpowered	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A2	21/09/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A73	16/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A17	16/11/2015	Turret A and B are leaking	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A73	04/05/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Fixed and tested.	cristian_santos
A62	25/03/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A55	01/09/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A39	03/06/2015	Leaks found at turrets A and B	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A20	27/10/2015	Maintenance on milling spindle needed	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A21	24/01/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A36	09/02/2015	Turret A and B are leaking	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A53	06/06/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A73	28/05/2015	Turret A and B are leaking	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A50	14/06/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A25	20/01/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A39	08/08/2015	Unit lost electrical power	Michele Williams noted: Repair completed.	michele_williams

A88	24/10/2015	Repair work needed on milling spindle	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A28	16/12/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A23	06/02/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A30	22/10/2015	Machine is unpowered	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A20	14/10/2015	Leak in side B hydraulic line	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A77	30/11/2015	Leaks found at turrets A and B	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A36	05/10/2015	Power supply failure detected	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A74	08/04/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A88	07/12/2015	Unit lost electrical power	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A3	27/09/2015	Spindle indexing error with overfeed	Michele Williams noted: System checked and accumulators charged.	michele_williams
A54	03/11/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A59	09/05/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A85	03/02/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A59	14/06/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A53	02/05/2015	Machine is unpowered	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A10	22/06/2015	Leak in side B hydraulic line	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A22	28/11/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A66	31/12/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A13	21/03/2015	Inspect and recharge accumulators	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A70	20/08/2015	Spindle indexing error with overfeed	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A49	15/12/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A94	21/09/2015	Leak in side B hydraulic line	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A69	18/04/2015	Machine is unpowered	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A83	25/08/2015	Spindle indexing error with overfeed	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A54	07/01/2016	Leak detected in hydraulic line of saw attachment	Michele Williams noted: No further details.	michele_williams
A93	24/06/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A58	20/11/2015	Machine is unpowered	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A26	17/04/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A40	11/07/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A10	16/09/2015	Unit lost electrical power	Cristian Santos noted: Fixed and tested.	cristian_santos
A43	14/04/2015	Turret sections A & B showing leaks	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A61	01/03/2015	Milling spindle requires repair	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A67	20/02/2015	Milling spindle requires repair	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A72	11/05/2015	Hydraulic line leak on side B	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A69	06/07/2015	Leaks found at turrets A and B	Michele Williams noted: System checked and accumulators charged.	michele_williams
A92	24/04/2015	Repair work needed on milling spindle	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A73	11/06/2015	Milling spindle requires repair	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A90	02/06/2015	Spindle fails to index, overfeeding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A61	20/02/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A4	02/09/2015	Power supply failure detected	Michele Williams noted: No further details.	michele_williams
A13	27/05/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A40	14/11/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A41	25/11/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A70	28/09/2015	Inspect and recharge accumulators	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A85	09/12/2015	Power supply failure detected	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A44	09/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Detail not recorded.	cristian_santos
A39	13/10/2015	Machine is unpowered	Gina Moore noted: No further details.	gina_moore, dylan_miller
A58	04/07/2015	Leaks found at turrets A and B	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A41	04/03/2015	Leak in side B hydraulic line	Cristian Santos noted: Fixed and tested.	cristian_santos
A52	18/09/2015	Turret A and B are leaking	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A47	02/11/2015	Maintenance on milling spindle needed	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A65	15/03/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A80	08/03/2015	Unit lost electrical power	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A80	20/04/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: No further details.	nathan_maldonado
A36	23/02/2015	Machine is unpowered	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A64	17/01/2015	Accumulator inspection and charging required	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A97	09/04/2015	Spindle indexing error with overfeed	Cristian Santos noted: Fixed and tested.	cristian_santos
A88	24/03/2015	Accumulator inspection and charging required	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A82	31/10/2015	Milling spindle requires repair	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A13	16/10/2015	Machine is unpowered	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A55	05/07/2015	Milling spindle requires repair	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A83	30/05/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A4	12/04/2015	Accumulator inspection and charging required	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A79	02/02/2015	Accumulator inspection and charging required	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A64	23/03/2015	Inspect and recharge accumulators	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A67	17/10/2015	Maintenance on milling spindle needed	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A44	05/12/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A24	04/05/2015	Accumulators need checking and charging	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A65	26/09/2015	Saw attachment is leaking hydraulics	Michele Williams noted: No further details.	michele_williams
A19	19/06/2015	Unit lost electrical power	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado

A52	12/02/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A13	13/06/2015	Accumulators need checking and charging	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A65	08/05/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A33	20/03/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A50	08/01/2016	Indexing issue causing overfeed on spindle	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A3	07/06/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A15	23/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A82	22/08/2015	Turret sections A & B showing leaks	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A53	12/08/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A88	25/10/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A59	25/12/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A32	27/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A67	18/02/2015	Hydraulic line leak on side B	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A58	26/02/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A95	15/07/2015	Accumulator inspection and charging required	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A47	03/10/2015	Maintenance on milling spindle needed	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A16	18/10/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A65	21/07/2015	Turret A and B are leaking	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A34	30/04/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: No additional information provided.	michele_williams
A42	12/05/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A79	25/02/2015	Accumulators need checking and charging	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A65	28/04/2015	Inspect and recharge accumulators	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A55	07/03/2015	Accumulator inspection and charging required	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A10	19/06/2015	Machine is unpowered	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A30	03/05/2015	Unit lost electrical power	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A91	08/09/2015	Milling spindle requires repair	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A46	01/12/2015	Leaks found at turrets A and B	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A52	21/09/2015	Hydraulic line leak on side B	Michele Williams noted: No further details.	michele_williams
A44	13/07/2015	Turret A and B are leaking	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A58	19/03/2015	Power supply failure detected	Cristian Santos noted: No further details.	cristian_santos
A70	25/07/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A27	06/11/2015	Inspect and recharge accumulators	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A13	23/09/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A24	15/11/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A52	12/05/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A33	19/02/2015	Machine is unpowered	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A12	01/10/2015	Turret A and B are leaking	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A60	22/08/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A72	13/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A78	14/06/2015	Hydraulic line leak on side B	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A95	27/05/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A94	01/10/2015	Repair work needed on milling spindle	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A70	23/04/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A1	21/03/2015	Hydraulic line leak on side B	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A83	25/11/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A34	12/08/2015	Inspect and recharge accumulators	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A69	10/08/2015	Leaks found at turrets A and B	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A49	29/11/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A48	05/03/2015	Milling spindle requires repair	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A14	01/02/2015	Milling spindle requires repair	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A80	24/01/2015	Unit lost electrical power	Michele Williams noted: System checked and accumulators charged.	michele_williams
A22	02/04/2015	Turret A and B are leaking	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A3	26/11/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A31	13/03/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A37	19/02/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: No further details.	nathan_maldonado
A90	07/06/2015	Unit lost electrical power	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A48	10/10/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A78	03/12/2015	Maintenance on milling spindle needed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A15	24/03/2015	Machine is unpowered	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A25	15/07/2015	Leak in side B hydraulic line	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A17	17/09/2015	Turret sections A & B showing leaks	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A95	16/06/2015	Milling spindle requires repair	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A22	01/05/2015	Unit lost electrical power	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A55	01/10/2015	Milling spindle requires repair	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A20	05/06/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A3	03/02/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A42	14/11/2015	Power supply failure detected	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A93	29/10/2015	Spindle fails to index, overfeeding	Michele Williams noted: Maintenance action successful.	michele_williams
A17	27/07/2015	Repair work needed on milling spindle	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A40	18/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Fixed and tested.	michele_williams

A73	31/05/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A5	04/12/2015	Turret A and B are leaking	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A99	29/06/2015	Spindle indexing error with overfeed	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A43	25/05/2015	Spindle indexing error with overfeed	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A43	09/07/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A59	03/08/2015	Saw attachment is leaking hydraulics	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A7	07/11/2015	Turret A and B are leaking	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A33	05/09/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A67	28/11/2015	Accumulator inspection and charging required	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A36	01/01/2016	Machine is unpowered	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A59	26/09/2015	Repair work needed on milling spindle	Cristian Santos noted: Maintenance action successful.	cristian_santos
A9	28/07/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A35	17/09/2015	Accumulators need checking and charging	Cristian Santos noted: No further details.	cristian_santos
A24	12/06/2015	Unit lost electrical power	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A31	24/06/2015	Unit lost electrical power	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A78	21/11/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A1	24/01/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A76	05/11/2015	Leaks found at turrets A and B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A12	25/02/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A52	12/05/2015	Maintenance on milling spindle needed	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A67	15/10/2015	Spindle fails to index, overfeeding	Cristian Santos noted: No further details.	cristian_santos
A14	30/04/2015	Milling spindle requires repair	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A84	22/02/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A91	09/09/2015	Accumulator inspection and charging required	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A84	22/06/2015	Turret A and B are leaking	Cristian Santos noted: No additional information provided.	cristian_santos
A99	08/12/2015	Machine is unpowered	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A9	17/01/2015	Hydraulic line leak on side B	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A62	26/05/2015	Hydraulic line leak on side B	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A85	16/11/2015	Leaks found at turrets A and B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A83	01/07/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A21	26/03/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A7	15/03/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A81	19/04/2015	Machine is unpowered	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A5	16/09/2015	Milling spindle requires repair	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A3	20/01/2015	Inspect and recharge accumulators	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A69	29/07/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A13	25/04/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A11	05/12/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A53	10/09/2015	Power supply failure detected	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A97	13/04/2015	Leaks found at turrets A and B	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A1	14/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A2	25/11/2015	Inspect and recharge accumulators	Michele Williams noted: Fixed and tested.	michele_williams
A69	17/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A78	17/12/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A52	11/03/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A3	05/07/2015	Machine is unpowered	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A34	13/07/2015	Spindle indexing error with overfeed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A28	20/01/2015	Inspect and recharge accumulators	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A21	18/10/2015	Leak in side B hydraulic line	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A90	29/12/2015	Turret sections A & B showing leaks	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A53	04/01/2016	Maintenance on milling spindle needed	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A35	11/01/2016	Unit lost electrical power	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A31	13/01/2016	Spindle fails to index, overfeeding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A47	18/06/2015	Leak in side B hydraulic line	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A62	19/11/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A31	30/06/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A63	15/02/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A42	11/09/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A54	02/08/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A13	17/10/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A36	08/09/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A90	31/10/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A29	17/06/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A58	17/07/2015	Accumulator inspection and charging required	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A49	19/06/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A16	26/05/2015	Power supply failure detected	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A18	29/05/2015	Turret A and B are leaking	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A95	02/07/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A94	10/07/2015	Repair work needed on milling spindle	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A49	13/09/2015	Maintenance on milling spindle needed	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams

A27	23/11/2015	Turret sections A & B showing leaks	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A63	08/01/2016	Hydraulic line leak on side B	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A73	28/04/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A71	22/05/2015	Milling spindle requires repair	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A98	31/10/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A36	20/05/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A5	03/09/2015	Unit lost electrical power	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A74	07/05/2015	Repair work needed on milling spindle	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A57	08/08/2015	Power supply failure detected	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A38	10/10/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A49	15/02/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A44	17/12/2015	Machine is unpowered	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A14	20/11/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A68	27/04/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A61	18/04/2015	Accumulators need checking and charging	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A59	20/03/2015	Maintenance on milling spindle needed	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A11	29/01/2015	Turret sections A & B showing leaks	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A23	13/05/2015	Turret sections A & B showing leaks	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A44	16/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: No additional information provided.	cristian_santos
A80	29/03/2015	Machine is unpowered	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A92	17/07/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A99	01/01/2016	Saw attachment gears are binding and grinding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A3	17/02/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A7	02/06/2015	Spindle indexing error with overfeed	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A13	27/12/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A59	16/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A22	14/05/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A96	03/08/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A89	15/03/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A51	13/08/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Maintenance action successful.	cristian_santos
A1	11/08/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A83	16/06/2015	Turret A and B are leaking	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A69	26/10/2015	Leak in side B hydraulic line	Cristian Santos noted: Repair completed.	cristian_santos
A57	03/09/2015	Unit lost electrical power	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A74	15/07/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A41	22/10/2015	Maintenance on milling spindle needed	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A41	06/06/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A50	30/05/2015	Repair work needed on milling spindle	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A29	09/09/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A43	21/10/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A81	23/02/2015	Power supply failure detected	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A65	12/07/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A42	17/11/2015	Hydraulic line leak on side B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A11	29/07/2015	Machine is unpowered	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A71	12/07/2015	Power supply failure detected	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A95	14/04/2015	Maintenance on milling spindle needed	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A10	09/03/2015	Accumulator inspection and charging required	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A59	22/11/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A62	14/04/2015	Repair work needed on milling spindle	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A79	01/07/2015	Power supply failure detected	Cristian Santos noted: Fixed and tested.	cristian_santos
A61	26/03/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A5	14/03/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A19	12/08/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A88	30/10/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A30	08/07/2015	Accumulator inspection and charging required	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A32	04/06/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A47	14/06/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A40	15/08/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A36	06/07/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A14	28/01/2015	Accumulators need checking and charging	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A77	30/09/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A15	23/06/2015	Turret A and B are leaking	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A75	12/02/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A22	30/08/2015	Inspect and recharge accumulators	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A16	07/03/2015	Maintenance on milling spindle needed	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A64	26/03/2015	Leak in side B hydraulic line	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A19	03/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A27	13/10/2015	Machine is unpowered	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A77	15/06/2015	Accumulator inspection and charging required	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A49	03/09/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams

A79	28/07/2015	Unit lost electrical power	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A66	30/03/2015	Accumulator inspection and charging required	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A33	11/11/2015	Milling spindle requires repair	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A78	17/07/2015	Repair work needed on milling spindle	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A5	15/08/2015	Turret A and B are leaking	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A59	04/03/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A68	14/07/2015	Accumulator inspection and charging required	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A63	16/09/2015	Power supply failure detected	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A91	23/09/2015	Turret sections A & B showing leaks	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A41	30/10/2015	Leak in side B hydraulic line	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A32	30/04/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A63	27/01/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A88	25/11/2015	Accumulators need checking and charging	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A21	27/07/2015	Accumulators need checking and charging	Michele Williams noted: Detail not recorded.	michele_williams
A29	10/08/2015	Power supply failure detected	Cristian Santos noted: Detail not recorded.	cristian_santos
A15	05/08/2015	Accumulator inspection and charging required	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A94	19/04/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A39	21/05/2015	Inspect and recharge accumulators	Michele Williams noted: Fixed and tested.	michele_williams
A38	04/01/2016	Unit lost electrical power	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A71	25/01/2015	Milling spindle requires repair	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A13	28/11/2015	Power supply failure detected	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A89	04/09/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A80	10/04/2015	Repair work needed on milling spindle	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A26	23/01/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A72	25/09/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A21	24/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A54	28/04/2015	Maintenance on milling spindle needed	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A62	20/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A30	10/02/2015	Accumulators need checking and charging	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A58	28/01/2015	Turret A and B are leaking	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A98	09/07/2015	Spindle indexing error with overfeed	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A1	26/01/2015	Leaks found at turrets A and B	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A26	25/03/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A99	15/07/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A99	21/03/2015	Accumulator inspection and charging required	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A89	05/06/2015	Repair work needed on milling spindle	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A13	06/06/2015	Accumulator inspection and charging required	Michele Williams noted: Maintenance action successful.	michele_williams
A11	05/04/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A16	04/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A95	30/07/2015	Repair work needed on milling spindle	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A65	18/02/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A65	14/07/2015	Turret sections A & B showing leaks	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A65	13/03/2015	Power supply failure detected	Michele Williams noted: Repair completed.	michele_williams
A22	01/04/2015	Accumulator inspection and charging required	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A10	01/02/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A94	20/03/2015	Accumulators need checking and charging	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A18	30/11/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A64	20/06/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A92	12/07/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A40	07/04/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A83	30/03/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A47	27/02/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A41	12/12/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A67	29/12/2015	Inspect and recharge accumulators	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A49	25/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A4	26/05/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A30	02/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A77	05/05/2015	Spindle indexing error with overfeed	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A44	17/06/2015	Repair work needed on milling spindle	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A96	24/01/2015	Inspect and recharge accumulators	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A10	07/04/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A53	02/09/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A67	14/11/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Repair completed.	michele_williams
A83	18/10/2015	Turret sections A & B showing leaks	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A73	30/04/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A1	21/11/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A33	28/02/2015	Inspect and recharge accumulators	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A1	24/05/2015	Hydraulic line leak on side B	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A10	09/02/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A36	19/03/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams

A48	08/05/2015	Accumulator inspection and charging required	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A99	14/10/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A38	08/05/2015	Hydraulic line leak on side B	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A19	12/09/2015	Leaks found at turrets A and B	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A78	21/05/2015	Machine is unpowered	Cristian Santos noted: No additional information provided.	cristian_santos
A52	26/12/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A44	18/09/2015	Turret sections A & B showing leaks	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A21	01/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A58	20/08/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A19	02/07/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A58	16/05/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A94	13/12/2015	Maintenance on milling spindle needed	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A49	10/08/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A20	20/01/2015	Unit lost electrical power	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A29	02/05/2015	Inspect and recharge accumulators	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A8	14/05/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A1	12/12/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A1	13/03/2015	Turret sections A & B showing leaks	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A13	18/01/2015	Accumulator inspection and charging required	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A5	14/08/2015	Unit lost electrical power	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A55	23/04/2015	Accumulators need checking and charging	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A4	26/09/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A55	06/09/2015	Accumulators need checking and charging	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A85	17/02/2015	Machine is unpowered	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A20	12/06/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A36	09/12/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A33	22/03/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A50	07/12/2015	Spindle indexing error with overfeed	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A95	04/12/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A24	26/01/2015	Maintenance on milling spindle needed	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A67	16/02/2015	Unit lost electrical power	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A95	09/10/2015	Leak in side B hydraulic line	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A22	08/06/2015	Accumulators need checking and charging	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A90	04/09/2015	Maintenance on milling spindle needed	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A79	02/06/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A30	17/09/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A19	21/04/2015	Accumulators need checking and charging	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A65	23/10/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A49	10/03/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A31	27/03/2015	Power supply failure detected	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A92	08/03/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: No further details.	cristian_santos
A45	07/10/2015	Turret sections A & B showing leaks	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A68	17/09/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A96	02/09/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A88	04/06/2015	Power supply failure detected	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A69	08/02/2015	Leak in side B hydraulic line	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A68	09/07/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A49	05/11/2015	Milling spindle requires repair	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A62	07/04/2015	Unit lost electrical power	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A9	09/03/2015	Leaks found at turrets A and B	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A4	14/10/2015	Repair work needed on milling spindle	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A91	12/07/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A71	20/02/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A22	09/05/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A8	15/04/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A87	05/11/2015	Turret A and B are leaking	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A79	13/05/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A28	30/08/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A88	11/05/2015	Spindle indexing error with overfeed	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A12	10/02/2015	Machine is unpowered	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A29	25/04/2015	Milling spindle requires repair	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A29	01/08/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: No further details.	gina_moore, dylan_miller
A2	28/12/2015	Accumulator inspection and charging required	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A65	06/08/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A55	25/04/2015	Hydraulic line leak on side B	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A72	31/03/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A42	24/12/2015	Accumulators need checking and charging	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A41	27/10/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A30	26/10/2015	Maintenance on milling spindle needed	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A38	25/12/2015	Inspect and recharge accumulators	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams

A58	28/10/2015	Accumulators need checking and charging	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A94	15/02/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A16	24/05/2015	Accumulators need checking and charging	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A85	22/04/2015	Milling spindle requires repair	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A87	06/07/2015	Milling spindle requires repair	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A19	27/02/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A28	27/06/2015	Power supply failure detected	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A95	12/12/2015	Milling spindle requires repair	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A12	29/04/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A48	14/05/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A88	11/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A60	20/08/2015	Unit lost electrical power	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A62	12/01/2016	Saw attachment gears are binding and grinding	Cristian Santos noted: Maintenance action successful.	cristian_santos
A26	23/09/2015	Spindle fails to index, overfeeding	Michele Williams noted: Maintenance action successful.	michele_williams
A78	21/02/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A57	20/10/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A31	14/02/2015	Machine is unpowered	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A41	23/12/2015	Turret A and B are leaking	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A75	05/09/2015	Milling spindle requires repair	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A50	29/03/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A15	12/12/2015	Spindle indexing error with overfeed	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A82	05/04/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A49	28/07/2015	Accumulators need checking and charging	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A92	12/11/2015	Spindle indexing error with overfeed	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A39	20/06/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A57	23/09/2015	Leak in side B hydraulic line	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A39	02/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A71	28/10/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A15	06/03/2015	Inspect and recharge accumulators	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A22	06/08/2015	Unit lost electrical power	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A16	14/02/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A24	13/09/2015	Accumulators need checking and charging	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A67	15/09/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A44	24/02/2015	Leaks found at turrets A and B	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A75	14/08/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A95	17/12/2015	Turret sections A & B showing leaks	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A55	06/10/2015	Machine is unpowered	Cristian Santos noted: Repair completed.	cristian_santos
A62	30/09/2015	Machine is unpowered	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A43	25/09/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A54	13/03/2015	Maintenance on milling spindle needed	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A55	04/10/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A19	19/08/2015	Hydraulic line leak on side B	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A15	03/02/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A5	03/04/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A95	23/04/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A76	05/06/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A42	05/07/2015	Milling spindle requires repair	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A33	28/08/2015	Accumulators need checking and charging	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A90	02/06/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A87	10/11/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A60	28/08/2015	Accumulators need checking and charging	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A53	06/03/2015	Power supply failure detected	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A79	13/06/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: No additional information provided.	cristian_santos
A74	21/07/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A47	04/09/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A19	06/08/2015	Spindle indexing error with overfeed	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A51	12/07/2015	Turret A and B are leaking	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A71	25/03/2015	Machine is unpowered	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A38	30/07/2015	Turret sections A & B showing leaks	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A62	07/12/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A90	25/05/2015	Hydraulic line leak on side B	Michele Williams noted: No further details.	michele_williams
A79	10/07/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A30	12/11/2015	Machine is unpowered	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A65	07/01/2016	Milling spindle requires repair	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A76	12/01/2016	Accumulators need checking and charging	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A77	17/08/2015	Accumulators need checking and charging	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A48	14/09/2015	Turret A and B are leaking	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A24	15/06/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Repair completed.	cristian_santos
A49	27/01/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A48	04/05/2015	Turret A and B are leaking	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams

A86	11/03/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A61	09/09/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A8	13/05/2015	Turret A and B are leaking	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A40	14/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A18	06/08/2015	Leaks found at turrets A and B	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A74	25/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Repair completed.	michele_williams
A20	15/01/2015	Accumulator inspection and charging required	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A58	25/12/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A13	08/10/2015	Spindle indexing error with overfeed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A76	31/10/2015	Turret sections A & B showing leaks	Cristian Santos noted: Maintenance action successful.	cristian_santos
A24	24/11/2015	Accumulators need checking and charging	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A22	23/09/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A98	17/01/2015	Spindle indexing error with overfeed	Cristian Santos noted: Fixed and tested.	cristian_santos
A25	11/06/2015	Leak in side B hydraulic line	Michele Williams noted: No additional information provided.	michele_williams
A57	04/03/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A41	31/01/2015	Power supply failure detected	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A81	25/01/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A97	27/12/2015	Milling spindle requires repair	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A25	09/07/2015	Turret sections A & B showing leaks	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A5	07/09/2015	Accumulators need checking and charging	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A69	06/12/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A27	24/07/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A29	27/12/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A46	08/05/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A29	03/04/2015	Turret A and B are leaking	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A52	19/07/2015	Repair work needed on milling spindle	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A17	18/09/2015	Unit lost electrical power	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A21	21/06/2015	Maintenance on milling spindle needed	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A37	30/07/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A84	27/08/2015	Leaks found at turrets A and B	Cristian Santos noted: Maintenance action successful.	cristian_santos
A35	19/12/2015	Accumulator inspection and charging required	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A23	20/05/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A72	15/02/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A79	24/01/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A90	23/07/2015	Unit lost electrical power	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A29	12/07/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A98	16/09/2015	Machine is unpowered	Cristian Santos noted: Fixed and tested.	cristian_santos
A38	01/07/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A35	12/03/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A97	17/07/2015	Milling spindle requires repair	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A68	24/09/2015	Spindle indexing error with overfeed	Michele Williams noted: Repair completed.	michele_williams
A96	22/08/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A32	21/03/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A27	23/10/2015	Maintenance on milling spindle needed	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A6	16/09/2015	Unit lost electrical power	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A57	04/03/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A15	15/04/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A62	16/02/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A19	07/01/2016	Turret A and B are leaking	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A95	10/06/2015	Spindle fails to index, overfeeding	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A47	27/05/2015	Turret A and B are leaking	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A93	03/07/2015	Milling spindle requires repair	Michele Williams noted: Fixed and tested.	michele_williams
A32	30/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A52	02/07/2015	Repair work needed on milling spindle	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A23	11/08/2015	Inspect and recharge accumulators	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A46	01/10/2015	Turret sections A & B showing leaks	Michele Williams noted: System checked and accumulators charged.	michele_williams
A17	02/01/2016	Leak in side B hydraulic line	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A52	22/05/2015	Power supply failure detected	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A65	23/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A81	22/03/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Repair completed.	cristian_santos
A96	28/09/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A30	06/05/2015	Turret A and B are leaking	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A16	01/09/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A43	06/08/2015	Machine is unpowered	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A29	07/03/2015	Hydraulic line leak on side B	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A58	11/02/2015	Leaks found at turrets A and B	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A43	25/02/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A97	21/07/2015	Accumulators need checking and charging	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A73	01/07/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Detail not recorded.	michele_williams
A99	28/08/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado

A45	28/03/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A26	20/03/2015	Accumulator inspection and charging required	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A52	30/03/2015	Spindle indexing error with overfeed	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A84	20/03/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A18	08/11/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A23	26/03/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Repair completed.	michele_williams
A92	12/09/2015	Milling spindle requires repair	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A61	27/03/2015	Inspect and recharge accumulators	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A87	12/11/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A1	26/04/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A73	06/10/2015	Unit lost electrical power	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A71	09/11/2015	Maintenance on milling spindle needed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A56	31/05/2015	Saw attachment is leaking hydraulics	Michele Williams noted: No further details.	michele_williams
A15	06/10/2015	Spindle fails to index, overfeeding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A55	01/11/2015	Maintenance on milling spindle needed	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A36	31/03/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A91	06/05/2015	Maintenance on milling spindle needed	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A24	16/06/2015	Leaks found at turrets A and B	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A48	11/05/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A85	28/08/2015	Milling spindle requires repair	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A81	18/04/2015	Power supply failure detected	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A86	09/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A42	23/06/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A74	07/04/2015	Unit lost electrical power	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A13	17/08/2015	Unit lost electrical power	Gina Moore noted: No further details.	gina_moore, dylan_miller
A90	23/01/2015	Unit lost electrical power	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A31	18/08/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A72	28/06/2015	Repair work needed on milling spindle	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A64	26/05/2015	Turret A and B are leaking	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A46	16/08/2015	Spindle indexing error with overfeed	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A50	13/02/2015	Spindle fails to index, overfeeding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A1	25/04/2015	Repair work needed on milling spindle	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A16	19/02/2015	Machine is unpowered	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A58	02/11/2015	Turret sections A & B showing leaks	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A66	20/07/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A66	03/06/2015	Hydraulic line leak on side B	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A79	02/12/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A88	31/07/2015	Accumulator inspection and charging required	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A62	21/09/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A29	07/11/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A99	19/07/2015	Leaks found at turrets A and B	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A77	10/06/2015	Machine is unpowered	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A20	03/08/2015	Repair work needed on milling spindle	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A67	23/10/2015	Machine is unpowered	Michele Williams noted: Maintenance action successful.	michele_williams
A18	12/07/2015	Spindle indexing error with overfeed	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A34	30/03/2015	Leak in side B hydraulic line	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A19	20/03/2015	Spindle fails to index, overfeeding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A49	17/02/2015	Machine is unpowered	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A36	11/06/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A78	07/07/2015	Maintenance on milling spindle needed	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A18	07/09/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A78	15/04/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A12	05/07/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A91	09/10/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A93	21/07/2015	Milling spindle requires repair	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A74	24/09/2015	Inspect and recharge accumulators	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A61	28/02/2015	Turret A and B are leaking	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A79	15/04/2015	Spindle indexing error with overfeed	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A10	04/10/2015	Accumulators need checking and charging	Michele Williams noted: Detail not recorded.	michele_williams
A47	02/07/2015	Machine is unpowered	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A9	17/11/2015	Leaks found at turrets A and B	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A9	12/08/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A92	01/09/2015	Spindle indexing error with overfeed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A28	06/09/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A18	20/05/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A43	13/07/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Fixed and tested.	cristian_santos
A37	25/02/2015	Leak in side B hydraulic line	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A5	28/06/2015	Accumulator inspection and charging required	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A87	09/09/2015	Inspect and recharge accumulators	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A48	18/01/2015	Power supply failure detected	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams

A36	15/07/2015	Turret A and B are leaking	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A26	25/08/2015	Turret A and B are leaking	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A18	30/07/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A94	04/10/2015	Maintenance on milling spindle needed	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A31	05/07/2015	Machine is unpowered	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A5	18/06/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A4	20/01/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A76	09/11/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A10	05/07/2015	Leaks found at turrets A and B	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A19	03/08/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A37	06/06/2015	Repair work needed on milling spindle	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A21	03/06/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A20	22/01/2015	Hydraulic line leak on side B	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A41	18/08/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A94	28/09/2015	Power supply failure detected	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A78	06/07/2015	Milling spindle requires repair	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A76	07/01/2016	Repair work needed on milling spindle	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A94	10/05/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A75	02/07/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Detail not recorded.	cristian_santos
A9	11/10/2015	Unit lost electrical power	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A23	28/04/2015	Hydraulic line leak on side B	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A48	01/12/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A4	05/03/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A59	02/02/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A37	27/09/2015	Hydraulic line leak on side B	Nathan Maldonado noted: No further details.	nathan_maldonado
A73	02/08/2015	Repair work needed on milling spindle	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A13	05/06/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A62	24/03/2015	Inspect and recharge accumulators	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A36	01/06/2015	Accumulators need checking and charging	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A65	09/12/2015	Spindle indexing error with overfeed	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A11	10/01/2016	Machine is unpowered	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A6	28/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A4	11/06/2015	Machine is unpowered	Michele Williams noted: System checked and accumulators charged.	michele_williams
A61	16/10/2015	Leaks found at turrets A and B	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A13	18/04/2015	Turret sections A & B showing leaks	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A1	12/02/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A96	31/01/2015	Turret A and B are leaking	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A47	27/06/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A4	03/10/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A49	23/05/2015	Hydraulic line leak on side B	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A11	18/05/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Fixed and tested.	michele_williams
A7	21/07/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A29	10/08/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A92	06/01/2016	Leak in side B hydraulic line	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A54	16/01/2015	Accumulator inspection and charging required	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A23	28/12/2015	Inspect and recharge accumulators	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A77	21/06/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A74	21/10/2015	Power supply failure detected	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A52	20/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A68	02/06/2015	Repair work needed on milling spindle	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A86	07/07/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A7	30/01/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A79	13/10/2015	Accumulator inspection and charging required	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A62	20/02/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A94	07/06/2015	Accumulators need checking and charging	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A4	16/04/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A41	26/04/2015	Leak in side B hydraulic line	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A48	30/09/2015	Power supply failure detected	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A4	12/01/2016	Accumulator inspection and charging required	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A70	08/03/2015	Unit lost electrical power	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A75	21/01/2015	Spindle indexing error with overfeed	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A28	05/04/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A31	06/06/2015	Inspect and recharge accumulators	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A90	13/08/2015	Hydraulic line leak on side B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A21	07/05/2015	Milling spindle requires repair	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A46	28/07/2015	Maintenance on milling spindle needed	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A87	20/12/2015	Leak in side B hydraulic line	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A3	21/11/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A80	12/09/2015	Machine is unpowered	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A64	10/02/2015	Hydraulic line leak on side B	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams

A2	02/12/2015	Leaks found at turrets A and B	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A40	02/03/2015	Turret A and B are leaking	Michele Williams noted: Repair completed.	michele_williams
A88	19/10/2015	Spindle indexing error with overfeed	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A85	17/04/2015	Hydraulic line leak on side B	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A86	06/07/2015	Accumulators need checking and charging	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A20	07/08/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A86	20/12/2015	Inspect and recharge accumulators	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A38	07/06/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: System checked and accumulators charged.	michele_williams
A31	15/12/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A81	02/11/2015	Machine is unpowered	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A92	06/05/2015	Milling spindle requires repair	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A6	04/10/2015	Inspect and recharge accumulators	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A48	23/06/2015	Turret A and B are leaking	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A22	07/12/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A60	09/06/2015	Accumulators need checking and charging	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A10	29/10/2015	Leaks found at turrets A and B	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A1	15/02/2015	Leak in side B hydraulic line	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A11	30/11/2015	Repair work needed on milling spindle	Michele Williams noted: Maintenance action successful.	michele_williams
A61	26/02/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A58	31/05/2015	Power supply failure detected	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A13	10/02/2015	Spindle fails to index, overfeeding	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A20	17/07/2015	Spindle fails to index, overfeeding	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A15	13/09/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A37	20/06/2015	Turret sections A & B showing leaks	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A30	24/03/2015	Machine is unpowered	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A74	20/12/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A56	03/03/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A97	01/10/2015	Unit lost electrical power	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A60	19/01/2015	Turret A and B are leaking	Cristian Santos noted: Maintenance action successful.	cristian_santos
A7	06/07/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A98	30/07/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A18	03/06/2015	Machine is unpowered	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A82	06/02/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A93	16/07/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A86	26/11/2015	Machine is unpowered	Nathan Maldonado noted: No further details.	nathan_maldonado
A51	07/12/2015	Accumulators need checking and charging	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A28	17/04/2015	Power supply failure detected	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A76	22/12/2015	Milling spindle requires repair	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A93	07/07/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A34	31/07/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A9	31/07/2015	Repair work needed on milling spindle	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A36	07/11/2015	Turret A and B are leaking	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A17	14/10/2015	Hydraulic line leak on side B	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A89	18/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A59	02/07/2015	Turret A and B are leaking	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A74	23/08/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A30	28/06/2015	Accumulators need checking and charging	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A2	27/03/2015	Hydraulic line leak on side B	Michele Williams noted: Repair completed.	michele_williams
A46	06/12/2015	Spindle indexing error with overfeed	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A32	02/12/2015	Machine is unpowered	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A7	26/01/2015	Repair work needed on milling spindle	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A61	12/11/2015	Accumulators need checking and charging	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A2	13/04/2015	Inspect and recharge accumulators	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A61	10/11/2015	Milling spindle requires repair	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A63	29/05/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A97	04/01/2016	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A65	29/06/2015	Machine is unpowered	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A46	01/02/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A38	16/11/2015	Milling spindle requires repair	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A38	06/01/2016	Accumulators need checking and charging	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A23	19/03/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A2	14/12/2015	Machine is unpowered	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A88	17/07/2015	Accumulator inspection and charging required	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A29	25/02/2015	Spindle fails to index, overfeeding	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A69	08/06/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A66	28/11/2015	Leak in side B hydraulic line	Michele Williams noted: Detail not recorded.	michele_williams
A84	11/12/2015	Unit lost electrical power	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A27	14/10/2015	Milling spindle requires repair	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A3	20/09/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Repair completed.	michele_williams
A94	12/07/2015	Maintenance on milling spindle needed	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller

A56	14/03/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A49	01/07/2015	Accumulator inspection and charging required	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A23	01/02/2015	Leak in side B hydraulic line	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A50	06/01/2016	Saw attachment is leaking hydraulics	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A60	19/07/2015	Leak in side B hydraulic line	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A23	31/08/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A80	10/04/2015	Milling spindle requires repair	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A17	11/10/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: No further details.	nathan_maldonado
A51	11/10/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A25	20/06/2015	Unit lost electrical power	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A64	29/06/2015	Power supply failure detected	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A94	29/08/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A73	13/05/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A79	25/12/2015	Leaks found at turrets A and B	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A33	22/07/2015	Turret A and B are leaking	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A73	30/11/2015	Unit lost electrical power	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A57	23/04/2015	Accumulator inspection and charging required	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A4	17/09/2015	Turret A and B are leaking	Cristian Santos noted: No additional information provided.	cristian_santos
A15	04/02/2015	Hydraulic line leak on side B	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A5	16/06/2015	Unit lost electrical power	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A47	26/03/2015	Repair work needed on milling spindle	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A30	13/10/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A90	13/03/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A71	23/01/2015	Unit lost electrical power	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A24	13/01/2016	Accumulator inspection and charging required	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A21	22/07/2015	Leak in side B hydraulic line	Cristian Santos noted: Fixed and tested.	cristian_santos
A60	10/03/2015	Hydraulic line leak on side B	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A92	03/03/2015	Milling spindle requires repair	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A22	05/12/2015	Spindle indexing error with overfeed	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A61	04/05/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A52	13/08/2015	Hydraulic line leak on side B	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A60	18/06/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A37	09/04/2015	Turret A and B are leaking	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A81	15/02/2015	Leaks found at turrets A and B	Cristian Santos noted: Detail not recorded.	cristian_santos
A66	11/04/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A36	27/02/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A57	18/07/2015	Spindle fails to index, overfeeding	Michele Williams noted: No further details.	michele_williams
A55	25/04/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A82	12/05/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A27	13/04/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A91	22/06/2015	Turret sections A & B showing leaks	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A71	18/09/2015	Turret A and B are leaking	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A6	22/08/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A19	20/02/2015	Unit lost electrical power	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A79	20/03/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A12	08/12/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A88	13/08/2015	Leaks found at turrets A and B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A32	15/03/2015	Spindle indexing error with overfeed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A50	24/05/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A57	22/06/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A87	25/02/2015	Hydraulic line leak on side B	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A83	08/08/2015	Maintenance on milling spindle needed	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A77	20/08/2015	Milling spindle requires repair	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A4	02/10/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A76	15/10/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: No further details.	cristian_santos
A38	01/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A61	08/02/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A65	14/02/2015	Unit lost electrical power	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A18	09/12/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A16	19/10/2015	Power supply failure detected	Cristian Santos noted: Repair completed.	cristian_santos
A72	06/09/2015	Leaks found at turrets A and B	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A99	29/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A49	06/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A15	23/06/2015	Power supply failure detected	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A10	20/10/2015	Milling spindle requires repair	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A12	28/09/2015	Power supply failure detected	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A70	10/05/2015	Unit lost electrical power	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A68	22/03/2015	Milling spindle requires repair	Michele Williams noted: Detail not recorded.	michele_williams
A53	27/06/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A39	12/09/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado

A14	02/09/2015	Machine is unpowered	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A14	21/03/2015	Machine is unpowered	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A70	03/11/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A8	27/09/2015	Saw attachment gears are binding and grinding	Michele Williams noted: System checked and accumulators charged.	michele_williams
A32	25/11/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A79	21/12/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A68	16/03/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A19	16/02/2015	Leak in side B hydraulic line	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A66	07/07/2015	Inspect and recharge accumulators	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A30	15/10/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A41	27/10/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Maintenance action successful.	cristian_santos
A25	05/03/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A21	24/10/2015	Accumulator inspection and charging required	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A76	29/09/2015	Unit lost electrical power	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A61	09/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A64	12/05/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A38	17/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A74	01/11/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A65	08/11/2015	Accumulator inspection and charging required	Cristian Santos noted: Fixed and tested.	cristian_santos
A35	04/09/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A55	21/06/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A2	28/04/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A76	14/12/2015	Unit lost electrical power	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A82	04/08/2015	Machine is unpowered	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A14	03/12/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A52	16/03/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A2	02/11/2015	Spindle indexing error with overfeed	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A79	15/01/2015	Hydraulic line leak on side B	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A94	31/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A85	06/10/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A27	09/03/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Maintenance action successful.	cristian_santos
A75	25/01/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A24	14/07/2015	Inspect and recharge accumulators	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A59	06/05/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A48	06/03/2015	Hydraulic line leak on side B	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A16	03/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A10	01/01/2016	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A10	03/02/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A18	16/11/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A37	19/11/2015	Spindle fails to index, overfeeding	Michele Williams noted: No additional information provided.	michele_williams
A82	16/03/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A30	03/07/2015	Machine is unpowered	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A87	24/01/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A95	04/07/2015	Hydraulic line leak on side B	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A23	11/10/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Fixed and tested.	cristian_santos
A62	02/01/2016	Leak in side B hydraulic line	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A43	13/03/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A86	16/06/2015	Hydraulic hose on side B is leaking	Gina Moore noted: No further details.	gina_moore, dylan_miller
A24	23/12/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A31	03/11/2015	Machine is unpowered	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A84	05/12/2015	Turret sections A & B showing leaks	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A3	21/07/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Detail not recorded.	cristian_santos
A34	06/07/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A81	15/06/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A90	24/02/2015	Machine is unpowered	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A85	01/12/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A70	25/05/2015	Turret sections A & B showing leaks	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A23	30/09/2015	Power supply failure detected	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A6	19/09/2015	Leak in side B hydraulic line	Cristian Santos noted: Repair completed.	cristian_santos
A24	07/01/2016	Hydraulic hose on side B is leaking	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A97	21/04/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A32	04/07/2015	Inspect and recharge accumulators	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A85	05/12/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A81	24/09/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A16	05/07/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A21	05/02/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A40	14/10/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A42	29/11/2015	Spindle indexing error with overfeed	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A7	12/07/2015	Accumulators need checking and charging	Michele Williams noted: Maintenance action successful.	michele_williams
A37	25/12/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams

A34	17/09/2015	Turret A and B are leaking	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A24	03/03/2015	Hydraulic line leak on side B	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A36	22/09/2015	Turret A and B are leaking	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A7	24/07/2015	Accumulator inspection and charging required	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A88	19/07/2015	Spindle indexing error with overfeed	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A20	22/01/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A38	01/06/2015	Accumulator inspection and charging required	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A49	23/09/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A16	11/08/2015	Leak in side B hydraulic line	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A57	28/10/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A78	26/05/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A75	27/07/2015	Turret sections A & B showing leaks	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A9	10/02/2015	Turret sections A & B showing leaks	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A18	28/10/2015	Maintenance on milling spindle needed	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A84	27/10/2015	Turret A and B are leaking	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A37	02/11/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A80	24/11/2015	Spindle fails to index, overfeeding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A99	31/01/2015	Turret A and B are leaking	Cristian Santos noted: Maintenance action successful.	cristian_santos
A27	20/12/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A83	21/10/2015	Leak in side B hydraulic line	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A40	21/09/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Fixed and tested.	cristian_santos
A26	22/07/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A86	07/06/2015	Leaks found at turrets A and B	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A38	27/05/2015	Spindle fails to index, overfeeding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A93	03/04/2015	Turret A and B are leaking	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A54	19/05/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A8	05/12/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A98	22/11/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: No further details.	gina_moore, dylan_miller
A67	16/03/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A49	19/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A26	25/07/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A98	24/05/2015	Maintenance on milling spindle needed	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A16	04/10/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A84	17/09/2015	Machine is unpowered	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A49	06/11/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A18	28/03/2015	Leaks found at turrets A and B	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A68	04/11/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A15	28/06/2015	Maintenance on milling spindle needed	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A13	16/06/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A14	10/03/2015	Turret A and B are leaking	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A60	19/04/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A96	20/12/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A70	18/01/2015	Inspect and recharge accumulators	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A61	06/11/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A75	12/07/2015	Hydraulic line leak on side B	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A52	10/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A93	11/10/2015	Hydraulic line leak on side B	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A38	09/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A33	04/10/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A36	03/02/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A58	01/04/2015	Turret A and B are leaking	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A57	29/12/2015	Turret A and B are leaking	Cristian Santos noted: Detail not recorded.	cristian_santos
A53	29/10/2015	Power supply failure detected	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A21	12/11/2015	Maintenance on milling spindle needed	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A36	25/12/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A29	02/03/2015	Accumulator inspection and charging required	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A22	25/12/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A39	30/12/2015	Inspect and recharge accumulators	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A62	07/01/2016	Leaks found at turrets A and B	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A69	13/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A8	11/10/2015	Unit lost electrical power	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A14	22/07/2015	Repair work needed on milling spindle	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A74	07/04/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A38	13/06/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A37	08/01/2016	Machine is unpowered	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A1	09/05/2015	Saw attachment gears are binding and grinding	Michele Williams noted: System checked and accumulators charged.	michele_williams
A99	11/10/2015	Spindle fails to index, overfeeding	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A7	30/09/2015	Machine is unpowered	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A45	04/04/2015	Repair work needed on milling spindle	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A33	10/03/2015	Spindle indexing error with overfeed	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller

A38	15/07/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A88	16/11/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A15	03/07/2015	Turret sections A & B showing leaks	Cristian Santos noted: Fixed and tested.	cristian_santos
A12	18/07/2015	Milling spindle requires repair	Gina Moore noted: No further details.	gina_moore, dylan_miller
A56	18/02/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A41	07/05/2015	Spindle indexing error with overfeed	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A32	17/02/2015	Maintenance on milling spindle needed	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A9	27/03/2015	Turret sections A & B showing leaks	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A32	25/02/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A17	24/09/2015	Turret sections A & B showing leaks	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A31	08/12/2015	Power supply failure detected	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A94	30/06/2015	Turret sections A & B showing leaks	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A94	15/08/2015	Hydraulic line leak on side B	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A38	08/03/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A47	21/01/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A10	05/09/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A74	21/09/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A56	25/02/2015	Spindle fails to index, overfeeding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A19	25/02/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A18	17/02/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Repair completed.	cristian_santos
A97	12/07/2015	Accumulator inspection and charging required	Cristian Santos noted: Repair completed.	cristian_santos
A17	08/10/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A93	19/07/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Repair completed.	michele_williams
A60	28/08/2015	Spindle fails to index, overfeeding	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A13	01/08/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: No further details.	nathan_maldonado
A28	20/09/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A49	20/03/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A41	17/05/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A11	24/05/2015	Turret A and B are leaking	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A87	18/08/2015	Accumulators need checking and charging	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A99	14/04/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A62	25/11/2015	Leak in side B hydraulic line	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A95	07/02/2015	Spindle indexing error with overfeed	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A98	27/02/2015	Turret A and B are leaking	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A50	07/04/2015	Unit lost electrical power	Cristian Santos noted: Maintenance action successful.	cristian_santos
A70	05/01/2016	Hydraulic fluid leak at saw attachment	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A55	10/07/2015	Hydraulic line leak on side B	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A10	09/06/2015	Spindle fails to index, overfeeding	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A80	02/06/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A28	17/03/2015	Maintenance on milling spindle needed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A99	05/11/2015	Accumulators need checking and charging	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A36	22/12/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A19	05/11/2015	Turret A and B are leaking	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A55	25/02/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A81	26/03/2015	Maintenance on milling spindle needed	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A68	06/07/2015	Repair work needed on milling spindle	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A33	03/01/2016	Spindle indexing error with overfeed	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A78	26/12/2015	Accumulators need checking and charging	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A51	19/01/2015	Turret A and B are leaking	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A48	31/08/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A84	14/02/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A24	23/04/2015	Machine is unpowered	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A35	25/03/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A66	13/05/2015	Accumulators need checking and charging	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A87	26/12/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A83	23/07/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A39	24/06/2015	Repair work needed on milling spindle	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A78	21/07/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A2	25/02/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Repair completed.	michele_williams
A41	25/11/2015	Turret A and B are leaking	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A81	15/01/2015	Unit lost electrical power	Michele Williams noted: Repair completed.	michele_williams
A49	24/02/2015	Milling spindle requires repair	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A18	19/11/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A17	22/03/2015	Milling spindle requires repair	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A92	21/10/2015	Machine is unpowered	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A91	07/06/2015	Leak in side B hydraulic line	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A96	15/11/2015	Unit lost electrical power	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A55	19/06/2015	Turret sections A & B showing leaks	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A53	15/12/2015	Inspect and recharge accumulators	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A41	31/03/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller

A62	23/03/2015	Turret A and B are leaking	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A97	19/12/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A12	23/12/2015	Leaks found at turrets A and B	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A36	18/11/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A34	29/10/2015	Machine is unpowered	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A34	02/03/2015	Turret A and B are leaking	Michele Williams noted: No further details.	michele_williams
A14	22/07/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A65	08/09/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A34	18/01/2015	Accumulator inspection and charging required	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A64	13/07/2015	Accumulators need checking and charging	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A31	05/11/2015	Unit lost electrical power	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A51	29/06/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A6	09/04/2015	Turret A and B are leaking	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A86	10/06/2015	Leak in side B hydraulic line	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A17	07/08/2015	Unit lost electrical power	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A85	23/04/2015	Accumulators need checking and charging	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A34	08/02/2015	Power supply failure detected	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A2	03/09/2015	Power supply failure detected	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A74	25/03/2015	Spindle indexing error with overfeed	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A49	04/02/2015	Leaks found at turrets A and B	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A15	21/02/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A4	01/05/2015	Machine is unpowered	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A72	10/04/2015	Machine is unpowered	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A10	25/10/2015	Unit lost electrical power	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A9	08/09/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A10	23/08/2015	Power supply failure detected	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A49	25/05/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A90	03/05/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A34	14/04/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A55	23/12/2015	Leaks found at turrets A and B	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A54	30/03/2015	Turret A and B are leaking	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A6	13/09/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A19	09/07/2015	Repair work needed on milling spindle	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A32	09/04/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A93	04/09/2015	Power supply failure detected	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A15	15/01/2015	Maintenance on milling spindle needed	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A49	29/09/2015	Leak in side B hydraulic line	Nathan Maldonado noted: No further details.	nathan_maldonado
A63	25/02/2015	Spindle fails to index, overfeeding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A74	26/12/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A17	28/02/2015	Hydraulic line leak on side B	Michele Williams noted: No additional information provided.	michele_williams
A43	23/11/2015	Machine is unpowered	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A53	22/09/2015	Leak in side B hydraulic line	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A21	15/07/2015	Unit lost electrical power	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A82	13/11/2015	Hydraulic line leak on side B	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A94	08/03/2015	Milling spindle requires repair	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A81	25/01/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A88	26/04/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A18	07/02/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A8	02/06/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A52	29/06/2015	Leaks found at turrets A and B	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A66	11/04/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A53	07/11/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A71	06/09/2015	Power supply failure detected	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A84	05/07/2015	Leak in side B hydraulic line	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A16	16/12/2015	Accumulators need checking and charging	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A81	04/05/2015	Inspect and recharge accumulators	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A91	23/09/2015	Turret A and B are leaking	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A48	21/10/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A10	05/09/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Fixed and tested.	michele_williams
A80	12/04/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: No further details.	michele_williams
A24	15/06/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A25	23/02/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A52	23/11/2015	Turret sections A & B showing leaks	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A70	14/04/2015	Spindle indexing error with overfeed	Michele Williams noted: No additional information provided.	michele_williams
A54	25/01/2015	Hydraulic line leak on side B	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A83	15/09/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A21	22/05/2015	Machine is unpowered	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A29	24/10/2015	Turret sections A & B showing leaks	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A50	10/02/2015	Turret sections A & B showing leaks	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A71	02/12/2015	Power supply failure detected	Michele Williams noted: Reviewed; system operating normally.	michele_williams

A56	20/11/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A36	10/08/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A71	08/01/2016	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A28	07/02/2015	Spindle indexing error with overfeed	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A2	13/05/2015	Repair work needed on milling spindle	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A81	29/09/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A38	03/03/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A84	16/02/2015	Turret sections A & B showing leaks	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A88	03/02/2015	Accumulator inspection and charging required	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A8	17/06/2015	Turret sections A & B showing leaks	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A34	16/12/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A91	15/12/2015	Inspect and recharge accumulators	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A7	05/02/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A33	11/09/2015	Turret A and B are leaking	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A98	16/10/2015	Turret sections A & B showing leaks	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A55	19/03/2015	Turret A and B are leaking	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A37	21/11/2015	Repair work needed on milling spindle	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A41	29/12/2015	Turret sections A & B showing leaks	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A25	22/10/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A95	05/05/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A37	27/06/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A13	10/05/2015	Leak in side B hydraulic line	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A3	25/02/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A70	25/12/2015	Accumulator inspection and charging required	Michele Williams noted: Maintenance action successful.	michele_williams
A48	06/07/2015	Hydraulic line leak on side B	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A49	11/04/2015	Hydraulic line leak on side B	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A73	23/09/2015	Leaks found at turrets A and B	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A11	29/10/2015	Turret sections A & B showing leaks	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A99	21/04/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A84	02/05/2015	Power supply failure detected	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A31	08/08/2015	Accumulators need checking and charging	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A64	25/03/2015	Turret A and B are leaking	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A77	28/02/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A13	09/07/2015	Turret sections A & B showing leaks	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A66	31/01/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A68	20/11/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: No further details.	cristian_santos
A61	17/09/2015	Leak in side B hydraulic line	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A70	14/01/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A35	04/01/2016	Gears on the saw attachment are too tight and grinding	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A57	24/07/2015	Repair work needed on milling spindle	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A64	21/12/2015	Turret sections A & B showing leaks	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A42	26/10/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A80	11/07/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: No further details.	nathan_maldonado
A64	04/12/2015	Turret sections A & B showing leaks	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A76	30/10/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A84	29/10/2015	Machine is unpowered	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A34	31/01/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A39	15/10/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A65	17/11/2015	Machine is unpowered	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A65	04/04/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A81	16/10/2015	Spindle indexing error with overfeed	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A59	08/08/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A1	31/01/2015	Unit lost electrical power	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A61	11/12/2015	Unit lost electrical power	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A71	15/06/2015	Accumulator inspection and charging required	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A54	25/05/2015	Leaks found at turrets A and B	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A83	24/11/2015	Maintenance on milling spindle needed	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A90	22/08/2015	Repair work needed on milling spindle	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A10	23/04/2015	Repair work needed on milling spindle	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A92	25/01/2015	Maintenance on milling spindle needed	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A93	06/04/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A34	26/03/2015	Maintenance on milling spindle needed	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A50	06/01/2016	Turret A and B are leaking	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A32	28/01/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A35	24/03/2015	Saw attachment is leaking hydraulics	Michele Williams noted: System checked and accumulators charged.	michele_williams
A58	01/01/2016	Indexing issue causing overfeed on spindle	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A20	20/03/2015	Milling spindle requires repair	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A94	27/05/2015	Milling spindle requires repair	Michele Williams noted: Maintenance action successful.	michele_williams
A14	29/09/2015	Maintenance on milling spindle needed	Cristian Santos noted: No additional information provided.	cristian_santos
A39	18/05/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado

A6	10/04/2015	Spindle indexing error with overfeed	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A74	12/04/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A14	19/01/2015	Hydraulic line leak on side B	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A20	11/10/2015	Milling spindle requires repair	Michele Williams noted: Detail not recorded.	michele_williams
A59	03/01/2016	Leaks found at turrets A and B	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A62	28/03/2015	Leaks found at turrets A and B	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A48	25/12/2015	Power supply failure detected	Cristian Santos noted: Fixed and tested.	cristian_santos
A8	29/11/2015	Leak in side B hydraulic line	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A67	26/06/2015	Turret sections A & B showing leaks	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A48	15/01/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A16	27/03/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A83	30/11/2015	Turret sections A & B showing leaks	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A41	15/08/2015	Turret A and B are leaking	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A30	10/06/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Detail not recorded.	michele_williams
A73	13/11/2015	Repair work needed on milling spindle	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A29	08/05/2015	Leak in side B hydraulic line	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A82	05/04/2015	Accumulators need checking and charging	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A49	24/07/2015	Accumulators need checking and charging	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A2	04/10/2015	Inspect and recharge accumulators	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A95	12/12/2015	Saw attachment is leaking hydraulics	Gina Moore noted: No further details.	gina_moore, dylan_miller
A11	02/09/2015	Leak in side B hydraulic line	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A85	17/06/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A54	05/02/2015	Milling spindle requires repair	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A59	30/08/2015	Turret A and B are leaking	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A84	23/01/2015	Maintenance on milling spindle needed	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A96	04/12/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A96	30/06/2015	Accumulator inspection and charging required	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A63	02/03/2015	Power supply failure detected	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A3	12/01/2016	Inspect and recharge accumulators	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A83	03/01/2016	Maintenance on milling spindle needed	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A34	10/08/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A9	25/11/2015	Milling spindle requires repair	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A57	16/07/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A31	12/07/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A36	04/05/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A23	19/02/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A38	29/11/2015	Spindle fails to index, overfeeding	Michele Williams noted: System checked and accumulators charged.	michele_williams
A92	25/01/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A48	20/03/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A80	31/01/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A26	15/01/2015	Turret sections A & B showing leaks	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A80	25/08/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A64	14/12/2015	Repair work needed on milling spindle	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A86	25/10/2015	Inspect and recharge accumulators	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A55	26/04/2015	Spindle indexing error with overfeed	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A80	23/06/2015	Accumulators need checking and charging	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A9	05/07/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A62	14/03/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A6	14/09/2015	Milling spindle requires repair	Michele Williams noted: Repair completed.	michele_williams
A59	14/01/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A21	01/03/2015	Power supply failure detected	Cristian Santos noted: Fixed and tested.	cristian_santos
A14	01/05/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A33	26/05/2015	Power supply failure detected	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A85	17/06/2015	Accumulators need checking and charging	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A16	04/10/2015	Power supply failure detected	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A68	11/01/2016	Spindle indexing error with overfeed	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A19	07/06/2015	Hydraulic hose on side B is leaking	Michele Williams noted: System checked and accumulators charged.	michele_williams
A87	29/11/2015	Unit lost electrical power	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A26	07/02/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Fixed and tested.	michele_williams
A18	09/03/2015	Turret sections A & B showing leaks	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A46	17/05/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A17	12/01/2016	Leak in side B hydraulic line	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A27	06/11/2015	Turret A and B are leaking	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A43	08/01/2016	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A20	23/03/2015	Spindle indexing error with overfeed	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A57	18/10/2015	Accumulators need checking and charging	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A14	03/09/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A55	14/04/2015	Turret sections A & B showing leaks	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A45	18/09/2015	Turret sections A & B showing leaks	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A3	23/01/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos

A2	18/07/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A14	26/08/2015	Turret A and B are leaking	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A60	01/07/2015	Leaks found at turrets A and B	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A31	28/07/2015	Machine is unpowered	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A58	18/08/2015	Power supply failure detected	Michele Williams noted: Detail not recorded.	michele_williams
A17	16/03/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A59	25/02/2015	Leak in side B hydraulic line	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A22	06/01/2016	Leaks found at turrets A and B	Michele Williams noted: No further details.	michele_williams
A22	07/05/2015	Turret A and B are leaking	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A71	21/10/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A48	29/10/2015	Spindle indexing error with overfeed	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A17	25/08/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A44	30/07/2015	Accumulator inspection and charging required	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A90	17/11/2015	Power supply failure detected	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A28	13/07/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A59	01/04/2015	Leak in side B hydraulic line	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A66	20/05/2015	Accumulator inspection and charging required	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A45	05/05/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A95	16/12/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A75	21/02/2015	Machine is unpowered	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A98	06/01/2016	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A78	23/01/2015	Accumulators need checking and charging	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A85	14/04/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A78	18/02/2015	Accumulator inspection and charging required	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A33	28/02/2015	Maintenance on milling spindle needed	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A26	29/06/2015	Maintenance on milling spindle needed	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A32	10/06/2015	Maintenance on milling spindle needed	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A53	28/08/2015	Repair work needed on milling spindle	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A62	29/05/2015	Turret A and B are leaking	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A10	03/10/2015	Maintenance on milling spindle needed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A9	06/12/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A49	29/08/2015	Accumulator inspection and charging required	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A49	15/01/2015	Turret A and B are leaking	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A2	28/01/2015	Leaks found at turrets A and B	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A3	05/01/2016	Indexing issue causing overfeed on spindle	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A45	23/04/2015	Spindle indexing error with overfeed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A43	10/07/2015	Machine is unpowered	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A4	09/06/2015	Power supply failure detected	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A59	27/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A79	15/04/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Maintenance action successful.	michele_williams
A47	05/05/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A49	03/05/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A8	11/07/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A70	18/12/2015	Maintenance on milling spindle needed	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A32	29/11/2015	Spindle fails to index, overfeeding	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A99	10/10/2015	Unit lost electrical power	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A3	08/02/2015	Power supply failure detected	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A14	22/02/2015	Maintenance on milling spindle needed	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A98	08/10/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A2	18/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A47	21/06/2015	Accumulators need checking and charging	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A33	27/06/2015	Inspect and recharge accumulators	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A63	19/03/2015	Machine is unpowered	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A8	13/12/2015	Unit lost electrical power	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A83	13/07/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A68	18/08/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A91	07/03/2015	Turret A and B are leaking	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A29	12/08/2015	Accumulator inspection and charging required	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A28	21/09/2015	Unit lost electrical power	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A57	06/06/2015	Unit lost electrical power	Cristian Santos noted: No further details.	cristian_santos
A63	17/02/2015	Accumulators need checking and charging	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A28	17/08/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A79	11/12/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A7	22/12/2015	Leaks found at turrets A and B	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A12	16/08/2015	Repair work needed on milling spindle	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A86	04/07/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A55	10/04/2015	Accumulators need checking and charging	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A27	01/06/2015	Leaks found at turrets A and B	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A66	11/08/2015	Turret sections A & B showing leaks	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A54	03/07/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Repair completed.	nathan_maldonado

A53	14/12/2015	Maintenance on milling spindle needed	Michele Williams noted: Fixed and tested.	michele_williams
A94	18/08/2015	Power supply failure detected	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A15	04/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: No further details.	cristian_santos
A99	22/07/2015	Inspect and recharge accumulators	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A43	29/10/2015	Maintenance on milling spindle needed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A41	17/11/2015	Accumulators need checking and charging	Michele Williams noted: Repair completed.	michele_williams
A84	20/01/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A92	21/03/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A26	11/02/2015	Turret sections A & B showing leaks	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A35	26/11/2015	Inspect and recharge accumulators	Michele Williams noted: No further details.	michele_williams
A7	07/09/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A84	26/04/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A57	16/01/2015	Turret sections A & B showing leaks	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A30	18/10/2015	Milling spindle requires repair	Cristian Santos noted: Detail not recorded.	cristian_santos
A4	07/05/2015	Repair work needed on milling spindle	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A77	03/10/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A34	28/09/2015	Turret sections A & B showing leaks	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A98	12/04/2015	Repair work needed on milling spindle	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A33	29/08/2015	Spindle indexing error with overfeed	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A46	08/11/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A56	03/04/2015	Spindle indexing error with overfeed	Michele Williams noted: Maintenance action successful.	michele_williams
A12	15/08/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A37	20/05/2015	Turret sections A & B showing leaks	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A8	03/10/2015	Power supply failure detected	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A4	15/06/2015	Accumulator inspection and charging required	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A54	05/03/2015	Unit lost electrical power	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A80	06/05/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A43	26/07/2015	Power supply failure detected	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A83	25/05/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A6	04/01/2016	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A62	13/05/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A8	16/01/2015	Maintenance on milling spindle needed	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A93	04/03/2015	Turret A and B are leaking	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A34	04/04/2015	Inspect and recharge accumulators	Cristian Santos noted: Maintenance action successful.	cristian_santos
A79	26/05/2015	Spindle indexing error with overfeed	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A59	11/06/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A78	10/03/2015	Spindle indexing error with overfeed	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A44	21/07/2015	Machine is unpowered	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A15	05/10/2015	Repair work needed on milling spindle	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A54	22/02/2015	Accumulator inspection and charging required	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A97	22/01/2015	Turret A and B are leaking	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A91	26/05/2015	Unit lost electrical power	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A30	13/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A97	15/01/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A43	19/10/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A37	02/03/2015	Turret A and B are leaking	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A19	27/04/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A56	31/03/2015	Spindle fails to index, overfeeding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A12	14/09/2015	Turret A and B are leaking	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A23	02/04/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A48	30/12/2015	Leaks found at turrets A and B	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A88	05/09/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A34	18/08/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A36	25/02/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A96	02/01/2016	Inspect and recharge accumulators	Michele Williams noted: No additional information provided.	michele_williams
A79	03/02/2015	Turret A and B are leaking	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A36	13/06/2015	Hydraulic hose on side B is leaking	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A28	19/05/2015	Turret A and B are leaking	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A55	18/10/2015	Turret sections A & B showing leaks	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A54	12/08/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A77	28/12/2015	Unit lost electrical power	Michele Williams noted: Fixed and tested.	michele_williams
A69	05/09/2015	Turret A and B are leaking	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A67	01/08/2015	Spindle fails to index, overfeeding	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A51	03/03/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A18	08/08/2015	Accumulator inspection and charging required	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A74	08/11/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A35	17/04/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A96	15/11/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A49	03/12/2015	Turret sections A & B showing leaks	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A56	08/10/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller

A51	22/03/2015	Accumulator inspection and charging required	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A99	02/05/2015	Spindle indexing error with overfeed	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A8	23/08/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A20	21/04/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A69	02/01/2016	Turret sections A & B showing leaks	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A88	20/01/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A70	07/12/2015	Machine is unpowered	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A43	12/06/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A81	23/10/2015	Accumulators need checking and charging	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A77	09/06/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A14	11/09/2015	Accumulator inspection and charging required	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A89	15/10/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A86	28/11/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A35	26/01/2015	Leak in side B hydraulic line	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A17	23/04/2015	Machine is unpowered	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A33	03/05/2015	Turret A and B are leaking	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A21	03/12/2015	Spindle fails to index, overfeeding	Michele Williams noted: Fixed and tested.	michele_williams
A74	25/11/2015	Leak in side B hydraulic line	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A33	22/11/2015	Hydraulic line leak on side B	Gina Moore noted: No further details.	gina_moore, dylan_miller
A68	27/04/2015	Power supply failure detected	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A61	19/01/2015	Turret sections A & B showing leaks	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A69	03/05/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A87	15/12/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: System checked and accumulators charged.	michele_williams
A97	13/11/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A91	05/03/2015	Leak in side B hydraulic line	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A73	04/10/2015	Repair work needed on milling spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A95	21/06/2015	Inspect and recharge accumulators	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A38	11/10/2015	Accumulator inspection and charging required	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A45	14/08/2015	Leak in side B hydraulic line	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A28	01/09/2015	Leaks found at turrets A and B	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A43	19/09/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A95	16/05/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A82	10/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A3	26/01/2015	Machine is unpowered	Cristian Santos noted: Maintenance action successful.	cristian_santos
A68	17/08/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A96	13/10/2015	Unit lost electrical power	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A98	16/04/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A24	03/01/2016	Indexing issue causing overfeed on spindle	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A67	02/05/2015	Leak in side B hydraulic line	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A63	01/09/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A92	16/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A70	27/12/2015	Repair work needed on milling spindle	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A55	24/02/2015	Turret sections A & B showing leaks	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A4	19/09/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A74	09/03/2015	Accumulators need checking and charging	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A58	10/09/2015	Leaks found at turrets A and B	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A47	21/07/2015	Leaks found at turrets A and B	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A76	03/07/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A90	23/04/2015	Accumulator inspection and charging required	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A40	16/05/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A12	24/11/2015	Turret A and B are leaking	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A65	08/03/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A8	11/05/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Repair completed.	michele_williams
A57	16/02/2015	Leaks found at turrets A and B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A3	10/05/2015	Accumulator inspection and charging required	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A41	27/01/2015	Maintenance on milling spindle needed	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A93	24/04/2015	Turret sections A & B showing leaks	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A48	02/12/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A10	05/11/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Repair completed.	michele_williams
A78	23/03/2015	Unit lost electrical power	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A65	20/06/2015	Turret A and B are leaking	Gina Moore noted: No further details.	gina_moore, dylan_miller
A27	28/10/2015	Milling spindle requires repair	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A51	26/03/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A21	02/12/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A17	28/01/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A3	17/05/2015	Machine is unpowered	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A69	18/02/2015	Hydraulic line leak on side B	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A4	29/07/2015	Milling spindle requires repair	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A75	28/04/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A17	04/04/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams

A7	03/11/2015	Unit lost electrical power	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A95	14/04/2015	Machine is unpowered	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A15	19/03/2015	Maintenance on milling spindle needed	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A21	04/02/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A23	30/05/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A64	19/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A91	26/03/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A76	03/07/2015	Accumulator inspection and charging required	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A49	27/09/2015	Turret A and B are leaking	Cristian Santos noted: Detail not recorded.	cristian_santos
A49	30/12/2015	Accumulator inspection and charging required	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A20	21/10/2015	Milling spindle requires repair	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A73	09/03/2015	Repair work needed on milling spindle	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A63	01/03/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A39	20/12/2015	Power supply failure detected	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A71	22/05/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A50	05/06/2015	Accumulator inspection and charging required	Michele Williams noted: Detail not recorded.	michele_williams
A93	28/08/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A11	21/11/2015	Maintenance on milling spindle needed	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A51	24/08/2015	Leak in side B hydraulic line	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A72	28/06/2015	Accumulator inspection and charging required	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A31	11/02/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A3	09/06/2015	Leak in side B hydraulic line	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A58	21/06/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A41	30/10/2015	Leak in side B hydraulic line	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A95	14/08/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A17	18/12/2015	Unit lost electrical power	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A66	22/12/2015	Turret A and B are leaking	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A44	08/01/2016	Maintenance on milling spindle needed	Michele Williams noted: Detail not recorded.	michele_williams
A20	14/05/2015	Maintenance on milling spindle needed	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A48	25/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A68	08/04/2015	Turret sections A & B showing leaks	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A2	11/02/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A62	15/05/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Repair completed.	cristian_santos
A88	20/12/2015	Maintenance on milling spindle needed	Michele Williams noted: No additional information provided.	michele_williams
A58	31/01/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A9	09/06/2015	Accumulator inspection and charging required	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A64	11/06/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A66	01/02/2015	Inspect and recharge accumulators	Michele Williams noted: No further details.	michele_williams
A73	17/04/2015	Leaks found at turrets A and B	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A8	02/12/2015	Spindle indexing error with overfeed	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A81	03/06/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A74	17/06/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A85	09/07/2015	Accumulators need checking and charging	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A64	28/05/2015	Turret sections A & B showing leaks	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A79	16/04/2015	Power supply failure detected	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A53	31/05/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A75	10/12/2015	Power supply failure detected	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A22	26/10/2015	Leaks found at turrets A and B	Michele Williams noted: System checked and accumulators charged.	michele_williams
A83	09/09/2015	Leak in side B hydraulic line	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A98	26/02/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Fixed and tested.	michele_williams
A16	12/04/2015	Milling spindle requires repair	Nathan Maldonado noted: No further details.	nathan_maldonado
A60	27/03/2015	Leaks found at turrets A and B	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A89	29/03/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A79	27/08/2015	Milling spindle requires repair	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A94	07/07/2015	Maintenance on milling spindle needed	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A23	20/03/2015	Unit lost electrical power	Michele Williams noted: Fixed and tested.	michele_williams
A68	10/11/2015	Unit lost electrical power	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A57	04/08/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A9	09/02/2015	Unit lost electrical power	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A38	15/05/2015	Accumulator inspection and charging required	Michele Williams noted: No additional information provided.	michele_williams
A73	22/11/2015	Inspect and recharge accumulators	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A94	08/05/2015	Repair work needed on milling spindle	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A15	31/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A55	23/09/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A41	24/12/2015	Maintenance on milling spindle needed	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A95	04/09/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A50	22/05/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A46	17/02/2015	Unit lost electrical power	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A6	04/02/2015	Inspect and recharge accumulators	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A3	02/06/2015	Turret sections A & B showing leaks	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams

A78	10/08/2015	Leak in side B hydraulic line	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A57	17/04/2015	Spindle indexing error with overfeed	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A54	25/01/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A49	04/01/2016	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A15	20/10/2015	Spindle fails to index, overfeeding	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A37	31/10/2015	Maintenance on milling spindle needed	Michele Williams noted: Fixed and tested.	michele_williams
A20	24/01/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A31	26/11/2015	Accumulator inspection and charging required	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A87	08/01/2016	Saw attachment gears are binding and grinding	Cristian Santos noted: Detail not recorded.	cristian_santos
A88	05/03/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A13	01/07/2015	Milling spindle requires repair	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A53	15/12/2015	Spindle fails to index, overfeeding	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A8	20/09/2015	Machine is unpowered	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A48	15/04/2015	Hydraulic hose on side B is leaking	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A86	16/06/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A61	21/12/2015	Machine is unpowered	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A87	21/04/2015	Maintenance on milling spindle needed	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A81	16/03/2015	Milling spindle requires repair	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A51	15/07/2015	Unit lost electrical power	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A45	15/11/2015	Maintenance on milling spindle needed	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A57	15/07/2015	Spindle indexing error with overfeed	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A92	25/12/2015	Milling spindle requires repair	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A49	17/12/2015	Leaks found at turrets A and B	Cristian Santos noted: No further details.	cristian_santos
A41	17/11/2015	Hydraulic line leak on side B	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A55	14/06/2015	Leak in side B hydraulic line	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A79	09/07/2015	Turret A and B are leaking	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A60	19/05/2015	Unit lost electrical power	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A12	13/01/2016	Indexing issue causing overfeed on spindle	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A32	07/11/2015	Accumulators need checking and charging	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A90	26/03/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A59	13/02/2015	Repair work needed on milling spindle	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A51	28/09/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A26	21/12/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A38	13/10/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A57	28/04/2015	Power supply failure detected	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A78	02/08/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A31	08/04/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A94	25/04/2015	Accumulator inspection and charging required	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A64	09/12/2015	Maintenance on milling spindle needed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A39	03/09/2015	Unit lost electrical power	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A20	21/07/2015	Accumulator inspection and charging required	Gina Moore noted: No further details.	gina_moore, dylan_miller
A60	29/11/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A71	31/07/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A57	25/05/2015	Machine is unpowered	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A70	04/03/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A20	11/11/2015	Inspect and recharge accumulators	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A58	07/05/2015	Power supply failure detected	Michele Williams noted: System checked and accumulators charged.	michele_williams
A26	23/10/2015	Spindle indexing error with overfeed	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A33	27/02/2015	Hydraulic line leak on side B	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A17	26/11/2015	Power supply failure detected	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A67	27/05/2015	Maintenance on milling spindle needed	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A60	19/04/2015	Repair work needed on milling spindle	Michele Williams noted: Maintenance action successful.	michele_williams
A8	04/06/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A14	30/07/2015	Machine is unpowered	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A95	19/05/2015	Hydraulic line leak on side B	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A69	03/08/2015	Machine is unpowered	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A23	28/12/2015	Inspect and recharge accumulators	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A47	05/11/2015	Maintenance on milling spindle needed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A87	13/04/2015	Machine is unpowered	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A89	19/09/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A54	07/05/2015	Spindle fails to index, overfeeding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A85	13/08/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A13	26/12/2015	Power supply failure detected	Michele Williams noted: Fixed and tested.	michele_williams
A27	23/02/2015	Turret A and B are leaking	Cristian Santos noted: Repair completed.	cristian_santos
A77	23/11/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A88	01/11/2015	Inspect and recharge accumulators	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A65	01/03/2015	Inspect and recharge accumulators	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A37	10/01/2016	Inspect and recharge accumulators	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A77	08/01/2016	Leak in side B hydraulic line	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A2	15/08/2015	Spindle indexing error with overfeed	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller

A4	17/01/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A33	17/08/2015	Unit lost electrical power	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A89	15/04/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A64	07/05/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A25	15/06/2015	Turret sections A & B showing leaks	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A90	14/10/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A75	20/10/2015	Inspect and recharge accumulators	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A30	10/05/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A30	02/02/2015	Unit lost electrical power	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A85	12/10/2015	Maintenance on milling spindle needed	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A81	06/06/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A72	01/09/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A91	22/12/2015	Leak in side B hydraulic line	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A4	01/03/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A60	14/04/2015	Unit lost electrical power	Michele Williams noted: Repair completed.	michele_williams
A3	07/08/2015	Maintenance on milling spindle needed	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A22	07/08/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A97	28/09/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A54	04/03/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A20	02/02/2015	Machine is unpowered	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A76	16/03/2015	Unit lost electrical power	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A16	19/05/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A3	29/05/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A81	07/08/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A22	15/12/2015	Inspect and recharge accumulators	Cristian Santos noted: Fixed and tested.	cristian_santos
A19	03/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Repair completed.	michele_williams
A94	17/10/2015	Hydraulic line leak on side B	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A96	14/10/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A35	15/07/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A81	29/06/2015	Turret A and B are leaking	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A78	25/11/2015	Power supply failure detected	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A23	02/07/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A74	30/08/2015	Accumulator inspection and charging required	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A48	07/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A3	08/06/2015	Repair work needed on milling spindle	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A41	11/04/2015	Inspect and recharge accumulators	Michele Williams noted: Maintenance action successful.	michele_williams
A87	20/04/2015	Maintenance on milling spindle needed	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A4	06/02/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A94	19/08/2015	Turret sections A & B showing leaks	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A38	16/03/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A10	20/07/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A9	18/03/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A86	03/07/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A15	05/06/2015	Hydraulic line leak on side B	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A69	02/08/2015	Leak in side B hydraulic line	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A26	18/08/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A4	23/07/2015	Unit lost electrical power	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A67	16/12/2015	Repair work needed on milling spindle	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A7	31/08/2015	Leak in side B hydraulic line	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A87	27/12/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A60	29/11/2015	Unit lost electrical power	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A86	27/02/2015	Hydraulic line leak on side B	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A35	21/10/2015	Power supply failure detected	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A90	29/04/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A13	10/02/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A26	04/08/2015	Leaks found at turrets A and B	Michele Williams noted: Detail not recorded.	michele_williams
A90	01/06/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A98	18/08/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Repair completed.	cristian_santos
A71	17/11/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A26	28/03/2015	Power supply failure detected	Michele Williams noted: No further details.	michele_williams
A27	24/11/2015	Accumulator inspection and charging required	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A49	27/05/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A37	21/09/2015	Power supply failure detected	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A7	03/06/2015	Maintenance on milling spindle needed	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A48	30/12/2015	Leaks found at turrets A and B	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A73	24/04/2015	Milling spindle requires repair	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A52	24/10/2015	Accumulators need checking and charging	Cristian Santos noted: Repair completed.	cristian_santos
A6	21/07/2015	Power supply failure detected	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A91	24/12/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A50	10/05/2015	Power supply failure detected	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller

A28	28/01/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A94	09/06/2015	Accumulator inspection and charging required	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A28	10/04/2015	Turret A and B are leaking	Cristian Santos noted: Fixed and tested.	cristian_santos
A55	02/03/2015	Power supply failure detected	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A63	16/12/2015	Milling spindle requires repair	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A4	26/04/2015	Hydraulic line leak on side B	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A43	06/08/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A74	15/02/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A61	07/06/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A55	04/04/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A73	05/04/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A55	16/04/2015	Spindle indexing error with overfeed	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A24	11/02/2015	Accumulator inspection and charging required	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A8	05/12/2015	Unit lost electrical power	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A66	05/03/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A86	01/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A45	05/09/2015	Power supply failure detected	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A70	03/03/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Repair completed.	cristian_santos
A9	07/07/2015	Inspect and recharge accumulators	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A8	22/12/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Fixed and tested.	cristian_santos
A22	29/08/2015	Machine is unpowered	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A42	22/10/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A70	13/08/2015	Milling spindle requires repair	Nathan Maldonado noted: No further details.	nathan_maldonado
A26	07/07/2015	Repair work needed on milling spindle	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A65	16/05/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A99	14/03/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A71	02/02/2015	Spindle fails to index, overfeeding	Michele Williams noted: Detail not recorded.	michele_williams
A32	26/10/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A92	13/11/2015	Milling spindle requires repair	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A4	05/03/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A11	15/09/2015	Accumulator inspection and charging required	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A72	31/12/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A43	24/09/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A74	21/06/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A79	27/07/2015	Power supply failure detected	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A42	01/04/2015	Unit lost electrical power	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A2	30/01/2015	Unit lost electrical power	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A51	26/10/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A77	02/02/2015	Inspect and recharge accumulators	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A25	13/09/2015	Leaks found at turrets A and B	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A49	30/06/2015	Leak in side B hydraulic line	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A73	02/05/2015	Spindle indexing error with overfeed	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A42	10/05/2015	Inspect and recharge accumulators	Cristian Santos noted: Fixed and tested.	cristian_santos
A73	09/08/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A98	04/05/2015	Machine is unpowered	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A34	19/10/2015	Accumulator inspection and charging required	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A95	28/02/2015	Power supply failure detected	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A50	30/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A3	12/07/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A26	21/02/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Maintenance action successful.	michele_williams
A35	06/11/2015	Accumulators need checking and charging	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A22	26/06/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A61	02/02/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A82	16/12/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Fixed and tested.	cristian_santos
A25	25/10/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A7	03/01/2016	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A96	05/06/2015	Leak in side B hydraulic line	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A94	30/11/2015	Milling spindle requires repair	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A87	27/06/2015	Hydraulic line leak on side B	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A31	21/12/2015	Turret A and B are leaking	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A54	12/01/2016	Leak in side B hydraulic line	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A69	07/11/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A26	30/09/2015	Accumulator inspection and charging required	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A34	20/05/2015	Inspect and recharge accumulators	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A43	12/06/2015	Milling spindle requires repair	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A28	21/08/2015	Accumulator inspection and charging required	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A96	29/03/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A71	04/10/2015	Accumulators need checking and charging	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A95	18/08/2015	Accumulators need checking and charging	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A70	04/01/2016	Hydraulic hose on side B is leaking	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams

A76	11/01/2016	Indexing issue causing overfeed on spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A88	08/12/2015	Spindle indexing error with overfeed	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A62	12/04/2015	Inspect and recharge accumulators	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A37	20/10/2015	Unit lost electrical power	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A47	20/06/2015	Spindle fails to index, overfeeding	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A43	06/05/2015	Power supply failure detected	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A21	25/02/2015	Turret A and B are leaking	Michele Williams noted: Fixed and tested.	michele_williams
A65	14/06/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A95	20/07/2015	Power supply failure detected	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A43	26/08/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A7	11/01/2016	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A63	25/08/2015	Milling spindle requires repair	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A24	29/09/2015	Leak in side B hydraulic line	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A66	10/12/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A23	10/03/2015	Maintenance on milling spindle needed	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A95	06/05/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A15	27/03/2015	Maintenance on milling spindle needed	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A85	07/02/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Fixed and tested.	cristian_santos
A5	12/08/2015	Power supply failure detected	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A48	18/08/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A91	19/07/2015	Machine is unpowered	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A35	24/04/2015	Accumulators need checking and charging	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A39	24/01/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A43	13/10/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A38	18/09/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A60	05/06/2015	Accumulators need checking and charging	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A24	19/12/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A3	02/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A39	17/10/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A94	14/05/2015	Machine is unpowered	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A54	25/10/2015	Inspect and recharge accumulators	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A41	04/07/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A61	17/12/2015	Turret sections A & B showing leaks	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A80	02/07/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A49	08/10/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Fixed and tested.	cristian_santos
A87	04/10/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A59	11/12/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A71	05/09/2015	Hydraulic line leak on side B	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A62	02/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A17	15/02/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A83	05/02/2015	Unit lost electrical power	Cristian Santos noted: Maintenance action successful.	cristian_santos
A43	02/08/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A96	12/02/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A28	25/07/2015	Accumulators need checking and charging	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A24	22/02/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A82	02/11/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A33	20/02/2015	Machine is unpowered	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A9	14/04/2015	Spindle fails to index, overfeeding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A42	28/12/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Repair completed.	cristian_santos
A11	09/03/2015	Spindle indexing error with overfeed	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A31	21/08/2015	Inspect and recharge accumulators	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A97	25/01/2015	Power supply failure detected	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A29	23/02/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A61	21/11/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A83	20/05/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A43	17/08/2015	Repair work needed on milling spindle	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A50	09/06/2015	Power supply failure detected	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A63	21/07/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A88	19/09/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A33	24/11/2015	Spindle indexing error with overfeed	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A79	09/03/2015	Hydraulic line leak on side B	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A1	11/03/2015	Machine is unpowered	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A19	24/04/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A30	06/12/2015	Power supply failure detected	Gina Moore noted: No further details.	gina_moore, dylan_miller
A78	24/02/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A23	11/11/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A54	05/08/2015	Unit lost electrical power	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A31	31/10/2015	Unit lost electrical power	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A97	11/11/2015	Repair work needed on milling spindle	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A82	16/04/2015	Inspect and recharge accumulators	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams

A97	27/07/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A69	05/12/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A77	10/08/2015	Milling spindle requires repair	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A91	04/01/2016	Power supply failure detected	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A76	24/05/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A23	14/05/2015	Hydraulic line leak on side B	Michele Williams noted: Detail not recorded.	michele_williams
A67	11/02/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A8	19/10/2015	Unit lost electrical power	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A13	18/12/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A33	12/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A12	09/10/2015	Power supply failure detected	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A56	27/02/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A79	16/08/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A56	13/04/2015	Spindle indexing error with overfeed	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A41	09/08/2015	Unit lost electrical power	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A16	07/12/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A18	13/10/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A2	26/10/2015	Leak in side B hydraulic line	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A7	30/01/2015	Unit lost electrical power	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A87	27/04/2015	Unit lost electrical power	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A4	31/03/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A56	12/02/2015	Power supply failure detected	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A31	20/05/2015	Turret sections A & B showing leaks	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A67	18/08/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A44	12/07/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A93	09/09/2015	Milling spindle requires repair	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A80	01/08/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A70	23/12/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A70	02/09/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A23	01/06/2015	Accumulator inspection and charging required	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A79	22/02/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A37	08/02/2015	Repair work needed on milling spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A92	09/11/2015	Leaks found at turrets A and B	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A46	14/06/2015	Accumulators need checking and charging	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A65	27/11/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A84	26/11/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Fixed and tested.	michele_williams
A91	26/01/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A61	05/08/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A47	09/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A41	02/01/2016	Accumulators need checking and charging	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A38	06/01/2016	Power supply failure detected	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A93	18/10/2015	Maintenance on milling spindle needed	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A27	23/06/2015	Hydraulic line leak on side B	Michele Williams noted: Fixed and tested.	michele_williams
A18	17/09/2015	Spindle indexing error with overfeed	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A76	01/03/2015	Turret A and B are leaking	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A22	25/01/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A88	15/06/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A73	23/09/2015	Power supply failure detected	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A39	03/08/2015	Machine is unpowered	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A6	14/03/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A40	16/06/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A32	27/11/2015	Turret sections A & B showing leaks	Michele Williams noted: Repair completed.	michele_williams
A34	02/10/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A55	27/01/2015	Milling spindle requires repair	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A83	24/05/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A37	23/12/2015	Unit lost electrical power	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A99	16/06/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A86	05/04/2015	Milling spindle requires repair	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A95	08/07/2015	Repair work needed on milling spindle	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A2	21/12/2015	Machine is unpowered	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A20	21/12/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A80	13/10/2015	Turret A and B are leaking	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A70	15/07/2015	Machine is unpowered	Cristian Santos noted: Maintenance action successful.	cristian_santos
A59	09/01/2016	Accumulator inspection and charging required	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A33	08/01/2016	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A26	09/01/2016	Machine is unpowered	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A57	29/08/2015	Turret sections A & B showing leaks	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A59	25/06/2015	Leak in side B hydraulic line	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A57	29/04/2015	Inspect and recharge accumulators	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A75	25/10/2015	Leaks found at turrets A and B	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams

A61	07/07/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A16	22/10/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A66	31/05/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Maintenance action successful.	michele_williams
A21	31/10/2015	Repair work needed on milling spindle	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A87	27/11/2015	Inspect and recharge accumulators	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A29	25/09/2015	Unit lost electrical power	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A57	28/04/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A61	11/05/2015	Leaks found at turrets A and B	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A79	30/06/2015	Power supply failure detected	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A58	01/05/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A19	02/07/2015	Hydraulic line leak on side B	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A2	19/08/2015	Spindle indexing error with overfeed	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A41	11/07/2015	Accumulator inspection and charging required	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A23	02/06/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Maintenance action successful.	michele_williams
A17	05/12/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A56	18/08/2015	Inspect and recharge accumulators	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A50	09/04/2015	Turret sections A & B showing leaks	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A94	09/03/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A54	16/06/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A49	12/09/2015	Accumulator inspection and charging required	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A78	26/01/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A71	28/12/2015	Hydraulic line leak on side B	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A49	06/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A73	21/09/2015	Accumulators need checking and charging	Cristian Santos noted: Maintenance action successful.	cristian_santos
A44	24/01/2015	Turret sections A & B showing leaks	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A19	02/12/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A45	30/08/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A61	05/11/2015	Turret sections A & B showing leaks	Michele Williams noted: System checked and accumulators charged.	michele_williams
A33	13/03/2015	Accumulators need checking and charging	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A38	12/02/2015	Turret A and B are leaking	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A67	12/04/2015	Accumulator inspection and charging required	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A51	09/03/2015	Spindle indexing error with overfeed	Cristian Santos noted: Detail not recorded.	cristian_santos
A50	31/07/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A77	31/03/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A59	30/09/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Repair completed.	cristian_santos
A23	12/08/2015	Power supply failure detected	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A59	17/09/2015	Turret sections A & B showing leaks	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A60	10/04/2015	Maintenance on milling spindle needed	Cristian Santos noted: No additional information provided.	cristian_santos
A94	06/11/2015	Inspect and recharge accumulators	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A56	05/12/2015	Leaks found at turrets A and B	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A32	03/08/2015	Turret A and B are leaking	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A6	24/03/2015	Hydraulic line leak on side B	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A58	08/07/2015	Turret A and B are leaking	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A62	13/09/2015	Unit lost electrical power	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A86	07/10/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A63	20/12/2015	Repair work needed on milling spindle	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A84	03/08/2015	Turret A and B are leaking	Cristian Santos noted: No additional information provided.	cristian_santos
A93	21/11/2015	Machine is unpowered	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A84	01/02/2015	Repair work needed on milling spindle	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A95	16/01/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A64	19/06/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A62	07/04/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A81	29/09/2015	Repair work needed on milling spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A33	24/03/2015	Spindle fails to index, overfeeding	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A39	06/02/2015	Milling spindle requires repair	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A88	17/05/2015	Leaks found at turrets A and B	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A5	04/02/2015	Saw attachment gears are binding and grinding	Michele Williams noted: No further details.	michele_williams
A81	06/05/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Repair completed.	michele_williams
A4	08/01/2016	Spindle indexing error with overfeed	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A94	04/11/2015	Accumulator inspection and charging required	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A2	15/06/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A30	14/07/2015	Inspect and recharge accumulators	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A60	13/09/2015	Accumulators need checking and charging	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A70	15/10/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A7	09/05/2015	Turret A and B are leaking	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A33	28/04/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A2	02/01/2016	Spindle indexing error with overfeed	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A9	08/07/2015	Machine is unpowered	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A25	21/03/2015	Unit lost electrical power	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A69	22/05/2015	Accumulators need checking and charging	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams

A5	13/04/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A14	10/10/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A58	18/06/2015	Milling spindle requires repair	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A83	12/03/2015	Spindle indexing error with overfeed	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A2	11/01/2016	Leaks found at turrets A and B	Michele Williams noted: Maintenance action successful.	michele_williams
A91	24/10/2015	Machine is unpowered	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A98	13/06/2015	Turret A and B are leaking	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A18	27/08/2015	Accumulators need checking and charging	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A60	02/05/2015	Machine is unpowered	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A70	03/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A26	16/10/2015	Machine is unpowered	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A54	20/05/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A81	21/06/2015	Accumulators need checking and charging	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A60	04/09/2015	Hydraulic hose on side B is leaking	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A79	31/07/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A60	29/10/2015	Leaks found at turrets A and B	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A91	23/11/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A21	22/08/2015	Inspect and recharge accumulators	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A35	17/08/2015	Accumulators need checking and charging	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A77	07/11/2015	Accumulator inspection and charging required	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A57	14/04/2015	Power supply failure detected	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A64	11/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: No further details.	michele_williams
A23	07/02/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: No further details.	nathan_maldonado
A59	21/05/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A29	21/03/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A50	03/07/2015	Power supply failure detected	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A74	22/11/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A77	22/11/2015	Inspect and recharge accumulators	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A54	10/09/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A82	03/08/2015	Machine is unpowered	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A86	31/07/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A35	17/09/2015	Maintenance on milling spindle needed	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A94	30/01/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A40	31/08/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A16	27/03/2015	Milling spindle requires repair	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A82	20/02/2015	Power supply failure detected	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A1	02/01/2016	Accumulator inspection and charging required	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A23	23/07/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A89	11/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A14	21/10/2015	Power supply failure detected	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A63	10/09/2015	Maintenance on milling spindle needed	Cristian Santos noted: No further details.	cristian_santos
A62	21/01/2015	Accumulators need checking and charging	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A21	24/02/2015	Machine is unpowered	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A43	24/02/2015	Leaks found at turrets A and B	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A48	30/01/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A73	13/07/2015	Spindle indexing error with overfeed	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A45	02/10/2015	Accumulator inspection and charging required	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A43	07/11/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A24	19/10/2015	Power supply failure detected	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A43	11/09/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A19	02/06/2015	Inspect and recharge accumulators	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A68	31/12/2015	Power supply failure detected	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A70	30/09/2015	Spindle indexing error with overfeed	Michele Williams noted: No additional information provided.	michele_williams
A5	14/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A40	18/07/2015	Power supply failure detected	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A3	03/06/2015	Accumulator inspection and charging required	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A34	01/03/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A6	10/04/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A77	11/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A66	03/08/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A57	08/04/2015	Spindle fails to index, overfeeding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A62	30/01/2015	Turret A and B are leaking	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A72	18/03/2015	Spindle indexing error with overfeed	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A36	20/07/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A58	04/09/2015	Leak in side B hydraulic line	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A69	29/09/2015	Maintenance on milling spindle needed	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A99	16/02/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A78	17/07/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A74	19/07/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A34	24/09/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams

A86	26/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A75	28/12/2015	Hydraulic line leak on side B	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A20	06/12/2015	Leak in side B hydraulic line	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A48	22/02/2015	Leak in side B hydraulic line	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A80	31/07/2015	Hydraulic line leak on side B	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A12	08/03/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A19	25/05/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A71	13/11/2015	Power supply failure detected	Cristian Santos noted: Fixed and tested.	cristian_santos
A96	21/11/2015	Leaks found at turrets A and B	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A61	04/10/2015	Milling spindle requires repair	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A5	18/05/2015	Turret sections A & B showing leaks	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A65	20/12/2015	Turret A and B are leaking	Cristian Santos noted: Fixed and tested.	cristian_santos
A46	25/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A47	11/09/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A94	10/01/2016	Power supply failure detected	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A35	18/05/2015	Accumulators need checking and charging	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A50	08/01/2016	Accumulator inspection and charging required	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A8	14/08/2015	Repair work needed on milling spindle	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A7	11/01/2016	Turret sections A & B showing leaks	Michele Williams noted: No further details.	michele_williams
A87	07/12/2015	Turret A and B are leaking	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A28	20/11/2015	Maintenance on milling spindle needed	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A6	30/07/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Detail not recorded.	cristian_santos
A81	08/12/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A4	26/07/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A96	27/06/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A21	09/11/2015	Hydraulic line leak on side B	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A69	18/07/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A10	05/06/2015	Power supply failure detected	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A60	14/06/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A4	12/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A50	11/03/2015	Milling spindle requires repair	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A11	19/09/2015	Milling spindle requires repair	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A42	04/03/2015	Spindle indexing error with overfeed	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A5	23/03/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A13	28/03/2015	Maintenance on milling spindle needed	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A48	11/07/2015	Milling spindle requires repair	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A67	06/09/2015	Turret A and B are leaking	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A22	30/01/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A67	18/10/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Maintenance action successful.	cristian_santos
A49	20/11/2015	Turret A and B are leaking	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A1	23/12/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A26	01/11/2015	Machine is unpowered	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A25	08/11/2015	Hydraulic line leak on side B	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A32	14/08/2015	Turret sections A & B showing leaks	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A91	29/12/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A97	14/12/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A67	01/10/2015	Leak in side B hydraulic line	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A56	06/10/2015	Inspect and recharge accumulators	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A64	21/04/2015	Leaks found at turrets A and B	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A93	02/06/2015	Turret A and B are leaking	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A68	17/02/2015	Turret A and B are leaking	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A54	07/07/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A50	30/12/2015	Power supply failure detected	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A85	02/09/2015	Leaks found at turrets A and B	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A86	26/01/2015	Hydraulic line leak on side B	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A65	21/06/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A60	04/05/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A70	15/12/2015	Unit lost electrical power	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A7	15/11/2015	Accumulator inspection and charging required	Nathan Maldonado noted: No further details.	nathan_maldonado
A25	26/12/2015	Unit lost electrical power	Cristian Santos noted: Fixed and tested.	cristian_santos
A64	06/04/2015	Unit lost electrical power	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A49	30/07/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A74	08/07/2015	Accumulator inspection and charging required	Cristian Santos noted: Maintenance action successful.	cristian_santos
A12	15/09/2015	Repair work needed on milling spindle	Michele Williams noted: Fixed and tested.	michele_williams
A43	09/02/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Repair completed.	michele_williams
A70	14/09/2015	Inspect and recharge accumulators	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A73	05/06/2015	Milling spindle requires repair	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A19	09/09/2015	Leak in side B hydraulic line	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A3	04/01/2016	Turret sections A & B showing leaks	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A16	03/01/2016	Hydraulic hose on side B is leaking	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller

A32	25/05/2015	Maintenance on milling spindle needed	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A15	26/07/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A84	16/04/2015	Maintenance on milling spindle needed	Michele Williams noted: No additional information provided.	michele_williams
A54	17/03/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A56	16/03/2015	Leaks found at turrets A and B	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A56	26/11/2015	Inspect and recharge accumulators	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A84	26/07/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A76	15/11/2015	Turret A and B are leaking	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A73	04/04/2015	Leaks found at turrets A and B	Cristian Santos noted: Detail not recorded.	cristian_santos
A12	21/11/2015	Milling spindle requires repair	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A20	05/01/2016	Repair work needed on milling spindle	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A39	20/05/2015	Power supply failure detected	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A11	23/06/2015	Maintenance on milling spindle needed	Cristian Santos noted: Detail not recorded.	cristian_santos
A85	10/03/2015	Inspect and recharge accumulators	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A51	15/12/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: No additional information provided.	michele_williams
A32	03/08/2015	Spindle indexing error with overfeed	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A89	28/09/2015	Repair work needed on milling spindle	Michele Williams noted: Fixed and tested.	michele_williams
A98	12/12/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Detail not recorded.	cristian_santos
A72	14/11/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Repair completed.	michele_williams
A70	08/11/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A97	13/12/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A47	27/11/2015	Unit lost electrical power	Cristian Santos noted: Detail not recorded.	cristian_santos
A57	29/07/2015	Maintenance on milling spindle needed	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A18	04/03/2015	Power supply failure detected	Michele Williams noted: No additional information provided.	michele_williams
A18	05/01/2016	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A94	07/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A18	15/02/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A82	01/04/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A41	08/01/2016	Maintenance on milling spindle needed	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A81	31/03/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A75	04/03/2015	Power supply failure detected	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A62	07/02/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A26	09/08/2015	Machine is unpowered	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A2	30/07/2015	Hydraulic line leak on side B	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A21	13/11/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A21	15/01/2015	Turret sections A & B showing leaks	Cristian Santos noted: Maintenance action successful.	cristian_santos
A45	31/05/2015	Hydraulic line leak on side B	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A35	21/10/2015	Unit lost electrical power	Cristian Santos noted: No further details.	cristian_santos
A87	05/03/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A93	25/12/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A83	09/07/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A60	09/04/2015	Power supply failure detected	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A59	15/12/2015	Machine is unpowered	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A67	22/08/2015	Spindle indexing error with overfeed	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A49	27/11/2015	Spindle indexing error with overfeed	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A14	24/02/2015	Machine is unpowered	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A52	01/09/2015	Power supply failure detected	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A59	23/03/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A77	14/06/2015	Repair work needed on milling spindle	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A55	05/02/2015	Hydraulic line leak on side B	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A59	23/05/2015	Machine is unpowered	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A84	26/06/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A16	26/04/2015	Milling spindle requires repair	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A31	06/11/2015	Accumulators need checking and charging	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A3	07/10/2015	Power supply failure detected	Michele Williams noted: No further details.	michele_williams
A43	17/01/2015	Hydraulic line leak on side B	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A77	16/11/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A28	03/12/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A52	23/09/2015	Leak in side B hydraulic line	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A24	24/05/2015	Leak in side B hydraulic line	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A20	14/10/2015	Accumulators need checking and charging	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A4	05/01/2016	Unit lost electrical power	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A57	03/08/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A11	17/09/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A8	14/03/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A44	14/03/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: No further details.	cristian_santos
A79	19/09/2015	Unit lost electrical power	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A84	22/06/2015	Repair work needed on milling spindle	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A22	15/06/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A77	25/08/2015	Power supply failure detected	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos

A18	03/07/2015	Turret sections A & B showing leaks	Gina Moore noted: No further details.	gina_moore, dylan_miller
A45	03/08/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A23	20/03/2015	Repair work needed on milling spindle	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A27	02/07/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A78	06/01/2016	Indexing issue causing overfeed on spindle	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A13	10/11/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A60	19/03/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A95	20/06/2015	Hydraulic hose on side B is leaking	Michele Williams noted: No further details.	michele_williams
A79	15/07/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A1	30/01/2015	Accumulators need checking and charging	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A75	16/04/2015	Spindle indexing error with overfeed	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A59	09/09/2015	Spindle indexing error with overfeed	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A51	01/02/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A1	08/10/2015	Leaks found at turrets A and B	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A41	06/01/2016	Leak in side B hydraulic line	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A96	24/08/2015	Unit lost electrical power	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A84	08/04/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A64	07/12/2015	Machine is unpowered	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A25	27/07/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A71	03/05/2015	Accumulator inspection and charging required	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A28	02/08/2015	Unit lost electrical power	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A6	30/04/2015	Accumulator inspection and charging required	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A44	31/12/2015	Power supply failure detected	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A12	07/11/2015	Accumulator inspection and charging required	Cristian Santos noted: Detail not recorded.	cristian_santos
A45	23/08/2015	Accumulator inspection and charging required	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A85	15/08/2015	Hydraulic hose on side B is leaking	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A80	30/06/2015	Spindle indexing error with overfeed	Cristian Santos noted: No additional information provided.	cristian_santos
A77	26/08/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A48	08/09/2015	Repair work needed on milling spindle	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A15	19/10/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A45	08/08/2015	Leak in side B hydraulic line	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A57	06/04/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A79	25/10/2015	Leak in side B hydraulic line	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A51	24/11/2015	Power supply failure detected	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A26	24/12/2015	Inspect and recharge accumulators	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A45	13/08/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A29	29/10/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A90	29/06/2015	Accumulator inspection and charging required	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A69	26/12/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A6	16/03/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A4	18/03/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A9	04/02/2015	Milling spindle requires repair	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A96	03/07/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: No further details.	michele_williams
A97	17/06/2015	Leaks found at turrets A and B	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A27	11/07/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A47	25/06/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A80	31/05/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A94	30/07/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A10	19/09/2015	Milling spindle requires repair	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A49	10/04/2015	Power supply failure detected	Gina Moore noted: No further details.	gina_moore, dylan_miller
A94	08/04/2015	Milling spindle requires repair	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A7	04/06/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A13	11/06/2015	Turret sections A & B showing leaks	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A60	08/08/2015	Accumulators need checking and charging	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A61	31/08/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A37	31/05/2015	Hydraulic line leak on side B	Cristian Santos noted: Repair completed.	cristian_santos
A80	30/08/2015	Turret A and B are leaking	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A90	10/11/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A58	17/01/2015	Inspect and recharge accumulators	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A66	30/12/2015	Unit lost electrical power	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A87	19/04/2015	Maintenance on milling spindle needed	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A10	29/01/2015	Inspect and recharge accumulators	Cristian Santos noted: Detail not recorded.	cristian_santos
A48	23/11/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A71	06/03/2015	Milling spindle requires repair	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A34	20/07/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A58	02/04/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A7	04/02/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A76	03/12/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A73	08/03/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A40	12/10/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams

A40	13/03/2015	Machine is unpowered	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A15	29/11/2015	Leaks found at turrets A and B	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A50	12/10/2015	Accumulators need checking and charging	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A90	12/02/2015	Inspect and recharge accumulators	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A52	31/03/2015	Maintenance on milling spindle needed	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A83	21/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A16	17/02/2015	Inspect and recharge accumulators	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A57	13/06/2015	Machine is unpowered	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A79	01/04/2015	Leaks found at turrets A and B	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A77	12/06/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A38	29/08/2015	Accumulator inspection and charging required	Cristian Santos noted: No additional information provided.	cristian_santos
A17	26/07/2015	Accumulator inspection and charging required	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A20	19/05/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A37	13/06/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A16	24/08/2015	Accumulator inspection and charging required	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A68	24/10/2015	Repair work needed on milling spindle	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A76	14/04/2015	Power supply failure detected	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A95	10/02/2015	Leaks found at turrets A and B	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A71	20/07/2015	Hydraulic line leak on side B	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A85	02/08/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Maintenance action successful.	michele_williams
A84	21/04/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A66	07/05/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: No further details.	nathan_maldonado
A60	02/02/2015	Inspect and recharge accumulators	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A19	21/10/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A14	31/01/2015	Spindle fails to index, overfeeding	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A59	16/06/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A70	22/02/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A40	30/04/2015	Leaks found at turrets A and B	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A22	15/05/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: No further details.	gina_moore, dylan_miller
A92	10/08/2015	Leaks found at turrets A and B	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A2	18/08/2015	Spindle indexing error with overfeed	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A72	19/09/2015	Hydraulic line leak on side B	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A27	11/09/2015	Leaks found at turrets A and B	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A31	09/12/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A94	14/01/2015	Leak in side B hydraulic line	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A91	07/06/2015	Power supply failure detected	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A28	04/12/2015	Spindle indexing error with overfeed	Michele Williams noted: Repair completed.	michele_williams
A89	12/05/2015	Repair work needed on milling spindle	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A64	13/11/2015	Inspect and recharge accumulators	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A67	02/11/2015	Inspect and recharge accumulators	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A21	11/03/2015	Maintenance on milling spindle needed	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A27	01/07/2015	Inspect and recharge accumulators	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A97	13/02/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A6	06/04/2015	Machine is unpowered	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A48	10/08/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A52	01/11/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A27	07/07/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A82	01/07/2015	Unit lost electrical power	Michele Williams noted: Repair completed.	michele_williams
A24	13/07/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A24	01/06/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A24	12/05/2015	Unit lost electrical power	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A66	30/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: No further details.	michele_williams
A99	20/03/2015	Accumulator inspection and charging required	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A99	15/07/2015	Inspect and recharge accumulators	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A73	23/03/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A79	15/04/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A56	02/01/2016	Maintenance on milling spindle needed	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A16	28/08/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A74	28/01/2015	Accumulator inspection and charging required	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A65	27/04/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A79	19/11/2015	Accumulator inspection and charging required	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A90	03/05/2015	Accumulator inspection and charging required	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A74	25/06/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A41	22/04/2015	Machine is unpowered	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A52	02/04/2015	Power supply failure detected	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A2	21/03/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A92	03/09/2015	Inspect and recharge accumulators	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A83	24/05/2015	Spindle indexing error with overfeed	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A28	25/05/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A78	11/06/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams

A4	17/09/2015	Unit lost electrical power	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A23	23/06/2015	Hydraulic line leak on side B	Nathan Maldonado noted: No further details.	nathan_maldonado
A94	01/08/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A28	05/07/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A11	02/11/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A30	25/11/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A62	25/04/2015	Accumulator inspection and charging required	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A72	11/02/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A80	10/07/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A11	18/07/2015	Accumulator inspection and charging required	Gina Moore noted: No further details.	gina_moore, dylan_miller
A84	19/03/2015	Leaks found at turrets A and B	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A56	10/07/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A88	19/01/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A65	12/03/2015	Hydraulic hose on side B is leaking	Michele Williams noted: No additional information provided.	michele_williams
A8	31/07/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A26	27/07/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A12	20/09/2015	Inspect and recharge accumulators	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A33	06/05/2015	Spindle indexing error with overfeed	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A39	07/05/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A97	31/08/2015	Leaks found at turrets A and B	Michele Williams noted: Maintenance action successful.	michele_williams
A34	16/05/2015	Power supply failure detected	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A53	01/02/2015	Accumulators need checking and charging	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A38	06/03/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A56	17/04/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A29	06/10/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A33	11/05/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A81	31/03/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A41	07/04/2015	Unit lost electrical power	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A42	19/01/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A4	02/03/2015	Machine is unpowered	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A23	10/03/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A76	23/08/2015	Spindle indexing error with overfeed	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A74	16/04/2015	Turret sections A & B showing leaks	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A85	14/07/2015	Leak in side B hydraulic line	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A77	21/06/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A70	13/05/2015	Machine is unpowered	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A87	08/06/2015	Turret A and B are leaking	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A9	19/12/2015	Accumulator inspection and charging required	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A12	02/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A31	25/12/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A61	23/09/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A8	23/05/2015	Inspect and recharge accumulators	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A59	28/04/2015	Leaks found at turrets A and B	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A97	12/04/2015	Inspect and recharge accumulators	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A76	29/07/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A31	11/05/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A79	04/04/2015	Spindle fails to index, overfeeding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A64	16/08/2015	Accumulator inspection and charging required	Cristian Santos noted: Fixed and tested.	cristian_santos
A4	02/12/2015	Turret A and B are leaking	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A13	01/01/2016	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A50	03/11/2015	Accumulator inspection and charging required	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A68	01/06/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A61	25/12/2015	Repair work needed on milling spindle	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A22	10/02/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A19	08/08/2015	Leaks found at turrets A and B	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A37	06/01/2016	Turret A and B are leaking	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A25	13/11/2015	Leaks found at turrets A and B	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A24	21/06/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A60	26/08/2015	Spindle fails to index, overfeeding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A54	10/02/2015	Turret A and B are leaking	Michele Williams noted: Detail not recorded.	michele_williams
A79	04/06/2015	Hydraulic line leak on side B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A1	26/01/2015	Power supply failure detected	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A41	12/05/2015	Repair work needed on milling spindle	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A93	15/01/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A57	20/04/2015	Spindle indexing error with overfeed	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A97	20/10/2015	Turret A and B are leaking	Nathan Maldonado noted: No further details.	nathan_maldonado
A73	28/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A85	12/07/2015	Maintenance on milling spindle needed	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A38	25/11/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A58	16/01/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado

A82	31/10/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A21	27/09/2015	Machine is unpowered	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A35	21/09/2015	Inspect and recharge accumulators	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A32	07/12/2015	Accumulator inspection and charging required	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A24	28/08/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A42	20/10/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A63	24/09/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A26	04/11/2015	Maintenance on milling spindle needed	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A89	22/11/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A68	07/05/2015	Machine is unpowered	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A69	09/05/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A96	05/11/2015	Spindle fails to index, overfeeding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A25	24/10/2015	Unit lost electrical power	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A7	31/12/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A4	10/07/2015	Accumulator inspection and charging required	Cristian Santos noted: Detail not recorded.	cristian_santos
A93	08/05/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A3	01/02/2015	Turret sections A & B showing leaks	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A59	26/11/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A87	22/05/2015	Turret A and B are leaking	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A4	19/02/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A83	13/04/2015	Leak in side B hydraulic line	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A93	01/05/2015	Repair work needed on milling spindle	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A53	20/12/2015	Milling spindle requires repair	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A39	07/05/2015	Repair work needed on milling spindle	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A14	08/06/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A92	17/03/2015	Spindle indexing error with overfeed	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A3	09/10/2015	Accumulators need checking and charging	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A41	21/12/2015	Machine is unpowered	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A22	26/01/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A2	30/06/2015	Unit lost electrical power	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A89	30/05/2015	Repair work needed on milling spindle	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A52	02/02/2015	Hydraulic line leak on side B	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A79	22/07/2015	Repair work needed on milling spindle	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A5	08/01/2016	Saw attachment is leaking hydraulics	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A80	20/10/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A71	24/09/2015	Inspect and recharge accumulators	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A47	31/12/2015	Power supply failure detected	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A58	11/05/2015	Machine is unpowered	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A6	29/12/2015	Inspect and recharge accumulators	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A36	07/08/2015	Machine is unpowered	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A46	04/11/2015	Leak in side B hydraulic line	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A15	29/06/2015	Leak in side B hydraulic line	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A94	21/06/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A47	19/11/2015	Leaks found at turrets A and B	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A77	01/02/2015	Power supply failure detected	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A10	26/01/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A7	30/07/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A13	09/06/2015	Inspect and recharge accumulators	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A35	04/09/2015	Maintenance on milling spindle needed	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A80	10/12/2015	Hydraulic line leak on side B	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A20	18/02/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A25	22/03/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Repair completed.	cristian_santos
A33	05/09/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A35	17/06/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A75	24/11/2015	Unit lost electrical power	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A59	23/04/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A11	26/07/2015	Machine is unpowered	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A84	16/04/2015	Turret sections A & B showing leaks	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A80	25/06/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A38	15/09/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A2	21/10/2015	Power supply failure detected	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A50	31/05/2015	Accumulators need checking and charging	Michele Williams noted: No further details.	michele_williams
A89	25/09/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A99	02/08/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A89	19/03/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A50	19/09/2015	Accumulators need checking and charging	Nathan Maldonado noted: No further details.	nathan_maldonado
A36	28/04/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A73	08/09/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A16	26/05/2015	Milling spindle requires repair	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A39	12/12/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams

A8	28/10/2015	Accumulators need checking and charging	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A2	28/03/2015	Leak in side B hydraulic line	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A59	20/05/2015	Unit lost electrical power	Michele Williams noted: Detail not recorded.	michele_williams
A58	02/08/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A61	06/05/2015	Unit lost electrical power	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A67	27/07/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A31	04/04/2015	Turret A and B are leaking	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A10	27/06/2015	Machine is unpowered	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A28	08/09/2015	Hydraulic line leak on side B	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A44	07/04/2015	Repair work needed on milling spindle	Nathan Maldonado noted: No further details.	nathan_maldonado
A12	19/09/2015	Maintenance on milling spindle needed	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A39	27/01/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A97	01/12/2015	Leak in side B hydraulic line	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A45	05/09/2015	Milling spindle requires repair	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A18	26/10/2015	Unit lost electrical power	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A6	13/12/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A89	28/03/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A65	11/01/2016	Spindle fails to index, overfeeding	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A42	23/09/2015	Inspect and recharge accumulators	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A1	14/05/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A93	01/10/2015	Milling spindle requires repair	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A65	18/09/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A80	08/05/2015	Leaks found at turrets A and B	Gina Moore noted: No further details.	gina_moore, dylan_miller
A32	04/05/2015	Turret A and B are leaking	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A45	08/08/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A7	20/10/2015	Leak in side B hydraulic line	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A22	09/12/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A16	18/09/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A58	04/12/2015	Accumulators need checking and charging	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A64	04/09/2015	Leak in side B hydraulic line	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A27	20/03/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A21	07/04/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Fixed and tested.	cristian_santos
A16	11/01/2016	Indexing issue causing overfeed on spindle	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A66	25/06/2015	Accumulator inspection and charging required	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A36	30/05/2015	Inspect and recharge accumulators	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A78	18/12/2015	Power supply failure detected	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A83	01/03/2015	Milling spindle requires repair	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A58	17/05/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A60	25/04/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A28	11/08/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A84	06/06/2015	Hydraulic line leak on side B	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A31	12/01/2016	Milling spindle requires repair	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A38	30/05/2015	Turret A and B are leaking	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A30	28/07/2015	Turret A and B are leaking	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A17	17/04/2015	Spindle fails to index, overfeeding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A90	08/11/2015	Milling spindle requires repair	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A1	03/12/2015	Inspect and recharge accumulators	Cristian Santos noted: No further details.	cristian_santos
A81	15/09/2015	Accumulators need checking and charging	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A21	18/01/2015	Maintenance on milling spindle needed	Michele Williams noted: Fixed and tested.	michele_williams
A63	06/03/2015	Milling spindle requires repair	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A86	07/01/2016	Leaks found at turrets A and B	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A48	24/12/2015	Inspect and recharge accumulators	Michele Williams noted: Detail not recorded.	michele_williams
A43	23/08/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A95	23/06/2015	Unit lost electrical power	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A45	05/06/2015	Power supply failure detected	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A70	30/03/2015	Milling spindle requires repair	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A99	20/11/2015	Repair work needed on milling spindle	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A38	11/11/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A98	01/03/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Detail not recorded.	michele_williams
A65	04/08/2015	Turret sections A & B showing leaks	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A58	14/07/2015	Machine is unpowered	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A49	14/08/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A47	24/07/2015	Turret A and B are leaking	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A69	18/09/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A20	18/09/2015	Turret sections A & B showing leaks	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A95	21/11/2015	Turret sections A & B showing leaks	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A81	22/09/2015	Spindle indexing error with overfeed	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A93	16/10/2015	Accumulators need checking and charging	Michele Williams noted: Repair completed.	michele_williams
A75	11/04/2015	Milling spindle requires repair	Michele Williams noted: Detail not recorded.	michele_williams
A44	08/03/2015	Milling spindle requires repair	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller

A41	16/05/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A57	26/04/2015	Turret sections A & B showing leaks	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A66	07/07/2015	Spindle indexing error with overfeed	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A17	21/11/2015	Accumulators need checking and charging	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A12	12/04/2015	Leak in side B hydraulic line	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A47	01/09/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A36	21/02/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A60	25/07/2015	Milling spindle requires repair	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A41	20/12/2015	Leak in side B hydraulic line	Michele Williams noted: Repair completed.	michele_williams
A83	22/02/2015	Turret A and B are leaking	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A23	31/01/2015	Hydraulic line leak on side B	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A34	23/02/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A20	03/06/2015	Milling spindle requires repair	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A75	07/10/2015	Unit lost electrical power	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A33	03/03/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A95	02/10/2015	Turret sections A & B showing leaks	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A58	21/01/2015	Turret sections A & B showing leaks	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A62	23/09/2015	Milling spindle requires repair	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A32	11/12/2015	Accumulators need checking and charging	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A73	13/07/2015	Accumulators need checking and charging	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A46	22/05/2015	Repair work needed on milling spindle	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A6	04/08/2015	Machine is unpowered	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A16	06/10/2015	Inspect and recharge accumulators	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A13	09/10/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A72	22/05/2015	Leaks found at turrets A and B	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A60	28/06/2015	Power supply failure detected	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A30	04/11/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A28	23/12/2015	Hydraulic hose on side B is leaking	Michele Williams noted: System checked and accumulators charged.	michele_williams
A55	12/08/2015	Leaks found at turrets A and B	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A71	16/06/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A39	24/02/2015	Turret sections A & B showing leaks	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A3	18/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A12	26/11/2015	Unit lost electrical power	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A72	18/10/2015	Power supply failure detected	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A36	12/05/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A76	09/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A9	04/06/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A45	05/07/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A73	08/07/2015	Repair work needed on milling spindle	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A69	15/09/2015	Turret A and B are leaking	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A57	21/10/2015	Milling spindle requires repair	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A75	07/01/2016	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A98	03/09/2015	Maintenance on milling spindle needed	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A15	23/01/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A78	01/01/2016	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A97	22/02/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A82	20/02/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A3	29/03/2015	Accumulator inspection and charging required	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A60	08/10/2015	Turret sections A & B showing leaks	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A16	09/07/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A70	25/09/2015	Leak in side B hydraulic line	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A68	15/07/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A13	15/02/2015	Accumulators need checking and charging	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A87	20/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A90	03/10/2015	Accumulators need checking and charging	Michele Williams noted: No further details.	michele_williams
A43	29/07/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A1	14/04/2015	Hydraulic line leak on side B	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A24	13/05/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A40	28/08/2015	Turret A and B are leaking	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A43	22/12/2015	Leaks found at turrets A and B	Michele Williams noted: Fixed and tested.	michele_williams
A54	28/03/2015	Turret A and B are leaking	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A65	07/08/2015	Spindle fails to index, overfeeding	Michele Williams noted: Repair completed.	michele_williams
A37	26/01/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A99	18/03/2015	Turret sections A & B showing leaks	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A69	19/02/2015	Milling spindle requires repair	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A1	25/01/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A40	19/08/2015	Leaks found at turrets A and B	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A28	05/08/2015	Unit lost electrical power	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A40	04/08/2015	Accumulators need checking and charging	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A21	11/05/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller

A6	01/02/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A3	17/12/2015	Accumulators need checking and charging	Michele Williams noted: No further details.	michele_williams
A14	25/04/2015	Repair work needed on milling spindle	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A29	01/08/2015	Maintenance on milling spindle needed	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A97	27/08/2015	Machine is unpowered	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A64	26/04/2015	Machine is unpowered	Michele Williams noted: Maintenance action successful.	michele_williams
A78	23/10/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A62	13/07/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A91	20/03/2015	Turret sections A & B showing leaks	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A79	07/09/2015	Milling spindle requires repair	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A84	07/01/2016	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A21	17/08/2015	Turret A and B are leaking	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A13	26/12/2015	Repair work needed on milling spindle	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A54	31/01/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A41	17/05/2015	Turret A and B are leaking	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A82	26/11/2015	Inspect and recharge accumulators	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A92	17/06/2015	Hydraulic line leak on side B	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A24	01/02/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A3	04/09/2015	Milling spindle requires repair	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A49	20/12/2015	Accumulators need checking and charging	Michele Williams noted: Repair completed.	michele_williams
A27	09/04/2015	Inspect and recharge accumulators	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A63	26/10/2015	Accumulators need checking and charging	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A77	21/04/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A52	23/10/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A99	22/08/2015	Machine is unpowered	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A20	29/09/2015	Unit lost electrical power	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A77	22/11/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A64	06/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A7	23/02/2015	Milling spindle requires repair	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A29	25/03/2015	Hydraulic line leak on side B	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A47	08/01/2016	Unit lost electrical power	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A39	15/04/2015	Unit lost electrical power	Cristian Santos noted: Fixed and tested.	cristian_santos
A10	11/07/2015	Leaks found at turrets A and B	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A53	03/10/2015	Inspect and recharge accumulators	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A66	17/03/2015	Hydraulic line leak on side B	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A36	23/05/2015	Inspect and recharge accumulators	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A26	24/07/2015	Accumulators need checking and charging	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A90	22/08/2015	Spindle fails to index, overfeeding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A4	15/01/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: No additional information provided.	cristian_santos
A38	10/06/2015	Machine is unpowered	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A35	08/09/2015	Accumulators need checking and charging	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A73	01/09/2015	Maintenance on milling spindle needed	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A60	18/08/2015	Power supply failure detected	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A5	16/09/2015	Spindle indexing error with overfeed	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A57	24/06/2015	Spindle indexing error with overfeed	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A75	03/04/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A92	19/12/2015	Inspect and recharge accumulators	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A25	21/05/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A79	28/10/2015	Maintenance on milling spindle needed	Michele Williams noted: Maintenance action successful.	michele_williams
A95	27/11/2015	Machine is unpowered	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A9	13/02/2015	Unit lost electrical power	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A32	23/04/2015	Turret sections A & B showing leaks	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A50	04/09/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A24	03/07/2015	Machine is unpowered	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A98	13/12/2015	Spindle indexing error with overfeed	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A24	22/02/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A63	09/02/2015	Milling spindle requires repair	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A23	24/07/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A7	05/01/2016	Inspect and recharge accumulators	Cristian Santos noted: Fixed and tested.	cristian_santos
A2	13/12/2015	Accumulator inspection and charging required	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A89	20/11/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A54	18/11/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A59	13/09/2015	Unit lost electrical power	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A31	02/08/2015	Hydraulic line leak on side B	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A48	19/10/2015	Turret A and B are leaking	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A51	07/07/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A7	18/08/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: No further details.	nathan_maldonado
A86	18/07/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A28	03/12/2015	Maintenance on milling spindle needed	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A21	19/10/2015	Machine is unpowered	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams

A74	12/06/2015	Inspect and recharge accumulators	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A38	09/01/2016	Grinding noise from tight gears on saw attachment	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A62	06/05/2015	Repair work needed on milling spindle	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A48	08/11/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A75	18/05/2015	Hydraulic line leak on side B	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A40	04/08/2015	Spindle fails to index, overfeeding	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A49	09/06/2015	Spindle indexing error with overfeed	Michele Williams noted: Repair completed.	michele_williams
A29	25/11/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A99	23/07/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A6	10/07/2015	Unit lost electrical power	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A9	19/04/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A14	27/08/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A64	14/05/2015	Leak in side B hydraulic line	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A58	21/04/2015	Maintenance on milling spindle needed	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A25	22/05/2015	Spindle indexing error with overfeed	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A19	23/05/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A63	17/03/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A54	24/05/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A1	24/07/2015	Accumulator inspection and charging required	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A33	23/04/2015	Repair work needed on milling spindle	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A32	09/01/2016	Unit lost electrical power	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A19	23/04/2015	Turret sections A & B showing leaks	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A63	17/10/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A74	10/01/2016	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: No further details.	cristian_santos
A12	27/01/2015	Repair work needed on milling spindle	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A11	11/12/2015	Unit lost electrical power	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A51	14/04/2015	Power supply failure detected	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A87	02/03/2015	Accumulator inspection and charging required	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A75	01/12/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A15	01/08/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A4	01/01/2016	Machine is unpowered	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A40	14/09/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A20	25/07/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A71	23/05/2015	Saw attachment is leaking hydraulics	Michele Williams noted: System checked and accumulators charged.	michele_williams
A42	13/06/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A35	23/08/2015	Repair work needed on milling spindle	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A79	04/10/2015	Unit lost electrical power	Michele Williams noted: Repair completed.	michele_williams
A64	14/04/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A28	05/03/2015	Milling spindle requires repair	Michele Williams noted: Detail not recorded.	michele_williams
A33	11/12/2015	Turret sections A & B showing leaks	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A22	01/02/2015	Maintenance on milling spindle needed	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A38	29/09/2015	Hydraulic hose on side B is leaking	Gina Moore noted: No further details.	gina_moore, dylan_miller
A31	27/04/2015	Machine is unpowered	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A80	07/06/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A29	13/12/2015	Accumulators need checking and charging	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A70	23/08/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A1	08/11/2015	Milling spindle requires repair	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A7	03/12/2015	Inspect and recharge accumulators	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A87	07/05/2015	Turret sections A & B showing leaks	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A36	10/10/2015	Power supply failure detected	Cristian Santos noted: No additional information provided.	cristian_santos
A68	04/05/2015	Power supply failure detected	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A30	19/10/2015	Turret A and B are leaking	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A8	21/10/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A9	27/12/2015	Spindle indexing error with overfeed	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A50	23/06/2015	Machine is unpowered	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A24	10/11/2015	Turret A and B are leaking	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A82	23/10/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A84	13/10/2015	Milling spindle requires repair	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A99	08/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A88	19/01/2015	Maintenance on milling spindle needed	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A50	09/04/2015	Inspect and recharge accumulators	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A21	25/01/2015	Accumulators need checking and charging	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A90	08/11/2015	Unit lost electrical power	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A92	28/05/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A37	31/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A28	19/12/2015	Accumulator inspection and charging required	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A68	08/06/2015	Repair work needed on milling spindle	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A41	13/01/2016	Maintenance on milling spindle needed	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A93	06/09/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A63	06/03/2015	Unit lost electrical power	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller

A44	23/04/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A94	17/04/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A7	27/03/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A58	07/06/2015	Spindle indexing error with overfeed	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A83	19/04/2015	Inspect and recharge accumulators	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A68	20/07/2015	Leaks found at turrets A and B	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A50	04/12/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A47	07/11/2015	Accumulators need checking and charging	Gina Moore noted: No further details.	gina_moore, dylan_miller
A5	23/09/2015	Power supply failure detected	Michele Williams noted: Repair completed.	michele_williams
A83	12/07/2015	Leak in side B hydraulic line	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A13	19/11/2015	Leak in side B hydraulic line	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A44	23/01/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A75	02/08/2015	Machine is unpowered	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A5	14/07/2015	Accumulators need checking and charging	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A27	02/06/2015	Inspect and recharge accumulators	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A41	12/01/2016	Leaks found at turrets A and B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A49	11/09/2015	Accumulator inspection and charging required	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A22	09/01/2016	Accumulators need checking and charging	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A95	21/11/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A78	24/06/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A92	05/11/2015	Leak in side B hydraulic line	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A63	19/02/2015	Accumulators need checking and charging	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A1	17/06/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Fixed and tested.	michele_williams
A4	26/03/2015	Accumulators need checking and charging	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A41	20/01/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A16	17/07/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A70	22/02/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A36	30/12/2015	Milling spindle requires repair	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A37	13/07/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A51	21/04/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A20	25/10/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A7	24/10/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A45	27/07/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A22	26/09/2015	Accumulators need checking and charging	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A33	23/09/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A68	08/03/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A94	18/11/2015	Leak in side B hydraulic line	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A36	09/03/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A54	15/06/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A90	06/07/2015	Repair work needed on milling spindle	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A38	01/09/2015	Leak in side B hydraulic line	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A80	14/10/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A36	05/11/2015	Accumulators need checking and charging	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A46	18/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A88	01/10/2015	Unit lost electrical power	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A66	02/12/2015	Leaks found at turrets A and B	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A16	07/03/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A28	14/11/2015	Accumulators need checking and charging	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A63	09/06/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A38	09/10/2015	Saw attachment gears are binding and grinding	Michele Williams noted: No further details.	michele_williams
A50	31/08/2015	Milling spindle requires repair	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A83	13/07/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A31	19/02/2015	Maintenance on milling spindle needed	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A90	17/09/2015	Milling spindle requires repair	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A50	08/06/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A84	09/02/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A86	30/01/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A65	16/03/2015	Repair work needed on milling spindle	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A94	05/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A99	21/03/2015	Accumulator inspection and charging required	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A6	26/11/2015	Inspect and recharge accumulators	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A78	09/08/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A89	11/03/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A39	17/08/2015	Spindle indexing error with overfeed	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A60	08/11/2015	Machine is unpowered	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A43	17/11/2015	Repair work needed on milling spindle	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A72	17/10/2015	Spindle indexing error with overfeed	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A26	04/11/2015	Inspect and recharge accumulators	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A81	06/03/2015	Leaks found at turrets A and B	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A83	11/01/2016	Milling spindle requires repair	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams

A60	03/01/2016	Maintenance on milling spindle needed	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A86	12/08/2015	Maintenance on milling spindle needed	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A57	29/12/2015	Inspect and recharge accumulators	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A44	02/08/2015	Inspect and recharge accumulators	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A31	09/03/2015	Accumulator inspection and charging required	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A72	21/08/2015	Turret sections A & B showing leaks	Cristian Santos noted: Maintenance action successful.	cristian_santos
A88	12/12/2015	Milling spindle requires repair	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A6	30/01/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A27	21/10/2015	Power supply failure detected	Michele Williams noted: Maintenance action successful.	michele_williams
A91	26/05/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A33	15/08/2015	Accumulators need checking and charging	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A49	30/08/2015	Power supply failure detected	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A4	26/05/2015	Inspect and recharge accumulators	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A9	22/02/2015	Maintenance on milling spindle needed	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A65	25/02/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A16	23/04/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A68	23/02/2015	Spindle fails to index, overfeeding	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A38	06/06/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A28	07/05/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A84	08/09/2015	Leak in side B hydraulic line	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A70	17/09/2015	Milling spindle requires repair	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A74	14/06/2015	Machine is unpowered	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A81	12/11/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A49	29/10/2015	Inspect and recharge accumulators	Nathan Maldonado noted: No further details.	nathan_maldonado
A84	28/04/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A23	21/02/2015	Turret A and B are leaking	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A75	21/03/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A83	28/12/2015	Spindle indexing error with overfeed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A69	07/09/2015	Accumulator inspection and charging required	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A80	19/06/2015	Unit lost electrical power	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A36	25/06/2015	Repair work needed on milling spindle	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A39	09/02/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A35	24/12/2015	Turret A and B are leaking	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A13	28/12/2015	Accumulators need checking and charging	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A80	08/09/2015	Hydraulic line leak on side B	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A76	22/08/2015	Leaks found at turrets A and B	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A32	01/11/2015	Turret A and B are leaking	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A82	18/04/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A17	19/07/2015	Turret sections A & B showing leaks	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A32	07/12/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A40	27/12/2015	Leak in side B hydraulic line	Michele Williams noted: No further details.	michele_williams
A28	25/07/2015	Accumulators need checking and charging	Gina Moore noted: No further details.	gina_moore, dylan_miller
A90	16/06/2015	Inspect and recharge accumulators	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A27	29/05/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A38	24/03/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A81	18/04/2015	Accumulators need checking and charging	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A66	09/10/2015	Turret sections A & B showing leaks	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A41	06/02/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A1	27/10/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A65	11/03/2015	Repair work needed on milling spindle	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A45	06/06/2015	Spindle indexing error with overfeed	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A15	18/03/2015	Accumulator inspection and charging required	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A31	01/11/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A91	20/08/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A3	22/12/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: No additional information provided.	michele_williams
A71	05/10/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A60	24/11/2015	Inspect and recharge accumulators	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A88	01/10/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A48	19/12/2015	Leaks found at turrets A and B	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A8	24/11/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A87	26/01/2015	Spindle indexing error with overfeed	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A96	04/12/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A95	24/04/2015	Leaks found at turrets A and B	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A90	19/04/2015	Saw attachment gears are binding and grinding	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A51	19/02/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A22	29/12/2015	Maintenance on milling spindle needed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A85	27/05/2015	Turret sections A & B showing leaks	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A26	27/04/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A80	28/10/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: No further details.	nathan_maldonado
A59	13/09/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams

A7	01/10/2015	Machine is unpowered	Michele Williams noted: System checked and accumulators charged.	michele_williams
A17	21/12/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A45	28/01/2015	Inspect and recharge accumulators	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A25	13/02/2015	Leak in side B hydraulic line	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A54	11/10/2015	Power supply failure detected	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A44	19/07/2015	Milling spindle requires repair	Cristian Santos noted: Detail not recorded.	cristian_santos
A26	13/11/2015	Accumulators need checking and charging	Michele Williams noted: No further details.	michele_williams
A43	07/06/2015	Inspect and recharge accumulators	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A40	29/08/2015	Saw attachment gears are binding and grinding	Michele Williams noted: No further details.	michele_williams
A80	12/08/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A19	12/05/2015	Leak in side B hydraulic line	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A74	09/12/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A67	16/07/2015	Leaks found at turrets A and B	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A30	01/02/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A74	23/11/2015	Leaks found at turrets A and B	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A46	30/07/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A39	15/06/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A59	01/03/2015	Leak in side B hydraulic line	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A56	20/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A58	04/06/2015	Machine is unpowered	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A70	07/10/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A84	23/12/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A32	19/09/2015	Turret A and B are leaking	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A99	12/08/2015	Milling spindle requires repair	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A74	17/10/2015	Unit lost electrical power	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A45	22/02/2015	Power supply failure detected	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A38	15/11/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A43	21/02/2015	Inspect and recharge accumulators	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A70	23/10/2015	Power supply failure detected	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A76	15/08/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A51	11/08/2015	Unit lost electrical power	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A79	29/07/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Detail not recorded.	michele_williams
A84	15/04/2015	Maintenance on milling spindle needed	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A61	28/10/2015	Hydraulic line leak on side B	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A72	10/12/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A95	25/09/2015	Turret A and B are leaking	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A63	18/10/2015	Machine is unpowered	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A86	11/05/2015	Leaks found at turrets A and B	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A2	01/07/2015	Inspect and recharge accumulators	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A42	17/03/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Repair completed.	cristian_santos
A8	30/10/2015	Leaks found at turrets A and B	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A58	14/09/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A89	30/01/2015	Machine is unpowered	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A96	22/01/2015	Unit lost electrical power	Cristian Santos noted: Detail not recorded.	cristian_santos
A13	26/06/2015	Leaks found at turrets A and B	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A67	02/02/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A54	11/01/2016	Power supply failure detected	Michele Williams noted: Repair completed.	michele_williams
A15	19/10/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A80	02/01/2016	Maintenance on milling spindle needed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A18	26/08/2015	Accumulators need checking and charging	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A90	28/12/2015	Maintenance on milling spindle needed	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A11	13/06/2015	Repair work needed on milling spindle	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A30	27/06/2015	Turret A and B are leaking	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A19	30/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: System checked and accumulators charged.	michele_williams
A10	15/01/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A49	15/08/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A72	28/05/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A82	29/01/2015	Inspect and recharge accumulators	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A78	24/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A52	21/04/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A96	06/01/2016	Turret A and B are leaking	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A7	23/04/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A54	15/06/2015	Turret sections A & B showing leaks	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A90	02/04/2015	Repair work needed on milling spindle	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A29	17/06/2015	Spindle indexing error with overfeed	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A83	02/01/2016	Milling spindle requires repair	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A16	03/08/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A56	06/04/2015	Maintenance on milling spindle needed	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A79	04/12/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A54	09/11/2015	Leaks found at turrets A and B	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams

A86	10/01/2016	Milling spindle requires repair	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A24	06/02/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A80	05/12/2015	Leaks found at turrets A and B	Cristian Santos noted: Maintenance action successful.	cristian_santos
A84	28/12/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A7	06/01/2016	Hydraulic line leak on side B	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A92	08/07/2015	Turret A and B are leaking	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A63	15/07/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A65	09/12/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A79	16/03/2015	Turret A and B are leaking	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A1	09/04/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A44	28/09/2015	Machine is unpowered	Michele Williams noted: No further details.	michele_williams
A11	03/09/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A19	10/07/2015	Spindle indexing error with overfeed	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A49	01/12/2015	Maintenance on milling spindle needed	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A43	01/09/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A91	26/12/2015	Inspect and recharge accumulators	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A41	22/03/2015	Spindle fails to index, overfeeding	Michele Williams noted: Maintenance action successful.	michele_williams
A68	09/04/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A26	08/05/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A35	18/11/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A54	22/07/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A53	02/01/2016	Indexing issue causing overfeed on spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A49	16/07/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A29	09/11/2015	Turret A and B are leaking	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A39	08/11/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A24	28/01/2015	Milling spindle requires repair	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A86	29/09/2015	Machine is unpowered	Cristian Santos noted: Maintenance action successful.	cristian_santos
A2	05/01/2016	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A83	21/08/2015	Unit lost electrical power	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A49	25/11/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A3	18/05/2015	Accumulators need checking and charging	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A2	08/11/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A27	28/11/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A81	07/04/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A40	26/02/2015	Milling spindle requires repair	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A9	31/03/2015	Unit lost electrical power	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A95	06/02/2015	Turret sections A & B showing leaks	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A84	01/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A23	21/12/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A55	22/08/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A54	01/12/2015	Accumulator inspection and charging required	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A40	19/06/2015	Power supply failure detected	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A48	17/05/2015	Unit lost electrical power	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A40	15/10/2015	Leak in side B hydraulic line	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A96	07/11/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A11	19/01/2015	Inspect and recharge accumulators	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A10	13/07/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: No additional information provided.	cristian_santos
A18	22/11/2015	Maintenance on milling spindle needed	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A75	29/09/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A41	30/09/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A54	26/11/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A60	17/07/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A76	03/04/2015	Inspect and recharge accumulators	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A73	09/01/2016	Accumulator inspection and charging required	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A49	10/01/2016	Accumulators need checking and charging	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A35	17/02/2015	Inspect and recharge accumulators	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A59	03/11/2015	Turret sections A & B showing leaks	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A46	24/11/2015	Leak in side B hydraulic line	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A24	22/03/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A23	29/04/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A61	11/01/2016	Indexing issue causing overfeed on spindle	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A5	14/05/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A27	28/11/2015	Accumulator inspection and charging required	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A86	11/02/2015	Inspect and recharge accumulators	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A98	19/05/2015	Milling spindle requires repair	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A82	07/04/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A52	18/12/2015	Accumulators need checking and charging	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A40	01/01/2016	Repair work needed on milling spindle	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A68	16/05/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A86	09/10/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams

A62	28/11/2015	Turret A and B are leaking	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A12	10/11/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A20	21/10/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A27	13/12/2015	Turret A and B are leaking	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A26	08/08/2015	Repair work needed on milling spindle	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A10	26/02/2015	Milling spindle requires repair	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A38	05/08/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A70	19/11/2015	Milling spindle requires repair	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A42	14/10/2015	Milling spindle requires repair	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A91	14/01/2015	Machine is unpowered	Michele Williams noted: System checked and accumulators charged.	michele_williams
A2	07/03/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A49	17/05/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A70	24/09/2015	Leaks found at turrets A and B	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A45	12/07/2015	Leaks found at turrets A and B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A61	13/03/2015	Accumulators need checking and charging	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A52	27/03/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A81	08/03/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A18	20/01/2015	Unit lost electrical power	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A52	12/03/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A87	24/05/2015	Power supply failure detected	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A96	11/02/2015	Turret sections A & B showing leaks	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A52	27/01/2015	Leak in side B hydraulic line	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A50	08/04/2015	Leaks found at turrets A and B	Michele Williams noted: No further details.	michele_williams
A32	16/09/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A29	06/01/2016	Spindle fails to index, overfeeding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A22	11/07/2015	Inspect and recharge accumulators	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A18	07/01/2016	Machine is unpowered	Cristian Santos noted: No further details.	cristian_santos
A1	26/04/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A89	08/05/2015	Machine is unpowered	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A64	24/02/2015	Leak in side B hydraulic line	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A15	03/02/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A6	14/11/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A25	23/03/2015	Hydraulic line leak on side B	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A46	16/09/2015	Leak in side B hydraulic line	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A95	24/11/2015	Accumulator inspection and charging required	Michele Williams noted: No further details.	michele_williams
A34	01/03/2015	Leak in side B hydraulic line	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A88	09/05/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A31	13/04/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A78	31/03/2015	Turret A and B are leaking	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A94	22/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A41	05/02/2015	Leak in side B hydraulic line	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A74	21/10/2015	Turret sections A & B showing leaks	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A82	18/01/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A80	28/05/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A51	24/07/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A73	28/03/2015	Accumulators need checking and charging	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A68	05/11/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A54	07/06/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A94	15/05/2015	Turret A and B are leaking	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A14	15/12/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A49	16/11/2015	Spindle indexing error with overfeed	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A38	19/02/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A31	08/03/2015	Spindle indexing error with overfeed	Michele Williams noted: Detail not recorded.	michele_williams
A79	18/12/2015	Spindle indexing error with overfeed	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A15	25/12/2015	Accumulators need checking and charging	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A35	07/04/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Fixed and tested.	michele_williams
A29	24/11/2015	Accumulator inspection and charging required	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A54	22/09/2015	Saw attachment gears are binding and grinding	Michele Williams noted: System checked and accumulators charged.	michele_williams
A47	22/05/2015	Inspect and recharge accumulators	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A37	31/08/2015	Power supply failure detected	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A47	12/08/2015	Leaks found at turrets A and B	Michele Williams noted: Fixed and tested.	michele_williams
A68	28/01/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A26	21/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A97	31/10/2015	Leak in side B hydraulic line	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A7	27/10/2015	Leak in side B hydraulic line	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A84	30/10/2015	Spindle indexing error with overfeed	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A2	11/04/2015	Hydraulic line leak on side B	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A21	17/05/2015	Turret A and B are leaking	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A31	06/11/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A53	28/12/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado

A1	20/10/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A40	26/01/2015	Milling spindle requires repair	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A78	06/09/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A22	28/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Repair completed.	cristian_santos
A93	31/01/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A86	26/03/2015	Turret A and B are leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A98	21/06/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A66	05/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A70	24/07/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A20	03/04/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A12	11/02/2015	Accumulator inspection and charging required	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A67	26/07/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A7	29/10/2015	Accumulators need checking and charging	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A67	07/04/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A55	30/08/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A55	18/02/2015	Accumulators need checking and charging	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A79	30/10/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A65	13/07/2015	Accumulators need checking and charging	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A52	14/04/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A2	23/03/2015	Repair work needed on milling spindle	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A59	23/10/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A90	05/05/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: No further details.	nathan_maldonado
A95	09/05/2015	Accumulator inspection and charging required	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A55	02/06/2015	Milling spindle requires repair	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A51	21/06/2015	Milling spindle requires repair	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A54	11/04/2015	Spindle indexing error with overfeed	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A76	08/03/2015	Leak in side B hydraulic line	Michele Williams noted: Fixed and tested.	michele_williams
A53	07/06/2015	Accumulator inspection and charging required	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A50	30/10/2015	Power supply failure detected	Cristian Santos noted: Maintenance action successful.	cristian_santos
A92	05/05/2015	Turret A and B are leaking	Nathan Maldonado noted: No further details.	nathan_maldonado
A50	01/02/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A56	13/02/2015	Leak in side B hydraulic line	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A60	09/02/2015	Spindle indexing error with overfeed	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A11	06/11/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A87	06/05/2015	Accumulators need checking and charging	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A57	20/04/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A3	17/05/2015	Milling spindle requires repair	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A41	10/06/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A4	23/04/2015	Leak in side B hydraulic line	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A61	04/11/2015	Milling spindle requires repair	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A76	04/03/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A67	27/01/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A38	30/12/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A96	28/08/2015	Spindle indexing error with overfeed	Michele Williams noted: No additional information provided.	michele_williams
A2	20/07/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A43	13/11/2015	Leak in side B hydraulic line	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A1	26/11/2015	Leak in side B hydraulic line	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A27	09/07/2015	Turret sections A & B showing leaks	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A17	10/01/2016	Accumulators need checking and charging	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A55	13/12/2015	Machine is unpowered	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A1	23/09/2015	Unit lost electrical power	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A5	20/10/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A88	03/03/2015	Spindle indexing error with overfeed	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A49	17/07/2015	Accumulator inspection and charging required	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A96	16/05/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A66	22/11/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A85	20/11/2015	Accumulators need checking and charging	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A22	14/12/2015	Accumulator inspection and charging required	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A5	03/12/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A25	14/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A5	25/09/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A74	27/01/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A95	02/05/2015	Milling spindle requires repair	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A47	26/08/2015	Inspect and recharge accumulators	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A54	09/12/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A62	20/04/2015	Unit lost electrical power	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A64	28/01/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A82	02/02/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A46	14/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A80	20/03/2015	Machine is unpowered	Cristian Santos noted: Maintenance action successful.	cristian_santos

A12	16/07/2015	Unit lost electrical power	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A77	13/12/2015	Spindle indexing error with overfeed	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A3	11/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A89	12/06/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A81	09/06/2015	Turret sections A & B showing leaks	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A11	18/11/2015	Hydraulic line leak on side B	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A5	17/11/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A82	17/02/2015	Turret A and B are leaking	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A23	24/08/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A3	06/03/2015	Repair work needed on milling spindle	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A64	23/02/2015	Hydraulic line leak on side B	Michele Williams noted: No additional information provided.	michele_williams
A35	01/02/2015	Accumulator inspection and charging required	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A96	29/12/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A50	21/02/2015	Inspect and recharge accumulators	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A34	10/07/2015	Leaks found at turrets A and B	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A59	21/10/2015	Hydraulic line leak on side B	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A41	25/09/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A4	30/07/2015	Spindle fails to index, overfeeding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A95	07/07/2015	Spindle indexing error with overfeed	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A21	22/06/2015	Leaks found at turrets A and B	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A77	25/07/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A73	18/09/2015	Milling spindle requires repair	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A57	24/02/2015	Accumulator inspection and charging required	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A66	16/04/2015	Turret A and B are leaking	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A13	08/07/2015	Turret A and B are leaking	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A93	23/03/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A10	05/01/2016	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A67	11/11/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A16	12/08/2015	Inspect and recharge accumulators	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A59	06/01/2016	Accumulators need checking and charging	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A58	11/08/2015	Leak in side B hydraulic line	Cristian Santos noted: No additional information provided.	cristian_santos
A8	22/11/2015	Power supply failure detected	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A66	24/09/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A87	29/06/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A28	03/11/2015	Inspect and recharge accumulators	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A81	02/01/2016	Unit lost electrical power	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A13	04/03/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A71	09/06/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A13	26/05/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A41	19/11/2015	Leak in side B hydraulic line	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A22	15/09/2015	Repair work needed on milling spindle	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A16	19/07/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A37	12/03/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A77	14/03/2015	Milling spindle requires repair	Michele Williams noted: No additional information provided.	michele_williams
A68	25/02/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A43	08/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A42	29/06/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A40	07/06/2015	Power supply failure detected	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A2	28/07/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A7	29/08/2015	Turret sections A & B showing leaks	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A70	10/11/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A26	06/05/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A21	31/01/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A44	11/11/2015	Turret A and B are leaking	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A97	17/10/2015	Milling spindle requires repair	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A80	19/11/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A58	16/12/2015	Power supply failure detected	Michele Williams noted: Maintenance action successful.	michele_williams
A88	14/05/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A88	01/08/2015	Milling spindle requires repair	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A17	04/01/2016	Grinding noise from tight gears on saw attachment	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A28	19/08/2015	Inspect and recharge accumulators	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A20	30/12/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A69	10/10/2015	Power supply failure detected	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A80	29/01/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A2	07/06/2015	Hydraulic line leak on side B	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A6	20/08/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A76	13/11/2015	Leaks found at turrets A and B	Michele Williams noted: No further details.	michele_williams
A61	21/02/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A20	06/02/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A97	20/06/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos

A33	25/11/2015	Milling spindle requires repair	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A27	26/12/2015	Accumulators need checking and charging	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A29	14/10/2015	Inspect and recharge accumulators	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A50	27/12/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A7	10/05/2015	Power supply failure detected	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A19	24/06/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A83	21/02/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A28	15/06/2015	Unit lost electrical power	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A83	10/01/2016	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A69	22/12/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A75	28/12/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A58	02/06/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A63	13/01/2016	Saw attachment gears are binding and grinding	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A85	14/10/2015	Leak in side B hydraulic line	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A13	27/01/2015	Accumulator inspection and charging required	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A47	03/09/2015	Hydraulic line leak on side B	Cristian Santos noted: Detail not recorded.	cristian_santos
A52	26/09/2015	Leaks found at turrets A and B	Cristian Santos noted: Detail not recorded.	cristian_santos
A14	25/06/2015	Turret sections A & B showing leaks	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A41	16/12/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A88	05/05/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A65	24/08/2015	Machine is unpowered	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A32	11/11/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A63	04/02/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A42	17/01/2015	Unit lost electrical power	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A18	05/01/2016	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A81	06/01/2016	Repair work needed on milling spindle	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A8	30/05/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Detail not recorded.	cristian_santos
A45	07/07/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A65	01/07/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A71	10/06/2015	Repair work needed on milling spindle	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A6	07/07/2015	Unit lost electrical power	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A38	08/11/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A23	09/09/2015	Hydraulic line leak on side B	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A64	14/10/2015	Machine is unpowered	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A44	03/04/2015	Accumulator inspection and charging required	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A93	23/06/2015	Turret A and B are leaking	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A16	05/05/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A96	20/02/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A82	16/11/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A18	08/07/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A63	11/01/2016	Hydraulic line leak on side B	Cristian Santos noted: Fixed and tested.	cristian_santos
A97	15/09/2015	Power supply failure detected	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A96	26/08/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A15	22/10/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A28	15/01/2015	Accumulator inspection and charging required	Michele Williams noted: No further details.	michele_williams
A15	13/08/2015	Turret sections A & B showing leaks	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A3	16/06/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A59	26/11/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A57	06/02/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A40	13/01/2016	Turret A and B are leaking	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A8	27/08/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A37	06/05/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A58	06/09/2015	Hydraulic line leak on side B	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A28	08/02/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A93	28/03/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A91	30/12/2015	Machine is unpowered	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A47	05/10/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A45	02/10/2015	Power supply failure detected	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A25	30/01/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A46	06/05/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A50	26/06/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A91	22/12/2015	Machine is unpowered	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A76	04/11/2015	Spindle indexing error with overfeed	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A53	19/10/2015	Leaks found at turrets A and B	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A7	24/04/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A96	03/04/2015	Machine is unpowered	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A70	04/03/2015	Leaks found at turrets A and B	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A10	02/04/2015	Accumulators need checking and charging	Nathan Maldonado noted: No further details.	nathan_maldonado
A91	01/10/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A14	18/11/2015	Machine is unpowered	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos

A82	18/06/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A66	05/02/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A77	30/06/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A65	12/01/2016	Leak in side B hydraulic line	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A51	06/08/2015	Hydraulic line leak on side B	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A11	07/07/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A70	21/11/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A48	15/04/2015	Accumulator inspection and charging required	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A53	26/05/2015	Leaks found at turrets A and B	Michele Williams noted: System checked and accumulators charged.	michele_williams
A64	03/01/2016	Turret sections A & B showing leaks	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A53	16/01/2015	Hydraulic line leak on side B	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A79	08/06/2015	Unit lost electrical power	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A25	05/02/2015	Maintenance on milling spindle needed	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A8	25/06/2015	Spindle indexing error with overfeed	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A94	22/10/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A19	13/01/2016	Unit lost electrical power	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A29	01/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A40	21/12/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A77	20/08/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A41	07/05/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: No further details.	nathan_maldonado
A41	11/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Fixed and tested.	cristian_santos
A54	01/09/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A35	13/03/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A48	05/09/2015	Repair work needed on milling spindle	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A68	16/09/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A80	16/08/2015	Leak in side B hydraulic line	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A33	08/05/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A45	19/10/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A68	30/08/2015	Power supply failure detected	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A10	17/08/2015	Spindle fails to index, overfeeding	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A23	25/12/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A76	19/04/2015	Milling spindle requires repair	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A46	20/02/2015	Spindle indexing error with overfeed	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A85	08/10/2015	Maintenance on milling spindle needed	Cristian Santos noted: No further details.	cristian_santos
A5	20/04/2015	Power supply failure detected	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A65	12/05/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A3	23/09/2015	Machine is unpowered	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A96	30/05/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A35	08/09/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: System checked and accumulators charged.	michele_williams
A68	01/07/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A65	08/11/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A40	13/01/2016	Accumulator inspection and charging required	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A61	01/08/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A64	15/03/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A4	21/10/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A28	03/03/2015	Inspect and recharge accumulators	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A37	15/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A44	01/10/2015	Maintenance on milling spindle needed	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A31	04/09/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A57	20/04/2015	Unit lost electrical power	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A53	01/07/2015	Inspect and recharge accumulators	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A7	30/08/2015	Milling spindle requires repair	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A16	16/10/2015	Accumulators need checking and charging	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A6	07/05/2015	Leak in side B hydraulic line	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A79	19/05/2015	Leak in side B hydraulic line	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A57	01/08/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A39	22/08/2015	Machine is unpowered	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A92	07/08/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Detail not recorded.	michele_williams
A58	14/03/2015	Accumulator inspection and charging required	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A47	10/07/2015	Milling spindle requires repair	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A1	23/08/2015	Spindle fails to index, overfeeding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A2	02/12/2015	Power supply failure detected	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A45	03/06/2015	Leak in side B hydraulic line	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A21	26/01/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A54	20/03/2015	Turret A and B are leaking	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A75	16/02/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A35	01/04/2015	Milling spindle requires repair	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A30	29/01/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A76	12/12/2015	Inspect and recharge accumulators	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A69	17/04/2015	Inspect and recharge accumulators	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams

A96	13/09/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A54	14/05/2015	Accumulator inspection and charging required	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A43	09/03/2015	Repair work needed on milling spindle	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A3	21/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A93	27/08/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Repair completed.	michele_williams
A97	09/08/2015	Leaks found at turrets A and B	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A68	13/02/2015	Accumulators need checking and charging	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A88	31/12/2015	Leak in side B hydraulic line	Cristian Santos noted: No further details.	cristian_santos
A5	04/11/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A68	20/07/2015	Accumulators need checking and charging	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A83	13/01/2016	Machine is unpowered	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A2	17/06/2015	Turret sections A & B showing leaks	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A92	13/12/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A61	08/06/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A1	09/05/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A76	24/06/2015	Power supply failure detected	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A26	19/11/2015	Leaks found at turrets A and B	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A68	09/02/2015	Power supply failure detected	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A88	15/03/2015	Milling spindle requires repair	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A32	11/04/2015	Turret sections A & B showing leaks	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A54	27/09/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A41	02/05/2015	Accumulators need checking and charging	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A69	01/06/2015	Leak in side B hydraulic line	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A19	28/05/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A6	18/08/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: No further details.	nathan_maldonado
A49	20/07/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A30	15/08/2015	Accumulator inspection and charging required	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A85	27/11/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A59	25/05/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A52	09/10/2015	Machine is unpowered	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A38	14/06/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A82	24/03/2015	Spindle indexing error with overfeed	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A62	09/12/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A71	10/11/2015	Inspect and recharge accumulators	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A22	16/12/2015	Spindle indexing error with overfeed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A66	14/08/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A7	18/02/2015	Turret A and B are leaking	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A75	01/04/2015	Turret sections A & B showing leaks	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A81	05/03/2015	Repair work needed on milling spindle	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A45	20/03/2015	Machine is unpowered	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A50	04/01/2016	Inspect and recharge accumulators	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A70	05/06/2015	Milling spindle requires repair	Michele Williams noted: System checked and accumulators charged.	michele_williams
A21	01/09/2015	Turret A and B are leaking	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A72	08/10/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A85	01/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A61	10/05/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A90	15/01/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A96	21/09/2015	Leak in side B hydraulic line	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A56	07/08/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A1	03/08/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A7	26/03/2015	Accumulator inspection and charging required	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A26	06/10/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A33	10/01/2016	Hydraulic line leak on side B	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A64	15/08/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A52	24/10/2015	Inspect and recharge accumulators	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A30	01/11/2015	Milling spindle requires repair	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A2	13/10/2015	Maintenance on milling spindle needed	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A84	26/12/2015	Spindle indexing error with overfeed	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A66	16/05/2015	Milling spindle requires repair	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A37	21/09/2015	Spindle indexing error with overfeed	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A59	14/02/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A63	05/10/2015	Power supply failure detected	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A35	16/05/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A51	15/04/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A81	19/08/2015	Turret sections A & B showing leaks	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A52	14/08/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A66	03/01/2016	Leaks found at turrets A and B	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A38	24/10/2015	Accumulator inspection and charging required	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A7	23/04/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Detail not recorded.	cristian_santos
A9	18/06/2015	Repair work needed on milling spindle	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams

A69	14/09/2015	Leak in side B hydraulic line	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A93	17/01/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A8	21/12/2015	Milling spindle requires repair	Michele Williams noted: Detail not recorded.	michele_williams
A31	14/01/2015	Accumulator inspection and charging required	Cristian Santos noted: Fixed and tested.	cristian_santos
A77	22/04/2015	Hydraulic line leak on side B	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A47	07/10/2015	Leak in side B hydraulic line	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A21	19/08/2015	Machine is unpowered	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A71	20/04/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A21	28/10/2015	Hydraulic line leak on side B	Michele Williams noted: Detail not recorded.	michele_williams
A64	14/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A84	08/02/2015	Accumulators need checking and charging	Michele Williams noted: Maintenance action successful.	michele_williams
A6	08/03/2015	Spindle indexing error with overfeed	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A91	27/02/2015	Leaks found at turrets A and B	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A20	13/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A76	08/08/2015	Inspect and recharge accumulators	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A6	25/08/2015	Leak in side B hydraulic line	Michele Williams noted: System checked and accumulators charged.	michele_williams
A71	06/06/2015	Machine is unpowered	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A59	19/08/2015	Milling spindle requires repair	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A37	18/08/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A43	12/10/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A26	02/04/2015	Milling spindle requires repair	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A43	14/11/2015	Milling spindle requires repair	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A85	11/03/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A56	13/11/2015	Spindle indexing error with overfeed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A79	04/05/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A77	14/04/2015	Machine is unpowered	Cristian Santos noted: Maintenance action successful.	cristian_santos
A70	07/07/2015	Leaks found at turrets A and B	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A81	28/10/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A83	27/07/2015	Accumulator inspection and charging required	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A82	24/10/2015	Unit lost electrical power	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A87	29/08/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A85	25/11/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A72	24/11/2015	Turret sections A & B showing leaks	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A91	31/07/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A53	31/12/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A74	04/11/2015	Turret sections A & B showing leaks	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A3	08/11/2015	Milling spindle requires repair	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A26	01/04/2015	Power supply failure detected	Michele Williams noted: Fixed and tested.	michele_williams
A57	27/06/2015	Leaks found at turrets A and B	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A12	13/06/2015	Inspect and recharge accumulators	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A25	13/07/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A79	03/06/2015	Accumulators need checking and charging	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A84	15/10/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A77	18/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A82	09/02/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A62	10/12/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A73	21/10/2015	Power supply failure detected	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A22	21/02/2015	Accumulators need checking and charging	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A15	04/05/2015	Unit lost electrical power	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A87	11/12/2015	Maintenance on milling spindle needed	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A15	03/06/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A33	09/12/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A16	13/12/2015	Accumulators need checking and charging	Cristian Santos noted: Fixed and tested.	cristian_santos
A82	16/05/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A87	04/09/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A8	10/06/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A39	20/11/2015	Turret sections A & B showing leaks	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A8	26/03/2015	Milling spindle requires repair	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A19	22/12/2015	Machine is unpowered	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A39	07/08/2015	Unit lost electrical power	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A45	06/01/2016	Hydraulic line leak on side B	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A45	17/04/2015	Unit lost electrical power	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A18	17/04/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A61	17/07/2015	Accumulator inspection and charging required	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A82	20/01/2015	Milling spindle requires repair	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A35	23/11/2015	Leaks found at turrets A and B	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A40	13/11/2015	Hydraulic line leak on side B	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A65	27/11/2015	Milling spindle requires repair	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A2	23/11/2015	Unit lost electrical power	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A46	28/05/2015	Unit lost electrical power	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams

A96	22/10/2015	Accumulators need checking and charging	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A3	05/01/2016	Repair work needed on milling spindle	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A85	02/11/2015	Spindle indexing error with overfeed	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A44	27/04/2015	Milling spindle requires repair	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A30	22/11/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A45	12/02/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A18	06/12/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A55	02/11/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A72	06/12/2015	Repair work needed on milling spindle	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A13	03/06/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A28	16/10/2015	Turret A and B are leaking	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A80	28/05/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Maintenance action successful.	michele_williams
A90	06/08/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A89	09/08/2015	Accumulator inspection and charging required	Cristian Santos noted: Detail not recorded.	cristian_santos
A83	31/08/2015	Turret sections A & B showing leaks	Cristian Santos noted: Repair completed.	cristian_santos
A54	11/07/2015	Turret A and B are leaking	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A8	06/04/2015	Power supply failure detected	Cristian Santos noted: No additional information provided.	cristian_santos
A4	19/09/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A57	10/07/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A40	24/01/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A35	26/07/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A63	16/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A40	13/02/2015	Unit lost electrical power	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A67	30/11/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A10	30/04/2015	Maintenance on milling spindle needed	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A25	23/09/2015	Repair work needed on milling spindle	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A9	31/01/2015	Repair work needed on milling spindle	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A70	01/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A35	15/05/2015	Hydraulic line leak on side B	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A34	21/05/2015	Milling spindle requires repair	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A41	16/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A14	18/03/2015	Turret sections A & B showing leaks	Michele Williams noted: Repair completed.	michele_williams
A92	12/10/2015	Accumulator inspection and charging required	Michele Williams noted: Maintenance action successful.	michele_williams
A97	26/01/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A67	18/01/2015	Maintenance on milling spindle needed	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A86	25/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A80	27/05/2015	Turret A and B are leaking	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A36	12/02/2015	Unit lost electrical power	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A32	24/03/2015	Inspect and recharge accumulators	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A33	09/02/2015	Machine is unpowered	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A54	09/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A1	15/04/2015	Turret A and B are leaking	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A83	18/08/2015	Hydraulic line leak on side B	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A49	13/04/2015	Milling spindle requires repair	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A77	05/02/2015	Turret A and B are leaking	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A60	05/04/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A94	30/01/2015	Spindle indexing error with overfeed	Gina Moore noted: No further details.	gina_moore, dylan_miller
A38	27/10/2015	Milling spindle requires repair	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A17	16/02/2015	Spindle indexing error with overfeed	Michele Williams noted: System checked and accumulators charged.	michele_williams
A34	08/02/2015	Power supply failure detected	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A52	22/10/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A53	13/09/2015	Hydraulic line leak on side B	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A76	24/08/2015	Inspect and recharge accumulators	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A19	22/03/2015	Unit lost electrical power	Cristian Santos noted: Repair completed.	cristian_santos
A36	08/04/2015	Power supply failure detected	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A33	30/10/2015	Repair work needed on milling spindle	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A53	13/11/2015	Unit lost electrical power	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A88	17/06/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A48	04/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A60	02/08/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A91	05/02/2015	Turret A and B are leaking	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A42	09/10/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A62	18/07/2015	Turret sections A & B showing leaks	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A65	05/04/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A63	23/01/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A79	27/03/2015	Repair work needed on milling spindle	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A42	09/02/2015	Accumulators need checking and charging	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A70	11/03/2015	Turret sections A & B showing leaks	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A19	22/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A16	29/07/2015	Spindle indexing error with overfeed	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller

A79	21/04/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A33	23/09/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A68	28/11/2015	Turret A and B are leaking	Gina Moore noted: No further details.	gina_moore, dylan_miller
A16	17/12/2015	Machine is unpowered	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A27	15/05/2015	Repair work needed on milling spindle	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A83	05/01/2016	Machine is unpowered	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A16	07/09/2015	Milling spindle requires repair	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A73	25/05/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Detail not recorded.	cristian_santos
A62	18/01/2015	Spindle fails to index, overfeeding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A45	09/01/2016	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A39	30/10/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A11	25/05/2015	Turret sections A & B showing leaks	Michele Williams noted: Maintenance action successful.	michele_williams
A78	26/05/2015	Turret sections A & B showing leaks	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A99	22/08/2015	Turret A and B are leaking	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A65	23/04/2015	Turret A and B are leaking	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A30	30/12/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A1	07/12/2015	Machine is unpowered	Michele Williams noted: Maintenance action successful.	michele_williams
A9	29/03/2015	Accumulators need checking and charging	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A78	21/01/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Repair completed.	cristian_santos
A70	12/05/2015	Inspect and recharge accumulators	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A34	06/01/2016	Turret A and B are leaking	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A45	05/03/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A67	01/07/2015	Turret A and B are leaking	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A70	25/04/2015	Machine is unpowered	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A73	09/12/2015	Power supply failure detected	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A32	14/09/2015	Unit lost electrical power	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A65	14/12/2015	Hydraulic line leak on side B	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A55	09/06/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A69	04/02/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A92	26/02/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A40	21/12/2015	Repair work needed on milling spindle	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A52	05/09/2015	Hydraulic line leak on side B	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A29	25/04/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A27	19/02/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A14	28/12/2015	Power supply failure detected	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A60	16/04/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A22	16/10/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A17	02/10/2015	Maintenance on milling spindle needed	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A68	05/08/2015	Hydraulic line leak on side B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A53	29/06/2015	Inspect and recharge accumulators	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A73	31/10/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A3	26/12/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A5	27/10/2015	Spindle indexing error with overfeed	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A75	19/10/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A33	08/02/2015	Power supply failure detected	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A70	04/04/2015	Accumulators need checking and charging	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A70	07/05/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A2	15/11/2015	Maintenance on milling spindle needed	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A53	01/10/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A81	26/07/2015	Spindle indexing error with overfeed	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A33	13/10/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: No further details.	nathan_maldonado
A44	26/12/2015	Accumulators need checking and charging	Cristian Santos noted: No further details.	cristian_santos
A83	22/12/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A64	12/03/2015	Maintenance on milling spindle needed	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A59	10/08/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A21	24/04/2015	Maintenance on milling spindle needed	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A81	21/05/2015	Leak in side B hydraulic line	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A29	14/11/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A85	09/07/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A66	01/09/2015	Leak in side B hydraulic line	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A37	23/07/2015	Milling spindle requires repair	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A31	10/02/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A51	05/06/2015	Unit lost electrical power	Michele Williams noted: Fixed and tested.	michele_williams
A40	31/12/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A13	09/10/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A25	23/11/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A32	28/02/2015	Inspect and recharge accumulators	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A99	29/04/2015	Unit lost electrical power	Michele Williams noted: No additional information provided.	michele_williams
A24	02/09/2015	Repair work needed on milling spindle	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A71	15/04/2015	Power supply failure detected	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams

A55	31/03/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A98	24/12/2015	Power supply failure detected	Michele Williams noted: System checked and accumulators charged.	michele_williams
A19	09/06/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A2	02/03/2015	Repair work needed on milling spindle	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A56	10/12/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A63	09/09/2015	Repair work needed on milling spindle	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A33	12/02/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A31	25/05/2015	Accumulator inspection and charging required	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A8	16/09/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A16	31/07/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A82	05/07/2015	Repair work needed on milling spindle	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A51	28/09/2015	Leaks found at turrets A and B	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A89	30/04/2015	Repair work needed on milling spindle	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A80	20/07/2015	Turret A and B are leaking	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A38	05/08/2015	Spindle fails to index, overfeeding	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A39	15/02/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A46	02/08/2015	Accumulator inspection and charging required	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A75	30/12/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A5	06/08/2015	Spindle indexing error with overfeed	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A79	23/05/2015	Machine is unpowered	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A49	28/12/2015	Leaks found at turrets A and B	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A24	11/05/2015	Milling spindle requires repair	Cristian Santos noted: Fixed and tested.	cristian_santos
A60	21/02/2015	Repair work needed on milling spindle	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A15	29/01/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A55	09/12/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A26	04/09/2015	Spindle indexing error with overfeed	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A48	24/06/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A6	27/03/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A90	13/07/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A19	21/12/2015	Turret sections A & B showing leaks	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A88	13/10/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A29	31/01/2015	Accumulators need checking and charging	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A77	25/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A29	09/03/2015	Leak in side B hydraulic line	Cristian Santos noted: Detail not recorded.	cristian_santos
A76	13/08/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A22	16/11/2015	Accumulators need checking and charging	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A8	19/03/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A37	14/12/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A21	02/08/2015	Unit lost electrical power	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A65	24/04/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A49	04/12/2015	Spindle fails to index, overfeeding	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A20	25/07/2015	Power supply failure detected	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A48	13/12/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A83	06/09/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A1	16/03/2015	Accumulators need checking and charging	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A80	20/06/2015	Unit lost electrical power	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A32	22/05/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A31	18/08/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A17	06/11/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A58	14/06/2015	Leak in side B hydraulic line	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A80	16/11/2015	Turret sections A & B showing leaks	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A38	11/12/2015	Unit lost electrical power	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A15	02/09/2015	Accumulators need checking and charging	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A83	31/05/2015	Turret A and B are leaking	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A21	30/11/2015	Unit lost electrical power	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A88	24/04/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A70	06/01/2016	Unit lost electrical power	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A97	01/12/2015	Accumulator inspection and charging required	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A70	27/12/2015	Spindle indexing error with overfeed	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A14	25/08/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A15	29/10/2015	Leaks found at turrets A and B	Michele Williams noted: Repair completed.	michele_williams
A68	03/05/2015	Repair work needed on milling spindle	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A93	26/05/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A40	21/11/2015	Inspect and recharge accumulators	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A43	11/01/2016	Grinding noise from tight gears on saw attachment	Michele Williams noted: Fixed and tested.	michele_williams
A9	11/11/2015	Inspect and recharge accumulators	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A73	24/04/2015	Machine is unpowered	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A43	06/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A41	15/04/2015	Spindle indexing error with overfeed	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A53	05/06/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado

A62	30/03/2015	Leak in side B hydraulic line	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A87	07/11/2015	Machine is unpowered	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A52	16/12/2015	Turret A and B are leaking	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A80	02/10/2015	Leak in side B hydraulic line	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A59	20/06/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A70	08/12/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A21	14/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Maintenance action successful.	michele_williams
A73	23/05/2015	Machine is unpowered	Cristian Santos noted: Detail not recorded.	cristian_santos
A28	21/12/2015	Maintenance on milling spindle needed	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A40	30/10/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A72	12/01/2016	Repair work needed on milling spindle	Cristian Santos noted: Repair completed.	cristian_santos
A37	20/03/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A24	13/11/2015	Repair work needed on milling spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A87	25/09/2015	Turret sections A & B showing leaks	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A76	20/11/2015	Machine is unpowered	Cristian Santos noted: Repair completed.	cristian_santos
A82	19/11/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A30	19/10/2015	Machine is unpowered	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A96	02/04/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A84	18/05/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A41	09/06/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A75	23/05/2015	Unit lost electrical power	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A38	13/01/2016	Spindle indexing error with overfeed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A59	15/08/2015	Unit lost electrical power	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A77	23/02/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Fixed and tested.	michele_williams
A16	15/05/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A63	30/08/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A44	23/01/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A68	25/06/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A25	09/08/2015	Accumulators need checking and charging	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A16	30/09/2015	Turret sections A & B showing leaks	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A25	16/05/2015	Accumulator inspection and charging required	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A22	15/11/2015	Milling spindle requires repair	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A36	25/03/2015	Leaks found at turrets A and B	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A34	09/04/2015	Inspect and recharge accumulators	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A48	13/03/2015	Unit lost electrical power	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A75	19/09/2015	Repair work needed on milling spindle	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A53	07/11/2015	Hydraulic line leak on side B	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A98	29/05/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A70	21/10/2015	Machine is unpowered	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A13	08/10/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A36	19/04/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A43	16/03/2015	Inspect and recharge accumulators	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A16	15/01/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Fixed and tested.	michele_williams
A44	12/03/2015	Turret A and B are leaking	Cristian Santos noted: No additional information provided.	cristian_santos
A46	29/08/2015	Power supply failure detected	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A76	01/05/2015	Inspect and recharge accumulators	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A25	05/01/2016	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A83	08/05/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A98	01/02/2015	Power supply failure detected	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A75	21/12/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Fixed and tested.	cristian_santos
A85	08/12/2015	Accumulator inspection and charging required	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A78	05/12/2015	Repair work needed on milling spindle	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A15	30/05/2015	Leak in side B hydraulic line	Michele Williams noted: Repair completed.	michele_williams
A92	15/03/2015	Milling spindle requires repair	Cristian Santos noted: Detail not recorded.	cristian_santos
A65	27/01/2015	Leak in side B hydraulic line	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A86	21/04/2015	Turret A and B are leaking	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A2	16/11/2015	Inspect and recharge accumulators	Michele Williams noted: No additional information provided.	michele_williams
A27	13/03/2015	Turret sections A & B showing leaks	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A26	10/03/2015	Milling spindle requires repair	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A55	06/05/2015	Turret A and B are leaking	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A60	08/01/2016	Leaks found at turrets A and B	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A14	12/03/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A43	23/12/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A1	21/02/2015	Turret A and B are leaking	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A72	25/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A14	31/12/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A67	11/11/2015	Leaks found at turrets A and B	Cristian Santos noted: No further details.	cristian_santos
A85	31/01/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A52	22/07/2015	Machine is unpowered	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A80	04/01/2016	Indexing issue causing overfeed on spindle	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller

A95	20/06/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A66	02/12/2015	Repair work needed on milling spindle	Michele Williams noted: Repair completed.	michele_williams
A33	01/12/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A26	26/05/2015	Spindle indexing error with overfeed	Michele Williams noted: No additional information provided.	michele_williams
A47	12/08/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A35	29/01/2015	Milling spindle requires repair	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A68	24/05/2015	Accumulators need checking and charging	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A66	07/11/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A12	31/08/2015	Repair work needed on milling spindle	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A27	19/04/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A91	22/02/2015	Leak in side B hydraulic line	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A87	23/12/2015	Leak in side B hydraulic line	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A26	20/05/2015	Maintenance on milling spindle needed	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A30	01/07/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A83	01/10/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A83	23/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A42	16/06/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Detail not recorded.	michele_williams
A32	27/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A63	22/05/2015	Leak in side B hydraulic line	Cristian Santos noted: Maintenance action successful.	cristian_santos
A24	07/03/2015	Accumulator inspection and charging required	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A64	25/10/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A36	21/08/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A6	05/10/2015	Milling spindle requires repair	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A2	21/11/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A56	27/01/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A86	14/06/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A34	22/12/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A34	10/08/2015	Spindle indexing error with overfeed	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A14	09/08/2015	Repair work needed on milling spindle	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A30	15/10/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A70	05/07/2015	Machine is unpowered	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A59	11/08/2015	Maintenance on milling spindle needed	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A15	04/10/2015	Accumulators need checking and charging	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A74	28/07/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A92	18/04/2015	Turret sections A & B showing leaks	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A51	12/09/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A93	10/01/2016	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A24	07/04/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A4	01/06/2015	Accumulators need checking and charging	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A35	08/06/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A28	13/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Repair completed.	michele_williams
A61	19/09/2015	Accumulator inspection and charging required	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A5	15/02/2015	Leaks found at turrets A and B	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A77	18/03/2015	Inspect and recharge accumulators	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A72	14/03/2015	Machine is unpowered	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A47	23/12/2015	Maintenance on milling spindle needed	Michele Williams noted: Repair completed.	michele_williams
A81	12/05/2015	Accumulator inspection and charging required	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A61	28/04/2015	Hydraulic hose on side B is leaking	Michele Williams noted: No additional information provided.	michele_williams
A36	01/03/2015	Leak in side B hydraulic line	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A90	30/06/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A74	19/08/2015	Milling spindle requires repair	Cristian Santos noted: No further details.	cristian_santos
A67	26/11/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A34	25/12/2015	Turret sections A & B showing leaks	Michele Williams noted: Repair completed.	michele_williams
A33	25/10/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A36	09/01/2016	Power supply failure detected	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A86	05/02/2015	Unit lost electrical power	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A46	15/11/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Repair completed.	michele_williams
A29	31/08/2015	Maintenance on milling spindle needed	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A95	05/06/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A88	30/12/2015	Machine is unpowered	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A87	12/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A3	21/02/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A24	23/10/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A13	16/06/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A43	02/11/2015	Maintenance on milling spindle needed	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A77	01/11/2015	Turret A and B are leaking	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A50	11/01/2016	Saw attachment gears are binding and grinding	Michele Williams noted: No further details.	michele_williams
A65	04/01/2016	Power supply failure detected	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A69	31/07/2015	Inspect and recharge accumulators	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A34	21/07/2015	Spindle indexing error with overfeed	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams

A93	09/09/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A12	05/06/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A67	02/08/2015	Machine is unpowered	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A87	22/11/2015	Leak in side B hydraulic line	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A65	24/12/2015	Leaks found at turrets A and B	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A14	22/08/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A20	28/01/2015	Spindle indexing error with overfeed	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A40	22/06/2015	Milling spindle requires repair	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A78	19/10/2015	Inspect and recharge accumulators	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A38	02/10/2015	Machine is unpowered	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A51	23/05/2015	Accumulator inspection and charging required	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A33	24/12/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: System checked and accumulators charged.	michele_williams
A90	25/04/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A4	01/06/2015	Hydraulic line leak on side B	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A30	13/06/2015	Spindle indexing error with overfeed	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A12	23/04/2015	Machine is unpowered	Cristian Santos noted: Maintenance action successful.	cristian_santos
A32	06/01/2016	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A63	24/11/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A80	20/08/2015	Inspect and recharge accumulators	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A40	12/08/2015	Turret A and B are leaking	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A50	29/03/2015	Machine is unpowered	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A75	30/06/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A3	15/11/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A9	27/04/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A21	07/07/2015	Machine is unpowered	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A18	31/12/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A79	11/11/2015	Inspect and recharge accumulators	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A18	13/09/2015	Repair work needed on milling spindle	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A70	01/02/2015	Leak in side B hydraulic line	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A15	13/10/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A73	14/09/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A96	02/02/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A28	29/12/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A76	05/10/2015	Milling spindle requires repair	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A31	21/04/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A1	02/01/2016	Hydraulic fluid leak at saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A18	01/02/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A7	09/11/2015	Turret sections A & B showing leaks	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A97	13/11/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A33	24/09/2015	Machine is unpowered	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A51	20/04/2015	Leak in side B hydraulic line	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A57	15/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A48	06/07/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A11	15/10/2015	Machine is unpowered	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A86	13/04/2015	Machine is unpowered	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A55	19/06/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A10	05/07/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Detail not recorded.	cristian_santos
A91	02/01/2016	Indexing issue causing overfeed on spindle	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A96	16/07/2015	Inspect and recharge accumulators	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A42	21/02/2015	Turret A and B are leaking	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A34	06/11/2015	Turret sections A & B showing leaks	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A51	23/05/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A96	06/10/2015	Maintenance on milling spindle needed	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A82	01/06/2015	Spindle indexing error with overfeed	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A60	27/04/2015	Unit lost electrical power	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A50	20/04/2015	Leak in side B hydraulic line	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A11	03/06/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A8	11/06/2015	Spindle indexing error with overfeed	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A75	08/04/2015	Accumulator inspection and charging required	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A96	21/09/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A11	05/04/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A60	01/02/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A28	10/02/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A61	10/10/2015	Maintenance on milling spindle needed	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A55	13/12/2015	Spindle fails to index, overfeeding	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A88	13/08/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A38	05/08/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A22	30/07/2015	Machine is unpowered	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A32	27/03/2015	Machine is unpowered	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A21	24/12/2015	Inspect and recharge accumulators	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams

A55	08/05/2015	Maintenance on milling spindle needed	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A12	27/08/2015	Leaks found at turrets A and B	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A56	08/12/2015	Accumulator inspection and charging required	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A54	31/12/2015	Repair work needed on milling spindle	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A37	15/07/2015	Leak in side B hydraulic line	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A97	12/07/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A59	20/01/2015	Inspect and recharge accumulators	Cristian Santos noted: No further details.	cristian_santos
A76	17/04/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A10	17/11/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A32	09/10/2015	Milling spindle requires repair	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A95	22/07/2015	Accumulators need checking and charging	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A4	11/05/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A81	06/08/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A30	11/02/2015	Machine is unpowered	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A16	23/11/2015	Repair work needed on milling spindle	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A90	12/12/2015	Machine is unpowered	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A9	12/04/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A27	09/03/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A27	18/03/2015	Hydraulic line leak on side B	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A42	30/03/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A30	14/12/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A18	05/08/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A14	01/02/2015	Hydraulic line leak on side B	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A88	21/03/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A77	02/10/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A79	13/12/2015	Maintenance on milling spindle needed	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A46	28/08/2015	Machine is unpowered	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A5	08/07/2015	Leak in side B hydraulic line	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A42	12/02/2015	Repair work needed on milling spindle	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A35	14/07/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: No further details.	nathan_maldonado
A98	27/11/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A90	11/07/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A36	19/07/2015	Accumulators need checking and charging	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A77	13/06/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A22	04/07/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A62	20/06/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A86	15/09/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A90	18/07/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A18	26/01/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A95	15/12/2015	Accumulators need checking and charging	Michele Williams noted: System checked and accumulators charged.	michele_williams
A3	07/02/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A82	22/04/2015	Unit lost electrical power	Gina Moore noted: No further details.	gina_moore, dylan_miller
A44	06/10/2015	Turret A and B are leaking	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A15	12/03/2015	Turret A and B are leaking	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A29	18/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Repair completed.	michele_williams
A82	29/07/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A14	25/01/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A54	11/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A69	02/09/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A56	26/05/2015	Unit lost electrical power	Cristian Santos noted: Detail not recorded.	cristian_santos
A26	26/03/2015	Maintenance on milling spindle needed	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A63	14/12/2015	Leak in side B hydraulic line	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A36	17/11/2015	Turret A and B are leaking	Michele Williams noted: Fixed and tested.	michele_williams
A84	10/01/2016	Milling spindle requires repair	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A58	13/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A83	31/12/2015	Accumulator inspection and charging required	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A9	11/07/2015	Power supply failure detected	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A94	29/03/2015	Hydraulic line leak on side B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A72	19/05/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A91	20/12/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A96	30/06/2015	Maintenance on milling spindle needed	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A82	11/01/2016	Turret sections A & B showing leaks	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A69	10/06/2015	Repair work needed on milling spindle	Michele Williams noted: Fixed and tested.	michele_williams
A54	04/07/2015	Unit lost electrical power	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A18	10/05/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Repair completed.	cristian_santos
A73	22/07/2015	Turret A and B are leaking	Cristian Santos noted: No additional information provided.	cristian_santos
A39	12/05/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A5	12/04/2015	Accumulator inspection and charging required	Michele Williams noted: Maintenance action successful.	michele_williams
A60	22/03/2015	Maintenance on milling spindle needed	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A97	07/11/2015	Leak in side B hydraulic line	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams

A52	05/05/2015	Leaks found at turrets A and B	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A2	13/01/2016	Inspect and recharge accumulators	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A36	26/08/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A16	25/06/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A46	08/04/2015	Spindle fails to index, overfeeding	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A62	09/02/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: No additional information provided.	cristian_santos
A9	09/05/2015	Turret A and B are leaking	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A55	14/11/2015	Leaks found at turrets A and B	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A31	24/07/2015	Maintenance on milling spindle needed	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A71	06/08/2015	Accumulators need checking and charging	Cristian Santos noted: Repair completed.	cristian_santos
A55	25/08/2015	Power supply failure detected	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A15	17/07/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A91	16/11/2015	Milling spindle requires repair	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A80	31/07/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A76	23/08/2015	Spindle indexing error with overfeed	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A15	27/05/2015	Accumulator inspection and charging required	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A27	10/05/2015	Leak in side B hydraulic line	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A89	13/07/2015	Hydraulic line leak on side B	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A84	03/02/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A78	09/09/2015	Accumulators need checking and charging	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A64	26/03/2015	Machine is unpowered	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A94	10/08/2015	Turret sections A & B showing leaks	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A56	21/05/2015	Accumulator inspection and charging required	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A72	18/01/2015	Turret sections A & B showing leaks	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A54	01/02/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A50	27/10/2015	Milling spindle requires repair	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A75	09/12/2015	Accumulators need checking and charging	Michele Williams noted: No additional information provided.	michele_williams
A7	06/12/2015	Leaks found at turrets A and B	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A52	10/10/2015	Turret sections A & B showing leaks	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A1	28/08/2015	Milling spindle requires repair	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A5	02/07/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A60	16/10/2015	Maintenance on milling spindle needed	Michele Williams noted: Repair completed.	michele_williams
A62	23/07/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A43	01/03/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A19	03/10/2015	Power supply failure detected	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A75	19/01/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A58	01/06/2015	Turret sections A & B showing leaks	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A86	27/02/2015	Spindle indexing error with overfeed	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A50	26/01/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A55	28/08/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A81	25/09/2015	Turret sections A & B showing leaks	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A86	02/09/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Detail not recorded.	cristian_santos
A19	08/07/2015	Milling spindle requires repair	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A77	09/01/2016	Leak in side B hydraulic line	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A78	24/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A38	02/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A85	10/12/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A55	08/07/2015	Leaks found at turrets A and B	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A79	08/03/2015	Spindle indexing error with overfeed	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A37	25/12/2015	Repair work needed on milling spindle	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A34	10/04/2015	Turret A and B are leaking	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A28	06/12/2015	Unit lost electrical power	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A72	21/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A72	02/09/2015	Turret sections A & B showing leaks	Cristian Santos noted: Repair completed.	cristian_santos
A83	21/09/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A2	09/10/2015	Power supply failure detected	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A53	16/06/2015	Accumulators need checking and charging	Michele Williams noted: Fixed and tested.	michele_williams
A57	25/09/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A5	20/05/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A88	31/07/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A99	25/12/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A45	20/11/2015	Leaks found at turrets A and B	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A82	12/04/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A78	27/06/2015	Turret A and B are leaking	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A80	28/01/2015	Hydraulic line leak on side B	Michele Williams noted: Detail not recorded.	michele_williams
A8	10/08/2015	Turret A and B are leaking	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A37	23/10/2015	Power supply failure detected	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A54	22/08/2015	Accumulators need checking and charging	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A84	06/09/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A40	13/03/2015	Power supply failure detected	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams

A23	09/09/2015	Maintenance on milling spindle needed	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A20	06/04/2015	Turret A and B are leaking	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A65	22/07/2015	Power supply failure detected	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A77	22/12/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A60	16/06/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A77	05/10/2015	Leak in side B hydraulic line	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A90	05/07/2015	Leak in side B hydraulic line	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A68	06/02/2015	Milling spindle requires repair	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A97	07/09/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A68	23/04/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A33	30/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A22	03/04/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A21	13/12/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A58	28/07/2015	Leaks found at turrets A and B	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A88	24/01/2015	Inspect and recharge accumulators	Cristian Santos noted: No additional information provided.	cristian_santos
A10	23/07/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A13	11/11/2015	Maintenance on milling spindle needed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A99	24/08/2015	Turret A and B are leaking	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A61	19/04/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A78	28/03/2015	Maintenance on milling spindle needed	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A17	12/11/2015	Accumulators need checking and charging	Michele Williams noted: Detail not recorded.	michele_williams
A10	05/04/2015	Turret A and B are leaking	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A91	27/10/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A91	09/07/2015	Maintenance on milling spindle needed	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A78	21/06/2015	Leaks found at turrets A and B	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A19	26/08/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A48	03/08/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A49	17/05/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A76	13/12/2015	Inspect and recharge accumulators	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A95	29/09/2015	Accumulators need checking and charging	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A13	05/06/2015	Leaks found at turrets A and B	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A55	03/09/2015	Leak in side B hydraulic line	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A41	31/10/2015	Spindle fails to index, overfeeding	Cristian Santos noted: No additional information provided.	cristian_santos
A20	29/11/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A56	01/02/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A24	13/08/2015	Turret sections A & B showing leaks	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A20	13/08/2015	Accumulator inspection and charging required	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A48	26/11/2015	Turret A and B are leaking	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A23	30/08/2015	Spindle indexing error with overfeed	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A62	16/05/2015	Power supply failure detected	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A98	24/02/2015	Accumulators need checking and charging	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A13	23/12/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A52	07/12/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A88	21/03/2015	Accumulator inspection and charging required	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A1	03/07/2015	Power supply failure detected	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A4	16/08/2015	Milling spindle requires repair	Michele Williams noted: Fixed and tested.	michele_williams
A70	05/12/2015	Milling spindle requires repair	Cristian Santos noted: Fixed and tested.	cristian_santos
A29	14/02/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A38	02/10/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A63	17/11/2015	Leak in side B hydraulic line	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A65	23/03/2015	Machine is unpowered	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A81	22/11/2015	Repair work needed on milling spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A71	01/09/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A65	04/10/2015	Hydraulic line leak on side B	Cristian Santos noted: No additional information provided.	cristian_santos
A57	22/09/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A9	11/07/2015	Spindle fails to index, overfeeding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A51	16/06/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A41	29/08/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: No additional information provided.	michele_williams
A86	11/03/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A88	13/05/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A80	12/11/2015	Spindle indexing error with overfeed	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A46	21/10/2015	Leaks found at turrets A and B	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A54	01/06/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A19	22/01/2015	Repair work needed on milling spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A42	20/12/2015	Repair work needed on milling spindle	Cristian Santos noted: Detail not recorded.	cristian_santos
A19	01/02/2015	Leaks found at turrets A and B	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A11	10/06/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A22	06/10/2015	Leaks found at turrets A and B	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A96	09/02/2015	Leak in side B hydraulic line	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A96	02/02/2015	Turret sections A & B showing leaks	Michele Williams noted: Maintenance action successful.	michele_williams

A76	18/08/2015	Spindle indexing error with overfeed	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A88	26/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A73	30/05/2015	Maintenance on milling spindle needed	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A25	19/06/2015	Accumulator inspection and charging required	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A95	02/04/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A28	05/06/2015	Accumulators need checking and charging	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A90	11/03/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Fixed and tested.	cristian_santos
A57	03/09/2015	Power supply failure detected	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A82	29/12/2015	Accumulator inspection and charging required	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A42	25/02/2015	Turret sections A & B showing leaks	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A71	30/06/2015	Spindle fails to index, overfeeding	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A22	31/03/2015	Leak in side B hydraulic line	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A66	02/02/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A73	01/12/2015	Milling spindle requires repair	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A34	25/02/2015	Turret sections A & B showing leaks	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A86	06/10/2015	Leak in side B hydraulic line	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A61	10/03/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A10	07/09/2015	Maintenance on milling spindle needed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A64	15/09/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A1	03/06/2015	Turret sections A & B showing leaks	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A50	30/05/2015	Power supply failure detected	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A99	20/03/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A74	23/12/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A44	25/01/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A23	02/07/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A42	21/05/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A62	14/10/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A76	26/12/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A2	18/02/2015	Leak in side B hydraulic line	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A52	13/12/2015	Unit lost electrical power	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A7	11/07/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A63	13/04/2015	Repair work needed on milling spindle	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A53	04/06/2015	Turret A and B are leaking	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A34	10/04/2015	Leak in side B hydraulic line	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A9	17/06/2015	Milling spindle requires repair	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A5	22/05/2015	Turret A and B are leaking	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A69	26/11/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A92	08/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A98	21/05/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A72	02/06/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A39	30/07/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A35	06/12/2015	Leak in side B hydraulic line	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A82	11/04/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A75	27/11/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A80	27/01/2015	Turret sections A & B showing leaks	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A13	14/09/2015	Maintenance on milling spindle needed	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A90	27/09/2015	Spindle fails to index, overfeeding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A31	29/09/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A86	05/08/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A79	13/05/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A55	17/09/2015	Machine is unpowered	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A9	03/12/2015	Milling spindle requires repair	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A3	01/06/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A41	15/07/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A38	05/11/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A27	30/03/2015	Unit lost electrical power	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A65	31/07/2015	Machine is unpowered	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A64	23/11/2015	Spindle fails to index, overfeeding	Michele Williams noted: No additional information provided.	michele_williams
A91	02/12/2015	Power supply failure detected	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A19	31/05/2015	Repair work needed on milling spindle	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A12	07/03/2015	Leaks found at turrets A and B	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A72	22/05/2015	Maintenance on milling spindle needed	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A6	16/01/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A76	17/11/2015	Accumulators need checking and charging	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A85	20/06/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A88	26/07/2015	Hydraulic hose on side B is leaking	Gina Moore noted: No further details.	gina_moore, dylan_miller
A79	28/02/2015	Unit lost electrical power	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A8	03/05/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A67	22/10/2015	Spindle fails to index, overfeeding	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A68	08/02/2015	Machine is unpowered	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado

A72	29/03/2015	Milling spindle requires repair	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A4	25/11/2015	Turret A and B are leaking	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A57	11/09/2015	Power supply failure detected	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A3	27/06/2015	Accumulators need checking and charging	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A21	24/01/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A66	20/05/2015	Milling spindle requires repair	Michele Williams noted: Detail not recorded.	michele_williams
A97	24/11/2015	Inspect and recharge accumulators	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A97	16/03/2015	Unit lost electrical power	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A44	18/01/2015	Spindle indexing error with overfeed	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A8	08/10/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A94	30/06/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A78	07/02/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A81	26/01/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A30	15/03/2015	Machine is unpowered	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A81	28/06/2015	Inspect and recharge accumulators	Cristian Santos noted: No further details.	cristian_santos
A6	09/06/2015	Turret sections A & B showing leaks	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A92	14/03/2015	Milling spindle requires repair	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A73	28/03/2015	Spindle fails to index, overfeeding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A72	04/01/2016	Inspect and recharge accumulators	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A5	31/08/2015	Hydraulic line leak on side B	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A26	01/09/2015	Power supply failure detected	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A51	14/02/2015	Machine is unpowered	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A86	21/11/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A97	12/07/2015	Power supply failure detected	Cristian Santos noted: No additional information provided.	cristian_santos
A24	29/08/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A43	09/01/2016	Saw attachment is leaking hydraulics	Michele Williams noted: Fixed and tested.	michele_williams
A91	28/05/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A11	10/12/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A88	28/05/2015	Inspect and recharge accumulators	Michele Williams noted: Fixed and tested.	michele_williams
A41	23/12/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A13	05/01/2016	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A21	26/07/2015	Leaks found at turrets A and B	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A95	18/04/2015	Leaks found at turrets A and B	Cristian Santos noted: No additional information provided.	cristian_santos
A70	03/09/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A22	15/12/2015	Accumulators need checking and charging	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A11	17/02/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A13	05/06/2015	Machine is unpowered	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A91	03/01/2016	Power supply failure detected	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A66	04/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A47	08/12/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A74	30/05/2015	Milling spindle requires repair	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A40	21/05/2015	Maintenance on milling spindle needed	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A66	20/06/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A71	22/11/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A12	16/03/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A76	01/06/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A46	28/02/2015	Saw attachment gears are binding and grinding	Michele Williams noted: System checked and accumulators charged.	michele_williams
A60	06/01/2016	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A28	23/12/2015	Spindle fails to index, overfeeding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A62	03/08/2015	Accumulator inspection and charging required	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A47	17/09/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A14	13/08/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A54	01/04/2015	Milling spindle requires repair	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A24	31/08/2015	Machine is unpowered	Michele Williams noted: Repair completed.	michele_williams
A61	22/10/2015	Milling spindle requires repair	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A33	14/08/2015	Leaks found at turrets A and B	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A56	26/06/2015	Power supply failure detected	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A10	29/09/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A43	24/07/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A83	03/06/2015	Maintenance on milling spindle needed	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A40	02/06/2015	Leaks found at turrets A and B	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A65	08/03/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A21	02/09/2015	Hydraulic line leak on side B	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A3	30/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Repair completed.	cristian_santos
A27	27/06/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A90	11/10/2015	Unit lost electrical power	Cristian Santos noted: Repair completed.	cristian_santos
A23	20/08/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A7	04/02/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A16	23/03/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A39	06/01/2016	Accumulators need checking and charging	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams

A99	18/10/2015	Accumulators need checking and charging	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A80	15/05/2015	Leak in side B hydraulic line	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A37	25/03/2015	Turret A and B are leaking	Cristian Santos noted: No further details.	cristian_santos
A25	12/08/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A87	12/07/2015	Repair work needed on milling spindle	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A72	25/05/2015	Inspect and recharge accumulators	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A9	22/07/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A36	17/04/2015	Repair work needed on milling spindle	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A86	29/07/2015	Milling spindle requires repair	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A80	05/09/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A78	26/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A35	17/12/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A81	22/06/2015	Inspect and recharge accumulators	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A96	07/09/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A29	28/05/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Maintenance action successful.	michele_williams
A51	01/12/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A29	05/03/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A69	01/01/2016	Milling spindle requires repair	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A74	31/03/2015	Turret sections A & B showing leaks	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A92	09/08/2015	Accumulators need checking and charging	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A32	03/07/2015	Spindle indexing error with overfeed	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A22	18/01/2015	Inspect and recharge accumulators	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A74	17/11/2015	Turret A and B are leaking	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A58	04/06/2015	Hydraulic line leak on side B	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A37	06/07/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A27	22/04/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A78	30/06/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A55	07/02/2015	Accumulators need checking and charging	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A17	30/06/2015	Machine is unpowered	Cristian Santos noted: No further details.	cristian_santos
A63	17/01/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A56	07/07/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A4	11/02/2015	Leak in side B hydraulic line	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A67	15/11/2015	Milling spindle requires repair	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A89	31/08/2015	Turret sections A & B showing leaks	Michele Williams noted: Maintenance action successful.	michele_williams
A75	21/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A2	22/05/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A89	23/08/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A3	20/11/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A88	10/04/2015	Hydraulic line leak on side B	Michele Williams noted: Detail not recorded.	michele_williams
A34	26/12/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A73	06/12/2015	Unit lost electrical power	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A20	31/12/2015	Turret A and B are leaking	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A54	01/02/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A8	11/03/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A85	14/02/2015	Spindle indexing error with overfeed	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A93	11/12/2015	Hydraulic line leak on side B	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A85	08/10/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A4	02/05/2015	Milling spindle requires repair	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A85	17/08/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A60	03/11/2015	Turret sections A & B showing leaks	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A23	03/01/2016	Power supply failure detected	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A51	13/08/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A94	24/12/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A14	13/06/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A95	26/01/2015	Repair work needed on milling spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A4	02/01/2016	Hydraulic hose on side B is leaking	Cristian Santos noted: Detail not recorded.	cristian_santos
A82	18/02/2015	Power supply failure detected	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A69	30/11/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A21	07/02/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A93	27/11/2015	Machine is unpowered	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A6	24/12/2015	Leaks found at turrets A and B	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A35	23/11/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A55	01/02/2015	Power supply failure detected	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A86	02/04/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A84	05/09/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A53	16/11/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A78	06/02/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A67	05/04/2015	Accumulators need checking and charging	Michele Williams noted: No further details.	michele_williams
A64	03/11/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A74	25/05/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams

A57	15/09/2015	Machine is unpowered	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A4	22/06/2015	Turret A and B are leaking	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A60	29/04/2015	Hydraulic hose on side B is leaking	Michele Williams noted: No further details.	michele_williams
A63	15/04/2015	Power supply failure detected	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A52	20/09/2015	Spindle indexing error with overfeed	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A43	14/07/2015	Inspect and recharge accumulators	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A62	12/07/2015	Inspect and recharge accumulators	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A39	08/04/2015	Maintenance on milling spindle needed	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A43	21/09/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: No further details.	cristian_santos
A1	14/02/2015	Power supply failure detected	Michele Williams noted: Repair completed.	michele_williams
A38	07/07/2015	Maintenance on milling spindle needed	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A40	01/08/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A7	12/03/2015	Turret sections A & B showing leaks	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A32	28/04/2015	Power supply failure detected	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A50	26/02/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A99	01/01/2016	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A89	17/02/2015	Accumulator inspection and charging required	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A13	14/03/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A90	04/07/2015	Accumulator inspection and charging required	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A16	08/02/2015	Unit lost electrical power	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A2	15/06/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A98	01/06/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A57	20/11/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A35	11/08/2015	Hydraulic line leak on side B	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A3	06/06/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Detail not recorded.	cristian_santos
A27	06/04/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A42	04/12/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A76	05/10/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A11	04/10/2015	Maintenance on milling spindle needed	Michele Williams noted: No further details.	michele_williams
A94	15/06/2015	Turret sections A & B showing leaks	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A33	29/09/2015	Accumulator inspection and charging required	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A33	18/06/2015	Unit lost electrical power	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A3	11/08/2015	Leaks found at turrets A and B	Nathan Maldonado noted: No further details.	nathan_maldonado
A14	20/08/2015	Power supply failure detected	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A20	30/11/2015	Turret sections A & B showing leaks	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A44	13/07/2015	Leaks found at turrets A and B	Michele Williams noted: Maintenance action successful.	michele_williams
A65	22/06/2015	Spindle indexing error with overfeed	Cristian Santos noted: No additional information provided.	cristian_santos
A86	01/03/2015	Spindle indexing error with overfeed	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A18	22/12/2015	Repair work needed on milling spindle	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A35	05/11/2015	Unit lost electrical power	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A45	11/06/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A68	09/11/2015	Turret A and B are leaking	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A77	11/02/2015	Turret sections A & B showing leaks	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A15	06/04/2015	Turret A and B are leaking	Gina Moore noted: No further details.	gina_moore, dylan_miller
A2	25/09/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A71	20/07/2015	Milling spindle requires repair	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A67	17/07/2015	Turret A and B are leaking	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A70	16/09/2015	Accumulators need checking and charging	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A18	02/09/2015	Turret A and B are leaking	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A16	28/11/2015	Power supply failure detected	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A28	24/02/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A75	24/10/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A51	07/12/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A56	21/07/2015	Machine is unpowered	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A21	20/01/2015	Accumulators need checking and charging	Michele Williams noted: Detail not recorded.	michele_williams
A18	02/05/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A77	03/05/2015	Milling spindle requires repair	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A31	18/03/2015	Hydraulic line leak on side B	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A15	11/05/2015	Turret sections A & B showing leaks	Michele Williams noted: Detail not recorded.	michele_williams
A57	23/12/2015	Hydraulic line leak on side B	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A58	12/02/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A97	12/09/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A36	22/04/2015	Leaks found at turrets A and B	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A51	19/03/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Detail not recorded.	michele_williams
A36	13/05/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A86	15/06/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A14	12/07/2015	Accumulators need checking and charging	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A39	06/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A85	22/02/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A42	07/01/2016	Milling spindle requires repair	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams

A73	05/12/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A12	24/04/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A5	06/08/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A44	25/09/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A63	30/12/2015	Hydraulic line leak on side B	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A38	23/04/2015	Spindle fails to index, overfeeding	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A27	13/01/2016	Indexing issue causing overfeed on spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A57	11/12/2015	Spindle indexing error with overfeed	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A13	11/03/2015	Power supply failure detected	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A91	12/09/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A63	28/06/2015	Maintenance on milling spindle needed	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A23	14/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A45	19/01/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A76	18/02/2015	Repair work needed on milling spindle	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A8	18/04/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A96	05/11/2015	Repair work needed on milling spindle	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A32	17/04/2015	Accumulators need checking and charging	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A83	03/01/2016	Saw attachment gears are binding and grinding	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A36	16/09/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A99	02/05/2015	Unit lost electrical power	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A82	12/11/2015	Turret sections A & B showing leaks	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A97	12/06/2015	Accumulator inspection and charging required	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A65	23/09/2015	Power supply failure detected	Nathan Maldonado noted: No further details.	nathan_maldonado
A60	09/07/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A76	21/04/2015	Accumulators need checking and charging	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A62	28/07/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A75	22/06/2015	Turret sections A & B showing leaks	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A85	11/12/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A71	29/03/2015	Accumulator inspection and charging required	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A87	18/07/2015	Accumulators need checking and charging	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A44	13/10/2015	Turret sections A & B showing leaks	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A84	18/11/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A3	30/01/2015	Turret sections A & B showing leaks	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A85	09/07/2015	Accumulators need checking and charging	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A24	22/07/2015	Leaks found at turrets A and B	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A82	26/05/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A76	28/11/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A5	09/07/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A65	30/06/2015	Accumulators need checking and charging	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A55	25/06/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A60	20/10/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A87	22/01/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: No further details.	gina_moore, dylan_miller
A42	18/06/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A96	21/12/2015	Unit lost electrical power	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A34	19/08/2015	Turret sections A & B showing leaks	Michele Williams noted: No additional information provided.	michele_williams
A45	11/08/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A23	18/02/2015	Accumulators need checking and charging	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A24	25/05/2015	Accumulators need checking and charging	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A28	18/04/2015	Machine is unpowered	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A92	05/07/2015	Accumulator inspection and charging required	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A23	28/01/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A38	03/08/2015	Unit lost electrical power	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A38	20/01/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A22	04/11/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A25	13/03/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A69	09/07/2015	Maintenance on milling spindle needed	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A43	29/07/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A19	27/05/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A33	12/05/2015	Maintenance on milling spindle needed	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A39	18/12/2015	Power supply failure detected	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A89	25/01/2015	Turret A and B are leaking	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A35	20/03/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A86	08/11/2015	Accumulators need checking and charging	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A71	11/04/2015	Machine is unpowered	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A85	29/07/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A31	08/02/2015	Milling spindle requires repair	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A1	15/11/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A21	02/03/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A17	15/01/2015	Maintenance on milling spindle needed	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A12	21/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado

A21	21/02/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A12	13/05/2015	Leaks found at turrets A and B	Cristian Santos noted: Repair completed.	cristian_santos
A89	06/05/2015	Unit lost electrical power	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A41	26/02/2015	Leaks found at turrets A and B	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A66	11/05/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A84	26/03/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A97	28/12/2015	Unit lost electrical power	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A65	17/10/2015	Turret A and B are leaking	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A84	16/03/2015	Maintenance on milling spindle needed	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A33	02/06/2015	Spindle fails to index, overfeeding	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A9	21/07/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A32	20/11/2015	Hydraulic line leak on side B	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A25	04/02/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A16	31/12/2015	Maintenance on milling spindle needed	Michele Williams noted: Fixed and tested.	michele_williams
A60	13/11/2015	Machine is unpowered	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A85	31/07/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A94	02/08/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A62	06/07/2015	Inspect and recharge accumulators	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A52	27/10/2015	Unit lost electrical power	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A70	04/08/2015	Leak in side B hydraulic line	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A66	07/07/2015	Milling spindle requires repair	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A93	28/06/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A64	02/07/2015	Accumulators need checking and charging	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A57	18/05/2015	Repair work needed on milling spindle	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A64	11/01/2016	Spindle fails to index, overfeeding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A72	07/12/2015	Turret sections A & B showing leaks	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A30	21/01/2015	Power supply failure detected	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A38	31/07/2015	Machine is unpowered	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A48	05/11/2015	Inspect and recharge accumulators	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A78	24/05/2015	Turret sections A & B showing leaks	Cristian Santos noted: Fixed and tested.	cristian_santos
A70	19/12/2015	Accumulators need checking and charging	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A45	10/07/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A97	04/02/2015	Unit lost electrical power	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A85	06/08/2015	Accumulators need checking and charging	Cristian Santos noted: Maintenance action successful.	cristian_santos
A67	15/12/2015	Inspect and recharge accumulators	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A75	22/12/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A73	28/09/2015	Machine is unpowered	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A94	26/01/2015	Repair work needed on milling spindle	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A31	25/06/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A60	12/08/2015	Hydraulic line leak on side B	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A37	18/10/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A20	07/03/2015	Unit lost electrical power	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A67	13/07/2015	Turret sections A & B showing leaks	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A70	28/05/2015	Inspect and recharge accumulators	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A26	27/01/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A28	24/04/2015	Maintenance on milling spindle needed	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A47	09/12/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A30	02/03/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A4	20/08/2015	Inspect and recharge accumulators	Nathan Maldonado noted: No further details.	nathan_maldonado
A21	24/01/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A78	28/06/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: No further details.	cristian_santos
A59	04/10/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A72	10/12/2015	Spindle indexing error with overfeed	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A5	18/04/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A71	27/06/2015	Saw attachment is leaking hydraulics	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A67	03/05/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A84	06/01/2016	Hydraulic line leak on side B	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A28	18/02/2015	Spindle fails to index, overfeeding	Michele Williams noted: No additional information provided.	michele_williams
A86	21/10/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A3	22/06/2015	Turret sections A & B showing leaks	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A56	22/12/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A31	28/04/2015	Accumulator inspection and charging required	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A39	27/06/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A76	09/08/2015	Hydraulic line leak on side B	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A51	24/02/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A38	11/06/2015	Inspect and recharge accumulators	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A40	04/11/2015	Machine is unpowered	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A76	24/04/2015	Repair work needed on milling spindle	Michele Williams noted: System checked and accumulators charged.	michele_williams
A13	27/01/2015	Hydraulic line leak on side B	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A79	07/12/2015	Turret sections A & B showing leaks	Michele Williams noted: System checked and accumulators charged.	michele_williams

A94	10/07/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A15	21/08/2015	Turret sections A & B showing leaks	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A73	07/08/2015	Power supply failure detected	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A33	06/02/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: No further details.	nathan_maldonado
A37	26/03/2015	Inspect and recharge accumulators	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A30	16/03/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A33	31/07/2015	Turret A and B are leaking	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A47	23/04/2015	Repair work needed on milling spindle	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A24	21/10/2015	Spindle indexing error with overfeed	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A30	14/03/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A44	20/03/2015	Leak in side B hydraulic line	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A87	13/01/2016	Saw attachment gears are binding and grinding	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A97	04/06/2015	Maintenance on milling spindle needed	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A97	02/08/2015	Hydraulic line leak on side B	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A73	10/11/2015	Machine is unpowered	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A44	20/08/2015	Repair work needed on milling spindle	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A28	13/02/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A41	27/09/2015	Spindle indexing error with overfeed	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A49	12/07/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A1	07/11/2015	Turret sections A & B showing leaks	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A58	14/04/2015	Power supply failure detected	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A59	19/07/2015	Turret A and B are leaking	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A57	31/10/2015	Maintenance on milling spindle needed	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A64	14/11/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A61	22/12/2015	Power supply failure detected	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A20	04/04/2015	Power supply failure detected	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A72	08/04/2015	Hydraulic line leak on side B	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A60	01/04/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A50	15/10/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A68	28/05/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Repair completed.	cristian_santos
A38	07/05/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A60	07/08/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A54	08/06/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A13	12/06/2015	Machine is unpowered	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A67	14/04/2015	Turret A and B are leaking	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A71	25/04/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A14	10/01/2016	Turret sections A & B showing leaks	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A60	13/08/2015	Leak in side B hydraulic line	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A17	16/01/2015	Turret sections A & B showing leaks	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A97	26/07/2015	Turret sections A & B showing leaks	Michele Williams noted: No additional information provided.	michele_williams
A60	11/01/2016	Leaks found at turrets A and B	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A31	01/04/2015	Machine is unpowered	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A10	12/08/2015	Accumulators need checking and charging	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A81	14/11/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A51	14/08/2015	Turret sections A & B showing leaks	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A76	14/06/2015	Leak in side B hydraulic line	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A52	07/04/2015	Spindle indexing error with overfeed	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A55	14/09/2015	Milling spindle requires repair	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A41	30/03/2015	Milling spindle requires repair	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A57	05/10/2015	Power supply failure detected	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A31	09/10/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: No further details.	gina_moore, dylan_miller
A4	23/07/2015	Power supply failure detected	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A86	11/06/2015	Accumulators need checking and charging	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A23	25/06/2015	Hydraulic line leak on side B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A58	04/03/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A30	26/10/2015	Leak in side B hydraulic line	Gina Moore noted: No further details.	gina_moore, dylan_miller
A97	11/03/2015	Milling spindle requires repair	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A52	16/10/2015	Inspect and recharge accumulators	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A96	22/03/2015	Spindle fails to index, overfeeding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A76	01/01/2016	Turret sections A & B showing leaks	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A67	02/04/2015	Leak in side B hydraulic line	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A75	11/12/2015	Spindle indexing error with overfeed	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A96	17/04/2015	Turret sections A & B showing leaks	Michele Williams noted: No additional information provided.	michele_williams
A76	10/08/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A20	01/05/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A42	12/09/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A10	15/08/2015	Power supply failure detected	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A1	22/03/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A34	16/10/2015	Leak in side B hydraulic line	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A13	22/03/2015	Leak in side B hydraulic line	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams

A93	19/03/2015	Spindle indexing error with overfeed	Cristian Santos noted: Fixed and tested.	cristian_santos
A53	31/05/2015	Spindle indexing error with overfeed	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A52	07/03/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A44	21/01/2015	Accumulators need checking and charging	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A45	06/12/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A18	08/12/2015	Milling spindle requires repair	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A65	13/01/2016	Leaks found at turrets A and B	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A55	12/01/2016	Hydraulic hose on side B is leaking	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A27	25/07/2015	Accumulators need checking and charging	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A61	18/12/2015	Accumulators need checking and charging	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A7	16/10/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A60	10/09/2015	Inspect and recharge accumulators	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A5	22/08/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A48	25/05/2015	Maintenance on milling spindle needed	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A3	28/04/2015	Hydraulic line leak on side B	Cristian Santos noted: Maintenance action successful.	cristian_santos
A46	15/09/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A97	04/01/2016	Turret A and B are leaking	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A75	28/05/2015	Leaks found at turrets A and B	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A79	08/11/2015	Accumulators need checking and charging	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A88	27/10/2015	Unit lost electrical power	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A70	28/03/2015	Maintenance on milling spindle needed	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A85	24/05/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A65	18/03/2015	Power supply failure detected	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A80	03/07/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A11	11/05/2015	Turret A and B are leaking	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A53	04/12/2015	Machine is unpowered	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A83	31/07/2015	Repair work needed on milling spindle	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A37	18/08/2015	Spindle indexing error with overfeed	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A20	06/06/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A31	31/01/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A20	22/09/2015	Turret A and B are leaking	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A78	11/11/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A19	22/04/2015	Spindle indexing error with overfeed	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A29	09/06/2015	Hydraulic line leak on side B	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A5	22/11/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A71	01/07/2015	Leak in side B hydraulic line	Cristian Santos noted: No additional information provided.	cristian_santos
A2	12/05/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A19	02/06/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A20	16/03/2015	Unit lost electrical power	Cristian Santos noted: No further details.	cristian_santos
A6	21/11/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A76	29/12/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A93	28/07/2015	Spindle indexing error with overfeed	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A2	23/05/2015	Unit lost electrical power	Cristian Santos noted: Detail not recorded.	cristian_santos
A69	24/01/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A20	20/04/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A52	04/03/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A24	03/07/2015	Power supply failure detected	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A74	20/10/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A42	25/09/2015	Hydraulic line leak on side B	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A34	01/09/2015	Repair work needed on milling spindle	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A37	06/07/2015	Maintenance on milling spindle needed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A42	16/04/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A80	12/04/2015	Milling spindle requires repair	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A7	23/04/2015	Inspect and recharge accumulators	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A60	04/03/2015	Milling spindle requires repair	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A5	06/11/2015	Hydraulic line leak on side B	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A46	01/10/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A93	26/11/2015	Turret sections A & B showing leaks	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A52	18/07/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A86	12/06/2015	Unit lost electrical power	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A42	17/02/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A4	19/07/2015	Hydraulic line leak on side B	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A10	25/05/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A47	08/05/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A53	07/05/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: No additional information provided.	cristian_santos
A9	24/06/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A48	03/08/2015	Machine is unpowered	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A1	16/04/2015	Inspect and recharge accumulators	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A1	10/05/2015	Turret sections A & B showing leaks	Michele Williams noted: Repair completed.	michele_williams
A39	09/10/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Fixed and tested.	cristian_santos

A77	14/10/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A40	20/08/2015	Maintenance on milling spindle needed	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A9	28/12/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A72	20/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A68	25/04/2015	Maintenance on milling spindle needed	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A1	19/09/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A16	29/03/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A12	26/08/2015	Turret A and B are leaking	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A99	17/09/2015	Hydraulic line leak on side B	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A9	12/09/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A11	02/06/2015	Unit lost electrical power	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A51	26/04/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A14	10/11/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A45	05/04/2015	Hydraulic line leak on side B	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A16	28/01/2015	Spindle indexing error with overfeed	Gina Moore noted: No further details.	gina_moore, dylan_miller
A85	09/08/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A5	29/07/2015	Unit lost electrical power	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A79	12/09/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A4	04/03/2015	Spindle fails to index, overfeeding	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A95	19/08/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A28	09/08/2015	Milling spindle requires repair	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A30	20/10/2015	Accumulators need checking and charging	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A11	29/12/2015	Maintenance on milling spindle needed	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A48	24/01/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A54	13/11/2015	Leaks found at turrets A and B	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A34	07/02/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A72	24/01/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A17	30/08/2015	Leaks found at turrets A and B	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A73	25/09/2015	Unit lost electrical power	Cristian Santos noted: Repair completed.	cristian_santos
A29	26/10/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A24	17/03/2015	Hydraulic line leak on side B	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A26	04/12/2015	Accumulator inspection and charging required	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A69	10/12/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A75	10/07/2015	Turret A and B are leaking	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A70	11/01/2016	Accumulators need checking and charging	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A75	19/03/2015	Machine is unpowered	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A72	19/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A95	06/01/2016	Spindle indexing error with overfeed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A89	02/01/2016	Turret A and B are leaking	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A41	24/08/2015	Accumulator inspection and charging required	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A93	28/10/2015	Machine is unpowered	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A26	23/05/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A61	08/11/2015	Spindle fails to index, overfeeding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A53	15/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A8	18/10/2015	Turret sections A & B showing leaks	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A9	15/03/2015	Spindle indexing error with overfeed	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A52	09/03/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: No further details.	cristian_santos
A36	10/08/2015	Unit lost electrical power	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A60	23/08/2015	Leaks found at turrets A and B	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A59	17/03/2015	Unit lost electrical power	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A24	08/11/2015	Spindle fails to index, overfeeding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A67	19/05/2015	Unit lost electrical power	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A61	26/11/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A74	02/01/2016	Accumulator inspection and charging required	Nathan Maldonado noted: No further details.	nathan_maldonado
A98	19/12/2015	Power supply failure detected	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A59	21/02/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A11	11/01/2016	Milling spindle requires repair	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A98	29/07/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A53	07/02/2015	Milling spindle requires repair	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A57	21/08/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A9	03/07/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A81	22/09/2015	Spindle fails to index, overfeeding	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A38	27/01/2015	Power supply failure detected	Cristian Santos noted: No further details.	cristian_santos
A60	17/08/2015	Accumulators need checking and charging	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A49	15/10/2015	Hydraulic hose on side B is leaking	Michele Williams noted: No further details.	michele_williams
A32	12/12/2015	Milling spindle requires repair	Michele Williams noted: Detail not recorded.	michele_williams
A89	29/11/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A81	15/11/2015	Power supply failure detected	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A34	29/03/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A12	06/12/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller

A54	12/03/2015	Unit lost electrical power	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A12	05/10/2015	Accumulators need checking and charging	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A57	13/09/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A64	10/10/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A13	12/08/2015	Milling spindle requires repair	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A82	16/06/2015	Inspect and recharge accumulators	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A1	29/07/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A16	18/11/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A15	20/12/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A78	23/03/2015	Turret sections A & B showing leaks	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A29	20/02/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A10	12/10/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A88	29/12/2015	Power supply failure detected	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A99	17/06/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A71	22/05/2015	Turret sections A & B showing leaks	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A97	26/06/2015	Turret sections A & B showing leaks	Cristian Santos noted: Maintenance action successful.	cristian_santos
A56	21/08/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A14	30/10/2015	Spindle indexing error with overfeed	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A70	11/11/2015	Accumulator inspection and charging required	Michele Williams noted: Maintenance action successful.	michele_williams
A20	09/02/2015	Repair work needed on milling spindle	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A86	27/02/2015	Power supply failure detected	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A62	18/05/2015	Spindle fails to index, overfeeding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A74	02/01/2016	Maintenance on milling spindle needed	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A22	13/01/2016	Repair work needed on milling spindle	Cristian Santos noted: Fixed and tested.	cristian_santos
A44	26/10/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A81	17/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A24	14/02/2015	Maintenance on milling spindle needed	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A7	24/07/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A25	04/12/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A1	15/10/2015	Repair work needed on milling spindle	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A81	30/12/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A20	02/02/2015	Inspect and recharge accumulators	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A34	24/09/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A10	28/02/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A89	22/05/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A26	13/05/2015	Hydraulic line leak on side B	Michele Williams noted: Detail not recorded.	michele_williams
A81	01/10/2015	Accumulator inspection and charging required	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A30	31/08/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A25	23/09/2015	Leak in side B hydraulic line	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A21	06/03/2015	Turret A and B are leaking	Michele Williams noted: Fixed and tested.	michele_williams
A31	05/03/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A24	22/04/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A99	10/12/2015	Inspect and recharge accumulators	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A54	18/05/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A58	24/04/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A17	25/03/2015	Turret sections A & B showing leaks	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A15	05/04/2015	Spindle fails to index, overfeeding	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A96	01/10/2015	Power supply failure detected	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A48	08/07/2015	Hydraulic line leak on side B	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A56	10/09/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A28	03/03/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A61	30/01/2015	Repair work needed on milling spindle	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A77	22/06/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A73	31/12/2015	Machine is unpowered	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A62	03/12/2015	Spindle fails to index, overfeeding	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A75	15/01/2015	Leaks found at turrets A and B	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A95	24/09/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A92	08/08/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A30	12/06/2015	Leaks found at turrets A and B	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A63	08/03/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A13	22/01/2015	Machine is unpowered	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A87	06/06/2015	Milling spindle requires repair	Michele Williams noted: No additional information provided.	michele_williams
A77	10/03/2015	Turret A and B are leaking	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A86	29/11/2015	Maintenance on milling spindle needed	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A33	29/07/2015	Leaks found at turrets A and B	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A23	04/03/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A11	16/10/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A13	18/07/2015	Machine is unpowered	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A67	25/08/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A4	22/10/2015	Hydraulic line leak on side B	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams

A72	22/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A44	17/11/2015	Unit lost electrical power	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A47	11/09/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A19	05/01/2016	Spindle fails to index, overfeeding	Michele Williams noted: Maintenance action successful.	michele_williams
A90	23/05/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A89	03/02/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A80	10/07/2015	Leak in side B hydraulic line	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A65	14/12/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A59	08/03/2015	Power supply failure detected	Cristian Santos noted: No additional information provided.	cristian_santos
A4	28/10/2015	Milling spindle requires repair	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A18	12/05/2015	Inspect and recharge accumulators	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A13	25/12/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A90	29/08/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A58	09/06/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A35	30/07/2015	Turret A and B are leaking	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A88	15/04/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A59	04/07/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A97	11/04/2015	Turret A and B are leaking	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A76	18/08/2015	Machine is unpowered	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A76	29/05/2015	Inspect and recharge accumulators	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A3	05/12/2015	Accumulators need checking and charging	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A1	23/11/2015	Accumulator inspection and charging required	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A56	06/03/2015	Turret sections A & B showing leaks	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A35	14/03/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A37	17/12/2015	Accumulators need checking and charging	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A59	24/01/2015	Power supply failure detected	Michele Williams noted: Detail not recorded.	michele_williams
A98	16/06/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A42	19/09/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A45	19/10/2015	Turret A and B are leaking	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A2	05/03/2015	Inspect and recharge accumulators	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A4	11/03/2015	Machine is unpowered	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A77	17/11/2015	Repair work needed on milling spindle	Michele Williams noted: No additional information provided.	michele_williams
A26	19/03/2015	Accumulator inspection and charging required	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A46	14/12/2015	Accumulator inspection and charging required	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A89	06/08/2015	Leaks found at turrets A and B	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A93	03/11/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A22	16/05/2015	Repair work needed on milling spindle	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A84	30/08/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A7	02/08/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A84	30/12/2015	Turret A and B are leaking	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A31	21/06/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A7	07/12/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A51	27/03/2015	Spindle fails to index, overfeeding	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A88	26/04/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Detail not recorded.	cristian_santos
A80	22/07/2015	Accumulator inspection and charging required	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A81	19/04/2015	Power supply failure detected	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A81	10/09/2015	Milling spindle requires repair	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A86	08/11/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A4	30/06/2015	Machine is unpowered	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A24	03/10/2015	Turret sections A & B showing leaks	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A67	27/10/2015	Repair work needed on milling spindle	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A38	18/12/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A55	04/12/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A50	23/09/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Detail not recorded.	cristian_santos
A88	11/06/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A70	25/07/2015	Unit lost electrical power	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A33	01/12/2015	Maintenance on milling spindle needed	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A34	25/07/2015	Saw attachment gears are binding and grinding	Michele Williams noted: System checked and accumulators charged.	michele_williams
A7	06/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: No further details.	michele_williams
A62	03/06/2015	Power supply failure detected	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A63	07/08/2015	Unit lost electrical power	Cristian Santos noted: No additional information provided.	cristian_santos
A16	20/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A15	11/03/2015	Unit lost electrical power	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A6	13/07/2015	Spindle indexing error with overfeed	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A30	19/06/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A98	25/06/2015	Leak in side B hydraulic line	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A81	14/06/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A29	18/04/2015	Maintenance on milling spindle needed	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A8	02/08/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A39	20/07/2015	Turret sections A & B showing leaks	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller

A32	11/02/2015	Repair work needed on milling spindle	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A92	21/12/2015	Repair work needed on milling spindle	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A67	27/05/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A74	30/09/2015	Power supply failure detected	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A60	23/05/2015	Accumulator inspection and charging required	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A91	04/04/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A25	31/05/2015	Turret A and B are leaking	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A10	25/05/2015	Repair work needed on milling spindle	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A52	07/09/2015	Unit lost electrical power	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A61	11/11/2015	Turret A and B are leaking	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A15	24/03/2015	Inspect and recharge accumulators	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A74	06/03/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A70	21/12/2015	Accumulator inspection and charging required	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A54	15/01/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A63	14/04/2015	Accumulator inspection and charging required	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A16	31/10/2015	Turret A and B are leaking	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A5	28/07/2015	Power supply failure detected	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A14	01/02/2015	Leaks found at turrets A and B	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A76	28/01/2015	Turret A and B are leaking	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A40	24/07/2015	Leak in side B hydraulic line	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A8	07/07/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Fixed and tested.	michele_williams
A27	03/12/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A35	03/03/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A13	15/01/2015	Unit lost electrical power	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A69	06/09/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A37	05/02/2015	Accumulator inspection and charging required	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A83	25/08/2015	Accumulator inspection and charging required	Michele Williams noted: System checked and accumulators charged.	michele_williams
A64	22/02/2015	Inspect and recharge accumulators	Cristian Santos noted: No additional information provided.	cristian_santos
A90	29/05/2015	Unit lost electrical power	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A81	25/01/2015	Accumulators need checking and charging	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A39	21/07/2015	Turret A and B are leaking	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A27	20/01/2015	Inspect and recharge accumulators	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A99	30/10/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A43	12/10/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A8	10/03/2015	Leak in side B hydraulic line	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A24	18/11/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A72	18/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A84	27/09/2015	Accumulators need checking and charging	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A90	16/03/2015	Accumulator inspection and charging required	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A72	25/07/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A54	17/01/2015	Power supply failure detected	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A39	12/07/2015	Leaks found at turrets A and B	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A12	07/04/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A29	27/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A74	05/04/2015	Milling spindle requires repair	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A36	04/10/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A81	30/05/2015	Turret A and B are leaking	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A4	02/08/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A22	29/05/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A64	18/06/2015	Accumulators need checking and charging	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A93	19/03/2015	Leak in side B hydraulic line	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A20	26/07/2015	Repair work needed on milling spindle	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A49	28/07/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Fixed and tested.	cristian_santos
A95	19/02/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A41	07/07/2015	Spindle indexing error with overfeed	Gina Moore noted: No further details.	gina_moore, dylan_miller
A20	07/07/2015	Repair work needed on milling spindle	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A19	28/07/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A9	06/10/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A29	10/10/2015	Repair work needed on milling spindle	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A84	26/01/2015	Unit lost electrical power	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A33	25/08/2015	Power supply failure detected	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A74	07/01/2016	Leak in side B hydraulic line	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A26	25/01/2015	Accumulators need checking and charging	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A93	22/04/2015	Hydraulic line leak on side B	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A62	13/12/2015	Turret sections A & B showing leaks	Cristian Santos noted: Fixed and tested.	cristian_santos
A78	17/04/2015	Machine is unpowered	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A10	21/01/2015	Leak in side B hydraulic line	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A85	23/05/2015	Leaks found at turrets A and B	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A50	06/09/2015	Leaks found at turrets A and B	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A81	10/10/2015	Accumulator inspection and charging required	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams

A18	01/04/2015	Hydraulic hose on side B is leaking	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A70	16/05/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A64	10/09/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A37	19/03/2015	Accumulator inspection and charging required	Michele Williams noted: Maintenance action successful.	michele_williams
A87	01/08/2015	Turret sections A & B showing leaks	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A17	07/04/2015	Repair work needed on milling spindle	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A32	08/03/2015	Leak in side B hydraulic line	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A12	17/11/2015	Milling spindle requires repair	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A71	25/06/2015	Spindle indexing error with overfeed	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A12	19/02/2015	Machine is unpowered	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A73	16/01/2015	Spindle indexing error with overfeed	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A44	02/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A10	03/01/2016	Hydraulic hose on side B is leaking	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A77	20/12/2015	Unit lost electrical power	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A27	02/12/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: No further details.	cristian_santos
A32	05/12/2015	Turret sections A & B showing leaks	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A67	16/02/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A61	28/02/2015	Turret A and B are leaking	Cristian Santos noted: Maintenance action successful.	cristian_santos
A15	07/05/2015	Unit lost electrical power	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A54	13/08/2015	Turret sections A & B showing leaks	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A88	31/05/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Repair completed.	cristian_santos
A14	24/09/2015	Spindle indexing error with overfeed	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A25	10/03/2015	Turret A and B are leaking	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A15	24/10/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Repair completed.	cristian_santos
A21	18/03/2015	Inspect and recharge accumulators	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A47	19/08/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A32	17/01/2015	Unit lost electrical power	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A68	08/06/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A49	28/12/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A55	28/08/2015	Turret sections A & B showing leaks	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A12	26/11/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A29	22/09/2015	Spindle indexing error with overfeed	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A62	23/06/2015	Maintenance on milling spindle needed	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A8	12/03/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A71	11/06/2015	Accumulator inspection and charging required	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A42	14/11/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Fixed and tested.	michele_williams
A12	23/03/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A62	18/05/2015	Accumulators need checking and charging	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A43	31/10/2015	Hydraulic line leak on side B	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A13	05/05/2015	Milling spindle requires repair	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A98	22/11/2015	Repair work needed on milling spindle	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A10	06/08/2015	Inspect and recharge accumulators	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A66	07/10/2015	Turret sections A & B showing leaks	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A57	04/03/2015	Turret A and B are leaking	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A61	11/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A73	05/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A59	09/08/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A48	23/09/2015	Maintenance on milling spindle needed	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A85	21/07/2015	Power supply failure detected	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A33	17/04/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A59	10/12/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A53	19/05/2015	Repair work needed on milling spindle	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A73	11/12/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A59	24/12/2015	Unit lost electrical power	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A69	26/05/2015	Accumulator inspection and charging required	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A13	13/12/2015	Milling spindle requires repair	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A73	30/08/2015	Inspect and recharge accumulators	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A88	10/04/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A84	09/11/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A39	05/09/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A68	28/12/2015	Repair work needed on milling spindle	Michele Williams noted: System checked and accumulators charged.	michele_williams
A72	26/04/2015	Accumulator inspection and charging required	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A40	28/05/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A39	01/03/2015	Unit lost electrical power	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A53	14/11/2015	Leak in side B hydraulic line	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A60	02/03/2015	Accumulators need checking and charging	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A54	28/01/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A16	16/10/2015	Repair work needed on milling spindle	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A33	10/03/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A20	29/07/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado

A85	08/04/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A73	19/04/2015	Hydraulic hose on side B is leaking	Michele Williams noted: No additional information provided.	michele_williams
A26	11/04/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A17	08/10/2015	Maintenance on milling spindle needed	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A80	17/07/2015	Accumulators need checking and charging	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A96	14/05/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A24	03/12/2015	Spindle fails to index, overfeeding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A38	05/12/2015	Turret A and B are leaking	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A42	16/09/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A77	14/04/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A27	06/07/2015	Power supply failure detected	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A33	28/09/2015	Power supply failure detected	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A11	01/11/2015	Machine is unpowered	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A59	17/04/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A44	19/01/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A21	29/04/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A79	14/02/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A39	08/07/2015	Leak in side B hydraulic line	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A19	23/06/2015	Accumulators need checking and charging	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A64	26/08/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A52	26/02/2015	Turret A and B are leaking	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A79	27/10/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A95	28/04/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A62	13/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A18	29/07/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A25	20/12/2015	Machine is unpowered	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A77	01/09/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A46	17/08/2015	Leaks found at turrets A and B	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A33	01/04/2015	Milling spindle requires repair	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A92	12/07/2015	Power supply failure detected	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A82	29/07/2015	Turret A and B are leaking	Michele Williams noted: Detail not recorded.	michele_williams
A61	30/05/2015	Accumulator inspection and charging required	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A66	11/05/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A37	05/10/2015	Maintenance on milling spindle needed	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A65	29/12/2015	Spindle fails to index, overfeeding	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A28	31/10/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A92	30/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Repair completed.	michele_williams
A93	04/11/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A85	28/04/2015	Repair work needed on milling spindle	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A37	04/11/2015	Leak in side B hydraulic line	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A62	12/06/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A38	24/08/2015	Spindle indexing error with overfeed	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A89	13/10/2015	Turret A and B are leaking	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A25	15/07/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A93	26/02/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A84	09/08/2015	Turret sections A & B showing leaks	Gina Moore noted: No further details.	gina_moore, dylan_miller
A9	14/04/2015	Inspect and recharge accumulators	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A18	07/04/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A93	16/08/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A81	03/01/2016	Accumulators need checking and charging	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A11	10/06/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A70	22/03/2015	Leaks found at turrets A and B	Michele Williams noted: Maintenance action successful.	michele_williams
A8	06/07/2015	Turret sections A & B showing leaks	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A14	20/02/2015	Unit lost electrical power	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A64	11/07/2015	Machine is unpowered	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A4	16/08/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A46	01/06/2015	Repair work needed on milling spindle	Nathan Maldonado noted: No further details.	nathan_maldonado
A30	16/05/2015	Milling spindle requires repair	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A7	09/08/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A9	26/09/2015	Maintenance on milling spindle needed	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A9	11/02/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A24	28/01/2015	Leaks found at turrets A and B	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A14	01/03/2015	Unit lost electrical power	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A2	18/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Detail not recorded.	cristian_santos
A27	08/02/2015	Machine is unpowered	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A22	27/01/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A29	02/01/2016	Indexing issue causing overfeed on spindle	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A79	05/09/2015	Spindle fails to index, overfeeding	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A79	29/07/2015	Leaks found at turrets A and B	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A5	01/07/2015	Leaks found at turrets A and B	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos

A84	23/12/2015	Unit lost electrical power	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A23	28/03/2015	Inspect and recharge accumulators	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A33	04/10/2015	Spindle fails to index, overfeeding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A67	31/12/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A82	31/03/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A50	05/07/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A83	10/11/2015	Turret A and B are leaking	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A25	12/03/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A55	10/11/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A80	11/09/2015	Unit lost electrical power	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A10	08/09/2015	Spindle indexing error with overfeed	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A54	07/04/2015	Turret A and B are leaking	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A43	30/01/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A12	15/11/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A98	25/08/2015	Accumulators need checking and charging	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A37	08/06/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A37	06/04/2015	Turret sections A & B showing leaks	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A50	05/07/2015	Machine is unpowered	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A10	18/09/2015	Hydraulic line leak on side B	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A43	01/12/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Maintenance action successful.	michele_williams
A1	08/06/2015	Accumulator inspection and charging required	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A59	07/05/2015	Maintenance on milling spindle needed	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A42	26/05/2015	Leak in side B hydraulic line	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A8	15/08/2015	Accumulator inspection and charging required	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A68	13/11/2015	Maintenance on milling spindle needed	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A97	18/04/2015	Accumulator inspection and charging required	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A34	26/03/2015	Accumulators need checking and charging	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A54	02/08/2015	Inspect and recharge accumulators	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A2	10/02/2015	Turret sections A & B showing leaks	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A46	14/08/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A99	29/11/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A96	29/08/2015	Hydraulic line leak on side B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A49	21/07/2015	Inspect and recharge accumulators	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A37	12/02/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A62	16/08/2015	Hydraulic line leak on side B	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A98	16/06/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A24	23/03/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A56	28/01/2015	Accumulator inspection and charging required	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A25	03/11/2015	Unit lost electrical power	Nathan Maldonado noted: No further details.	nathan_maldonado
A79	07/03/2015	Hydraulic line leak on side B	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A13	28/12/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A25	27/02/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A92	28/01/2015	Leak in side B hydraulic line	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A32	26/02/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A78	15/04/2015	Inspect and recharge accumulators	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A73	31/07/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A88	16/05/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A67	01/03/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A22	08/07/2015	Accumulator inspection and charging required	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A3	08/10/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A57	26/01/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A90	22/04/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A21	10/07/2015	Maintenance on milling spindle needed	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A12	25/11/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A74	21/05/2015	Spindle indexing error with overfeed	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A40	16/07/2015	Unit lost electrical power	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A84	27/02/2015	Power supply failure detected	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A78	21/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A97	24/06/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A13	02/12/2015	Accumulator inspection and charging required	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A31	18/05/2015	Machine is unpowered	Cristian Santos noted: Repair completed.	cristian_santos
A74	30/07/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A51	14/02/2015	Power supply failure detected	Cristian Santos noted: Maintenance action successful.	cristian_santos
A6	23/05/2015	Power supply failure detected	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A16	05/11/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A26	03/09/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A78	15/08/2015	Power supply failure detected	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A86	03/08/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A24	12/01/2016	Turret sections A & B showing leaks	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A9	24/12/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams

A13	30/12/2015	Unit lost electrical power	Michele Williams noted: System checked and accumulators charged.	michele_williams
A84	30/06/2015	Accumulator inspection and charging required	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A72	10/03/2015	Power supply failure detected	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A37	29/05/2015	Spindle fails to index, overfeeding	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A6	17/12/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A8	07/09/2015	Power supply failure detected	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A67	08/10/2015	Hydraulic line leak on side B	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A97	10/04/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A22	15/03/2015	Accumulators need checking and charging	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A87	01/09/2015	Machine is unpowered	Michele Williams noted: Fixed and tested.	michele_williams
A93	11/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A44	27/12/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A55	10/08/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A7	18/11/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A4	30/06/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A35	15/02/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A43	12/02/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A10	02/06/2015	Unit lost electrical power	Michele Williams noted: Detail not recorded.	michele_williams
A42	19/06/2015	Unit lost electrical power	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A71	13/06/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A15	29/05/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A29	20/03/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A55	06/09/2015	Unit lost electrical power	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A86	29/04/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A95	29/08/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A22	15/06/2015	Milling spindle requires repair	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A58	27/03/2015	Accumulator inspection and charging required	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A77	06/10/2015	Hydraulic line leak on side B	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A84	03/07/2015	Unit lost electrical power	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A86	17/08/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A87	19/08/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A92	31/05/2015	Accumulator inspection and charging required	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A24	03/05/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Detail not recorded.	cristian_santos
A96	19/11/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A88	25/05/2015	Turret A and B are leaking	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A41	02/10/2015	Maintenance on milling spindle needed	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A6	27/05/2015	Leaks found at turrets A and B	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A65	18/03/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A53	02/09/2015	Spindle fails to index, overfeeding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A61	27/01/2015	Power supply failure detected	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A61	08/06/2015	Machine is unpowered	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A44	03/12/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A96	29/06/2015	Unit lost electrical power	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A33	29/12/2015	Inspect and recharge accumulators	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A34	01/08/2015	Milling spindle requires repair	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A26	10/12/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A73	11/04/2015	Machine is unpowered	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A33	22/03/2015	Turret A and B are leaking	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A65	05/08/2015	Leaks found at turrets A and B	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A39	15/10/2015	Turret A and B are leaking	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A54	23/12/2015	Leaks found at turrets A and B	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A6	15/10/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A54	16/10/2015	Hydraulic line leak on side B	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A74	17/01/2015	Spindle indexing error with overfeed	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A31	11/11/2015	Accumulators need checking and charging	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A47	25/10/2015	Turret A and B are leaking	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A4	30/11/2015	Repair work needed on milling spindle	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A92	07/02/2015	Leaks found at turrets A and B	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A21	04/10/2015	Inspect and recharge accumulators	Cristian Santos noted: No additional information provided.	cristian_santos
A42	07/06/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A44	17/04/2015	Spindle indexing error with overfeed	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A28	27/03/2015	Repair work needed on milling spindle	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A75	26/01/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A51	29/12/2015	Milling spindle requires repair	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A91	25/10/2015	Accumulators need checking and charging	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A23	17/05/2015	Power supply failure detected	Nathan Maldonado noted: No further details.	nathan_maldonado
A96	14/06/2015	Accumulators need checking and charging	Gina Moore noted: No further details.	gina_moore, dylan_miller
A18	22/11/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A14	04/09/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A5	14/07/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams

A93	17/03/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A27	27/11/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A55	04/06/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A56	05/08/2015	Accumulator inspection and charging required	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A36	29/09/2015	Leak in side B hydraulic line	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A6	18/04/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A61	28/05/2015	Machine is unpowered	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A24	02/04/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A91	08/03/2015	Accumulators need checking and charging	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A18	12/05/2015	Spindle fails to index, overfeeding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A33	05/12/2015	Milling spindle requires repair	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A84	14/05/2015	Power supply failure detected	Cristian Santos noted: Repair completed.	cristian_santos
A54	28/08/2015	Maintenance on milling spindle needed	Michele Williams noted: System checked and accumulators charged.	michele_williams
A40	27/11/2015	Leak in side B hydraulic line	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A20	21/08/2015	Accumulator inspection and charging required	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A22	25/06/2015	Hydraulic line leak on side B	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A6	13/09/2015	Repair work needed on milling spindle	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A78	21/09/2015	Maintenance on milling spindle needed	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A14	24/11/2015	Maintenance on milling spindle needed	Michele Williams noted: No further details.	michele_williams
A52	12/12/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A19	23/10/2015	Accumulator inspection and charging required	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A15	03/03/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A85	16/04/2015	Accumulators need checking and charging	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A1	20/07/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Detail not recorded.	cristian_santos
A46	16/08/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A41	11/10/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A67	21/05/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A50	20/10/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A3	26/03/2015	Hydraulic line leak on side B	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A40	01/03/2015	Accumulator inspection and charging required	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A22	07/08/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A25	18/01/2015	Machine is unpowered	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A16	13/09/2015	Hydraulic line leak on side B	Cristian Santos noted: Detail not recorded.	cristian_santos
A39	05/07/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A73	01/04/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A4	01/02/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A5	12/03/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A65	29/08/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A66	08/11/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A73	09/08/2015	Maintenance on milling spindle needed	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A18	26/10/2015	Spindle indexing error with overfeed	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A4	10/06/2015	Machine is unpowered	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A70	15/11/2015	Accumulators need checking and charging	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A54	09/11/2015	Turret sections A & B showing leaks	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A25	08/07/2015	Turret A and B are leaking	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A73	17/06/2015	Accumulator inspection and charging required	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A10	26/10/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A19	21/11/2015	Inspect and recharge accumulators	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A4	02/03/2015	Machine is unpowered	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A20	29/07/2015	Turret A and B are leaking	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A69	28/08/2015	Spindle indexing error with overfeed	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A70	21/02/2015	Inspect and recharge accumulators	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A4	27/09/2015	Spindle fails to index, overfeeding	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A46	12/08/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A55	30/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A19	27/03/2015	Unit lost electrical power	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A88	12/09/2015	Maintenance on milling spindle needed	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A1	14/04/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A8	26/09/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A54	31/03/2015	Turret sections A & B showing leaks	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A18	12/04/2015	Leak in side B hydraulic line	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A44	17/04/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A58	29/12/2015	Milling spindle requires repair	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A64	15/07/2015	Spindle indexing error with overfeed	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A69	16/04/2015	Inspect and recharge accumulators	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A99	07/04/2015	Turret A and B are leaking	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A47	05/04/2015	Accumulator inspection and charging required	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A98	18/01/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A38	21/02/2015	Power supply failure detected	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A76	30/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado

A16	30/05/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A7	26/04/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A23	13/03/2015	Milling spindle requires repair	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A67	05/05/2015	Leaks found at turrets A and B	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A9	19/01/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A69	20/12/2015	Turret sections A & B showing leaks	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A42	04/07/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A29	20/01/2015	Maintenance on milling spindle needed	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A29	18/08/2015	Leaks found at turrets A and B	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A52	04/12/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: No further details.	gina_moore, dylan_miller
A19	01/11/2015	Maintenance on milling spindle needed	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A24	07/03/2015	Milling spindle requires repair	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A49	10/06/2015	Repair work needed on milling spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A71	02/11/2015	Leak in side B hydraulic line	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A28	28/06/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A64	12/06/2015	Milling spindle requires repair	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A33	10/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A61	27/10/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A44	05/11/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A60	13/01/2016	Saw attachment is leaking hydraulics	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A79	25/02/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A14	23/04/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A38	23/03/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A47	03/11/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A74	10/10/2015	Turret sections A & B showing leaks	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A39	02/03/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A99	07/08/2015	Unit lost electrical power	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A14	09/09/2015	Unit lost electrical power	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A49	10/10/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A75	13/05/2015	Turret sections A & B showing leaks	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A93	23/06/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A28	21/04/2015	Inspect and recharge accumulators	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A17	06/01/2016	Hydraulic line leak on side B	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A57	19/11/2015	Leak in side B hydraulic line	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A6	27/11/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A41	16/01/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A85	14/09/2015	Milling spindle requires repair	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A45	25/06/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: No further details.	gina_moore, dylan_miller
A51	29/01/2015	Milling spindle requires repair	Cristian Santos noted: Fixed and tested.	cristian_santos
A70	12/02/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: No additional information provided.	cristian_santos
A38	16/07/2015	Hydraulic line leak on side B	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A24	22/02/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A13	29/04/2015	Inspect and recharge accumulators	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A91	20/06/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A95	10/01/2016	Inspect and recharge accumulators	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A62	24/05/2015	Leak in side B hydraulic line	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A66	05/06/2015	Machine is unpowered	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A57	28/05/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A3	05/12/2015	Accumulator inspection and charging required	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A76	16/06/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A45	10/03/2015	Repair work needed on milling spindle	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A58	17/02/2015	Leak in side B hydraulic line	Michele Williams noted: Detail not recorded.	michele_williams
A69	03/10/2015	Unit lost electrical power	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A63	12/03/2015	Leak in side B hydraulic line	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A20	20/11/2015	Unit lost electrical power	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A58	10/02/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A12	05/02/2015	Leak in side B hydraulic line	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A29	08/09/2015	Repair work needed on milling spindle	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A36	20/10/2015	Unit lost electrical power	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A75	04/10/2015	Power supply failure detected	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A51	17/08/2015	Power supply failure detected	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A39	07/07/2015	Unit lost electrical power	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A51	25/06/2015	Machine is unpowered	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A30	14/11/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A39	15/04/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A26	23/12/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A67	15/07/2015	Repair work needed on milling spindle	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A37	01/05/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A40	27/11/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A42	21/03/2015	Power supply failure detected	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller

A44	14/08/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A42	06/08/2015	Unit lost electrical power	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A77	20/12/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A48	26/03/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A48	04/03/2015	Spindle indexing error with overfeed	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A87	14/07/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A75	23/09/2015	Unit lost electrical power	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A5	08/03/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A43	13/12/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A34	03/05/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A13	11/03/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A24	10/09/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A54	29/09/2015	Power supply failure detected	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A42	14/08/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A70	27/02/2015	Repair work needed on milling spindle	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A28	02/10/2015	Spindle fails to index, overfeeding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A74	30/08/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A52	17/11/2015	Power supply failure detected	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A13	26/04/2015	Leak in side B hydraulic line	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A57	04/07/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A98	04/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A99	16/09/2015	Machine is unpowered	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A27	20/10/2015	Accumulator inspection and charging required	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A16	01/03/2015	Spindle fails to index, overfeeding	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A12	26/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A51	17/01/2015	Machine is unpowered	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A19	26/08/2015	Spindle indexing error with overfeed	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A88	30/12/2015	Repair work needed on milling spindle	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A59	25/12/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A58	14/01/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A76	31/05/2015	Accumulators need checking and charging	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A96	17/06/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A97	03/06/2015	Turret sections A & B showing leaks	Michele Williams noted: System checked and accumulators charged.	michele_williams
A49	26/06/2015	Accumulator inspection and charging required	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A27	20/02/2015	Turret sections A & B showing leaks	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A59	15/06/2015	Accumulators need checking and charging	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A91	09/08/2015	Machine is unpowered	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A9	17/07/2015	Repair work needed on milling spindle	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A20	17/01/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A80	26/12/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A79	08/05/2015	Unit lost electrical power	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A49	03/05/2015	Turret sections A & B showing leaks	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A95	19/02/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A3	06/06/2015	Inspect and recharge accumulators	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A86	26/01/2015	Milling spindle requires repair	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A16	03/05/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A18	26/01/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A60	27/12/2015	Unit lost electrical power	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A53	30/03/2015	Machine is unpowered	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A7	25/12/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A49	05/08/2015	Leak in side B hydraulic line	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A59	02/09/2015	Machine is unpowered	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A60	12/10/2015	Leaks found at turrets A and B	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A72	09/03/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A11	24/05/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A84	02/10/2015	Spindle indexing error with overfeed	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A96	02/03/2015	Inspect and recharge accumulators	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A17	05/10/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A3	20/01/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A39	20/11/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A36	17/12/2015	Machine is unpowered	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A32	26/08/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: No further details.	nathan_maldonado
A75	15/10/2015	Accumulator inspection and charging required	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A20	26/01/2015	Turret sections A & B showing leaks	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A34	08/02/2015	Unit lost electrical power	Michele Williams noted: Repair completed.	michele_williams
A23	07/06/2015	Hydraulic line leak on side B	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A14	22/06/2015	Accumulator inspection and charging required	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A66	03/02/2015	Turret sections A & B showing leaks	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A92	23/11/2015	Spindle indexing error with overfeed	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A70	17/01/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams

A97	01/04/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A32	22/06/2015	Repair work needed on milling spindle	Cristian Santos noted: No further details.	cristian_santos
A89	22/01/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: No additional information provided.	michele_williams
A81	02/02/2015	Repair work needed on milling spindle	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A82	04/07/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A22	09/11/2015	Saw attachment gears are binding and grinding	Michele Williams noted: System checked and accumulators charged.	michele_williams
A71	09/02/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A35	13/09/2015	Maintenance on milling spindle needed	Cristian Santos noted: Detail not recorded.	cristian_santos
A86	15/08/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A12	25/11/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A73	22/01/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A1	06/09/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A11	29/10/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A85	29/09/2015	Hydraulic line leak on side B	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A87	11/07/2015	Turret sections A & B showing leaks	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A99	20/05/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A48	21/06/2015	Turret A and B are leaking	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A92	28/06/2015	Leak in side B hydraulic line	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A59	28/11/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A68	31/08/2015	Turret A and B are leaking	Michele Williams noted: No additional information provided.	michele_williams
A35	24/02/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A89	04/01/2016	Machine is unpowered	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A57	16/12/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: No further details.	cristian_santos
A24	05/10/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A45	11/10/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A31	03/06/2015	Unit lost electrical power	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A28	24/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A42	17/04/2015	Leaks found at turrets A and B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A5	26/04/2015	Milling spindle requires repair	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A92	07/05/2015	Repair work needed on milling spindle	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A55	14/10/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A61	10/10/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A80	19/09/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A74	29/03/2015	Milling spindle requires repair	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A65	28/04/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A67	25/12/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A54	03/06/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A11	07/12/2015	Milling spindle requires repair	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A52	28/06/2015	Hydraulic line leak on side B	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A62	08/02/2015	Accumulators need checking and charging	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A41	28/02/2015	Milling spindle requires repair	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A15	25/02/2015	Maintenance on milling spindle needed	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A13	23/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A32	27/12/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A43	02/03/2015	Maintenance on milling spindle needed	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A80	16/04/2015	Power supply failure detected	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A47	28/11/2015	Spindle indexing error with overfeed	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A87	19/12/2015	Accumulator inspection and charging required	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A62	04/10/2015	Accumulator inspection and charging required	Michele Williams noted: System checked and accumulators charged.	michele_williams
A84	27/07/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A65	28/07/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A12	04/11/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A41	20/06/2015	Spindle fails to index, overfeeding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A61	22/01/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A29	09/03/2015	Maintenance on milling spindle needed	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A16	08/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A67	15/03/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A53	14/09/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Repair completed.	cristian_santos
A48	24/05/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A71	31/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A33	01/12/2015	Spindle fails to index, overfeeding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A26	10/06/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A44	02/01/2016	Hydraulic line leak on side B	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A33	14/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A36	29/12/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A93	06/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A59	14/04/2015	Machine is unpowered	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A14	31/03/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A36	22/08/2015	Milling spindle requires repair	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A22	13/06/2015	Power supply failure detected	Gina Moore noted: No further details.	gina_moore, dylan_miller

A2	12/05/2015	Unit lost electrical power	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A80	04/04/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A99	01/02/2015	Turret A and B are leaking	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A22	09/05/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A3	18/04/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A69	16/12/2015	Spindle indexing error with overfeed	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A71	29/06/2015	Leaks found at turrets A and B	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A89	03/02/2015	Hydraulic line leak on side B	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A33	21/11/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A87	23/03/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A48	10/11/2015	Spindle indexing error with overfeed	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A11	24/12/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A41	12/07/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A92	05/03/2015	Turret sections A & B showing leaks	Michele Williams noted: Fixed and tested.	michele_williams
A81	27/05/2015	Unit lost electrical power	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A79	02/04/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A93	02/07/2015	Leaks found at turrets A and B	Michele Williams noted: No additional information provided.	michele_williams
A1	19/01/2015	Turret sections A & B showing leaks	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A95	25/01/2015	Leaks found at turrets A and B	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A11	20/10/2015	Accumulator inspection and charging required	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A98	30/01/2015	Spindle indexing error with overfeed	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A8	05/06/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A92	15/11/2015	Repair work needed on milling spindle	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A55	31/08/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A92	10/08/2015	Power supply failure detected	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A2	15/08/2015	Milling spindle requires repair	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A17	26/05/2015	Leaks found at turrets A and B	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A24	17/07/2015	Leaks found at turrets A and B	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A47	03/09/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: No further details.	cristian_santos
A24	17/05/2015	Inspect and recharge accumulators	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A19	14/10/2015	Leaks found at turrets A and B	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A4	13/01/2016	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A25	08/10/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A40	01/09/2015	Leak in side B hydraulic line	Nathan Maldonado noted: No further details.	nathan_maldonado
A33	04/12/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A70	14/06/2015	Milling spindle requires repair	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A51	09/01/2016	Milling spindle requires repair	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A72	06/06/2015	Leak in side B hydraulic line	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A88	28/08/2015	Hydraulic line leak on side B	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A91	28/10/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A91	26/11/2015	Repair work needed on milling spindle	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A8	28/03/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A82	19/01/2015	Hydraulic line leak on side B	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A3	28/03/2015	Power supply failure detected	Michele Williams noted: Repair completed.	michele_williams
A34	02/03/2015	Accumulators need checking and charging	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A23	21/05/2015	Inspect and recharge accumulators	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A55	26/02/2015	Repair work needed on milling spindle	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A20	04/07/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A63	14/05/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A31	03/09/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A44	28/09/2015	Hydraulic line leak on side B	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A39	06/03/2015	Hydraulic line leak on side B	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A25	13/04/2015	Spindle indexing error with overfeed	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A47	27/08/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A35	22/09/2015	Inspect and recharge accumulators	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A36	04/06/2015	Hydraulic line leak on side B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A15	20/09/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A56	29/05/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A7	20/04/2015	Turret A and B are leaking	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A68	18/02/2015	Maintenance on milling spindle needed	Cristian Santos noted: Fixed and tested.	cristian_santos
A24	12/05/2015	Leak in side B hydraulic line	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A12	23/09/2015	Power supply failure detected	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A98	28/12/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A28	17/06/2015	Inspect and recharge accumulators	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A79	26/08/2015	Turret sections A & B showing leaks	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A12	19/09/2015	Inspect and recharge accumulators	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A86	14/04/2015	Repair work needed on milling spindle	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A12	25/04/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A51	05/06/2015	Inspect and recharge accumulators	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A38	18/10/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado

A97	29/11/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Repair completed.	michele_williams
A60	24/04/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A62	17/09/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A91	23/07/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A25	13/07/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Fixed and tested.	cristian_santos
A61	05/06/2015	Milling spindle requires repair	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A83	20/10/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A58	12/11/2015	Power supply failure detected	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A4	10/09/2015	Machine is unpowered	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A43	10/10/2015	Power supply failure detected	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A57	03/12/2015	Spindle indexing error with overfeed	Cristian Santos noted: Detail not recorded.	cristian_santos
A1	22/09/2015	Maintenance on milling spindle needed	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A41	07/09/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: System checked and accumulators charged.	michele_williams
A22	12/10/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: No additional information provided.	michele_williams
A3	03/12/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A59	28/05/2015	Accumulators need checking and charging	Cristian Santos noted: Repair completed.	cristian_santos
A83	21/01/2015	Maintenance on milling spindle needed	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A19	16/04/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A24	15/09/2015	Power supply failure detected	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A37	06/07/2015	Milling spindle requires repair	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A47	12/10/2015	Accumulator inspection and charging required	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A18	12/02/2015	Spindle indexing error with overfeed	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A55	04/04/2015	Repair work needed on milling spindle	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A73	23/02/2015	Unit lost electrical power	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A92	29/09/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A40	28/08/2015	Spindle indexing error with overfeed	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A30	22/09/2015	Maintenance on milling spindle needed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A72	17/05/2015	Power supply failure detected	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A53	08/01/2016	Indexing issue causing overfeed on spindle	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A6	12/02/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A37	14/10/2015	Power supply failure detected	Michele Williams noted: No additional information provided.	michele_williams
A15	31/07/2015	Turret sections A & B showing leaks	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A97	27/06/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A84	16/11/2015	Turret A and B are leaking	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A99	18/03/2015	Power supply failure detected	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A25	11/02/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A74	05/05/2015	Turret A and B are leaking	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A18	31/12/2015	Hydraulic line leak on side B	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A74	28/01/2015	Unit lost electrical power	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A70	06/04/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: No further details.	nathan_maldonado
A49	05/02/2015	Machine is unpowered	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A20	06/08/2015	Accumulator inspection and charging required	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A73	22/01/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A11	19/07/2015	Unit lost electrical power	Michele Williams noted: Repair completed.	michele_williams
A15	04/08/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A97	12/09/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A84	18/01/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A98	21/02/2015	Accumulators need checking and charging	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A38	21/10/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A11	25/04/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A79	20/01/2015	Unit lost electrical power	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A80	15/11/2015	Inspect and recharge accumulators	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A55	06/01/2016	Spindle fails to index, overfeeding	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A65	20/04/2015	Turret A and B are leaking	Cristian Santos noted: Detail not recorded.	cristian_santos
A24	22/09/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A13	23/05/2015	Machine is unpowered	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A97	22/09/2015	Accumulators need checking and charging	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A58	14/05/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A21	13/08/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A40	13/04/2015	Machine is unpowered	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A7	26/05/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A94	08/03/2015	Turret A and B are leaking	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A10	17/05/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A84	22/09/2015	Unit lost electrical power	Cristian Santos noted: No additional information provided.	cristian_santos
A52	06/03/2015	Spindle indexing error with overfeed	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A4	24/09/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A99	26/01/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: No further details.	michele_williams
A78	24/10/2015	Maintenance on milling spindle needed	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A43	14/07/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A60	24/03/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller

A68	19/06/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A55	27/04/2015	Leaks found at turrets A and B	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A51	22/09/2015	Turret A and B are leaking	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A44	25/09/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: No further details.	michele_williams
A1	14/09/2015	Spindle indexing error with overfeed	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A82	22/01/2015	Accumulators need checking and charging	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A75	25/01/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A7	16/07/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A25	25/08/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A58	07/12/2015	Repair work needed on milling spindle	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A62	25/08/2015	Repair work needed on milling spindle	Cristian Santos noted: Maintenance action successful.	cristian_santos
A66	15/08/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A90	16/04/2015	Leak in side B hydraulic line	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A7	07/03/2015	Spindle fails to index, overfeeding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A6	25/04/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A95	29/05/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A53	08/07/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A66	23/02/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A60	09/03/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Maintenance action successful.	cristian_santos
A66	14/01/2015	Machine is unpowered	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A4	03/12/2015	Leak in side B hydraulic line	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A71	10/11/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A79	27/05/2015	Repair work needed on milling spindle	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A89	03/11/2015	Milling spindle requires repair	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A11	18/08/2015	Inspect and recharge accumulators	Michele Williams noted: Detail not recorded.	michele_williams
A61	26/03/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A34	11/09/2015	Spindle fails to index, overfeeding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A47	11/05/2015	Milling spindle requires repair	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A54	22/09/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A96	13/03/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A71	03/02/2015	Power supply failure detected	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A99	21/03/2015	Maintenance on milling spindle needed	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A76	14/11/2015	Machine is unpowered	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A32	18/03/2015	Machine is unpowered	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A48	23/05/2015	Milling spindle requires repair	Michele Williams noted: No further details.	michele_williams
A46	07/02/2015	Hydraulic line leak on side B	Cristian Santos noted: Repair completed.	cristian_santos
A27	07/01/2016	Spindle fails to index, overfeeding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A89	08/12/2015	Turret sections A & B showing leaks	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A85	17/08/2015	Unit lost electrical power	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A95	14/04/2015	Leaks found at turrets A and B	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A19	31/08/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A70	24/12/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A16	12/10/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A90	12/08/2015	Saw attachment gears are binding and grinding	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A77	10/08/2015	Power supply failure detected	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A58	21/03/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A38	18/01/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A23	13/11/2015	Spindle indexing error with overfeed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A82	27/07/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A51	10/06/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A37	02/05/2015	Inspect and recharge accumulators	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A36	09/10/2015	Milling spindle requires repair	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A6	24/10/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A64	12/05/2015	Leak in side B hydraulic line	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A34	26/03/2015	Accumulator inspection and charging required	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A30	26/01/2015	Turret A and B are leaking	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A70	13/03/2015	Unit lost electrical power	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A20	03/05/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A39	30/07/2015	Hydraulic line leak on side B	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A54	25/05/2015	Leak in side B hydraulic line	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A61	19/04/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A60	19/09/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A75	06/11/2015	Repair work needed on milling spindle	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A38	10/09/2015	Repair work needed on milling spindle	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A74	24/02/2015	Leaks found at turrets A and B	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A89	21/03/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Detail not recorded.	michele_williams
A96	18/04/2015	Milling spindle requires repair	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A35	08/09/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A74	26/02/2015	Spindle fails to index, overfeeding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A68	06/12/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado

A70	09/02/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A17	12/04/2015	Maintenance on milling spindle needed	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A96	22/11/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A74	12/08/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A20	18/02/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A24	15/03/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A85	20/01/2015	Hydraulic line leak on side B	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A77	16/11/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A7	14/09/2015	Maintenance on milling spindle needed	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A81	19/01/2015	Accumulator inspection and charging required	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A46	23/04/2015	Spindle indexing error with overfeed	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A19	16/10/2015	Accumulator inspection and charging required	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A96	06/07/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Repair completed.	michele_williams
A64	29/06/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A8	13/09/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A38	25/05/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A68	01/03/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A33	08/11/2015	Maintenance on milling spindle needed	Cristian Santos noted: No further details.	cristian_santos
A6	09/05/2015	Power supply failure detected	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A59	29/12/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A90	16/04/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A57	16/11/2015	Accumulator inspection and charging required	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A98	11/06/2015	Hydraulic line leak on side B	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A38	04/10/2015	Accumulators need checking and charging	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A82	12/05/2015	Repair work needed on milling spindle	Michele Williams noted: No further details.	michele_williams
A97	09/12/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A1	15/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A32	01/10/2015	Hydraulic line leak on side B	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A70	11/11/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A79	13/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A79	13/12/2015	Power supply failure detected	Gina Moore noted: No further details.	gina_moore, dylan_miller
A6	04/02/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A43	20/06/2015	Turret A and B are leaking	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A14	16/04/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A56	11/12/2015	Power supply failure detected	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A63	02/09/2015	Leaks found at turrets A and B	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A34	30/11/2015	Accumulators need checking and charging	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A35	25/06/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A28	05/06/2015	Power supply failure detected	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A27	19/04/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A63	14/11/2015	Unit lost electrical power	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A61	04/04/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A19	16/08/2015	Maintenance on milling spindle needed	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A38	10/08/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A80	19/07/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A95	28/04/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A2	06/02/2015	Accumulator inspection and charging required	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A39	11/11/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A21	30/05/2015	Leaks found at turrets A and B	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A55	23/07/2015	Leaks found at turrets A and B	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A57	27/01/2015	Accumulator inspection and charging required	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A96	03/03/2015	Turret sections A & B showing leaks	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A38	07/04/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A18	25/07/2015	Spindle indexing error with overfeed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A31	13/04/2015	Spindle indexing error with overfeed	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A71	13/05/2015	Leak in side B hydraulic line	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A8	18/02/2015	Turret sections A & B showing leaks	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A3	19/12/2015	Milling spindle requires repair	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A67	03/09/2015	Milling spindle requires repair	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A78	02/08/2015	Accumulators need checking and charging	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A52	05/11/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A86	21/11/2015	Turret sections A & B showing leaks	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A28	02/08/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A38	15/07/2015	Power supply failure detected	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A57	25/05/2015	Accumulators need checking and charging	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A1	14/06/2015	Machine is unpowered	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A95	16/09/2015	Repair work needed on milling spindle	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A21	30/10/2015	Turret A and B are leaking	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A6	05/04/2015	Inspect and recharge accumulators	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A11	12/09/2015	Accumulator inspection and charging required	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller

A28	25/04/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Detail not recorded.	michele_williams
A42	19/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A47	13/01/2016	Spindle indexing error with overfeed	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A40	12/10/2015	Unit lost electrical power	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A15	20/09/2015	Unit lost electrical power	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A93	09/01/2016	Machine is unpowered	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A52	31/12/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A94	23/11/2015	Repair work needed on milling spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A9	21/01/2015	Unit lost electrical power	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A75	18/07/2015	Leaks found at turrets A and B	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A57	28/01/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A32	07/09/2015	Spindle fails to index, overfeeding	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A29	12/02/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A24	12/02/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A5	04/10/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A17	07/03/2015	Repair work needed on milling spindle	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A80	22/05/2015	Turret A and B are leaking	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A89	12/11/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A28	19/07/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A1	15/12/2015	Leak in side B hydraulic line	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A31	04/08/2015	Turret sections A & B showing leaks	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A39	28/01/2015	Inspect and recharge accumulators	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A3	20/10/2015	Accumulator inspection and charging required	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A52	21/01/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A57	15/01/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A19	26/08/2015	Inspect and recharge accumulators	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A71	26/10/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A66	09/03/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A77	17/03/2015	Hydraulic line leak on side B	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A17	28/08/2015	Hydraulic line leak on side B	Cristian Santos noted: Repair completed.	cristian_santos
A22	08/07/2015	Repair work needed on milling spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A68	26/01/2015	Hydraulic line leak on side B	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A80	07/01/2016	Accumulator inspection and charging required	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A7	04/09/2015	Power supply failure detected	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A30	26/01/2015	Unit lost electrical power	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A23	13/01/2016	Power supply failure detected	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A24	19/12/2015	Inspect and recharge accumulators	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A25	29/04/2015	Power supply failure detected	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A22	20/03/2015	Leak in side B hydraulic line	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A77	21/06/2015	Accumulator inspection and charging required	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A2	12/08/2015	Power supply failure detected	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A18	16/10/2015	Accumulator inspection and charging required	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A41	13/01/2016	Unit lost electrical power	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A50	24/11/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A35	06/07/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A12	19/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A49	29/10/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A32	29/08/2015	Leaks found at turrets A and B	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A93	07/04/2015	Spindle indexing error with overfeed	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A71	21/08/2015	Unit lost electrical power	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A14	26/12/2015	Accumulators need checking and charging	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A61	10/10/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A6	11/04/2015	Accumulators need checking and charging	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A11	13/02/2015	Accumulator inspection and charging required	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A1	15/06/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A31	06/04/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A59	26/11/2015	Power supply failure detected	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A44	27/02/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A18	19/04/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A12	21/02/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A34	04/08/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A12	24/02/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A57	30/01/2015	Milling spindle requires repair	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A2	19/01/2015	Turret sections A & B showing leaks	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A27	25/12/2015	Spindle fails to index, overfeeding	Michele Williams noted: Fixed and tested.	michele_williams
A91	21/10/2015	Accumulators need checking and charging	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A57	12/08/2015	Accumulators need checking and charging	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A20	10/05/2015	Spindle indexing error with overfeed	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A75	29/11/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A20	16/12/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos

A31	17/08/2015	Turret sections A & B showing leaks	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A5	18/02/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A90	04/07/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A44	27/12/2015	Turret sections A & B showing leaks	Gina Moore noted: No further details.	gina_moore, dylan_miller
A12	02/10/2015	Repair work needed on milling spindle	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A36	30/01/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A97	07/05/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A79	03/06/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A82	28/08/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: No additional information provided.	michele_williams
A95	25/01/2015	Machine is unpowered	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A37	10/02/2015	Unit lost electrical power	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A5	01/07/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A42	13/02/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A24	04/07/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A95	24/08/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A85	03/12/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A90	02/10/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A44	21/03/2015	Leaks found at turrets A and B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A59	01/02/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A69	01/12/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A43	27/02/2015	Inspect and recharge accumulators	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A39	10/12/2015	Turret sections A & B showing leaks	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A94	21/01/2015	Turret A and B are leaking	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A87	15/04/2015	Machine is unpowered	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A70	08/02/2015	Inspect and recharge accumulators	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A90	14/11/2015	Accumulators need checking and charging	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A17	24/03/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A97	17/06/2015	Spindle indexing error with overfeed	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A22	25/06/2015	Power supply failure detected	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A33	12/03/2015	Leaks found at turrets A and B	Cristian Santos noted: No additional information provided.	cristian_santos
A54	15/09/2015	Power supply failure detected	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A72	18/09/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A93	13/09/2015	Leak in side B hydraulic line	Gina Moore noted: No further details.	gina_moore, dylan_miller
A18	02/11/2015	Unit lost electrical power	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A59	08/04/2015	Spindle indexing error with overfeed	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A17	23/01/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A67	27/03/2015	Power supply failure detected	Michele Williams noted: Repair completed.	michele_williams
A91	12/12/2015	Leak in side B hydraulic line	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A57	17/05/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A58	30/10/2015	Milling spindle requires repair	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A59	07/11/2015	Accumulators need checking and charging	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A49	24/03/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A73	15/09/2015	Turret A and B are leaking	Cristian Santos noted: Maintenance action successful.	cristian_santos
A99	07/02/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A35	13/11/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A67	24/08/2015	Accumulators need checking and charging	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A28	22/02/2015	Repair work needed on milling spindle	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A89	15/12/2015	Milling spindle requires repair	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A84	20/09/2015	Power supply failure detected	Michele Williams noted: Detail not recorded.	michele_williams
A24	05/06/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A10	14/11/2015	Accumulator inspection and charging required	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A86	15/07/2015	Spindle indexing error with overfeed	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A72	10/12/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A19	30/06/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A43	02/08/2015	Leaks found at turrets A and B	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A37	19/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A37	13/08/2015	Maintenance on milling spindle needed	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A42	15/03/2015	Unit lost electrical power	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A93	09/04/2015	Spindle indexing error with overfeed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A15	16/12/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A49	03/05/2015	Unit lost electrical power	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A13	19/05/2015	Turret A and B are leaking	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A83	31/12/2015	Hydraulic line leak on side B	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A4	03/11/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: No further details.	cristian_santos
A16	11/11/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A72	04/01/2016	Spindle fails to index, overfeeding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A30	29/06/2015	Leak in side B hydraulic line	Cristian Santos noted: No further details.	cristian_santos
A80	14/10/2015	Machine is unpowered	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A34	11/08/2015	Turret A and B are leaking	Michele Williams noted: Maintenance action successful.	michele_williams
A67	24/02/2015	Machine is unpowered	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams

A45	02/06/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A62	18/05/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A26	16/03/2015	Machine is unpowered	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A77	25/02/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A55	14/11/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A65	30/09/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A60	31/10/2015	Spindle indexing error with overfeed	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A77	19/05/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A56	18/12/2015	Spindle indexing error with overfeed	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A46	16/11/2015	Accumulators need checking and charging	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A62	22/01/2015	Repair work needed on milling spindle	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A71	23/01/2015	Milling spindle requires repair	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A20	11/10/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: No additional information provided.	michele_williams
A76	09/12/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A75	14/05/2015	Turret A and B are leaking	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A67	19/09/2015	Unit lost electrical power	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A3	03/09/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A31	23/05/2015	Turret sections A & B showing leaks	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A56	12/12/2015	Inspect and recharge accumulators	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A79	01/08/2015	Inspect and recharge accumulators	Michele Williams noted: Detail not recorded.	michele_williams
A72	17/11/2015	Repair work needed on milling spindle	Cristian Santos noted: No further details.	cristian_santos
A75	08/08/2015	Inspect and recharge accumulators	Michele Williams noted: Repair completed.	michele_williams
A94	23/09/2015	Inspect and recharge accumulators	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A16	09/02/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A65	06/12/2015	Inspect and recharge accumulators	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A35	08/04/2015	Repair work needed on milling spindle	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A35	06/02/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A36	11/06/2015	Machine is unpowered	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A19	28/01/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A92	16/06/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A88	29/08/2015	Maintenance on milling spindle needed	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A97	23/10/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A59	06/07/2015	Power supply failure detected	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A39	29/07/2015	Repair work needed on milling spindle	Michele Williams noted: Detail not recorded.	michele_williams
A29	07/02/2015	Milling spindle requires repair	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A57	05/11/2015	Turret A and B are leaking	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A55	19/11/2015	Leak in side B hydraulic line	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A13	25/12/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A59	03/01/2016	Hydraulic hose on side B is leaking	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A2	29/06/2015	Leak in side B hydraulic line	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A81	20/10/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A28	11/06/2015	Accumulators need checking and charging	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A72	15/03/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A8	11/11/2015	Inspect and recharge accumulators	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A15	13/04/2015	Spindle indexing error with overfeed	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A94	11/06/2015	Repair work needed on milling spindle	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A81	19/01/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A63	20/03/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A60	02/03/2015	Accumulators need checking and charging	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A78	20/01/2015	Spindle indexing error with overfeed	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A26	14/04/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A28	31/07/2015	Repair work needed on milling spindle	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A33	31/10/2015	Unit lost electrical power	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A73	07/06/2015	Hydraulic line leak on side B	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A50	15/11/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A57	24/02/2015	Leaks found at turrets A and B	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A40	27/06/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A13	28/02/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A53	15/07/2015	Spindle indexing error with overfeed	Michele Williams noted: Detail not recorded.	michele_williams
A18	27/05/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A18	29/03/2015	Unit lost electrical power	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A9	03/02/2015	Unit lost electrical power	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A49	20/05/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A36	10/07/2015	Milling spindle requires repair	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A15	10/05/2015	Turret A and B are leaking	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A88	01/10/2015	Maintenance on milling spindle needed	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A84	16/06/2015	Hydraulic line leak on side B	Cristian Santos noted: Maintenance action successful.	cristian_santos
A41	14/11/2015	Inspect and recharge accumulators	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A82	23/01/2015	Turret sections A & B showing leaks	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A65	10/07/2015	Milling spindle requires repair	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams

A38	12/09/2015	Inspect and recharge accumulators	Cristian Santos noted: Maintenance action successful.	cristian_santos
A84	18/07/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A77	12/09/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A40	20/10/2015	Hydraulic line leak on side B	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A3	21/08/2015	Turret sections A & B showing leaks	Michele Williams noted: Maintenance action successful.	michele_williams
A35	26/06/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A18	13/10/2015	Turret A and B are leaking	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A26	01/12/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A40	04/12/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A74	10/05/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A54	22/03/2015	Spindle fails to index, overfeeding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A77	25/10/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A3	03/06/2015	Accumulators need checking and charging	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A22	11/05/2015	Accumulators need checking and charging	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A11	17/09/2015	Unit lost electrical power	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A51	11/10/2015	Leak in side B hydraulic line	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A48	03/07/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A16	24/10/2015	Repair work needed on milling spindle	Michele Williams noted: Repair completed.	michele_williams
A52	04/01/2016	Leak in side B hydraulic line	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A93	08/03/2015	Accumulator inspection and charging required	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A91	19/08/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A52	10/02/2015	Turret A and B are leaking	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A73	06/05/2015	Hydraulic line leak on side B	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A24	08/08/2015	Accumulator inspection and charging required	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A63	22/08/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A62	14/11/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A3	06/03/2015	Power supply failure detected	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A68	12/01/2016	Power supply failure detected	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A42	14/10/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A40	02/07/2015	Unit lost electrical power	Michele Williams noted: System checked and accumulators charged.	michele_williams
A51	08/11/2015	Power supply failure detected	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A24	16/12/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A19	17/11/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A66	14/08/2015	Power supply failure detected	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A77	18/06/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A81	23/03/2015	Milling spindle requires repair	Cristian Santos noted: Repair completed.	cristian_santos
A86	02/04/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A82	12/01/2016	Turret sections A & B showing leaks	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A78	02/06/2015	Spindle indexing error with overfeed	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A76	14/11/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Detail not recorded.	cristian_santos
A30	19/04/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A99	15/01/2015	Spindle fails to index, overfeeding	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A72	19/11/2015	Inspect and recharge accumulators	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A68	25/05/2015	Maintenance on milling spindle needed	Cristian Santos noted: No additional information provided.	cristian_santos
A86	22/11/2015	Leak in side B hydraulic line	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A60	12/03/2015	Saw attachment is leaking hydraulics	Gina Moore noted: No further details.	gina_moore, dylan_miller
A7	28/12/2015	Spindle indexing error with overfeed	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A74	10/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A94	16/10/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A23	12/05/2015	Milling spindle requires repair	Cristian Santos noted: No further details.	cristian_santos
A91	08/11/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A45	25/08/2015	Hydraulic line leak on side B	Cristian Santos noted: Maintenance action successful.	cristian_santos
A89	26/06/2015	Milling spindle requires repair	Michele Williams noted: No additional information provided.	michele_williams
A68	21/05/2015	Power supply failure detected	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A3	08/04/2015	Leaks found at turrets A and B	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A1	31/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A13	05/05/2015	Turret A and B are leaking	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A47	11/10/2015	Turret sections A & B showing leaks	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A11	07/08/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: No further details.	michele_williams
A57	14/01/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A93	04/11/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A8	26/05/2015	Turret A and B are leaking	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A29	01/08/2015	Unit lost electrical power	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A63	31/03/2015	Hydraulic line leak on side B	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A26	22/11/2015	Leaks found at turrets A and B	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A82	25/08/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A38	17/10/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A6	04/02/2015	Repair work needed on milling spindle	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A56	18/12/2015	Maintenance on milling spindle needed	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A90	14/02/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos

A72	17/06/2015	Repair work needed on milling spindle	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A91	18/08/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A3	15/02/2015	Turret A and B are leaking	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A28	08/01/2016	Power supply failure detected	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A61	19/02/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A59	08/09/2015	Turret A and B are leaking	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A18	21/10/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A41	04/04/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Repair completed.	cristian_santos
A62	15/03/2015	Unit lost electrical power	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A98	13/12/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A2	12/11/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A3	23/10/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A92	20/12/2015	Machine is unpowered	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A30	04/06/2015	Leak in side B hydraulic line	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A54	30/01/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A37	10/01/2016	Accumulator inspection and charging required	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A53	27/06/2015	Leaks found at turrets A and B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A43	13/08/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A47	13/05/2015	Spindle fails to index, overfeeding	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A87	15/01/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A74	31/07/2015	Inspect and recharge accumulators	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A34	14/12/2015	Power supply failure detected	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A59	12/01/2016	Leaks found at turrets A and B	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A43	02/02/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A85	01/11/2015	Accumulators need checking and charging	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A71	12/05/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A19	14/12/2015	Accumulators need checking and charging	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A59	09/03/2015	Leaks found at turrets A and B	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A26	15/04/2015	Machine is unpowered	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A96	07/10/2015	Turret sections A & B showing leaks	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A44	01/07/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A50	26/05/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A26	01/05/2015	Spindle indexing error with overfeed	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A17	01/01/2016	Inspect and recharge accumulators	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A58	03/12/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A52	23/09/2015	Accumulators need checking and charging	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A93	14/08/2015	Accumulator inspection and charging required	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A38	13/12/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A84	05/06/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A64	05/01/2016	Saw attachment is leaking hydraulics	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A16	26/01/2015	Unit lost electrical power	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A43	25/12/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A38	28/05/2015	Turret sections A & B showing leaks	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A71	21/02/2015	Milling spindle requires repair	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A22	08/10/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A18	28/11/2015	Milling spindle requires repair	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A96	14/09/2015	Accumulator inspection and charging required	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A54	02/03/2015	Hydraulic line leak on side B	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A82	06/06/2015	Hydraulic line leak on side B	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A62	27/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A42	06/09/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A79	09/11/2015	Spindle fails to index, overfeeding	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A79	27/04/2015	Inspect and recharge accumulators	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A99	07/06/2015	Accumulators need checking and charging	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A20	27/02/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A60	01/05/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A32	04/02/2015	Spindle fails to index, overfeeding	Michele Williams noted: Detail not recorded.	michele_williams
A41	15/08/2015	Maintenance on milling spindle needed	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A78	17/02/2015	Accumulator inspection and charging required	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A28	28/09/2015	Leak in side B hydraulic line	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A67	30/10/2015	Maintenance on milling spindle needed	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A47	25/06/2015	Turret sections A & B showing leaks	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A12	19/07/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A54	08/03/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A31	17/08/2015	Power supply failure detected	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A11	28/06/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A84	29/12/2015	Spindle fails to index, overfeeding	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A41	21/05/2015	Machine is unpowered	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A35	19/05/2015	Maintenance on milling spindle needed	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A40	17/04/2015	Spindle indexing error with overfeed	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller

A35	17/04/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A71	12/02/2015	Machine is unpowered	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A7	23/12/2015	Accumulators need checking and charging	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A87	15/02/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A65	23/10/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A64	13/03/2015	Accumulators need checking and charging	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A22	20/04/2015	Repair work needed on milling spindle	Cristian Santos noted: No further details.	cristian_santos
A74	22/08/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A17	09/06/2015	Repair work needed on milling spindle	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A4	02/01/2016	Inspect and recharge accumulators	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A87	28/12/2015	Turret sections A & B showing leaks	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A56	13/04/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A93	16/04/2015	Leak in side B hydraulic line	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A33	14/02/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A60	24/02/2015	Accumulator inspection and charging required	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A50	15/03/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A76	14/11/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: No further details.	cristian_santos
A32	18/03/2015	Leak in side B hydraulic line	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A74	12/12/2015	Spindle indexing error with overfeed	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A54	20/12/2015	Leaks found at turrets A and B	Michele Williams noted: No further details.	michele_williams
A14	13/08/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A39	13/11/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A96	08/07/2015	Milling spindle requires repair	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A23	20/01/2015	Hydraulic line leak on side B	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A76	22/05/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A4	21/11/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A11	23/11/2015	Machine is unpowered	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A32	01/04/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A50	24/08/2015	Machine is unpowered	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A18	26/10/2015	Leaks found at turrets A and B	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A81	14/02/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: No additional information provided.	michele_williams
A76	29/09/2015	Spindle indexing error with overfeed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A44	26/01/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A53	10/12/2015	Spindle indexing error with overfeed	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A21	25/05/2015	Inspect and recharge accumulators	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A73	19/12/2015	Spindle indexing error with overfeed	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A56	29/07/2015	Machine is unpowered	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A14	11/05/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A75	13/10/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A95	19/08/2015	Hydraulic line leak on side B	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A94	21/03/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Fixed and tested.	michele_williams
A4	21/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A99	11/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A4	17/01/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A55	16/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A71	09/05/2015	Maintenance on milling spindle needed	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A14	20/11/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A68	19/09/2015	Turret A and B are leaking	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A51	30/09/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A19	12/07/2015	Turret sections A & B showing leaks	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A83	16/05/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A50	20/03/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A9	03/11/2015	Leaks found at turrets A and B	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A64	04/07/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A73	30/03/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A29	17/02/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A52	12/08/2015	Power supply failure detected	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A42	20/04/2015	Turret sections A & B showing leaks	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A40	02/09/2015	Maintenance on milling spindle needed	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A19	05/11/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A94	04/05/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A51	13/07/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A74	29/11/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A65	05/12/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A97	22/04/2015	Maintenance on milling spindle needed	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A53	27/06/2015	Accumulators need checking and charging	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A39	03/05/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A28	21/05/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A40	01/11/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A56	27/10/2015	Accumulators need checking and charging	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams

A37	07/05/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A85	04/09/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A73	19/08/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A98	16/06/2015	Unit lost electrical power	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A21	02/02/2015	Leaks found at turrets A and B	Michele Williams noted: No additional information provided.	michele_williams
A47	11/06/2015	Power supply failure detected	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A62	14/03/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A86	17/02/2015	Turret A and B are leaking	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A69	30/11/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A74	04/05/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A6	29/01/2015	Leak in side B hydraulic line	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A20	19/03/2015	Inspect and recharge accumulators	Michele Williams noted: Repair completed.	michele_williams
A69	09/01/2016	Maintenance on milling spindle needed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A89	21/07/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A98	19/04/2015	Accumulators need checking and charging	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A88	27/11/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A29	12/03/2015	Milling spindle requires repair	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A35	29/10/2015	Power supply failure detected	Michele Williams noted: No further details.	michele_williams
A42	18/07/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A83	13/09/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A90	12/01/2016	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A64	19/12/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A10	19/06/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A13	01/07/2015	Spindle indexing error with overfeed	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A42	30/06/2015	Milling spindle requires repair	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A59	21/08/2015	Machine is unpowered	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A84	09/06/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A9	03/08/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A6	22/02/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A55	24/12/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A67	14/07/2015	Turret sections A & B showing leaks	Cristian Santos noted: Fixed and tested.	cristian_santos
A71	30/10/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A13	03/12/2015	Milling spindle requires repair	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A1	05/11/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Maintenance action successful.	cristian_santos
A18	16/08/2015	Repair work needed on milling spindle	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A43	20/01/2015	Turret sections A & B showing leaks	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A99	14/09/2015	Repair work needed on milling spindle	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A69	31/03/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A68	21/10/2015	Inspect and recharge accumulators	Michele Williams noted: Repair completed.	michele_williams
A10	31/05/2015	Unit lost electrical power	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A64	25/04/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A85	18/10/2015	Turret sections A & B showing leaks	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A91	22/01/2015	Milling spindle requires repair	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A48	10/02/2015	Turret A and B are leaking	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A71	07/03/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A60	27/08/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A21	08/12/2015	Leaks found at turrets A and B	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A60	10/07/2015	Milling spindle requires repair	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A87	15/07/2015	Inspect and recharge accumulators	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A61	25/09/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A95	25/06/2015	Leaks found at turrets A and B	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A76	08/09/2015	Power supply failure detected	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A1	04/09/2015	Inspect and recharge accumulators	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A45	31/08/2015	Accumulators need checking and charging	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A44	13/05/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Fixed and tested.	michele_williams
A73	03/03/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A20	01/06/2015	Turret A and B are leaking	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A28	15/03/2015	Turret A and B are leaking	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A37	17/10/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A30	13/12/2015	Turret A and B are leaking	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A3	22/04/2015	Machine is unpowered	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A88	20/08/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A6	07/08/2015	Inspect and recharge accumulators	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A60	04/12/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A84	18/09/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A62	22/08/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A29	13/08/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A77	10/08/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A68	28/08/2015	Turret sections A & B showing leaks	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A79	22/10/2015	Repair work needed on milling spindle	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams

A43	05/01/2016	Machine is unpowered	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A29	02/07/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Detail not recorded.	michele_williams
A70	07/12/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A6	20/12/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A7	11/05/2015	Accumulator inspection and charging required	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A83	07/10/2015	Inspect and recharge accumulators	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A64	18/04/2015	Milling spindle requires repair	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A16	31/08/2015	Maintenance on milling spindle needed	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A71	02/09/2015	Spindle indexing error with overfeed	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A41	06/04/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A30	22/06/2015	Inspect and recharge accumulators	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A71	26/04/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A97	11/08/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A60	08/12/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A21	26/06/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: No further details.	nathan_maldonado
A31	14/09/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A19	01/09/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A1	07/10/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A60	03/11/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Repair completed.	michele_williams
A15	20/05/2015	Repair work needed on milling spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A11	23/12/2015	Turret A and B are leaking	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A93	05/03/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Fixed and tested.	michele_williams
A75	15/09/2015	Unit lost electrical power	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A70	20/06/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A11	24/04/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A39	20/06/2015	Turret A and B are leaking	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A96	24/12/2015	Accumulators need checking and charging	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A31	03/05/2015	Turret A and B are leaking	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A21	30/04/2015	Hydraulic line leak on side B	Michele Williams noted: Fixed and tested.	michele_williams
A8	06/04/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A35	17/03/2015	Inspect and recharge accumulators	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A15	18/09/2015	Turret A and B are leaking	Cristian Santos noted: No further details.	cristian_santos
A43	03/04/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Repair completed.	cristian_santos
A68	28/07/2015	Leak in side B hydraulic line	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A64	01/02/2015	Maintenance on milling spindle needed	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A3	25/09/2015	Machine is unpowered	Michele Williams noted: Fixed and tested.	michele_williams
A94	13/06/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A43	09/07/2015	Accumulators need checking and charging	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A79	11/07/2015	Turret sections A & B showing leaks	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A52	14/11/2015	Spindle indexing error with overfeed	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A7	20/07/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Detail not recorded.	cristian_santos
A50	01/12/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A46	11/11/2015	Turret A and B are leaking	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A36	09/02/2015	Maintenance on milling spindle needed	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A86	02/02/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A8	13/04/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A43	16/11/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A68	23/05/2015	Power supply failure detected	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A74	09/08/2015	Power supply failure detected	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A67	14/03/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A94	20/07/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A92	03/02/2015	Power supply failure detected	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A47	01/09/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A56	22/03/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A54	28/01/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A51	09/09/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A71	31/12/2015	Power supply failure detected	Cristian Santos noted: No further details.	cristian_santos
A99	31/07/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A42	05/12/2015	Machine is unpowered	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A72	16/01/2015	Repair work needed on milling spindle	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A80	02/02/2015	Repair work needed on milling spindle	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A63	12/05/2015	Accumulator inspection and charging required	Michele Williams noted: No further details.	michele_williams
A77	03/09/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A34	21/06/2015	Milling spindle requires repair	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A48	23/12/2015	Machine is unpowered	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A98	08/06/2015	Hydraulic line leak on side B	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A11	22/03/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: No additional information provided.	michele_williams
A18	11/07/2015	Inspect and recharge accumulators	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A53	12/08/2015	Spindle indexing error with overfeed	Michele Williams noted: No further details.	michele_williams
A32	04/12/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos

A60	10/08/2015	Unit lost electrical power	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A77	12/03/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A36	27/01/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A46	09/07/2015	Machine is unpowered	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A16	04/10/2015	Milling spindle requires repair	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A9	12/09/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A95	13/07/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A44	04/11/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A12	13/07/2015	Turret A and B are leaking	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A37	06/08/2015	Repair work needed on milling spindle	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A40	07/06/2015	Turret sections A & B showing leaks	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A88	15/02/2015	Accumulators need checking and charging	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A27	03/03/2015	Milling spindle requires repair	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A15	10/10/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A50	07/09/2015	Power supply failure detected	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A29	31/05/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A90	25/03/2015	Hydraulic line leak on side B	Michele Williams noted: Detail not recorded.	michele_williams
A44	16/03/2015	Milling spindle requires repair	Nathan Maldonado noted: No further details.	nathan_maldonado
A41	07/06/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A39	04/04/2015	Leak in side B hydraulic line	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A53	16/09/2015	Accumulator inspection and charging required	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A62	17/11/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A43	24/02/2015	Leak in side B hydraulic line	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A30	02/02/2015	Milling spindle requires repair	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A11	14/05/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A35	14/05/2015	Accumulator inspection and charging required	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A64	30/07/2015	Inspect and recharge accumulators	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A87	23/09/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: System checked and accumulators charged.	michele_williams
A24	09/01/2016	Spindle fails to index, overfeeding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A2	30/04/2015	Leak in side B hydraulic line	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A31	08/10/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A82	02/03/2015	Inspect and recharge accumulators	Cristian Santos noted: Maintenance action successful.	cristian_santos
A69	16/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A66	06/08/2015	Unit lost electrical power	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A33	03/01/2016	Accumulators need checking and charging	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A47	26/09/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A43	16/08/2015	Repair work needed on milling spindle	Cristian Santos noted: Fixed and tested.	cristian_santos
A35	30/08/2015	Inspect and recharge accumulators	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A39	20/04/2015	Accumulator inspection and charging required	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A24	02/06/2015	Inspect and recharge accumulators	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A82	15/10/2015	Machine is unpowered	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A41	08/02/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A46	05/12/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A49	04/10/2015	Turret sections A & B showing leaks	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A44	20/04/2015	Inspect and recharge accumulators	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A88	02/12/2015	Unit lost electrical power	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A56	25/03/2015	Spindle indexing error with overfeed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A61	19/07/2015	Maintenance on milling spindle needed	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A55	09/04/2015	Turret sections A & B showing leaks	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A60	03/05/2015	Turret A and B are leaking	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A81	03/04/2015	Machine is unpowered	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A93	03/09/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A43	10/02/2015	Maintenance on milling spindle needed	Cristian Santos noted: Fixed and tested.	cristian_santos
A55	22/09/2015	Inspect and recharge accumulators	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A88	07/03/2015	Milling spindle requires repair	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A63	01/01/2016	Grinding noise from tight gears on saw attachment	Gina Moore noted: No further details.	gina_moore, dylan_miller
A26	03/01/2016	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Repair completed.	michele_williams
A41	24/02/2015	Maintenance on milling spindle needed	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A35	01/04/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A1	23/11/2015	Unit lost electrical power	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A45	04/07/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A5	15/08/2015	Accumulator inspection and charging required	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A65	12/11/2015	Turret sections A & B showing leaks	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A95	14/09/2015	Milling spindle requires repair	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A61	22/04/2015	Machine is unpowered	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A56	10/01/2016	Inspect and recharge accumulators	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A70	23/03/2015	Repair work needed on milling spindle	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A30	08/10/2015	Power supply failure detected	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A87	23/04/2015	Leaks found at turrets A and B	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A10	27/09/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams

A47	24/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A26	15/01/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A20	27/05/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A27	18/08/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A53	07/03/2015	Hydraulic line leak on side B	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A34	23/01/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A75	30/08/2015	Machine is unpowered	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A57	01/07/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A83	26/05/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A99	09/04/2015	Leak in side B hydraulic line	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A23	29/05/2015	Milling spindle requires repair	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A18	12/07/2015	Machine is unpowered	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A91	11/12/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A66	06/08/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A65	04/09/2015	Maintenance on milling spindle needed	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A4	18/09/2015	Accumulators need checking and charging	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A59	06/04/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A54	15/05/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A86	03/10/2015	Accumulator inspection and charging required	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A7	30/12/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A3	18/04/2015	Leaks found at turrets A and B	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A57	13/09/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A98	18/02/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A41	14/12/2015	Leaks found at turrets A and B	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A57	11/05/2015	Repair work needed on milling spindle	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A62	28/12/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A68	27/08/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A45	08/04/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A51	03/03/2015	Turret A and B are leaking	Michele Williams noted: Repair completed.	michele_williams
A31	01/07/2015	Leak in side B hydraulic line	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A24	14/06/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A32	11/05/2015	Accumulator inspection and charging required	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A21	06/11/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A50	10/03/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A78	30/07/2015	Inspect and recharge accumulators	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A11	09/10/2015	Maintenance on milling spindle needed	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A52	12/07/2015	Hydraulic line leak on side B	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A6	05/05/2015	Spindle fails to index, overfeeding	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A2	02/03/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A91	19/08/2015	Inspect and recharge accumulators	Cristian Santos noted: No further details.	cristian_santos
A5	20/04/2015	Spindle fails to index, overfeeding	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A91	05/07/2015	Turret sections A & B showing leaks	Michele Williams noted: Fixed and tested.	michele_williams
A51	01/04/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A85	30/04/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A15	13/05/2015	Spindle indexing error with overfeed	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A61	12/09/2015	Leaks found at turrets A and B	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A36	29/12/2015	Maintenance on milling spindle needed	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A6	16/01/2015	Leaks found at turrets A and B	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A79	11/07/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A78	31/01/2015	Maintenance on milling spindle needed	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A85	29/09/2015	Turret A and B are leaking	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A82	30/03/2015	Power supply failure detected	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A73	10/03/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Maintenance action successful.	cristian_santos
A84	03/11/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A24	05/11/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A82	11/02/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A79	19/03/2015	Turret sections A & B showing leaks	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A48	27/10/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A70	07/02/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A28	12/07/2015	Repair work needed on milling spindle	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A89	01/07/2015	Unit lost electrical power	Michele Williams noted: No additional information provided.	michele_williams
A60	08/07/2015	Leaks found at turrets A and B	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A49	06/07/2015	Hydraulic hose on side B is leaking	Michele Williams noted: System checked and accumulators charged.	michele_williams
A19	17/09/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A47	22/08/2015	Machine is unpowered	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A33	21/12/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A83	08/04/2015	Repair work needed on milling spindle	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A51	31/05/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A89	13/01/2016	Spindle fails to index, overfeeding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A10	15/07/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams

A57	07/02/2015	Maintenance on milling spindle needed	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A13	09/11/2015	Accumulator inspection and charging required	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A48	03/07/2015	Hydraulic line leak on side B	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A18	13/06/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A67	06/10/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A72	11/01/2016	Leaks found at turrets A and B	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A34	11/12/2015	Accumulator inspection and charging required	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A77	21/08/2015	Unit lost electrical power	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A6	11/04/2015	Inspect and recharge accumulators	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A43	02/09/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A53	07/02/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A13	20/03/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A67	30/10/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A95	27/02/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A91	23/11/2015	Accumulators need checking and charging	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A25	08/12/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A52	03/08/2015	Machine is unpowered	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A59	06/12/2015	Accumulators need checking and charging	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A30	22/12/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: System checked and accumulators charged.	michele_williams
A11	14/06/2015	Turret sections A & B showing leaks	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A22	08/12/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A6	27/01/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A90	03/05/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A79	08/10/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A49	07/12/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A78	23/12/2015	Accumulators need checking and charging	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A98	13/01/2016	Spindle fails to index, overfeeding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A84	12/02/2015	Spindle indexing error with overfeed	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A10	25/08/2015	Machine is unpowered	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A77	22/04/2015	Accumulators need checking and charging	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A81	08/06/2015	Accumulators need checking and charging	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A62	07/01/2016	Inspect and recharge accumulators	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A82	05/12/2015	Turret A and B are leaking	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A19	13/02/2015	Spindle indexing error with overfeed	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A12	28/06/2015	Machine is unpowered	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A56	19/07/2015	Accumulators need checking and charging	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A12	03/10/2015	Turret A and B are leaking	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A82	26/01/2015	Leak in side B hydraulic line	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A94	19/01/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A58	14/02/2015	Spindle fails to index, overfeeding	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A50	11/01/2016	Inspect and recharge accumulators	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A98	22/10/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A81	09/11/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A88	19/02/2015	Turret sections A & B showing leaks	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A14	06/04/2015	Turret A and B are leaking	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A47	29/07/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A82	04/04/2015	Turret sections A & B showing leaks	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A46	13/08/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A71	15/06/2015	Turret sections A & B showing leaks	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A83	23/06/2015	Inspect and recharge accumulators	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A50	07/07/2015	Turret sections A & B showing leaks	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A73	09/08/2015	Accumulators need checking and charging	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A74	23/08/2015	Turret A and B are leaking	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A46	26/10/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A48	14/07/2015	Hydraulic line leak on side B	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A34	03/07/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A88	15/06/2015	Unit lost electrical power	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A49	16/09/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A63	04/06/2015	Repair work needed on milling spindle	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A45	05/05/2015	Leaks found at turrets A and B	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A41	12/03/2015	Maintenance on milling spindle needed	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A8	09/06/2015	Maintenance on milling spindle needed	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A69	23/08/2015	Power supply failure detected	Cristian Santos noted: No further details.	cristian_santos
A15	16/07/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A52	02/10/2015	Power supply failure detected	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A10	07/05/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A9	05/12/2015	Spindle indexing error with overfeed	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A72	15/08/2015	Accumulator inspection and charging required	Nathan Maldonado noted: No further details.	nathan_maldonado
A50	20/03/2015	Hydraulic line leak on side B	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A89	28/11/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado

A40	16/10/2015	Leak in side B hydraulic line	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A48	17/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A48	26/04/2015	Machine is unpowered	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A30	20/09/2015	Turret sections A & B showing leaks	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A6	18/11/2015	Milling spindle requires repair	Michele Williams noted: Repair completed.	michele_williams
A62	23/08/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A6	23/12/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A31	06/10/2015	Accumulators need checking and charging	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A17	19/09/2015	Spindle indexing error with overfeed	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A90	12/07/2015	Leak in side B hydraulic line	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A26	02/12/2015	Saw attachment gears are binding and grinding	Michele Williams noted: System checked and accumulators charged.	michele_williams
A92	01/11/2015	Milling spindle requires repair	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A82	15/01/2015	Inspect and recharge accumulators	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A26	30/10/2015	Turret sections A & B showing leaks	Cristian Santos noted: Detail not recorded.	cristian_santos
A66	20/10/2015	Leak in side B hydraulic line	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A16	14/02/2015	Accumulator inspection and charging required	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A12	06/01/2016	Hydraulic line leak on side B	Cristian Santos noted: Repair completed.	cristian_santos
A10	19/10/2015	Accumulator inspection and charging required	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A65	29/09/2015	Maintenance on milling spindle needed	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A62	11/05/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Fixed and tested.	cristian_santos
A30	10/09/2015	Turret sections A & B showing leaks	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A93	01/08/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A10	02/01/2016	Repair work needed on milling spindle	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A34	06/02/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A67	13/07/2015	Milling spindle requires repair	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A1	20/07/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A39	12/10/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A45	19/02/2015	Maintenance on milling spindle needed	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A66	01/09/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A85	06/10/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: No further details.	cristian_santos
A34	18/03/2015	Hydraulic line leak on side B	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A53	10/03/2015	Unit lost electrical power	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A77	20/09/2015	Accumulators need checking and charging	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A4	22/01/2015	Accumulator inspection and charging required	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A80	17/09/2015	Repair work needed on milling spindle	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A72	26/04/2015	Accumulator inspection and charging required	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A95	31/07/2015	Spindle fails to index, overfeeding	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A24	14/02/2015	Machine is unpowered	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A26	23/02/2015	Milling spindle requires repair	Michele Williams noted: Maintenance action successful.	michele_williams
A22	16/06/2015	Maintenance on milling spindle needed	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A47	09/06/2015	Repair work needed on milling spindle	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A80	12/02/2015	Spindle indexing error with overfeed	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A87	12/05/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A54	11/08/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A45	12/04/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A87	01/01/2016	Grinding noise from tight gears on saw attachment	Michele Williams noted: No additional information provided.	michele_williams
A87	09/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A89	07/11/2015	Repair work needed on milling spindle	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A38	28/12/2015	Spindle indexing error with overfeed	Cristian Santos noted: Detail not recorded.	cristian_santos
A98	06/02/2015	Milling spindle requires repair	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A15	16/01/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A63	08/03/2015	Turret A and B are leaking	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A57	15/06/2015	Leak in side B hydraulic line	Michele Williams noted: Repair completed.	michele_williams
A89	29/03/2015	Inspect and recharge accumulators	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A97	26/09/2015	Repair work needed on milling spindle	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A36	28/02/2015	Machine is unpowered	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A38	14/11/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A40	25/07/2015	Power supply failure detected	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A52	27/08/2015	Milling spindle requires repair	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A44	26/07/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A45	13/09/2015	Machine is unpowered	Michele Williams noted: System checked and accumulators charged.	michele_williams
A78	16/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A35	05/03/2015	Turret A and B are leaking	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A90	26/01/2015	Inspect and recharge accumulators	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A37	13/02/2015	Repair work needed on milling spindle	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A81	28/03/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A25	10/04/2015	Machine is unpowered	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A24	30/12/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A51	13/06/2015	Accumulators need checking and charging	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A2	20/06/2015	Machine is unpowered	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado

A96	16/07/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A38	06/08/2015	Spindle indexing error with overfeed	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A14	25/12/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A60	30/06/2015	Inspect and recharge accumulators	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A43	30/01/2015	Turret A and B are leaking	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A15	25/02/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A47	13/10/2015	Accumulators need checking and charging	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A90	06/05/2015	Power supply failure detected	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A12	22/05/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A72	18/11/2015	Unit lost electrical power	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A8	27/12/2015	Milling spindle requires repair	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A78	25/03/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A43	05/07/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A32	19/06/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A84	24/06/2015	Leaks found at turrets A and B	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A53	19/02/2015	Accumulators need checking and charging	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A24	22/08/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A22	21/11/2015	Turret A and B are leaking	Michele Williams noted: No additional information provided.	michele_williams
A89	23/03/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A85	01/05/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A61	15/03/2015	Milling spindle requires repair	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A48	12/03/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A41	23/04/2015	Accumulators need checking and charging	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A57	01/07/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A17	10/12/2015	Unit lost electrical power	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A12	13/07/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A83	19/02/2015	Power supply failure detected	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A87	07/09/2015	Leak in side B hydraulic line	Cristian Santos noted: No additional information provided.	cristian_santos
A64	10/08/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A22	17/06/2015	Milling spindle requires repair	Cristian Santos noted: Detail not recorded.	cristian_santos
A88	03/01/2016	Turret sections A & B showing leaks	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A83	14/09/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A95	22/10/2015	Repair work needed on milling spindle	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A98	29/01/2015	Milling spindle requires repair	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A45	19/04/2015	Power supply failure detected	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A37	31/05/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A2	29/05/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A92	11/08/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A83	30/07/2015	Accumulator inspection and charging required	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A29	26/05/2015	Leaks found at turrets A and B	Gina Moore noted: No further details.	gina_moore, dylan_miller
A44	16/04/2015	Leaks found at turrets A and B	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A86	04/07/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A54	15/02/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A39	08/05/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A35	09/09/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A7	05/05/2015	Milling spindle requires repair	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A35	15/05/2015	Leak in side B hydraulic line	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A95	09/03/2015	Milling spindle requires repair	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A91	23/03/2015	Hydraulic line leak on side B	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A21	03/11/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A87	15/10/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A67	22/11/2015	Maintenance on milling spindle needed	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A32	26/05/2015	Power supply failure detected	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A76	02/10/2015	Accumulator inspection and charging required	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A10	16/03/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A30	01/01/2016	Repair work needed on milling spindle	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A98	29/04/2015	Maintenance on milling spindle needed	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A46	04/05/2015	Machine is unpowered	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A66	25/06/2015	Accumulators need checking and charging	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A71	31/08/2015	Inspect and recharge accumulators	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A77	21/09/2015	Inspect and recharge accumulators	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A26	27/07/2015	Repair work needed on milling spindle	Cristian Santos noted: Repair completed.	cristian_santos
A71	23/02/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A90	13/08/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A6	09/09/2015	Repair work needed on milling spindle	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A21	13/03/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A31	16/06/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A43	18/12/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A29	30/10/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Maintenance action successful.	michele_williams
A78	20/09/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado

A17	25/04/2015	Accumulators need checking and charging	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A93	20/04/2015	Spindle indexing error with overfeed	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A78	06/06/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A23	01/05/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A26	25/02/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A68	31/08/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A30	15/01/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: System checked and accumulators charged.	michele_williams
A59	13/05/2015	Spindle indexing error with overfeed	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A1	12/08/2015	Turret A and B are leaking	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A78	01/03/2015	Spindle indexing error with overfeed	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A24	02/06/2015	Power supply failure detected	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A32	09/05/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A12	14/10/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Detail not recorded.	cristian_santos
A52	30/06/2015	Inspect and recharge accumulators	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A23	15/03/2015	Machine is unpowered	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A28	29/05/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A39	07/09/2015	Power supply failure detected	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A86	03/01/2016	Hydraulic line leak on side B	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A37	02/01/2016	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A75	04/09/2015	Spindle indexing error with overfeed	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A6	15/07/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A45	27/03/2015	Hydraulic line leak on side B	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A2	29/03/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A60	01/02/2015	Spindle indexing error with overfeed	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A34	12/12/2015	Turret A and B are leaking	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A77	10/03/2015	Machine is unpowered	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A34	12/05/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A77	25/05/2015	Turret sections A & B showing leaks	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A68	06/04/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A97	03/11/2015	Machine is unpowered	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A62	24/08/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A21	01/05/2015	Power supply failure detected	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A46	22/10/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A61	29/10/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A44	07/03/2015	Turret A and B are leaking	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A30	07/05/2015	Leak in side B hydraulic line	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A19	27/04/2015	Hydraulic line leak on side B	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A35	11/06/2015	Machine is unpowered	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A39	26/09/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Fixed and tested.	michele_williams
A48	16/05/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A60	24/08/2015	Spindle indexing error with overfeed	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A53	25/06/2015	Accumulator inspection and charging required	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A60	06/08/2015	Unit lost electrical power	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A57	07/02/2015	Accumulators need checking and charging	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A98	25/04/2015	Leak in side B hydraulic line	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A14	20/08/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A13	01/11/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A80	07/09/2015	Spindle indexing error with overfeed	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A83	10/07/2015	Maintenance on milling spindle needed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A63	04/12/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A2	14/08/2015	Spindle indexing error with overfeed	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A31	01/07/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A10	04/01/2016	Turret sections A & B showing leaks	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A27	07/02/2015	Maintenance on milling spindle needed	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A29	04/05/2015	Repair work needed on milling spindle	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A30	12/07/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A50	26/12/2015	Turret A and B are leaking	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A64	20/12/2015	Machine is unpowered	Cristian Santos noted: Repair completed.	cristian_santos
A78	06/02/2015	Turret A and B are leaking	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A57	30/10/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A70	30/12/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A1	19/10/2015	Milling spindle requires repair	Michele Williams noted: System checked and accumulators charged.	michele_williams
A44	04/12/2015	Inspect and recharge accumulators	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A9	10/05/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A53	16/10/2015	Leak in side B hydraulic line	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A60	13/11/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A94	10/09/2015	Turret sections A & B showing leaks	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A17	12/04/2015	Accumulator inspection and charging required	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A25	28/02/2015	Spindle fails to index, overfeeding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A35	09/10/2015	Leak in side B hydraulic line	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams

A74	18/10/2015	Turret sections A & B showing leaks	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A28	31/07/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A43	27/02/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A83	11/11/2015	Leak in side B hydraulic line	Michele Williams noted: No additional information provided.	michele_williams
A70	10/09/2015	Turret A and B are leaking	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A60	08/05/2015	Leak in side B hydraulic line	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A41	01/02/2015	Accumulators need checking and charging	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A96	11/04/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A5	30/08/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A44	16/09/2015	Maintenance on milling spindle needed	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A73	04/02/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A50	14/03/2015	Leaks found at turrets A and B	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A44	04/06/2015	Repair work needed on milling spindle	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A60	16/10/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A22	27/03/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A88	11/10/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Fixed and tested.	michele_williams
A53	19/10/2015	Leaks found at turrets A and B	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A43	21/01/2015	Accumulator inspection and charging required	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A12	27/01/2015	Power supply failure detected	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A30	25/05/2015	Turret A and B are leaking	Cristian Santos noted: Detail not recorded.	cristian_santos
A52	05/04/2015	Maintenance on milling spindle needed	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A91	17/01/2015	Inspect and recharge accumulators	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A21	13/07/2015	Hydraulic line leak on side B	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A72	09/07/2015	Hydraulic line leak on side B	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A77	08/07/2015	Power supply failure detected	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A85	27/09/2015	Spindle indexing error with overfeed	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A3	22/05/2015	Spindle indexing error with overfeed	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A56	05/03/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A61	12/06/2015	Accumulators need checking and charging	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A64	30/07/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A90	09/10/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A26	04/09/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A12	13/05/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A63	13/02/2015	Accumulators need checking and charging	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A27	03/11/2015	Power supply failure detected	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A81	19/10/2015	Spindle indexing error with overfeed	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A27	09/06/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A4	21/04/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: No further details.	cristian_santos
A64	13/02/2015	Turret sections A & B showing leaks	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A67	03/05/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A11	04/03/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A65	06/02/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A74	25/10/2015	Repair work needed on milling spindle	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A49	15/03/2015	Machine is unpowered	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A34	17/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A12	22/03/2015	Leaks found at turrets A and B	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A51	12/10/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A91	20/01/2015	Inspect and recharge accumulators	Michele Williams noted: System checked and accumulators charged.	michele_williams
A34	01/08/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A21	26/10/2015	Hydraulic line leak on side B	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A33	26/04/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Repair completed.	michele_williams
A36	27/09/2015	Leak in side B hydraulic line	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A64	31/03/2015	Machine is unpowered	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A79	10/04/2015	Machine is unpowered	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A19	08/12/2015	Accumulator inspection and charging required	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A5	10/10/2015	Repair work needed on milling spindle	Cristian Santos noted: Fixed and tested.	cristian_santos
A16	27/11/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A59	01/02/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A7	06/01/2016	Hydraulic line leak on side B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A51	29/05/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A34	02/06/2015	Machine is unpowered	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A88	29/05/2015	Hydraulic line leak on side B	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A95	14/12/2015	Spindle fails to index, overfeeding	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A78	03/01/2016	Inspect and recharge accumulators	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A10	25/07/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A67	02/02/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Detail not recorded.	cristian_santos
A14	22/03/2015	Hydraulic line leak on side B	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A74	01/03/2015	Accumulators need checking and charging	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A25	10/06/2015	Leak in side B hydraulic line	Michele Williams noted: Detail not recorded.	michele_williams
A11	06/08/2015	Maintenance on milling spindle needed	Michele Williams noted: Inspection complete; no issues found.	michele_williams

A55	23/11/2015	Leak in side B hydraulic line	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A65	20/11/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A52	17/03/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A86	14/06/2015	Power supply failure detected	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A76	23/01/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A77	09/05/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A64	06/08/2015	Power supply failure detected	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A48	26/10/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A80	13/06/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A50	06/05/2015	Maintenance on milling spindle needed	Gina Moore noted: No further details.	gina_moore, dylan_miller
A85	25/02/2015	Spindle indexing error with overfeed	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A45	16/02/2015	Accumulator inspection and charging required	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A39	27/04/2015	Power supply failure detected	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A76	05/05/2015	Spindle indexing error with overfeed	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A29	10/02/2015	Accumulators need checking and charging	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A44	03/02/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A1	26/01/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A33	16/02/2015	Accumulator inspection and charging required	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A38	30/11/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A65	16/04/2015	Power supply failure detected	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A86	12/02/2015	Accumulators need checking and charging	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A12	07/11/2015	Maintenance on milling spindle needed	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A1	02/03/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A31	08/04/2015	Turret sections A & B showing leaks	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A16	19/03/2015	Turret sections A & B showing leaks	Cristian Santos noted: Maintenance action successful.	cristian_santos
A83	15/04/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A37	01/04/2015	Spindle fails to index, overfeeding	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A19	15/09/2015	Turret A and B are leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A43	19/11/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A65	14/02/2015	Turret A and B are leaking	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A53	14/01/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A19	20/01/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A46	25/12/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A49	10/03/2015	Spindle indexing error with overfeed	Michele Williams noted: Repair completed.	michele_williams
A71	31/12/2015	Inspect and recharge accumulators	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A57	03/01/2016	Leak in side B hydraulic line	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A82	02/02/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A92	14/02/2015	Repair work needed on milling spindle	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A2	27/08/2015	Unit lost electrical power	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A97	28/12/2015	Turret sections A & B showing leaks	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A62	19/12/2015	Turret A and B are leaking	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A90	03/12/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A72	22/06/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A41	03/12/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A30	16/06/2015	Spindle indexing error with overfeed	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A9	21/10/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Repair completed.	michele_williams
A53	11/03/2015	Saw attachment is leaking hydraulics	Gina Moore noted: No further details.	gina_moore, dylan_miller
A76	23/01/2015	Accumulator inspection and charging required	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A12	06/02/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A92	23/07/2015	Unit lost electrical power	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A27	07/02/2015	Turret A and B are leaking	Cristian Santos noted: Repair completed.	cristian_santos
A97	01/10/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A53	16/12/2015	Accumulator inspection and charging required	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A93	02/06/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A87	17/04/2015	Turret A and B are leaking	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A44	19/06/2015	Hydraulic line leak on side B	Cristian Santos noted: No further details.	cristian_santos
A41	12/03/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A6	16/05/2015	Leaks found at turrets A and B	Michele Williams noted: No further details.	michele_williams
A1	24/08/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A14	15/11/2015	Spindle indexing error with overfeed	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A96	27/10/2015	Hydraulic line leak on side B	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A41	05/10/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A88	04/08/2015	Power supply failure detected	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A53	23/07/2015	Leaks found at turrets A and B	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A35	24/11/2015	Milling spindle requires repair	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A24	09/12/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A29	13/01/2016	Hydraulic fluid leak at saw attachment	Cristian Santos noted: No further details.	cristian_santos
A93	23/04/2015	Maintenance on milling spindle needed	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A35	15/05/2015	Turret A and B are leaking	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A38	09/03/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: No further details.	nathan_maldonado

A92	08/03/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A7	08/11/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A76	11/05/2015	Turret sections A & B showing leaks	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A64	27/10/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A99	29/03/2015	Turret sections A & B showing leaks	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A78	10/07/2015	Turret A and B are leaking	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A74	13/02/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A20	06/05/2015	Accumulator inspection and charging required	Michele Williams noted: Maintenance action successful.	michele_williams
A36	08/01/2016	Accumulators need checking and charging	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A67	12/03/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A10	02/10/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A67	13/05/2015	Power supply failure detected	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A47	10/08/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A4	31/07/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: No further details.	nathan_maldonado
A20	30/01/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: No additional information provided.	cristian_santos
A49	16/01/2015	Machine is unpowered	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A55	08/07/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A69	07/11/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: No further details.	nathan_maldonado
A4	12/08/2015	Unit lost electrical power	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A6	02/01/2016	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A27	09/10/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A63	04/09/2015	Unit lost electrical power	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A97	25/09/2015	Accumulators need checking and charging	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A51	19/11/2015	Inspect and recharge accumulators	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A49	21/06/2015	Turret sections A & B showing leaks	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A5	29/01/2015	Accumulator inspection and charging required	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A93	15/09/2015	Milling spindle requires repair	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A99	23/11/2015	Repair work needed on milling spindle	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A11	14/03/2015	Accumulators need checking and charging	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A55	06/01/2016	Leak in side B hydraulic line	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A97	20/10/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A90	12/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A75	15/09/2015	Unit lost electrical power	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A45	03/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A53	03/12/2015	Turret A and B are leaking	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A63	15/12/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A15	13/03/2015	Spindle indexing error with overfeed	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A96	13/03/2015	Maintenance on milling spindle needed	Gina Moore noted: No further details.	gina_moore, dylan_miller
A48	06/02/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A8	08/04/2015	Turret A and B are leaking	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A39	22/03/2015	Turret A and B are leaking	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A79	09/10/2015	Repair work needed on milling spindle	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A23	27/08/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A27	28/08/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A13	09/05/2015	Spindle indexing error with overfeed	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A38	14/05/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A5	06/03/2015	Leaks found at turrets A and B	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A55	04/04/2015	Milling spindle requires repair	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A42	19/06/2015	Spindle fails to index, overfeeding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A62	11/04/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A53	26/12/2015	Repair work needed on milling spindle	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A44	14/05/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A92	07/09/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A74	08/01/2016	Machine is unpowered	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A27	24/11/2015	Repair work needed on milling spindle	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A48	01/05/2015	Milling spindle requires repair	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A33	01/05/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A57	24/03/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A22	24/11/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A54	17/11/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A27	27/08/2015	Turret sections A & B showing leaks	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A2	06/02/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A18	14/10/2015	Unit lost electrical power	Nathan Maldonado noted: No further details.	nathan_maldonado
A28	31/07/2015	Leaks found at turrets A and B	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A81	11/10/2015	Accumulators need checking and charging	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A73	21/07/2015	Hydraulic line leak on side B	Michele Williams noted: No further details.	michele_williams
A20	01/08/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A95	13/11/2015	Unit lost electrical power	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A1	08/01/2016	Maintenance on milling spindle needed	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A77	28/12/2015	Turret sections A & B showing leaks	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams

A34	02/01/2016	Leak in side B hydraulic line	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A96	19/12/2015	Hydraulic line leak on side B	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A62	11/07/2015	Hydraulic line leak on side B	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A14	29/10/2015	Accumulators need checking and charging	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A42	09/11/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A41	06/12/2015	Spindle indexing error with overfeed	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A60	17/06/2015	Turret A and B are leaking	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A63	27/02/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A14	24/12/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A62	28/02/2015	Turret A and B are leaking	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A55	04/01/2016	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A79	14/12/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A88	02/10/2015	Power supply failure detected	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A94	08/02/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A94	23/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Maintenance action successful.	michele_williams
A54	10/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A69	27/06/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A25	28/03/2015	Machine is unpowered	Michele Williams noted: Maintenance action successful.	michele_williams
A92	10/12/2015	Hydraulic line leak on side B	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A16	04/08/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A46	30/05/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A57	07/07/2015	Accumulator inspection and charging required	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A33	12/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A82	27/10/2015	Turret A and B are leaking	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A27	27/05/2015	Unit lost electrical power	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A89	13/12/2015	Turret sections A & B showing leaks	Cristian Santos noted: Fixed and tested.	cristian_santos
A50	23/06/2015	Maintenance on milling spindle needed	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A16	14/07/2015	Hydraulic line leak on side B	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A6	17/11/2015	Turret A and B are leaking	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A75	15/08/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A3	17/07/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A29	20/09/2015	Spindle indexing error with overfeed	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A43	21/04/2015	Repair work needed on milling spindle	Michele Williams noted: System checked and accumulators charged.	michele_williams
A58	07/09/2015	Turret sections A & B showing leaks	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A36	17/10/2015	Unit lost electrical power	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A86	17/02/2015	Turret sections A & B showing leaks	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A29	23/08/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A75	03/06/2015	Spindle indexing error with overfeed	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A80	19/08/2015	Spindle indexing error with overfeed	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A89	14/05/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A14	06/10/2015	Accumulator inspection and charging required	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A13	21/07/2015	Hydraulic line leak on side B	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A83	30/08/2015	Turret A and B are leaking	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A5	20/06/2015	Maintenance on milling spindle needed	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A33	16/02/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A82	12/02/2015	Accumulators need checking and charging	Cristian Santos noted: Detail not recorded.	cristian_santos
A10	02/03/2015	Unit lost electrical power	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A93	30/06/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A12	24/06/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A82	25/08/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A11	11/10/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A71	30/10/2015	Repair work needed on milling spindle	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A49	17/08/2015	Maintenance on milling spindle needed	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A68	16/04/2015	Accumulators need checking and charging	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A46	16/08/2015	Repair work needed on milling spindle	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A73	27/07/2015	Accumulators need checking and charging	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A51	03/08/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A14	14/12/2015	Turret sections A & B showing leaks	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A59	03/12/2015	Inspect and recharge accumulators	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A90	29/01/2015	Hydraulic hose on side B is leaking	Gina Moore noted: No further details.	gina_moore, dylan_miller
A97	10/10/2015	Power supply failure detected	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A73	13/10/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A95	02/08/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A20	27/05/2015	Accumulator inspection and charging required	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A34	04/09/2015	Repair work needed on milling spindle	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A46	04/11/2015	Inspect and recharge accumulators	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A37	29/05/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A73	25/02/2015	Maintenance on milling spindle needed	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A94	22/07/2015	Spindle indexing error with overfeed	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A16	29/04/2015	Turret A and B are leaking	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams

A69	26/05/2015	Unit lost electrical power	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A37	13/06/2015	Machine is unpowered	Michele Williams noted: Maintenance action successful.	michele_williams
A59	13/09/2015	Turret A and B are leaking	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A30	12/08/2015	Accumulator inspection and charging required	Cristian Santos noted: Maintenance action successful.	cristian_santos
A86	25/05/2015	Spindle indexing error with overfeed	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A1	01/02/2015	Milling spindle requires repair	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A41	06/04/2015	Turret sections A & B showing leaks	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A53	12/07/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A36	04/11/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A13	20/11/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A25	01/10/2015	Turret sections A & B showing leaks	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A58	05/10/2015	Milling spindle requires repair	Nathan Maldonado noted: No further details.	nathan_maldonado
A19	13/02/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A13	27/01/2015	Maintenance on milling spindle needed	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A82	27/12/2015	Unit lost electrical power	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A70	23/12/2015	Turret A and B are leaking	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A10	12/04/2015	Unit lost electrical power	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A30	23/07/2015	Turret sections A & B showing leaks	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A15	30/10/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A97	08/02/2015	Turret sections A & B showing leaks	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A61	18/04/2015	Power supply failure detected	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A91	04/02/2015	Milling spindle requires repair	Michele Williams noted: Maintenance action successful.	michele_williams
A99	14/08/2015	Unit lost electrical power	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A37	16/01/2015	Inspect and recharge accumulators	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A76	19/10/2015	Spindle indexing error with overfeed	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A82	28/12/2015	Turret sections A & B showing leaks	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A89	26/03/2015	Milling spindle requires repair	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A59	18/02/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A11	17/03/2015	Power supply failure detected	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A45	23/12/2015	Accumulators need checking and charging	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A62	16/07/2015	Leak in side B hydraulic line	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A69	14/04/2015	Accumulators need checking and charging	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A48	02/06/2015	Hydraulic line leak on side B	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A37	16/05/2015	Hydraulic line leak on side B	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A72	16/05/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A45	29/05/2015	Turret sections A & B showing leaks	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A97	06/07/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Fixed and tested.	michele_williams
A50	06/08/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A36	19/05/2015	Inspect and recharge accumulators	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A67	01/07/2015	Accumulator inspection and charging required	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A22	30/03/2015	Hydraulic line leak on side B	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A75	07/06/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A39	07/05/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A1	12/03/2015	Unit lost electrical power	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A50	23/04/2015	Machine is unpowered	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A84	01/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A22	08/01/2016	Turret A and B are leaking	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A65	29/09/2015	Machine is unpowered	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A18	21/12/2015	Turret sections A & B showing leaks	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A44	05/05/2015	Turret sections A & B showing leaks	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A60	08/07/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A12	06/10/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A23	08/06/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A47	19/12/2015	Unit lost electrical power	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A92	29/07/2015	Repair work needed on milling spindle	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A7	30/05/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A76	12/09/2015	Milling spindle requires repair	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A41	01/10/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A34	08/10/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A2	05/12/2015	Spindle fails to index, overfeeding	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A59	09/08/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A77	28/02/2015	Spindle indexing error with overfeed	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A66	11/12/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A43	26/04/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A80	23/08/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A20	20/10/2015	Accumulator inspection and charging required	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A86	24/11/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A26	24/10/2015	Turret A and B are leaking	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A71	10/04/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A76	08/09/2015	Leak in side B hydraulic line	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller

A9	24/05/2015	Saw attachment gears are binding and grinding	Michele Williams noted: System checked and accumulators charged.	michele_williams
A93	27/10/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A27	14/11/2015	Turret A and B are leaking	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A77	28/11/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: No additional information provided.	michele_williams
A75	18/12/2015	Spindle indexing error with overfeed	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A9	13/05/2015	Leak in side B hydraulic line	Michele Williams noted: Repair completed.	michele_williams
A49	09/09/2015	Spindle fails to index, overfeeding	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A57	11/02/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A24	11/01/2016	Leak in side B hydraulic line	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A24	28/12/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A48	16/07/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A38	19/07/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A25	13/09/2015	Milling spindle requires repair	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A41	18/08/2015	Leak in side B hydraulic line	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A97	09/12/2015	Leaks found at turrets A and B	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A27	28/11/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A95	16/07/2015	Turret sections A & B showing leaks	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A15	18/12/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A91	03/12/2015	Unit lost electrical power	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A3	01/07/2015	Hydraulic line leak on side B	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A3	24/04/2015	Spindle indexing error with overfeed	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A44	08/10/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A10	29/05/2015	Leaks found at turrets A and B	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A63	14/08/2015	Turret sections A & B showing leaks	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A91	18/03/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A88	31/08/2015	Accumulators need checking and charging	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A90	13/01/2016	Saw attachment is leaking hydraulics	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A56	15/04/2015	Maintenance on milling spindle needed	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A78	13/02/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A28	23/04/2015	Maintenance on milling spindle needed	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A27	22/07/2015	Leak in side B hydraulic line	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A64	11/02/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A81	02/02/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A16	18/03/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: No further details.	cristian_santos
A66	25/09/2015	Repair work needed on milling spindle	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A71	22/01/2015	Repair work needed on milling spindle	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A34	27/05/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A57	10/01/2016	Unit lost electrical power	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A98	24/12/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A78	16/11/2015	Accumulator inspection and charging required	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A88	22/06/2015	Accumulators need checking and charging	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A26	23/08/2015	Accumulators need checking and charging	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A32	19/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A89	23/12/2015	Accumulator inspection and charging required	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A35	11/02/2015	Turret A and B are leaking	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A76	17/07/2015	Milling spindle requires repair	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A43	13/06/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A47	03/01/2016	Turret sections A & B showing leaks	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A2	25/07/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A44	09/04/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A83	11/06/2015	Inspect and recharge accumulators	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A87	08/05/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Maintenance action successful.	michele_williams
A15	14/01/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A32	04/04/2015	Hydraulic line leak on side B	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A85	10/03/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Fixed and tested.	cristian_santos
A2	21/05/2015	Spindle indexing error with overfeed	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A91	24/05/2015	Hydraulic hose on side B is leaking	Gina Moore noted: No further details.	gina_moore, dylan_miller
A30	08/06/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A47	05/08/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A59	08/01/2016	Repair work needed on milling spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A89	20/06/2015	Power supply failure detected	Michele Williams noted: Detail not recorded.	michele_williams
A91	27/11/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A14	30/10/2015	Leak in side B hydraulic line	Michele Williams noted: Fixed and tested.	michele_williams
A98	22/08/2015	Turret A and B are leaking	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A79	07/09/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A99	28/12/2015	Leak in side B hydraulic line	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A32	18/08/2015	Turret sections A & B showing leaks	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A20	22/12/2015	Repair work needed on milling spindle	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A67	05/11/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A82	03/05/2015	Repair work needed on milling spindle	Ethan Adams noted: No further details.	ethan_adams, michele_williams

A38	07/11/2015	Hydraulic line leak on side B	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A46	08/03/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A71	31/05/2015	Inspect and recharge accumulators	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A54	07/04/2015	Power supply failure detected	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A22	19/10/2015	Inspect and recharge accumulators	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A88	28/02/2015	Spindle fails to index, overfeeding	Cristian Santos noted: No additional information provided.	cristian_santos
A77	28/02/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A46	07/01/2016	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A62	31/03/2015	Machine is unpowered	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A54	03/02/2015	Maintenance on milling spindle needed	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A63	06/11/2015	Turret sections A & B showing leaks	Gina Moore noted: No further details.	gina_moore, dylan_miller
A65	07/11/2015	Accumulators need checking and charging	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A7	01/06/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A66	06/06/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A98	01/06/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A33	07/04/2015	Machine is unpowered	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A42	07/09/2015	Power supply failure detected	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A51	11/10/2015	Machine is unpowered	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A86	18/06/2015	Leaks found at turrets A and B	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A87	25/06/2015	Milling spindle requires repair	Cristian Santos noted: Detail not recorded.	cristian_santos
A27	05/07/2015	Hydraulic line leak on side B	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A43	20/03/2015	Maintenance on milling spindle needed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A76	03/02/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A77	02/12/2015	Unit lost electrical power	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A39	04/02/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A47	28/12/2015	Repair work needed on milling spindle	Cristian Santos noted: Fixed and tested.	cristian_santos
A66	11/04/2015	Unit lost electrical power	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A92	04/08/2015	Spindle indexing error with overfeed	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A36	17/10/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A95	08/03/2015	Turret sections A & B showing leaks	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A18	10/12/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A48	19/06/2015	Accumulator inspection and charging required	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A66	22/11/2015	Turret sections A & B showing leaks	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A74	12/12/2015	Hydraulic line leak on side B	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A55	11/11/2015	Turret sections A & B showing leaks	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A29	13/03/2015	Spindle fails to index, overfeeding	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A65	20/01/2015	Unit lost electrical power	Gina Moore noted: No further details.	gina_moore, dylan_miller
A98	06/06/2015	Turret A and B are leaking	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A4	12/12/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A84	24/02/2015	Leaks found at turrets A and B	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A24	12/07/2015	Turret sections A & B showing leaks	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A27	11/02/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A38	23/12/2015	Power supply failure detected	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A85	17/11/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Repair completed.	cristian_santos
A43	30/12/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A68	16/01/2015	Repair work needed on milling spindle	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A30	06/02/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A71	06/02/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Fixed and tested.	michele_williams
A78	13/01/2016	Milling spindle requires repair	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A23	01/02/2015	Turret A and B are leaking	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A47	26/09/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A47	19/05/2015	Power supply failure detected	Nathan Maldonado noted: No further details.	nathan_maldonado
A25	28/01/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A75	27/05/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A44	14/05/2015	Unit lost electrical power	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A17	17/02/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A38	09/06/2015	Maintenance on milling spindle needed	Michele Williams noted: Detail not recorded.	michele_williams
A4	20/11/2015	Accumulators need checking and charging	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A93	07/01/2016	Leaks found at turrets A and B	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A53	12/03/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A54	13/02/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A76	18/05/2015	Spindle indexing error with overfeed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A1	16/11/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A32	04/08/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A21	11/06/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A81	18/09/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A95	19/05/2015	Machine is unpowered	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A90	29/04/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A23	01/06/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A61	04/06/2015	Repair work needed on milling spindle	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos

A84	17/01/2015	Turret A and B are leaking	Michele Williams noted: Repair completed.	michele_williams
A96	04/08/2015	Machine is unpowered	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A64	20/12/2015	Leak in side B hydraulic line	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A2	04/12/2015	Power supply failure detected	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A21	26/06/2015	Hydraulic line leak on side B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A60	12/04/2015	Turret sections A & B showing leaks	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A16	26/05/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A52	01/01/2016	Hydraulic hose on side B is leaking	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A73	15/03/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A92	01/05/2015	Unit lost electrical power	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A45	18/09/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A33	27/08/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A83	18/02/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A50	05/06/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A28	19/03/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A92	24/06/2015	Turret A and B are leaking	Michele Williams noted: System checked and accumulators charged.	michele_williams
A53	18/04/2015	Power supply failure detected	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A78	30/05/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A32	26/04/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A84	29/07/2015	Milling spindle requires repair	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A69	23/05/2015	Unit lost electrical power	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A90	12/08/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A56	01/05/2015	Maintenance on milling spindle needed	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A89	14/08/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A60	11/05/2015	Hydraulic line leak on side B	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A87	04/07/2015	Spindle indexing error with overfeed	Cristian Santos noted: No further details.	cristian_santos
A88	14/06/2015	Turret sections A & B showing leaks	Michele Williams noted: Fixed and tested.	michele_williams
A85	04/03/2015	Spindle indexing error with overfeed	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A56	29/06/2015	Maintenance on milling spindle needed	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A54	04/09/2015	Unit lost electrical power	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A83	13/07/2015	Spindle indexing error with overfeed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A90	05/06/2015	Turret A and B are leaking	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A8	25/04/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A60	19/12/2015	Unit lost electrical power	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A89	20/12/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A63	29/04/2015	Spindle indexing error with overfeed	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A28	04/06/2015	Leaks found at turrets A and B	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A48	01/10/2015	Power supply failure detected	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A31	11/06/2015	Machine is unpowered	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A97	30/08/2015	Inspect and recharge accumulators	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A96	27/04/2015	Power supply failure detected	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A44	06/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A83	17/07/2015	Machine is unpowered	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A58	16/11/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A30	14/06/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A64	26/04/2015	Turret sections A & B showing leaks	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A28	23/10/2015	Milling spindle requires repair	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A13	27/01/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A90	15/07/2015	Leaks found at turrets A and B	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A43	18/05/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A71	28/07/2015	Accumulator inspection and charging required	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A45	13/09/2015	Power supply failure detected	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A97	16/11/2015	Leak in side B hydraulic line	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A97	06/03/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A23	23/02/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A12	02/12/2015	Leak in side B hydraulic line	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A8	20/03/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A62	23/07/2015	Machine is unpowered	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A84	03/12/2015	Spindle indexing error with overfeed	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A43	19/05/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A6	22/02/2015	Accumulator inspection and charging required	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A68	22/07/2015	Spindle fails to index, overfeeding	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A62	12/01/2016	Inspect and recharge accumulators	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A7	06/06/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A20	31/08/2015	Spindle indexing error with overfeed	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A92	05/02/2015	Accumulator inspection and charging required	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A86	28/01/2015	Spindle indexing error with overfeed	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A85	30/11/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A80	28/10/2015	Power supply failure detected	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A37	24/03/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado

A15	29/05/2015	Accumulators need checking and charging	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A36	26/06/2015	Hydraulic line leak on side B	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A45	29/09/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A18	02/02/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A3	23/08/2015	Spindle indexing error with overfeed	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A34	09/03/2015	Hydraulic line leak on side B	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A46	29/09/2015	Accumulator inspection and charging required	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A66	20/03/2015	Milling spindle requires repair	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A64	28/07/2015	Turret sections A & B showing leaks	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A15	12/11/2015	Inspect and recharge accumulators	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A29	16/04/2015	Leaks found at turrets A and B	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A57	07/09/2015	Leak in side B hydraulic line	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A81	15/09/2015	Leaks found at turrets A and B	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A19	25/10/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A14	11/11/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A28	29/09/2015	Leak in side B hydraulic line	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A34	13/10/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Maintenance action successful.	michele_williams
A85	08/02/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Detail not recorded.	cristian_santos
A58	13/08/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A32	25/12/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A65	31/03/2015	Machine is unpowered	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A66	27/11/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A15	17/04/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A86	27/10/2015	Repair work needed on milling spindle	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A5	10/02/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A50	19/06/2015	Accumulator inspection and charging required	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A36	20/04/2015	Unit lost electrical power	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A33	13/02/2015	Accumulators need checking and charging	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A20	03/09/2015	Spindle indexing error with overfeed	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A89	29/05/2015	Turret sections A & B showing leaks	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A77	08/02/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A37	13/12/2015	Milling spindle requires repair	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A90	26/01/2015	Leak in side B hydraulic line	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A92	05/05/2015	Spindle indexing error with overfeed	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A29	17/06/2015	Milling spindle requires repair	Michele Williams noted: Detail not recorded.	michele_williams
A88	11/02/2015	Milling spindle requires repair	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A40	27/02/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A25	24/11/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A95	28/06/2015	Milling spindle requires repair	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A24	19/07/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A20	09/10/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A81	03/06/2015	Accumulator inspection and charging required	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A92	30/03/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A81	30/10/2015	Spindle fails to index, overfeeding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A30	14/05/2015	Spindle fails to index, overfeeding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A82	23/02/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: No further details.	cristian_santos
A36	16/02/2015	Repair work needed on milling spindle	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A22	16/02/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A23	17/06/2015	Repair work needed on milling spindle	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A12	28/11/2015	Leak in side B hydraulic line	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A50	16/12/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A38	06/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A25	14/07/2015	Hydraulic line leak on side B	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A93	04/09/2015	Unit lost electrical power	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A48	04/07/2015	Power supply failure detected	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A8	17/04/2015	Accumulator inspection and charging required	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A46	15/10/2015	Leak in side B hydraulic line	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A79	12/07/2015	Spindle indexing error with overfeed	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A19	24/03/2015	Leak in side B hydraulic line	Cristian Santos noted: No additional information provided.	cristian_santos
A44	12/06/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A49	09/04/2015	Turret sections A & B showing leaks	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A21	02/06/2015	Power supply failure detected	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A99	28/10/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A68	16/10/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A71	24/08/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A69	01/01/2016	Repair work needed on milling spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A18	11/08/2015	Accumulators need checking and charging	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A45	03/07/2015	Accumulator inspection and charging required	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A68	01/09/2015	Accumulator inspection and charging required	Cristian Santos noted: No additional information provided.	cristian_santos
A83	17/04/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller

A31	16/02/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A18	03/04/2015	Leak in side B hydraulic line	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A52	25/07/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A38	15/04/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A22	18/08/2015	Milling spindle requires repair	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A5	19/01/2015	Leak in side B hydraulic line	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A66	27/04/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A31	13/08/2015	Machine is unpowered	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A30	29/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A81	22/12/2015	Hydraulic line leak on side B	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A54	17/04/2015	Repair work needed on milling spindle	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A8	08/07/2015	Maintenance on milling spindle needed	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A96	22/03/2015	Turret sections A & B showing leaks	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A11	26/06/2015	Hydraulic line leak on side B	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A8	16/03/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A55	22/07/2015	Milling spindle requires repair	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A46	21/10/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A26	30/11/2015	Saw attachment is leaking hydraulics	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A88	25/06/2015	Leaks found at turrets A and B	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A70	26/09/2015	Hydraulic hose on side B is leaking	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A96	20/10/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A9	17/03/2015	Milling spindle requires repair	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A38	22/02/2015	Accumulator inspection and charging required	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A30	10/11/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A17	26/04/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A25	13/04/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A66	17/10/2015	Machine is unpowered	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A56	08/10/2015	Milling spindle requires repair	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A21	06/04/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A25	27/04/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A64	17/03/2015	Turret sections A & B showing leaks	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A63	29/10/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A92	23/06/2015	Machine is unpowered	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A83	19/03/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A36	06/05/2015	Unit lost electrical power	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A90	30/05/2015	Accumulator inspection and charging required	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A78	12/01/2016	Leaks found at turrets A and B	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A28	25/03/2015	Inspect and recharge accumulators	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A13	03/02/2015	Accumulators need checking and charging	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A43	03/09/2015	Maintenance on milling spindle needed	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A39	04/03/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A44	21/06/2015	Maintenance on milling spindle needed	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A72	28/03/2015	Hydraulic line leak on side B	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A62	25/07/2015	Leaks found at turrets A and B	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A36	07/08/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A23	09/04/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A99	15/12/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A23	19/04/2015	Milling spindle requires repair	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A23	18/07/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A63	31/12/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A72	16/03/2015	Repair work needed on milling spindle	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A29	27/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A50	14/07/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A83	31/08/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A44	28/11/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A62	05/02/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A80	08/01/2016	Unit lost electrical power	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A93	13/07/2015	Maintenance on milling spindle needed	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A97	22/07/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A77	05/05/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: No further details.	cristian_santos
A84	03/02/2015	Spindle fails to index, overfeeding	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A57	22/12/2015	Accumulators need checking and charging	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A30	24/09/2015	Spindle indexing error with overfeed	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A77	10/09/2015	Maintenance on milling spindle needed	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A70	24/09/2015	Milling spindle requires repair	Cristian Santos noted: Fixed and tested.	cristian_santos
A47	24/12/2015	Leak in side B hydraulic line	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A15	07/04/2015	Inspect and recharge accumulators	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A15	10/05/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A53	08/02/2015	Repair work needed on milling spindle	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A2	01/02/2015	Machine is unpowered	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos

A79	17/02/2015	Machine is unpowered	Michele Williams noted: Repair completed.	michele_williams
A57	18/08/2015	Saw attachment gears are binding and grinding	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A81	18/05/2015	Accumulators need checking and charging	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A3	19/08/2015	Spindle indexing error with overfeed	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A23	31/10/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A19	20/06/2015	Hydraulic line leak on side B	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A16	13/11/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A21	20/10/2015	Spindle indexing error with overfeed	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A19	29/06/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A5	08/10/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A28	28/05/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A12	14/09/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A65	08/12/2015	Milling spindle requires repair	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A51	12/03/2015	Turret A and B are leaking	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A39	07/10/2015	Turret sections A & B showing leaks	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A94	03/05/2015	Machine is unpowered	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A52	15/04/2015	Leaks found at turrets A and B	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A77	06/10/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A1	15/07/2015	Repair work needed on milling spindle	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A29	03/03/2015	Accumulator inspection and charging required	Michele Williams noted: Fixed and tested.	michele_williams
A30	19/12/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A5	05/09/2015	Hydraulic line leak on side B	Michele Williams noted: System checked and accumulators charged.	michele_williams
A84	22/01/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A30	30/11/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A16	20/06/2015	Maintenance on milling spindle needed	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A64	03/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A89	04/12/2015	Unit lost electrical power	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A84	10/03/2015	Power supply failure detected	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A26	11/11/2015	Unit lost electrical power	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A17	15/04/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A96	22/07/2015	Accumulator inspection and charging required	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A1	19/01/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A89	26/09/2015	Milling spindle requires repair	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A6	14/10/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A40	07/12/2015	Milling spindle requires repair	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A15	28/06/2015	Unit lost electrical power	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A26	28/06/2015	Accumulator inspection and charging required	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A50	31/10/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A31	13/01/2016	Turret sections A & B showing leaks	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A58	04/11/2015	Leak in side B hydraulic line	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A75	20/06/2015	Turret A and B are leaking	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A46	16/08/2015	Milling spindle requires repair	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A51	24/03/2015	Repair work needed on milling spindle	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A49	09/12/2015	Power supply failure detected	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A95	28/11/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Fixed and tested.	michele_williams
A64	23/12/2015	Maintenance on milling spindle needed	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A92	03/02/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A41	18/09/2015	Machine is unpowered	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A80	28/03/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A76	17/10/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A94	05/08/2015	Milling spindle requires repair	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A2	12/07/2015	Accumulator inspection and charging required	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A21	22/02/2015	Repair work needed on milling spindle	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A26	03/08/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A71	03/06/2015	Unit lost electrical power	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A38	27/07/2015	Hydraulic line leak on side B	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A79	20/09/2015	Machine is unpowered	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A60	07/11/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A47	28/02/2015	Repair work needed on milling spindle	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A70	18/05/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A20	23/10/2015	Leaks found at turrets A and B	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A27	09/08/2015	Turret sections A & B showing leaks	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A85	08/03/2015	Machine is unpowered	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A53	16/07/2015	Power supply failure detected	Cristian Santos noted: Repair completed.	cristian_santos
A4	01/02/2015	Repair work needed on milling spindle	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A15	05/03/2015	Turret A and B are leaking	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A82	25/12/2015	Milling spindle requires repair	Cristian Santos noted: No further details.	cristian_santos
A40	24/03/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A27	24/10/2015	Maintenance on milling spindle needed	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A92	29/07/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams

A40	02/06/2015	Maintenance on milling spindle needed	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A37	12/11/2015	Power supply failure detected	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A49	06/11/2015	Spindle indexing error with overfeed	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A26	15/07/2015	Turret sections A & B showing leaks	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A88	23/04/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A90	16/07/2015	Accumulator inspection and charging required	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A63	11/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A31	18/04/2015	Turret A and B are leaking	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A10	04/05/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A30	19/04/2015	Spindle fails to index, overfeeding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A34	08/07/2015	Hydraulic line leak on side B	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A70	07/09/2015	Maintenance on milling spindle needed	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A49	17/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A70	15/12/2015	Spindle fails to index, overfeeding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A8	28/05/2015	Hydraulic line leak on side B	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A71	13/02/2015	Turret sections A & B showing leaks	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A94	05/07/2015	Leak in side B hydraulic line	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A96	28/03/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A5	20/11/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A53	30/08/2015	Power supply failure detected	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A33	17/01/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A62	30/09/2015	Milling spindle requires repair	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A64	22/12/2015	Spindle fails to index, overfeeding	Cristian Santos noted: No additional information provided.	cristian_santos
A74	17/07/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A16	31/07/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A13	03/08/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A43	03/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A1	09/05/2015	Unit lost electrical power	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A58	03/01/2016	Turret A and B are leaking	Cristian Santos noted: No additional information provided.	cristian_santos
A91	20/02/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A86	03/07/2015	Machine is unpowered	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A56	29/08/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A55	17/09/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A62	09/05/2015	Unit lost electrical power	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A83	21/10/2015	Inspect and recharge accumulators	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A41	21/08/2015	Turret sections A & B showing leaks	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A94	08/02/2015	Repair work needed on milling spindle	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A66	05/09/2015	Leak in side B hydraulic line	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A93	19/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: No further details.	nathan_maldonado
A87	09/01/2016	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A25	08/02/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A59	05/01/2016	Hydraulic line leak on side B	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A89	08/02/2015	Power supply failure detected	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A38	23/10/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A93	14/02/2015	Leak in side B hydraulic line	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A4	22/09/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A40	09/07/2015	Inspect and recharge accumulators	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A57	10/04/2015	Spindle indexing error with overfeed	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A40	08/01/2016	Indexing issue causing overfeed on spindle	Michele Williams noted: No further details.	michele_williams
A63	24/01/2015	Turret A and B are leaking	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A96	22/10/2015	Milling spindle requires repair	Michele Williams noted: Repair completed.	michele_williams
A14	15/12/2015	Spindle fails to index, overfeeding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A43	23/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A45	16/06/2015	Spindle indexing error with overfeed	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A23	02/10/2015	Accumulator inspection and charging required	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A60	25/01/2015	Accumulator inspection and charging required	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A59	08/08/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A37	21/01/2015	Leak in side B hydraulic line	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A35	25/08/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A96	30/09/2015	Hydraulic line leak on side B	Michele Williams noted: Repair completed.	michele_williams
A3	07/06/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A95	02/05/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A64	06/12/2015	Inspect and recharge accumulators	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A97	14/05/2015	Accumulators need checking and charging	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A2	15/03/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A16	22/08/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A97	26/05/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A43	08/10/2015	Turret A and B are leaking	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A26	28/05/2015	Unit lost electrical power	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A32	28/07/2015	Leaks found at turrets A and B	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams

A98	02/12/2015	Spindle indexing error with overfeed	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A71	06/02/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A87	17/05/2015	Unit lost electrical power	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A91	29/11/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A52	04/01/2016	Hydraulic hose on side B is leaking	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A36	16/04/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A39	20/10/2015	Turret sections A & B showing leaks	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A27	29/03/2015	Leaks found at turrets A and B	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A17	19/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A55	01/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A61	15/06/2015	Hydraulic line leak on side B	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A41	30/08/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A53	10/04/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A81	06/03/2015	Power supply failure detected	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A75	24/02/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: No further details.	nathan_maldonado
A32	23/12/2015	Leaks found at turrets A and B	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A72	13/10/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A98	22/11/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A35	08/01/2016	Power supply failure detected	Michele Williams noted: Maintenance action successful.	michele_williams
A38	05/01/2016	Repair work needed on milling spindle	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A40	16/06/2015	Power supply failure detected	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A74	09/06/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A21	20/06/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A51	09/10/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Detail not recorded.	cristian_santos
A64	21/12/2015	Hydraulic line leak on side B	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A75	07/04/2015	Milling spindle requires repair	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A62	22/12/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A13	31/12/2015	Accumulators need checking and charging	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A93	07/05/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A43	20/12/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A49	22/11/2015	Spindle indexing error with overfeed	Michele Williams noted: System checked and accumulators charged.	michele_williams
A78	31/12/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A13	03/03/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A32	21/01/2015	Turret A and B are leaking	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A61	09/01/2016	Spindle fails to index, overfeeding	Michele Williams noted: Detail not recorded.	michele_williams
A65	29/09/2015	Spindle indexing error with overfeed	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A49	04/06/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A96	30/10/2015	Spindle indexing error with overfeed	Michele Williams noted: Detail not recorded.	michele_williams
A63	24/12/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A28	14/09/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A14	06/11/2015	Machine is unpowered	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A6	23/02/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A63	20/10/2015	Turret A and B are leaking	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A10	15/02/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A22	06/10/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Fixed and tested.	michele_williams
A74	24/06/2015	Machine is unpowered	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A38	13/08/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A29	06/04/2015	Hydraulic line leak on side B	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A34	05/04/2015	Leak in side B hydraulic line	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A96	27/02/2015	Turret sections A & B showing leaks	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A5	27/05/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A53	14/12/2015	Machine is unpowered	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A92	09/08/2015	Leaks found at turrets A and B	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A83	05/10/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A75	30/09/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A94	21/04/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A30	21/11/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A77	13/11/2015	Turret A and B are leaking	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A74	08/09/2015	Maintenance on milling spindle needed	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A19	28/09/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A85	30/07/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A43	23/01/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A34	24/09/2015	Turret A and B are leaking	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A46	01/05/2015	Hydraulic line leak on side B	Gina Moore noted: No further details.	gina_moore, dylan_miller
A72	13/09/2015	Spindle indexing error with overfeed	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A76	26/08/2015	Milling spindle requires repair	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A96	17/02/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A88	24/09/2015	Maintenance on milling spindle needed	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A36	24/12/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A9	07/12/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado

A32	23/02/2015	Hydraulic line leak on side B	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A74	03/05/2015	Leaks found at turrets A and B	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A40	28/04/2015	Milling spindle requires repair	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A17	06/07/2015	Power supply failure detected	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A98	02/01/2016	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A64	21/12/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A75	07/07/2015	Leak in side B hydraulic line	Nathan Maldonado noted: No further details.	nathan_maldonado
A61	22/02/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A71	09/09/2015	Unit lost electrical power	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A91	23/03/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A44	16/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A90	30/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A83	24/08/2015	Milling spindle requires repair	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A25	22/12/2015	Turret sections A & B showing leaks	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A81	02/10/2015	Hydraulic line leak on side B	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A6	10/05/2015	Power supply failure detected	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A95	17/11/2015	Repair work needed on milling spindle	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A22	03/07/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A67	06/08/2015	Turret A and B are leaking	Cristian Santos noted: No further details.	cristian_santos
A72	11/12/2015	Accumulators need checking and charging	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A44	05/12/2015	Power supply failure detected	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A8	14/02/2015	Leaks found at turrets A and B	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A55	27/06/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A23	08/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A49	25/02/2015	Turret A and B are leaking	Cristian Santos noted: Detail not recorded.	cristian_santos
A77	10/04/2015	Hydraulic line leak on side B	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A50	03/06/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A6	13/12/2015	Power supply failure detected	Michele Williams noted: Repair completed.	michele_williams
A96	12/10/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A80	15/05/2015	Inspect and recharge accumulators	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A65	25/10/2015	Spindle indexing error with overfeed	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A35	14/01/2015	Repair work needed on milling spindle	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A62	08/04/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A48	02/12/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A81	23/08/2015	Unit lost electrical power	Cristian Santos noted: No additional information provided.	cristian_santos
A12	11/10/2015	Leaks found at turrets A and B	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A6	21/12/2015	Hydraulic line leak on side B	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A41	14/10/2015	Leak in side B hydraulic line	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A31	05/11/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A46	29/03/2015	Accumulator inspection and charging required	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A80	21/11/2015	Turret sections A & B showing leaks	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A86	06/09/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A12	04/12/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A12	01/11/2015	Power supply failure detected	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A83	08/04/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A65	21/07/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A24	31/07/2015	Accumulators need checking and charging	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A8	25/07/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A46	26/11/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A14	22/02/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A32	26/11/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A59	04/05/2015	Accumulators need checking and charging	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A52	12/02/2015	Power supply failure detected	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A60	13/04/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A95	21/01/2015	Turret A and B are leaking	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A96	19/01/2015	Inspect and recharge accumulators	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A30	24/04/2015	Machine is unpowered	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A38	18/04/2015	Repair work needed on milling spindle	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A57	15/05/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A51	25/11/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A69	18/06/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A9	15/02/2015	Spindle fails to index, overfeeding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A24	07/12/2015	Leaks found at turrets A and B	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A79	04/10/2015	Accumulators need checking and charging	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A6	24/03/2015	Milling spindle requires repair	Michele Williams noted: Maintenance action successful.	michele_williams
A55	25/11/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A18	03/05/2015	Repair work needed on milling spindle	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A83	19/02/2015	Turret A and B are leaking	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A64	28/12/2015	Accumulators need checking and charging	Nathan Maldonado noted: No further details.	nathan_maldonado
A70	05/04/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado

A31	30/07/2015	Power supply failure detected	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A55	09/01/2016	Accumulator inspection and charging required	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A91	16/12/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A26	17/02/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Maintenance action successful.	michele_williams
A40	26/10/2015	Turret sections A & B showing leaks	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A82	28/09/2015	Milling spindle requires repair	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A99	20/11/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A75	04/06/2015	Milling spindle requires repair	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A2	15/10/2015	Power supply failure detected	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A82	20/06/2015	Turret sections A & B showing leaks	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A66	06/10/2015	Repair work needed on milling spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A56	24/04/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A65	12/05/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A12	30/08/2015	Accumulators need checking and charging	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A88	19/01/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A93	15/09/2015	Inspect and recharge accumulators	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A59	06/08/2015	Machine is unpowered	Cristian Santos noted: No additional information provided.	cristian_santos
A4	03/08/2015	Repair work needed on milling spindle	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A51	09/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A38	26/01/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A16	20/11/2015	Accumulator inspection and charging required	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A20	12/05/2015	Machine is unpowered	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A17	16/06/2015	Accumulator inspection and charging required	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A85	26/01/2015	Turret A and B are leaking	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A93	29/09/2015	Accumulators need checking and charging	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A60	21/11/2015	Power supply failure detected	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A79	20/08/2015	Milling spindle requires repair	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A90	01/06/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A19	29/09/2015	Turret sections A & B showing leaks	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A59	31/07/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A68	17/06/2015	Repair work needed on milling spindle	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A45	09/03/2015	Inspect and recharge accumulators	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A10	23/03/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A23	09/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A30	18/09/2015	Leaks found at turrets A and B	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A96	12/02/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A79	13/02/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A99	18/11/2015	Inspect and recharge accumulators	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A7	10/12/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A38	21/06/2015	Accumulators need checking and charging	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A4	08/09/2015	Maintenance on milling spindle needed	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A58	16/09/2015	Repair work needed on milling spindle	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A71	09/01/2016	Hydraulic hose on side B is leaking	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A39	06/11/2015	Machine is unpowered	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A16	11/12/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Maintenance action successful.	michele_williams
A28	15/10/2015	Accumulator inspection and charging required	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A64	31/12/2015	Leaks found at turrets A and B	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A77	29/07/2015	Leak in side B hydraulic line	Cristian Santos noted: Detail not recorded.	cristian_santos
A17	16/12/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A11	18/06/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A46	06/02/2015	Spindle indexing error with overfeed	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A20	13/10/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A77	02/01/2016	Leak in side B hydraulic line	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A50	12/11/2015	Power supply failure detected	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A22	11/06/2015	Spindle indexing error with overfeed	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A2	21/08/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A97	06/03/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A71	15/02/2015	Machine is unpowered	Michele Williams noted: System checked and accumulators charged.	michele_williams
A79	28/05/2015	Repair work needed on milling spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A44	27/01/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A57	05/01/2016	Hydraulic hose on side B is leaking	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A43	06/02/2015	Inspect and recharge accumulators	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A81	05/08/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Detail not recorded.	michele_williams
A28	15/12/2015	Power supply failure detected	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A50	04/08/2015	Leaks found at turrets A and B	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A71	09/10/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A68	05/12/2015	Power supply failure detected	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A91	18/09/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A1	17/12/2015	Milling spindle requires repair	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A84	27/12/2015	Milling spindle requires repair	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams

A10	19/10/2015	Unit lost electrical power	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A68	21/05/2015	Spindle fails to index, overfeeding	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A50	15/09/2015	Machine is unpowered	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A68	20/10/2015	Leaks found at turrets A and B	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A40	29/07/2015	Accumulator inspection and charging required	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A88	23/09/2015	Hydraulic line leak on side B	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A75	09/09/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A93	13/10/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A79	06/05/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A53	30/11/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A85	09/11/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A34	14/03/2015	Hydraulic line leak on side B	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A44	09/01/2016	Maintenance on milling spindle needed	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A91	07/06/2015	Leak in side B hydraulic line	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A3	15/09/2015	Spindle indexing error with overfeed	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A23	26/11/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A40	11/06/2015	Machine is unpowered	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A44	22/11/2015	Accumulator inspection and charging required	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A59	15/02/2015	Maintenance on milling spindle needed	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A11	31/08/2015	Power supply failure detected	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A38	09/09/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A82	18/11/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A8	10/09/2015	Leak in side B hydraulic line	Cristian Santos noted: No further details.	cristian_santos
A75	13/06/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A6	11/08/2015	Turret A and B are leaking	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A35	30/08/2015	Power supply failure detected	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A60	11/04/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A58	14/08/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A36	26/05/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A82	10/04/2015	Unit lost electrical power	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A56	28/01/2015	Unit lost electrical power	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A29	01/05/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A30	20/05/2015	Turret sections A & B showing leaks	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A94	15/11/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A81	19/05/2015	Leak in side B hydraulic line	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A59	08/06/2015	Turret sections A & B showing leaks	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A33	08/06/2015	Unit lost electrical power	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A90	16/07/2015	Turret A and B are leaking	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A35	16/05/2015	Turret A and B are leaking	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A45	13/04/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A62	07/03/2015	Inspect and recharge accumulators	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A12	23/06/2015	Spindle fails to index, overfeeding	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A31	29/09/2015	Turret A and B are leaking	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A10	15/11/2015	Leaks found at turrets A and B	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A41	25/08/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A46	15/05/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A1	30/05/2015	Machine is unpowered	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A88	26/08/2015	Spindle indexing error with overfeed	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A39	22/04/2015	Leaks found at turrets A and B	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A34	07/03/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A61	08/12/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A95	31/05/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A53	06/10/2015	Turret sections A & B showing leaks	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A98	03/05/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A75	21/03/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A87	21/08/2015	Accumulator inspection and charging required	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A38	07/12/2015	Power supply failure detected	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A63	14/05/2015	Inspect and recharge accumulators	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A38	07/10/2015	Leaks found at turrets A and B	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A73	30/10/2015	Unit lost electrical power	Michele Williams noted: Repair completed.	michele_williams
A3	12/04/2015	Accumulators need checking and charging	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A75	26/03/2015	Leaks found at turrets A and B	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A65	21/01/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A86	03/03/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A71	18/10/2015	Spindle indexing error with overfeed	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A7	24/07/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A84	15/05/2015	Maintenance on milling spindle needed	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A32	04/01/2016	Hydraulic line leak on side B	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A16	04/10/2015	Repair work needed on milling spindle	Michele Williams noted: Fixed and tested.	michele_williams
A23	04/11/2015	Accumulator inspection and charging required	Cristian Santos noted: Detail not recorded.	cristian_santos

A6	13/02/2015	Power supply failure detected	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A36	03/09/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A3	21/03/2015	Milling spindle requires repair	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A14	06/01/2016	Turret sections A & B showing leaks	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A1	14/09/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A22	09/07/2015	Maintenance on milling spindle needed	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A56	19/08/2015	Maintenance on milling spindle needed	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A85	07/03/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A43	30/04/2015	Turret A and B are leaking	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A49	24/02/2015	Leak in side B hydraulic line	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A16	21/04/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A69	16/10/2015	Hydraulic line leak on side B	Cristian Santos noted: No additional information provided.	cristian_santos
A11	08/01/2016	Unit lost electrical power	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A96	11/12/2015	Leak in side B hydraulic line	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A32	26/06/2015	Hydraulic line leak on side B	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A32	25/02/2015	Leak in side B hydraulic line	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A94	26/01/2015	Spindle fails to index, overfeeding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A33	10/09/2015	Hydraulic line leak on side B	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A92	18/01/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Maintenance action successful.	cristian_santos
A46	06/09/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A27	29/05/2015	Milling spindle requires repair	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A95	25/06/2015	Inspect and recharge accumulators	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A62	26/03/2015	Leaks found at turrets A and B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A59	02/09/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A24	16/07/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A78	30/05/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A11	05/02/2015	Accumulator inspection and charging required	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A76	22/06/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A24	01/10/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A36	03/07/2015	Accumulator inspection and charging required	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A16	26/03/2015	Milling spindle requires repair	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A13	25/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A45	05/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A3	08/06/2015	Leak in side B hydraulic line	Michele Williams noted: System checked and accumulators charged.	michele_williams
A24	22/10/2015	Accumulator inspection and charging required	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A10	05/09/2015	Maintenance on milling spindle needed	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A36	10/08/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A94	02/04/2015	Maintenance on milling spindle needed	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A83	28/07/2015	Leak in side B hydraulic line	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A51	19/05/2015	Unit lost electrical power	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A30	07/02/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A34	30/01/2015	Turret sections A & B showing leaks	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A17	03/07/2015	Leak in side B hydraulic line	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A63	04/12/2015	Unit lost electrical power	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A5	23/02/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A17	27/02/2015	Turret sections A & B showing leaks	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A89	31/12/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A91	25/09/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A29	01/11/2015	Unit lost electrical power	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A6	21/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A21	28/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A65	23/04/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A5	14/08/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A95	30/09/2015	Unit lost electrical power	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A42	04/09/2015	Maintenance on milling spindle needed	Michele Williams noted: Detail not recorded.	michele_williams
A56	03/03/2015	Milling spindle requires repair	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A30	01/01/2016	Inspect and recharge accumulators	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A75	21/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A96	23/10/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A94	07/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A87	22/05/2015	Leak in side B hydraulic line	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A48	07/02/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A3	23/02/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A7	11/03/2015	Milling spindle requires repair	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A35	22/09/2015	Machine is unpowered	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A48	22/02/2015	Milling spindle requires repair	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A74	10/12/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A2	22/08/2015	Turret sections A & B showing leaks	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A46	30/06/2015	Leaks found at turrets A and B	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A56	16/07/2015	Hydraulic line leak on side B	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams

A39	09/08/2015	Accumulators need checking and charging	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A1	13/02/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A45	30/07/2015	Leaks found at turrets A and B	Cristian Santos noted: Maintenance action successful.	cristian_santos
A10	27/03/2015	Turret A and B are leaking	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A79	03/02/2015	Power supply failure detected	Michele Williams noted: Repair completed.	michele_williams
A81	29/08/2015	Accumulator inspection and charging required	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A74	11/01/2016	Power supply failure detected	Cristian Santos noted: Repair completed.	cristian_santos
A45	23/07/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A80	21/04/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A42	20/10/2015	Maintenance on milling spindle needed	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A45	14/09/2015	Inspect and recharge accumulators	Michele Williams noted: Maintenance action successful.	michele_williams
A39	12/05/2015	Power supply failure detected	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A54	27/04/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A4	27/03/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A81	28/11/2015	Unit lost electrical power	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A21	29/07/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A39	21/08/2015	Repair work needed on milling spindle	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A21	18/03/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A29	15/07/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A89	05/03/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A19	09/06/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A24	07/08/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A99	04/07/2015	Repair work needed on milling spindle	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A67	30/10/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A49	09/06/2015	Maintenance on milling spindle needed	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A92	06/08/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A96	15/10/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A93	25/06/2015	Accumulator inspection and charging required	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A86	16/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A64	08/10/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A56	13/04/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A27	11/10/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A73	16/03/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A1	10/11/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A47	11/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A6	11/12/2015	Leaks found at turrets A and B	Cristian Santos noted: No further details.	cristian_santos
A45	20/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A21	25/05/2015	Unit lost electrical power	Michele Williams noted: No additional information provided.	michele_williams
A15	31/03/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A97	04/02/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A10	08/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A21	14/07/2015	Milling spindle requires repair	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A67	12/05/2015	Power supply failure detected	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A26	08/08/2015	Unit lost electrical power	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A10	17/04/2015	Hydraulic line leak on side B	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A59	09/02/2015	Inspect and recharge accumulators	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A57	09/08/2015	Spindle fails to index, overfeeding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A85	30/05/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A82	06/10/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A70	11/11/2015	Turret sections A & B showing leaks	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A74	23/10/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A75	30/05/2015	Accumulators need checking and charging	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A91	17/11/2015	Inspect and recharge accumulators	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A47	10/06/2015	Spindle fails to index, overfeeding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A96	20/08/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A11	29/08/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A47	28/09/2015	Inspect and recharge accumulators	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A54	03/08/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A1	02/07/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A3	30/09/2015	Leak in side B hydraulic line	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A29	23/05/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A27	10/04/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A14	02/08/2015	Power supply failure detected	Michele Williams noted: Maintenance action successful.	michele_williams
A11	01/08/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A18	18/08/2015	Spindle indexing error with overfeed	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A82	08/02/2015	Machine is unpowered	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A85	28/07/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A34	05/11/2015	Hydraulic line leak on side B	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A22	05/01/2016	Accumulator inspection and charging required	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A93	27/12/2015	Unit lost electrical power	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams

A1	17/04/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A1	02/03/2015	Inspect and recharge accumulators	Nathan Maldonado noted: No further details.	nathan_maldonado
A25	23/09/2015	Machine is unpowered	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A80	24/05/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A19	16/02/2015	Unit lost electrical power	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A6	06/05/2015	Turret A and B are leaking	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A28	10/12/2015	Turret A and B are leaking	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A25	23/11/2015	Maintenance on milling spindle needed	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A28	31/01/2015	Machine is unpowered	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A65	01/08/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A17	22/02/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A40	30/10/2015	Unit lost electrical power	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A26	16/08/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A80	28/02/2015	Repair work needed on milling spindle	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A16	18/08/2015	Unit lost electrical power	Michele Williams noted: Fixed and tested.	michele_williams
A78	16/03/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A39	06/01/2016	Saw attachment is leaking hydraulics	Cristian Santos noted: No further details.	cristian_santos
A40	23/12/2015	Inspect and recharge accumulators	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A26	22/02/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A69	22/08/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A41	16/04/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A17	03/10/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A93	23/03/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A63	26/10/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A21	05/02/2015	Turret sections A & B showing leaks	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A25	04/05/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A86	15/11/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A16	18/10/2015	Leak in side B hydraulic line	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A54	31/01/2015	Accumulator inspection and charging required	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A77	26/02/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A72	20/11/2015	Hydraulic line leak on side B	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A68	01/10/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A52	31/12/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A70	22/11/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A58	23/11/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A76	25/06/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A20	11/10/2015	Milling spindle requires repair	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A44	12/12/2015	Accumulator inspection and charging required	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A19	16/12/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A16	03/09/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A11	04/12/2015	Milling spindle requires repair	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A58	23/10/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A59	04/05/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A31	27/07/2015	Maintenance on milling spindle needed	Cristian Santos noted: No additional information provided.	cristian_santos
A44	31/01/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A49	14/09/2015	Leak in side B hydraulic line	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A61	11/01/2016	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A75	29/04/2015	Inspect and recharge accumulators	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A65	10/09/2015	Unit lost electrical power	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A13	25/11/2015	Turret sections A & B showing leaks	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A77	02/04/2015	Turret sections A & B showing leaks	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A8	27/09/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A69	11/12/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A33	18/02/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A21	09/11/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A44	08/03/2015	Milling spindle requires repair	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A90	02/04/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A99	13/08/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A44	20/09/2015	Inspect and recharge accumulators	Cristian Santos noted: Fixed and tested.	cristian_santos
A79	19/02/2015	Power supply failure detected	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A6	07/08/2015	Accumulators need checking and charging	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A72	16/01/2015	Leak in side B hydraulic line	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A36	14/03/2015	Power supply failure detected	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A66	20/07/2015	Spindle fails to index, overfeeding	Michele Williams noted: System checked and accumulators charged.	michele_williams
A42	06/10/2015	Turret A and B are leaking	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A49	18/11/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A46	03/09/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A83	11/12/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A91	02/05/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A42	02/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos

A46	19/05/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A23	20/09/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Detail not recorded.	michele_williams
A54	29/11/2015	Turret sections A & B showing leaks	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A11	21/01/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A56	14/07/2015	Turret A and B are leaking	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A75	03/08/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A24	19/04/2015	Unit lost electrical power	Cristian Santos noted: Detail not recorded.	cristian_santos
A81	29/03/2015	Spindle indexing error with overfeed	Cristian Santos noted: Fixed and tested.	cristian_santos
A72	26/07/2015	Leaks found at turrets A and B	Cristian Santos noted: Repair completed.	cristian_santos
A95	26/08/2015	Unit lost electrical power	Michele Williams noted: Fixed and tested.	michele_williams
A55	12/06/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A62	17/04/2015	Power supply failure detected	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A86	23/03/2015	Milling spindle requires repair	Nathan Maldonado noted: No further details.	nathan_maldonado
A54	16/12/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A55	02/03/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A34	10/07/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A1	20/01/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A6	07/01/2016	Machine is unpowered	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A37	01/11/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A99	15/09/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A29	07/02/2015	Maintenance on milling spindle needed	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A5	28/03/2015	Power supply failure detected	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A95	29/01/2015	Spindle fails to index, overfeeding	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A9	19/03/2015	Accumulators need checking and charging	Gina Moore noted: No further details.	gina_moore, dylan_miller
A87	24/12/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A37	27/10/2015	Spindle indexing error with overfeed	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A9	19/01/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A57	26/09/2015	Turret A and B are leaking	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A5	20/07/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A32	30/03/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A65	08/12/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A90	20/02/2015	Turret sections A & B showing leaks	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A10	09/08/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A53	08/07/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A18	20/10/2015	Repair work needed on milling spindle	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A50	22/09/2015	Leaks found at turrets A and B	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A26	31/01/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A23	04/03/2015	Accumulators need checking and charging	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A84	05/05/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A89	09/02/2015	Maintenance on milling spindle needed	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A47	24/06/2015	Leak in side B hydraulic line	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A1	31/03/2015	Leak in side B hydraulic line	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A32	04/11/2015	Inspect and recharge accumulators	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A75	03/03/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Maintenance action successful.	cristian_santos
A59	10/04/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A50	01/06/2015	Milling spindle requires repair	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A24	14/01/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A46	08/03/2015	Accumulators need checking and charging	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A73	04/05/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A26	17/08/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A73	21/04/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A47	22/05/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A91	17/09/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A15	16/07/2015	Leak in side B hydraulic line	Michele Williams noted: No additional information provided.	michele_williams
A90	14/08/2015	Repair work needed on milling spindle	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A99	03/03/2015	Hydraulic line leak on side B	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A79	20/04/2015	Inspect and recharge accumulators	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A73	22/02/2015	Accumulator inspection and charging required	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A47	15/12/2015	Accumulators need checking and charging	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A74	14/04/2015	Unit lost electrical power	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A15	23/02/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A91	28/02/2015	Spindle fails to index, overfeeding	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A17	23/05/2015	Machine is unpowered	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A45	16/03/2015	Power supply failure detected	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A43	28/01/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A90	13/12/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A57	28/03/2015	Milling spindle requires repair	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A68	06/09/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A96	22/11/2015	Power supply failure detected	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A14	28/12/2015	Hydraulic line leak on side B	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller

A95	28/10/2015	Power supply failure detected	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A39	07/03/2015	Leak in side B hydraulic line	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A24	20/10/2015	Unit lost electrical power	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A32	09/07/2015	Turret A and B are leaking	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A74	13/03/2015	Machine is unpowered	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A50	13/10/2015	Hydraulic line leak on side B	Michele Williams noted: Fixed and tested.	michele_williams
A4	10/09/2015	Inspect and recharge accumulators	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A89	19/04/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A24	11/01/2016	Accumulator inspection and charging required	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A60	30/06/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A93	14/03/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A21	25/10/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A12	10/10/2015	Inspect and recharge accumulators	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A93	02/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A54	04/11/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A86	09/04/2015	Hydraulic line leak on side B	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A89	10/04/2015	Repair work needed on milling spindle	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A73	10/04/2015	Leak in side B hydraulic line	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A37	22/05/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A27	20/11/2015	Maintenance on milling spindle needed	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A45	01/10/2015	Spindle indexing error with overfeed	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A11	08/07/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A81	04/10/2015	Spindle fails to index, overfeeding	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A41	28/10/2015	Repair work needed on milling spindle	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A11	06/09/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A3	30/04/2015	Turret sections A & B showing leaks	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A68	05/05/2015	Repair work needed on milling spindle	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A28	11/08/2015	Turret A and B are leaking	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A86	28/11/2015	Turret A and B are leaking	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A51	18/04/2015	Power supply failure detected	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A56	30/01/2015	Power supply failure detected	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A61	13/09/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A77	25/10/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A87	25/03/2015	Accumulator inspection and charging required	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A57	23/10/2015	Power supply failure detected	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A35	23/07/2015	Milling spindle requires repair	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A41	09/04/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A19	16/12/2015	Unit lost electrical power	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A52	12/05/2015	Maintenance on milling spindle needed	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A34	15/04/2015	Turret sections A & B showing leaks	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A95	08/05/2015	Spindle indexing error with overfeed	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A83	30/09/2015	Leak in side B hydraulic line	Cristian Santos noted: Maintenance action successful.	cristian_santos
A54	22/09/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A2	12/03/2015	Unit lost electrical power	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A43	06/01/2016	Inspect and recharge accumulators	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A14	04/06/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A31	15/11/2015	Turret A and B are leaking	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A80	13/02/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A23	30/06/2015	Power supply failure detected	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A52	05/09/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A83	27/12/2015	Leaks found at turrets A and B	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A55	02/11/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A43	05/06/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A47	27/04/2015	Spindle indexing error with overfeed	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A6	24/01/2015	Maintenance on milling spindle needed	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A64	09/09/2015	Accumulator inspection and charging required	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A13	25/05/2015	Machine is unpowered	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A74	05/02/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: No further details.	nathan_maldonado
A97	02/07/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A17	24/01/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A67	03/03/2015	Spindle indexing error with overfeed	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A72	26/06/2015	Maintenance on milling spindle needed	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A23	17/02/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A99	10/10/2015	Machine is unpowered	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A85	24/01/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A91	06/03/2015	Turret A and B are leaking	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A50	04/05/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A5	03/09/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A47	18/12/2015	Power supply failure detected	Nathan Maldonado noted: No further details.	nathan_maldonado
A97	13/03/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams

A33	01/04/2015	Leaks found at turrets A and B	Gina Moore noted: No further details.	gina_moore, dylan_miller
A65	03/09/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A98	28/08/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A82	24/11/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A3	13/07/2015	Accumulators need checking and charging	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A17	05/08/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A38	20/12/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A39	12/06/2015	Power supply failure detected	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A7	08/11/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A14	12/01/2016	Gears on the saw attachment are too tight and grinding	Michele Williams noted: No further details.	michele_williams
A95	02/03/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A12	01/11/2015	Hydraulic line leak on side B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A55	19/12/2015	Unit lost electrical power	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A7	21/06/2015	Inspect and recharge accumulators	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A87	27/12/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A35	03/03/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Maintenance action successful.	cristian_santos
A43	14/06/2015	Maintenance on milling spindle needed	Michele Williams noted: No further details.	michele_williams
A15	26/07/2015	Hydraulic line leak on side B	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A21	07/04/2015	Spindle indexing error with overfeed	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A13	22/09/2015	Unit lost electrical power	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A75	30/07/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A92	05/09/2015	Power supply failure detected	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A67	12/05/2015	Repair work needed on milling spindle	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A1	24/01/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A47	11/09/2015	Hydraulic line leak on side B	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A24	08/05/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A92	13/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A63	12/03/2015	Inspect and recharge accumulators	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A77	25/09/2015	Leaks found at turrets A and B	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A20	24/04/2015	Accumulator inspection and charging required	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A74	25/07/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A86	26/11/2015	Turret sections A & B showing leaks	Cristian Santos noted: No additional information provided.	cristian_santos
A46	04/01/2016	Saw attachment is leaking hydraulics	Cristian Santos noted: No additional information provided.	cristian_santos
A46	12/03/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A19	11/05/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A7	17/02/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A18	24/09/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A69	02/04/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A79	02/03/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A91	04/01/2016	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A94	13/12/2015	Leaks found at turrets A and B	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A22	04/01/2016	Hydraulic fluid leak at saw attachment	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A34	02/07/2015	Machine is unpowered	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A95	10/10/2015	Milling spindle requires repair	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A73	05/07/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A54	23/01/2015	Maintenance on milling spindle needed	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A79	23/10/2015	Spindle indexing error with overfeed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A43	12/03/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A66	10/04/2015	Milling spindle requires repair	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A18	22/05/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A79	27/03/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A36	24/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A16	18/01/2015	Maintenance on milling spindle needed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A77	05/12/2015	Accumulators need checking and charging	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A77	07/11/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A53	26/12/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A40	06/05/2015	Inspect and recharge accumulators	Michele Williams noted: Repair completed.	michele_williams
A68	25/11/2015	Accumulator inspection and charging required	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A12	04/09/2015	Leak in side B hydraulic line	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A57	25/08/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A12	10/12/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A81	05/10/2015	Accumulators need checking and charging	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A80	06/10/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A82	16/06/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A71	10/05/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Fixed and tested.	cristian_santos
A13	27/07/2015	Milling spindle requires repair	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A73	07/05/2015	Inspect and recharge accumulators	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A49	26/02/2015	Milling spindle requires repair	Michele Williams noted: Maintenance action successful.	michele_williams
A1	18/06/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A28	18/04/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams

A28	30/10/2015	Inspect and recharge accumulators	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A1	10/05/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A6	04/01/2016	Milling spindle requires repair	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A38	08/10/2015	Accumulator inspection and charging required	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A14	30/08/2015	Power supply failure detected	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A84	22/07/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A36	11/03/2015	Turret A and B are leaking	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A43	20/03/2015	Leaks found at turrets A and B	Cristian Santos noted: No additional information provided.	cristian_santos
A15	15/03/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: No additional information provided.	cristian_santos
A11	03/12/2015	Maintenance on milling spindle needed	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A79	23/06/2015	Turret sections A & B showing leaks	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A38	10/03/2015	Milling spindle requires repair	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A28	24/09/2015	Accumulators need checking and charging	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A35	22/09/2015	Unit lost electrical power	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A43	28/02/2015	Unit lost electrical power	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A92	09/12/2015	Spindle fails to index, overfeeding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A37	04/12/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A76	09/01/2016	Indexing issue causing overfeed on spindle	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A19	14/07/2015	Repair work needed on milling spindle	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A63	06/04/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A34	03/08/2015	Power supply failure detected	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A78	31/07/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A13	27/04/2015	Machine is unpowered	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A3	02/09/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A1	18/09/2015	Inspect and recharge accumulators	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A58	05/12/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A24	20/02/2015	Hydraulic line leak on side B	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A29	18/04/2015	Machine is unpowered	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A82	01/07/2015	Leaks found at turrets A and B	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A24	27/05/2015	Turret A and B are leaking	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A16	08/05/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A75	27/09/2015	Accumulator inspection and charging required	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A7	19/10/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A22	13/03/2015	Spindle indexing error with overfeed	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A92	06/03/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A81	15/02/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A26	16/06/2015	Accumulator inspection and charging required	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A18	06/03/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A68	06/08/2015	Leaks found at turrets A and B	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A92	29/10/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A36	02/11/2015	Spindle indexing error with overfeed	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A61	04/05/2015	Accumulators need checking and charging	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A50	11/02/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A13	29/06/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A69	11/02/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A6	12/04/2015	Turret sections A & B showing leaks	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A60	07/05/2015	Hydraulic line leak on side B	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A10	10/08/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A47	21/06/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A65	09/09/2015	Spindle indexing error with overfeed	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A4	15/11/2015	Leak in side B hydraulic line	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A84	08/02/2015	Leak in side B hydraulic line	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A69	15/01/2015	Unit lost electrical power	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A69	12/12/2015	Milling spindle requires repair	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A36	21/11/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A26	24/03/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A43	25/11/2015	Turret sections A & B showing leaks	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A10	28/05/2015	Leak in side B hydraulic line	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A38	21/02/2015	Hydraulic line leak on side B	Gina Moore noted: No further details.	gina_moore, dylan_miller
A14	16/08/2015	Spindle indexing error with overfeed	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A65	24/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A97	23/08/2015	Turret sections A & B showing leaks	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A26	21/12/2015	Milling spindle requires repair	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A25	29/03/2015	Repair work needed on milling spindle	Michele Williams noted: System checked and accumulators charged.	michele_williams
A96	22/08/2015	Leak in side B hydraulic line	Michele Williams noted: Maintenance action successful.	michele_williams
A93	20/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A82	29/07/2015	Turret A and B are leaking	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A10	25/10/2015	Milling spindle requires repair	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A61	06/06/2015	Turret A and B are leaking	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A48	26/06/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams

A37	07/06/2015	Power supply failure detected	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A80	19/12/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A56	03/09/2015	Repair work needed on milling spindle	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A76	10/05/2015	Milling spindle requires repair	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A74	21/05/2015	Spindle indexing error with overfeed	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A49	26/01/2015	Repair work needed on milling spindle	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A69	02/11/2015	Hydraulic line leak on side B	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A16	30/09/2015	Power supply failure detected	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A1	07/12/2015	Turret A and B are leaking	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A41	04/02/2015	Unit lost electrical power	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A36	01/08/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A74	09/10/2015	Milling spindle requires repair	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A16	18/02/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A85	18/08/2015	Maintenance on milling spindle needed	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A26	04/05/2015	Leaks found at turrets A and B	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A8	21/02/2015	Accumulator inspection and charging required	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A4	08/03/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A42	09/09/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A87	26/08/2015	Repair work needed on milling spindle	Cristian Santos noted: Detail not recorded.	cristian_santos
A16	15/03/2015	Machine is unpowered	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A22	25/08/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A70	16/09/2015	Maintenance on milling spindle needed	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A30	26/06/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A77	09/02/2015	Maintenance on milling spindle needed	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A98	06/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A35	18/06/2015	Turret A and B are leaking	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A70	01/10/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A35	15/08/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A66	25/07/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A22	27/10/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A18	25/03/2015	Leak in side B hydraulic line	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A54	13/09/2015	Turret sections A & B showing leaks	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A19	25/11/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A93	08/06/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A8	21/08/2015	Accumulator inspection and charging required	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A96	19/01/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A2	20/07/2015	Milling spindle requires repair	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A10	19/08/2015	Power supply failure detected	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A41	29/12/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A32	22/01/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A45	29/03/2015	Unit lost electrical power	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A83	27/02/2015	Unit lost electrical power	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A82	04/11/2015	Machine is unpowered	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A35	02/01/2016	Spindle indexing error with overfeed	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A57	14/08/2015	Spindle fails to index, overfeeding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A42	20/11/2015	Spindle fails to index, overfeeding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A74	13/08/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A55	13/01/2016	Power supply failure detected	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A43	31/01/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A16	16/09/2015	Repair work needed on milling spindle	Cristian Santos noted: Repair completed.	cristian_santos
A65	23/06/2015	Maintenance on milling spindle needed	Michele Williams noted: Detail not recorded.	michele_williams
A68	10/11/2015	Hydraulic line leak on side B	Michele Williams noted: No additional information provided.	michele_williams
A83	05/02/2015	Leak in side B hydraulic line	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A33	03/10/2015	Turret sections A & B showing leaks	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A10	28/03/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A96	25/05/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A29	06/10/2015	Hydraulic line leak on side B	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A48	26/07/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A94	15/02/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A10	09/02/2015	Turret sections A & B showing leaks	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A19	10/10/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A98	11/06/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A10	31/12/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A49	04/06/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A7	27/12/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A14	09/06/2015	Unit lost electrical power	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A83	12/05/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A25	04/08/2015	Power supply failure detected	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A53	24/07/2015	Turret sections A & B showing leaks	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A55	17/08/2015	Inspect and recharge accumulators	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller

A19	26/11/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Repair completed.	michele_williams
A19	31/05/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A35	19/10/2015	Spindle fails to index, overfeeding	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A18	15/06/2015	Unit lost electrical power	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A93	09/09/2015	Inspect and recharge accumulators	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A43	10/09/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A2	16/02/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A78	28/03/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A25	16/08/2015	Accumulators need checking and charging	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A14	23/07/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A66	27/04/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A32	31/08/2015	Accumulators need checking and charging	Cristian Santos noted: No further details.	cristian_santos
A42	05/03/2015	Accumulators need checking and charging	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A9	16/03/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A92	26/10/2015	Accumulator inspection and charging required	Cristian Santos noted: No further details.	cristian_santos
A13	17/11/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Detail not recorded.	michele_williams
A33	26/06/2015	Repair work needed on milling spindle	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A6	26/11/2015	Leaks found at turrets A and B	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A29	15/08/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Fixed and tested.	michele_williams
A14	01/01/2016	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A81	07/01/2016	Machine is unpowered	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A68	23/08/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A44	05/10/2015	Maintenance on milling spindle needed	Michele Williams noted: Maintenance action successful.	michele_williams
A10	01/05/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A43	22/10/2015	Power supply failure detected	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A25	07/11/2015	Power supply failure detected	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A27	22/07/2015	Machine is unpowered	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A43	18/08/2015	Leak in side B hydraulic line	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A81	16/10/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A30	07/07/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A98	12/04/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A88	24/01/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A58	08/04/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A34	08/01/2016	Hydraulic hose on side B is leaking	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A64	26/05/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A58	25/11/2015	Milling spindle requires repair	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A56	23/02/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A10	17/02/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A24	03/06/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A78	14/12/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A52	14/07/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A79	13/06/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A44	24/08/2015	Machine is unpowered	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A30	15/02/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A84	11/10/2015	Hydraulic line leak on side B	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A98	26/03/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A50	05/05/2015	Leak in side B hydraulic line	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A39	08/01/2016	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A17	26/08/2015	Leak in side B hydraulic line	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A25	12/11/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A63	08/08/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A6	21/08/2015	Accumulators need checking and charging	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A28	24/02/2015	Inspect and recharge accumulators	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A68	16/08/2015	Maintenance on milling spindle needed	Michele Williams noted: No additional information provided.	michele_williams
A59	10/09/2015	Repair work needed on milling spindle	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A32	17/05/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A9	16/06/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Detail not recorded.	cristian_santos
A37	04/01/2016	Saw attachment gears are binding and grinding	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A21	14/08/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A4	26/05/2015	Turret A and B are leaking	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A37	24/10/2015	Machine is unpowered	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A41	21/01/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A74	11/01/2016	Leak in side B hydraulic line	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A61	14/04/2015	Milling spindle requires repair	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A27	25/07/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A8	30/10/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A55	30/08/2015	Maintenance on milling spindle needed	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A47	11/11/2015	Unit lost electrical power	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A59	28/10/2015	Spindle fails to index, overfeeding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A44	23/04/2015	Unit lost electrical power	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams

A77	08/02/2015	Milling spindle requires repair	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A70	02/01/2016	Machine is unpowered	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A66	25/02/2015	Maintenance on milling spindle needed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A3	09/11/2015	Hydraulic line leak on side B	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A62	01/09/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A92	25/02/2015	Machine is unpowered	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A73	08/01/2016	Power supply failure detected	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A86	27/02/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A19	21/10/2015	Power supply failure detected	Gina Moore noted: No further details.	gina_moore, dylan_miller
A61	03/10/2015	Leaks found at turrets A and B	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A7	31/10/2015	Turret sections A & B showing leaks	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A92	31/12/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A65	06/08/2015	Power supply failure detected	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A79	02/11/2015	Maintenance on milling spindle needed	Cristian Santos noted: Repair completed.	cristian_santos
A8	29/11/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A4	08/03/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A40	18/09/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A73	05/06/2015	Power supply failure detected	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A33	08/02/2015	Leak in side B hydraulic line	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A68	20/10/2015	Unit lost electrical power	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A61	09/03/2015	Accumulators need checking and charging	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A14	08/09/2015	Turret A and B are leaking	Cristian Santos noted: Detail not recorded.	cristian_santos
A17	24/12/2015	Accumulator inspection and charging required	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A55	11/06/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A51	24/06/2015	Turret A and B are leaking	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A17	25/03/2015	Spindle indexing error with overfeed	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A27	25/10/2015	Accumulators need checking and charging	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A89	19/01/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A85	28/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A45	31/08/2015	Accumulator inspection and charging required	Michele Williams noted: Fixed and tested.	michele_williams
A5	12/12/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: No further details.	michele_williams
A22	03/02/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A55	17/12/2015	Hydraulic line leak on side B	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A46	13/04/2015	Repair work needed on milling spindle	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A13	25/05/2015	Spindle fails to index, overfeeding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A70	27/02/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A50	12/10/2015	Inspect and recharge accumulators	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A69	15/08/2015	Accumulators need checking and charging	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A84	11/07/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A35	30/05/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A28	27/06/2015	Leaks found at turrets A and B	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A64	31/03/2015	Accumulator inspection and charging required	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A70	23/11/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A14	17/01/2015	Repair work needed on milling spindle	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A33	07/09/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A23	21/04/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A82	11/03/2015	Milling spindle requires repair	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A38	21/09/2015	Leak in side B hydraulic line	Michele Williams noted: No further details.	michele_williams
A56	10/07/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A14	19/07/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A58	10/02/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A17	06/08/2015	Leak in side B hydraulic line	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A96	11/01/2016	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A27	22/03/2015	Turret sections A & B showing leaks	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A39	23/01/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A56	28/09/2015	Leak in side B hydraulic line	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A65	16/09/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A59	07/07/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A85	19/05/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A40	27/05/2015	Power supply failure detected	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A42	11/07/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A19	20/08/2015	Accumulator inspection and charging required	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A23	17/03/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A77	26/04/2015	Accumulators need checking and charging	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A69	09/03/2015	Hydraulic line leak on side B	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A95	01/10/2015	Unit lost electrical power	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A30	19/03/2015	Spindle fails to index, overfeeding	Cristian Santos noted: No additional information provided.	cristian_santos
A67	08/08/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A46	19/07/2015	Turret sections A & B showing leaks	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A63	19/05/2015	Milling spindle requires repair	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams

A39	23/03/2015	Turret sections A & B showing leaks	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A86	27/03/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A28	17/07/2015	Turret A and B are leaking	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A68	13/09/2015	Accumulator inspection and charging required	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A69	10/03/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A60	16/02/2015	Unit lost electrical power	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A17	24/12/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A1	05/06/2015	Power supply failure detected	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A4	08/04/2015	Maintenance on milling spindle needed	Gina Moore noted: No further details.	gina_moore, dylan_miller
A20	14/06/2015	Turret A and B are leaking	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A22	24/11/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: No further details.	michele_williams
A57	19/07/2015	Spindle indexing error with overfeed	Michele Williams noted: Detail not recorded.	michele_williams
A10	09/02/2015	Power supply failure detected	Michele Williams noted: Repair completed.	michele_williams
A13	18/07/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: System checked and accumulators charged.	michele_williams
A3	23/01/2015	Maintenance on milling spindle needed	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A76	23/08/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A64	31/08/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A74	05/03/2015	Leaks found at turrets A and B	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A41	31/07/2015	Machine is unpowered	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A53	28/05/2015	Unit lost electrical power	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A1	25/10/2015	Turret sections A & B showing leaks	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A21	13/02/2015	Milling spindle requires repair	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A73	25/08/2015	Maintenance on milling spindle needed	Michele Williams noted: Fixed and tested.	michele_williams
A92	06/08/2015	Maintenance on milling spindle needed	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A45	20/08/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A87	14/12/2015	Milling spindle requires repair	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A55	13/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A46	28/02/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A35	09/07/2015	Accumulator inspection and charging required	Cristian Santos noted: No additional information provided.	cristian_santos
A30	11/04/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A1	14/03/2015	Leaks found at turrets A and B	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A97	05/10/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A11	21/06/2015	Milling spindle requires repair	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A33	23/12/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A89	23/02/2015	Accumulators need checking and charging	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A39	15/10/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Fixed and tested.	cristian_santos
A25	30/03/2015	Inspect and recharge accumulators	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A64	25/09/2015	Inspect and recharge accumulators	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A70	18/10/2015	Inspect and recharge accumulators	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A68	23/01/2015	Maintenance on milling spindle needed	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A7	17/12/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A34	07/06/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A64	10/07/2015	Leaks found at turrets A and B	Cristian Santos noted: Fixed and tested.	cristian_santos
A29	25/03/2015	Unit lost electrical power	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A18	18/08/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A18	26/06/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A60	16/11/2015	Turret A and B are leaking	Michele Williams noted: No additional information provided.	michele_williams
A88	16/07/2015	Machine is unpowered	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A26	11/10/2015	Spindle indexing error with overfeed	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A66	08/03/2015	Power supply failure detected	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A25	13/05/2015	Spindle fails to index, overfeeding	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A48	11/06/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A38	14/09/2015	Accumulators need checking and charging	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A29	12/03/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A88	08/12/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A98	27/01/2015	Repair work needed on milling spindle	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A67	15/08/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A81	04/12/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A54	22/05/2015	Milling spindle requires repair	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A44	02/04/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A65	26/05/2015	Milling spindle requires repair	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A17	12/02/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A79	15/10/2015	Power supply failure detected	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A20	04/02/2015	Inspect and recharge accumulators	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A36	06/01/2016	Inspect and recharge accumulators	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A36	02/02/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A67	03/12/2015	Turret A and B are leaking	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A58	06/09/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A2	06/04/2015	Turret A and B are leaking	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A35	28/11/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller

A43	09/10/2015	Turret A and B are leaking	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A22	12/05/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A82	21/06/2015	Milling spindle requires repair	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A28	02/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A99	20/12/2015	Turret sections A & B showing leaks	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A82	18/08/2015	Maintenance on milling spindle needed	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A68	02/02/2015	Maintenance on milling spindle needed	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A69	01/10/2015	Accumulator inspection and charging required	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A72	27/06/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A18	10/04/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A62	09/07/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A93	11/01/2016	Leak in side B hydraulic line	Michele Williams noted: No further details.	michele_williams
A93	16/02/2015	Leak in side B hydraulic line	Michele Williams noted: No further details.	michele_williams
A54	15/09/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A1	11/09/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: No further details.	cristian_santos
A43	07/03/2015	Spindle fails to index, overfeeding	Michele Williams noted: Fixed and tested.	michele_williams
A90	25/03/2015	Hydraulic line leak on side B	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A87	25/09/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A27	14/05/2015	Maintenance on milling spindle needed	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A65	04/06/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A6	03/02/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A40	16/04/2015	Leak in side B hydraulic line	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A6	02/08/2015	Leak in side B hydraulic line	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A57	15/01/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A28	01/11/2015	Power supply failure detected	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A8	02/07/2015	Inspect and recharge accumulators	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A26	28/04/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A58	18/12/2015	Hydraulic line leak on side B	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A82	31/05/2015	Unit lost electrical power	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A54	14/09/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A83	12/11/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A42	15/07/2015	Inspect and recharge accumulators	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A17	29/11/2015	Inspect and recharge accumulators	Michele Williams noted: No additional information provided.	michele_williams
A88	22/11/2015	Machine is unpowered	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A15	06/07/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A12	23/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A1	14/02/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A58	30/10/2015	Leak in side B hydraulic line	Cristian Santos noted: No further details.	cristian_santos
A44	18/05/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A50	10/07/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A31	29/12/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: No further details.	michele_williams
A19	01/11/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A16	19/10/2015	Leaks found at turrets A and B	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A15	01/05/2015	Milling spindle requires repair	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A34	15/05/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A2	24/07/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A20	07/12/2015	Spindle fails to index, overfeeding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A8	19/05/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A34	07/11/2015	Spindle fails to index, overfeeding	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A98	12/11/2015	Leak in side B hydraulic line	Cristian Santos noted: No further details.	cristian_santos
A49	14/09/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A58	10/06/2015	Hydraulic line leak on side B	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A21	25/03/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: No further details.	gina_moore, dylan_miller
A62	07/05/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A84	13/10/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Detail not recorded.	cristian_santos
A59	14/01/2015	Hydraulic hose on side B is leaking	Gina Moore noted: No further details.	gina_moore, dylan_miller
A76	09/05/2015	Power supply failure detected	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A37	28/06/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: No further details.	nathan_maldonado
A87	03/09/2015	Spindle indexing error with overfeed	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A13	10/05/2015	Accumulator inspection and charging required	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A37	20/09/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A70	16/02/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A5	14/11/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A91	10/10/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A14	17/09/2015	Accumulator inspection and charging required	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A45	15/05/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A46	30/03/2015	Accumulators need checking and charging	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A43	27/02/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A43	05/09/2015	Leak in side B hydraulic line	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A94	27/09/2015	Hydraulic line leak on side B	Michele Williams noted: Inspection complete; no issues found.	michele_williams

A2	13/05/2015	Hydraulic line leak on side B	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A21	24/05/2015	Inspect and recharge accumulators	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A98	24/08/2015	Inspect and recharge accumulators	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A36	09/01/2016	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A59	26/07/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A68	19/07/2015	Turret A and B are leaking	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A12	29/12/2015	Repair work needed on milling spindle	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A82	24/04/2015	Inspect and recharge accumulators	Cristian Santos noted: Maintenance action successful.	cristian_santos
A43	09/10/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A57	19/02/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A79	16/11/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A66	24/11/2015	Milling spindle requires repair	Cristian Santos noted: Detail not recorded.	cristian_santos
A36	16/10/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A4	24/11/2015	Spindle indexing error with overfeed	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A99	09/06/2015	Spindle fails to index, overfeeding	Michele Williams noted: Maintenance action successful.	michele_williams
A51	24/04/2015	Accumulator inspection and charging required	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A69	08/02/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A57	22/12/2015	Machine is unpowered	Michele Williams noted: No additional information provided.	michele_williams
A60	23/05/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A25	21/09/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A75	18/10/2015	Turret A and B are leaking	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A88	10/10/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A42	10/12/2015	Unit lost electrical power	Cristian Santos noted: Fixed and tested.	cristian_santos
A42	24/04/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A78	28/07/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A79	09/01/2016	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A67	14/11/2015	Milling spindle requires repair	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A41	05/11/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A31	26/01/2015	Power supply failure detected	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A75	08/06/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A6	09/03/2015	Inspect and recharge accumulators	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A73	15/02/2015	Maintenance on milling spindle needed	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A90	30/07/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A13	18/06/2015	Inspect and recharge accumulators	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A79	06/01/2016	Spindle fails to index, overfeeding	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A94	23/01/2015	Leaks found at turrets A and B	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A21	14/08/2015	Turret A and B are leaking	Michele Williams noted: Fixed and tested.	michele_williams
A76	15/07/2015	Leaks found at turrets A and B	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A88	08/02/2015	Accumulators need checking and charging	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A38	20/05/2015	Hydraulic line leak on side B	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A26	25/07/2015	Leak in side B hydraulic line	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A32	16/10/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A45	09/09/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A36	08/03/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: No further details.	cristian_santos
A8	02/07/2015	Accumulators need checking and charging	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A7	06/09/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A15	25/01/2015	Inspect and recharge accumulators	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A83	13/02/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A35	27/10/2015	Turret sections A & B showing leaks	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A18	10/09/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A17	16/05/2015	Leak in side B hydraulic line	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A67	08/06/2015	Unit lost electrical power	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A81	19/04/2015	Accumulators need checking and charging	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A79	23/11/2015	Maintenance on milling spindle needed	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A19	16/01/2015	Repair work needed on milling spindle	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A5	06/02/2015	Turret A and B are leaking	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A90	10/01/2016	Power supply failure detected	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A65	11/12/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A97	26/12/2015	Power supply failure detected	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A96	16/01/2015	Leak in side B hydraulic line	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A72	30/11/2015	Leaks found at turrets A and B	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A47	28/01/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A88	08/04/2015	Accumulator inspection and charging required	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A62	17/12/2015	Maintenance on milling spindle needed	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A10	08/12/2015	Leak in side B hydraulic line	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A19	05/11/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A53	19/01/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A37	26/09/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A71	15/06/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: No further details.	michele_williams
A54	27/10/2015	Maintenance on milling spindle needed	Michele Williams noted: No additional information provided.	michele_williams

A96	20/09/2015	Power supply failure detected	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A57	26/07/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A88	09/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A20	03/03/2015	Hydraulic line leak on side B	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A92	11/09/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A61	05/10/2015	Milling spindle requires repair	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A42	11/03/2015	Machine is unpowered	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A80	09/08/2015	Accumulator inspection and charging required	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A4	21/02/2015	Hydraulic line leak on side B	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A24	29/12/2015	Leak in side B hydraulic line	Michele Williams noted: No additional information provided.	michele_williams
A3	08/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: No further details.	michele_williams
A39	27/07/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A25	24/12/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: No additional information provided.	michele_williams
A6	30/07/2015	Leaks found at turrets A and B	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A72	18/10/2015	Leaks found at turrets A and B	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A69	21/02/2015	Accumulator inspection and charging required	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A94	17/11/2015	Turret sections A & B showing leaks	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A70	05/03/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A99	26/09/2015	Accumulator inspection and charging required	Michele Williams noted: No additional information provided.	michele_williams
A59	21/12/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A12	24/09/2015	Machine is unpowered	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A59	22/01/2015	Maintenance on milling spindle needed	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A40	20/05/2015	Repair work needed on milling spindle	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A3	26/08/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A44	30/04/2015	Unit lost electrical power	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A37	21/04/2015	Machine is unpowered	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A7	16/01/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: No further details.	cristian_santos
A63	14/03/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A2	24/03/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A78	05/01/2016	Machine is unpowered	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A52	04/08/2015	Repair work needed on milling spindle	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A61	12/05/2015	Milling spindle requires repair	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A73	28/07/2015	Turret A and B are leaking	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A58	19/06/2015	Spindle indexing error with overfeed	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A32	12/05/2015	Turret A and B are leaking	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A56	28/05/2015	Spindle indexing error with overfeed	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A73	08/01/2016	Spindle indexing error with overfeed	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A12	06/09/2015	Machine is unpowered	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A66	21/11/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A49	04/04/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A82	06/12/2015	Accumulators need checking and charging	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A77	04/12/2015	Unit lost electrical power	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A37	03/08/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A37	15/08/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A27	02/04/2015	Turret sections A & B showing leaks	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A53	05/09/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A40	13/05/2015	Spindle fails to index, overfeeding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A98	01/10/2015	Turret A and B are leaking	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A7	17/11/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A46	02/07/2015	Leak in side B hydraulic line	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A70	18/04/2015	Maintenance on milling spindle needed	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A48	24/05/2015	Repair work needed on milling spindle	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A29	08/05/2015	Power supply failure detected	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A13	31/07/2015	Machine is unpowered	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A4	05/07/2015	Milling spindle requires repair	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A70	04/07/2015	Milling spindle requires repair	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A91	13/04/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A39	11/05/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: System checked and accumulators charged.	michele_williams
A43	18/03/2015	Spindle fails to index, overfeeding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A65	01/04/2015	Repair work needed on milling spindle	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A90	15/03/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A96	26/06/2015	Unit lost electrical power	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A12	18/04/2015	Leaks found at turrets A and B	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A60	13/04/2015	Spindle indexing error with overfeed	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A43	19/08/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A99	01/01/2016	Hydraulic line leak on side B	Cristian Santos noted: Repair completed.	cristian_santos
A90	30/06/2015	Unit lost electrical power	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A77	31/10/2015	Unit lost electrical power	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A37	22/01/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A34	17/05/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams

A6	26/12/2015	Spindle indexing error with overfeed	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A86	10/09/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A25	18/08/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: No further details.	nathan_maldonado
A55	08/08/2015	Unit lost electrical power	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A22	02/03/2015	Power supply failure detected	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A25	04/03/2015	Inspect and recharge accumulators	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A69	15/07/2015	Accumulator inspection and charging required	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A90	19/06/2015	Leaks found at turrets A and B	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A53	29/06/2015	Accumulators need checking and charging	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A47	13/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A47	22/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A46	28/08/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A37	26/10/2015	Unit lost electrical power	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A18	01/09/2015	Spindle indexing error with overfeed	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A52	05/04/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A44	31/08/2015	Turret sections A & B showing leaks	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A25	06/05/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A95	10/07/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Repair completed.	michele_williams
A80	11/10/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A88	21/05/2015	Leak in side B hydraulic line	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A68	20/06/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A34	25/02/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A79	27/07/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A24	02/02/2015	Accumulator inspection and charging required	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A77	27/09/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A63	19/09/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A75	16/08/2015	Leak in side B hydraulic line	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A68	23/03/2015	Inspect and recharge accumulators	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A18	03/03/2015	Leak in side B hydraulic line	Cristian Santos noted: Detail not recorded.	cristian_santos
A85	17/09/2015	Accumulator inspection and charging required	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A62	17/03/2015	Machine is unpowered	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A82	11/05/2015	Inspect and recharge accumulators	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A20	02/05/2015	Milling spindle requires repair	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A90	05/02/2015	Leak in side B hydraulic line	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A88	30/03/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A46	19/10/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A22	03/09/2015	Accumulators need checking and charging	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A33	09/09/2015	Leak in side B hydraulic line	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A33	21/07/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A97	15/06/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A46	17/02/2015	Milling spindle requires repair	Gina Moore noted: No further details.	gina_moore, dylan_miller
A1	16/07/2015	Inspect and recharge accumulators	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A78	25/04/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A89	20/06/2015	Turret sections A & B showing leaks	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A3	15/03/2015	Inspect and recharge accumulators	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A23	19/03/2015	Hydraulic line leak on side B	Michele Williams noted: Detail not recorded.	michele_williams
A50	20/01/2015	Accumulators need checking and charging	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A26	05/04/2015	Unit lost electrical power	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A96	27/05/2015	Turret A and B are leaking	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A24	01/08/2015	Power supply failure detected	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A41	31/12/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A51	22/02/2015	Inspect and recharge accumulators	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A25	21/10/2015	Machine is unpowered	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A68	30/10/2015	Repair work needed on milling spindle	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A9	16/01/2015	Spindle indexing error with overfeed	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A14	21/07/2015	Repair work needed on milling spindle	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A38	05/06/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A38	03/09/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A40	23/05/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A81	26/03/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A38	28/06/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A73	31/07/2015	Milling spindle requires repair	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A87	05/07/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A73	10/05/2015	Maintenance on milling spindle needed	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A83	28/08/2015	Repair work needed on milling spindle	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A11	07/04/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A14	13/05/2015	Milling spindle requires repair	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A35	19/12/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A5	22/06/2015	Machine is unpowered	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A71	04/03/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller

A62	30/10/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A99	03/04/2015	Leaks found at turrets A and B	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A95	24/01/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Fixed and tested.	cristian_santos
A72	16/08/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A88	10/05/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A41	25/10/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A59	06/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A82	03/03/2015	Repair work needed on milling spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A48	18/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A10	10/01/2016	Repair work needed on milling spindle	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A51	21/06/2015	Leak in side B hydraulic line	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A71	22/08/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A75	06/02/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A73	11/01/2016	Turret sections A & B showing leaks	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A36	21/11/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Fixed and tested.	michele_williams
A66	20/07/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Maintenance action successful.	michele_williams
A65	12/05/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A1	26/11/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A93	13/03/2015	Turret A and B are leaking	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A8	06/06/2015	Turret A and B are leaking	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A16	02/12/2015	Leaks found at turrets A and B	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A57	21/12/2015	Leaks found at turrets A and B	Michele Williams noted: No additional information provided.	michele_williams
A86	20/08/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A96	20/11/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A57	19/11/2015	Turret A and B are leaking	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A95	27/02/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A22	23/05/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A8	04/05/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A93	21/11/2015	Accumulators need checking and charging	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A1	09/03/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A63	06/09/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A37	19/11/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A35	17/06/2015	Spindle indexing error with overfeed	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A76	20/01/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A91	18/10/2015	Turret A and B are leaking	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A69	09/09/2015	Turret sections A & B showing leaks	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A49	18/06/2015	Repair work needed on milling spindle	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A96	17/03/2015	Unit lost electrical power	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A76	10/06/2015	Unit lost electrical power	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A38	13/09/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A37	18/09/2015	Milling spindle requires repair	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A3	12/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A55	01/10/2015	Hydraulic line leak on side B	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A6	27/02/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A79	24/01/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A60	24/02/2015	Hydraulic line leak on side B	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A91	13/03/2015	Leaks found at turrets A and B	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A46	03/02/2015	Accumulators need checking and charging	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A37	06/04/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: No further details.	nathan_maldonado
A15	02/02/2015	Turret sections A & B showing leaks	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A92	30/06/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A78	26/06/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A90	18/06/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A33	14/11/2015	Hydraulic line leak on side B	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A2	06/02/2015	Leak in side B hydraulic line	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A46	24/02/2015	Accumulators need checking and charging	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A45	24/07/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A29	26/05/2015	Maintenance on milling spindle needed	Michele Williams noted: System checked and accumulators charged.	michele_williams
A59	07/10/2015	Turret sections A & B showing leaks	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A93	30/06/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A43	06/10/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A35	22/04/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A60	23/10/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A73	22/07/2015	Spindle indexing error with overfeed	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A78	31/10/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A29	30/07/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A25	16/12/2015	Machine is unpowered	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A69	18/11/2015	Spindle fails to index, overfeeding	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A93	08/10/2015	Leak in side B hydraulic line	Cristian Santos noted: No additional information provided.	cristian_santos
A94	10/10/2015	Repair work needed on milling spindle	Cristian Santos noted: System checked and accumulators charged.	cristian_santos

A96	24/04/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A13	04/01/2016	Inspect and recharge accumulators	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A70	24/04/2015	Unit lost electrical power	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A89	07/07/2015	Hydraulic line leak on side B	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A88	23/07/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A38	01/09/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A6	02/05/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A72	07/08/2015	Leak in side B hydraulic line	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A10	10/01/2016	Spindle indexing error with overfeed	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A35	05/01/2016	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A18	14/01/2015	Spindle indexing error with overfeed	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A18	08/08/2015	Repair work needed on milling spindle	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A66	08/11/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A31	18/09/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A20	01/12/2015	Inspect and recharge accumulators	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A6	17/02/2015	Leaks found at turrets A and B	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A95	01/12/2015	Hydraulic line leak on side B	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A86	31/08/2015	Accumulator inspection and charging required	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A34	19/02/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A15	16/06/2015	Turret A and B are leaking	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A82	03/11/2015	Saw attachment is leaking hydraulics	Michele Williams noted: System checked and accumulators charged.	michele_williams
A19	20/05/2015	Turret sections A & B showing leaks	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A95	15/06/2015	Spindle indexing error with overfeed	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A42	11/04/2015	Inspect and recharge accumulators	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A33	10/02/2015	Power supply failure detected	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A33	04/09/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A45	22/06/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A50	17/09/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A6	24/02/2015	Power supply failure detected	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A73	19/09/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A39	28/04/2015	Repair work needed on milling spindle	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A16	10/08/2015	Machine is unpowered	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A78	10/04/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A68	12/10/2015	Leaks found at turrets A and B	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A65	14/10/2015	Spindle fails to index, overfeeding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A35	28/07/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A1	10/08/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A70	11/03/2015	Milling spindle requires repair	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A94	02/08/2015	Milling spindle requires repair	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A42	19/07/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A76	01/06/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A18	22/09/2015	Leaks found at turrets A and B	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A3	24/07/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A63	28/01/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A25	08/06/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A49	10/12/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Maintenance action successful.	michele_williams
A27	04/01/2016	Hydraulic line leak on side B	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A22	07/11/2015	Inspect and recharge accumulators	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A40	29/06/2015	Leak in side B hydraulic line	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A48	07/09/2015	Hydraulic line leak on side B	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A86	03/11/2015	Machine is unpowered	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A7	17/12/2015	Turret sections A & B showing leaks	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A2	13/11/2015	Hydraulic hose on side B is leaking	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A56	27/10/2015	Power supply failure detected	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A51	07/02/2015	Accumulators need checking and charging	Michele Williams noted: No further details.	michele_williams
A70	12/02/2015	Leak in side B hydraulic line	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A88	23/06/2015	Turret sections A & B showing leaks	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A66	21/12/2015	Accumulators need checking and charging	Michele Williams noted: No further details.	michele_williams
A35	28/05/2015	Leak in side B hydraulic line	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A54	10/11/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A25	05/08/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A15	16/02/2015	Spindle indexing error with overfeed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A77	09/07/2015	Repair work needed on milling spindle	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A50	29/10/2015	Turret A and B are leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A82	07/10/2015	Unit lost electrical power	Cristian Santos noted: Fixed and tested.	cristian_santos
A27	06/09/2015	Milling spindle requires repair	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A8	30/06/2015	Accumulators need checking and charging	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A43	25/12/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A28	02/03/2015	Turret A and B are leaking	Michele Williams noted: No additional information provided.	michele_williams
A17	02/09/2015	Leak in side B hydraulic line	Michele Williams noted: Repair completed.	michele_williams

A34	15/02/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A45	13/11/2015	Hydraulic hose on side B is leaking	Michele Williams noted: No further details.	michele_williams
A76	30/01/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A29	13/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A6	11/09/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A68	08/03/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A84	31/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A68	25/06/2015	Hydraulic line leak on side B	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A64	18/01/2015	Spindle indexing error with overfeed	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A13	30/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A49	23/10/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A44	28/10/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A69	16/03/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Maintenance action successful.	michele_williams
A95	12/03/2015	Milling spindle requires repair	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A48	18/05/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A22	27/07/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: No further details.	nathan_maldonado
A31	11/07/2015	Leak in side B hydraulic line	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A36	12/02/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A95	10/02/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A24	07/09/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A47	06/05/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A91	23/08/2015	Machine is unpowered	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A88	25/04/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A29	23/02/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Maintenance action successful.	michele_williams
A12	17/03/2015	Turret sections A & B showing leaks	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A76	14/03/2015	Turret A and B are leaking	Michele Williams noted: No additional information provided.	michele_williams
A53	03/08/2015	Spindle indexing error with overfeed	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A56	15/01/2015	Repair work needed on milling spindle	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A83	06/09/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A66	16/05/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A9	26/05/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A61	11/09/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A25	14/02/2015	Turret A and B are leaking	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A71	11/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A66	24/02/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A64	10/10/2015	Unit lost electrical power	Michele Williams noted: System checked and accumulators charged.	michele_williams
A60	31/08/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A17	01/08/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A68	08/11/2015	Leak in side B hydraulic line	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A99	18/06/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A39	19/01/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A24	20/01/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A40	07/11/2015	Inspect and recharge accumulators	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A78	13/12/2015	Leak in side B hydraulic line	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A84	23/12/2015	Machine is unpowered	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A96	23/11/2015	Accumulator inspection and charging required	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A33	04/10/2015	Inspect and recharge accumulators	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A39	23/06/2015	Power supply failure detected	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A32	12/02/2015	Unit lost electrical power	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A35	17/09/2015	Unit lost electrical power	Cristian Santos noted: No further details.	cristian_santos
A60	29/12/2015	Power supply failure detected	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A71	13/08/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A61	07/10/2015	Power supply failure detected	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A7	21/03/2015	Machine is unpowered	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A37	24/05/2015	Spindle indexing error with overfeed	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A99	17/04/2015	Accumulators need checking and charging	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A61	09/09/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A4	25/12/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A6	01/03/2015	Maintenance on milling spindle needed	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A55	11/03/2015	Machine is unpowered	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A77	06/06/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A56	11/08/2015	Spindle indexing error with overfeed	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A15	14/08/2015	Power supply failure detected	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A80	27/10/2015	Accumulators need checking and charging	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A83	23/01/2015	Unit lost electrical power	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A15	31/12/2015	Repair work needed on milling spindle	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A58	10/03/2015	Leak in side B hydraulic line	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A88	07/09/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Fixed and tested.	cristian_santos
A2	01/10/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A70	31/08/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams

A80	18/12/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A60	14/02/2015	Repair work needed on milling spindle	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A43	11/11/2015	Leak in side B hydraulic line	Michele Williams noted: No additional information provided.	michele_williams
A59	22/05/2015	Hydraulic line leak on side B	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A5	21/10/2015	Leaks found at turrets A and B	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A13	03/04/2015	Turret sections A & B showing leaks	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A22	02/07/2015	Repair work needed on milling spindle	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A65	26/07/2015	Accumulator inspection and charging required	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A6	19/02/2015	Spindle indexing error with overfeed	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A80	02/03/2015	Leak in side B hydraulic line	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A36	13/03/2015	Accumulators need checking and charging	Cristian Santos noted: Repair completed.	cristian_santos
A75	17/01/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: No further details.	gina_moore, dylan_miller
A91	15/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A2	16/04/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A38	31/10/2015	Accumulators need checking and charging	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A10	10/09/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A7	09/01/2016	Maintenance on milling spindle needed	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A7	21/05/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A22	16/08/2015	Leaks found at turrets A and B	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A36	26/11/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A45	06/11/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A85	20/12/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A84	03/01/2016	Leaks found at turrets A and B	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A4	08/04/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A93	08/06/2015	Hydraulic line leak on side B	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A86	28/04/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A29	01/02/2015	Turret A and B are leaking	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A38	02/08/2015	Repair work needed on milling spindle	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A89	28/07/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A91	02/10/2015	Leaks found at turrets A and B	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A26	01/02/2015	Milling spindle requires repair	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A65	07/04/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Repair completed.	michele_williams
A63	13/07/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A42	24/12/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A57	11/06/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A40	18/06/2015	Power supply failure detected	Cristian Santos noted: Maintenance action successful.	cristian_santos
A85	05/04/2015	Power supply failure detected	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A98	10/01/2016	Hydraulic hose on side B is leaking	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A86	24/11/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A49	09/03/2015	Milling spindle requires repair	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A11	31/07/2015	Maintenance on milling spindle needed	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A16	25/03/2015	Machine is unpowered	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A62	21/12/2015	Accumulator inspection and charging required	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A21	07/01/2016	Spindle indexing error with overfeed	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A43	31/07/2015	Unit lost electrical power	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A84	06/01/2016	Spindle indexing error with overfeed	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A74	01/05/2015	Leak in side B hydraulic line	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A4	11/11/2015	Accumulators need checking and charging	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A48	10/09/2015	Turret A and B are leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A41	27/12/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A2	08/01/2016	Accumulator inspection and charging required	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A88	23/09/2015	Milling spindle requires repair	Nathan Maldonado noted: No further details.	nathan_maldonado
A49	16/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A92	26/11/2015	Turret A and B are leaking	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A22	02/04/2015	Inspect and recharge accumulators	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A70	30/03/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A71	19/03/2015	Accumulator inspection and charging required	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A16	02/10/2015	Accumulators need checking and charging	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A45	12/05/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A35	28/10/2015	Milling spindle requires repair	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A44	06/01/2016	Maintenance on milling spindle needed	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A15	25/07/2015	Maintenance on milling spindle needed	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A62	14/07/2015	Spindle fails to index, overfeeding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A94	05/12/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A57	12/05/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A39	08/12/2015	Spindle fails to index, overfeeding	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A77	26/01/2015	Repair work needed on milling spindle	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A24	06/11/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A62	20/01/2015	Accumulator inspection and charging required	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A47	12/08/2015	Milling spindle requires repair	Cristian Santos noted: Maintenance action successful.	cristian_santos

A11	01/02/2015	Accumulator inspection and charging required	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A51	19/01/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A70	22/01/2015	Milling spindle requires repair	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A43	22/11/2015	Leaks found at turrets A and B	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A56	18/12/2015	Spindle fails to index, overfeeding	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A2	03/05/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A86	04/11/2015	Milling spindle requires repair	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A55	05/07/2015	Machine is unpowered	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A65	14/04/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A24	17/11/2015	Spindle fails to index, overfeeding	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A89	23/04/2015	Unit lost electrical power	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A77	01/05/2015	Spindle fails to index, overfeeding	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A72	31/03/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: No additional information provided.	cristian_santos
A53	18/12/2015	Repair work needed on milling spindle	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A48	02/09/2015	Accumulator inspection and charging required	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A50	25/10/2015	Maintenance on milling spindle needed	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A53	27/03/2015	Hydraulic hose on side B is leaking	Michele Williams noted: System checked and accumulators charged.	michele_williams
A95	30/09/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A71	13/12/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A24	05/02/2015	Milling spindle requires repair	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A37	27/05/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A88	29/10/2015	Hydraulic line leak on side B	Cristian Santos noted: Fixed and tested.	cristian_santos
A53	13/02/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A44	13/10/2015	Accumulators need checking and charging	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A31	07/07/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A19	05/08/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A38	03/05/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A62	27/07/2015	Inspect and recharge accumulators	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A55	10/10/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A58	28/07/2015	Leak in side B hydraulic line	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A62	15/09/2015	Hydraulic line leak on side B	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A80	23/04/2015	Turret A and B are leaking	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A80	23/12/2015	Repair work needed on milling spindle	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A69	15/12/2015	Spindle fails to index, overfeeding	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A69	26/04/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Maintenance action successful.	cristian_santos
A53	13/07/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A53	24/06/2015	Maintenance on milling spindle needed	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A13	12/06/2015	Unit lost electrical power	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A29	04/02/2015	Milling spindle requires repair	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A6	27/12/2015	Turret sections A & B showing leaks	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A64	29/07/2015	Leaks found at turrets A and B	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A23	27/01/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A10	08/09/2015	Leak in side B hydraulic line	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A71	13/06/2015	Turret A and B are leaking	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A98	17/03/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A13	05/11/2015	Leak in side B hydraulic line	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A57	28/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A7	23/01/2015	Machine is unpowered	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A33	19/07/2015	Turret sections A & B showing leaks	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A64	08/08/2015	Spindle fails to index, overfeeding	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A22	25/12/2015	Spindle indexing error with overfeed	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A38	27/01/2015	Spindle fails to index, overfeeding	Michele Williams noted: No additional information provided.	michele_williams
A23	24/03/2015	Accumulators need checking and charging	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A28	27/01/2015	Maintenance on milling spindle needed	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A23	19/06/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A58	28/07/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A74	26/06/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A25	23/12/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A40	14/08/2015	Leak in side B hydraulic line	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A88	01/08/2015	Repair work needed on milling spindle	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A34	17/01/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A43	08/09/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A88	10/09/2015	Inspect and recharge accumulators	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A77	23/11/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A9	02/02/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A21	15/09/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A66	14/09/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A98	06/03/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Maintenance action successful.	michele_williams
A45	04/05/2015	Accumulators need checking and charging	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A81	16/04/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller

A22	14/07/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A1	12/07/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A8	04/10/2015	Hydraulic line leak on side B	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A14	18/11/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A6	25/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: No further details.	nathan_maldonado
A67	10/11/2015	Accumulator inspection and charging required	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A93	05/03/2015	Unit lost electrical power	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A13	10/05/2015	Leaks found at turrets A and B	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A46	02/07/2015	Turret sections A & B showing leaks	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A36	13/11/2015	Inspect and recharge accumulators	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A21	08/06/2015	Turret sections A & B showing leaks	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A34	04/11/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A66	03/07/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A12	06/09/2015	Machine is unpowered	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A94	08/04/2015	Power supply failure detected	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A82	04/06/2015	Machine is unpowered	Michele Williams noted: No further details.	michele_williams
A29	04/04/2015	Unit lost electrical power	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A42	06/02/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A75	28/07/2015	Maintenance on milling spindle needed	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A85	05/08/2015	Accumulators need checking and charging	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A35	29/07/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A33	25/08/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A40	09/08/2015	Turret sections A & B showing leaks	Cristian Santos noted: Detail not recorded.	cristian_santos
A13	31/08/2015	Turret sections A & B showing leaks	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A8	18/07/2015	Accumulators need checking and charging	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A61	31/12/2015	Machine is unpowered	Cristian Santos noted: Fixed and tested.	cristian_santos
A8	14/07/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A29	18/05/2015	Leak in side B hydraulic line	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A5	31/01/2015	Turret sections A & B showing leaks	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A69	01/01/2016	Saw attachment is leaking hydraulics	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A85	02/08/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A54	04/10/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A2	08/05/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A97	12/08/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A49	20/09/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A58	22/06/2015	Unit lost electrical power	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A46	28/10/2015	Inspect and recharge accumulators	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A96	22/03/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A83	07/10/2015	Hydraulic line leak on side B	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A60	29/10/2015	Leak in side B hydraulic line	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A59	20/04/2015	Unit lost electrical power	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A54	06/02/2015	Saw attachment gears are binding and grinding	Michele Williams noted: No further details.	michele_williams
A73	21/02/2015	Maintenance on milling spindle needed	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A17	26/12/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A17	01/02/2015	Power supply failure detected	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A35	12/06/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A84	01/02/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A18	22/07/2015	Spindle indexing error with overfeed	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A62	21/09/2015	Turret sections A & B showing leaks	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A51	13/12/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A38	23/03/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A62	19/06/2015	Hydraulic line leak on side B	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A94	04/06/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A86	02/10/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A88	29/03/2015	Maintenance on milling spindle needed	Michele Williams noted: Repair completed.	michele_williams
A99	04/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A21	19/09/2015	Accumulator inspection and charging required	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A69	07/08/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A48	01/12/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A5	29/05/2015	Repair work needed on milling spindle	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A35	17/01/2015	Accumulator inspection and charging required	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A54	21/11/2015	Machine is unpowered	Cristian Santos noted: No additional information provided.	cristian_santos
A40	18/09/2015	Unit lost electrical power	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A18	19/06/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A82	08/10/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A72	10/02/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A88	19/10/2015	Leaks found at turrets A and B	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A9	28/01/2015	Turret sections A & B showing leaks	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A61	22/06/2015	Unit lost electrical power	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A14	09/04/2015	Power supply failure detected	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado

A18	31/07/2015	Milling spindle requires repair	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A93	01/03/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A66	22/10/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A77	02/04/2015	Power supply failure detected	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A46	18/05/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A46	29/04/2015	Leaks found at turrets A and B	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A89	24/01/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A15	06/02/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A41	21/05/2015	Accumulator inspection and charging required	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A90	18/12/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A89	22/05/2015	Hydraulic line leak on side B	Cristian Santos noted: Maintenance action successful.	cristian_santos
A56	06/01/2016	Machine is unpowered	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A69	07/01/2016	Repair work needed on milling spindle	Gina Moore noted: No further details.	gina_moore, dylan_miller
A49	15/03/2015	Milling spindle requires repair	Cristian Santos noted: Fixed and tested.	cristian_santos
A77	04/11/2015	Hydraulic line leak on side B	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A1	09/11/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A1	12/04/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A46	23/03/2015	Power supply failure detected	Cristian Santos noted: Maintenance action successful.	cristian_santos
A48	17/03/2015	Leak in side B hydraulic line	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A29	24/02/2015	Maintenance on milling spindle needed	Michele Williams noted: System checked and accumulators charged.	michele_williams
A46	23/08/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: No further details.	cristian_santos
A75	06/09/2015	Leak in side B hydraulic line	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A33	30/04/2015	Power supply failure detected	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A80	22/07/2015	Repair work needed on milling spindle	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A44	27/11/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Maintenance action successful.	cristian_santos
A68	15/10/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A87	22/05/2015	Spindle indexing error with overfeed	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A34	14/06/2015	Repair work needed on milling spindle	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A48	05/04/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Maintenance action successful.	cristian_santos
A46	23/08/2015	Repair work needed on milling spindle	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A95	11/06/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: No further details.	nathan_maldonado
A13	18/08/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A72	26/09/2015	Accumulator inspection and charging required	Cristian Santos noted: Repair completed.	cristian_santos
A78	13/10/2015	Accumulators need checking and charging	Cristian Santos noted: Maintenance action successful.	cristian_santos
A42	04/07/2015	Power supply failure detected	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A6	16/01/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A72	04/06/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A53	19/08/2015	Unit lost electrical power	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A38	10/10/2015	Leaks found at turrets A and B	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A96	28/06/2015	Repair work needed on milling spindle	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A53	28/08/2015	Spindle indexing error with overfeed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A3	07/04/2015	Milling spindle requires repair	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A34	23/10/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A59	17/11/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A49	26/11/2015	Machine is unpowered	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A60	20/09/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A19	11/07/2015	Unit lost electrical power	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A40	19/06/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A38	04/10/2015	Unit lost electrical power	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A87	25/12/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Repair completed.	cristian_santos
A41	02/03/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A94	13/12/2015	Spindle indexing error with overfeed	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A19	17/02/2015	Accumulators need checking and charging	Michele Williams noted: Maintenance action successful.	michele_williams
A90	16/07/2015	Accumulator inspection and charging required	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A28	31/08/2015	Power supply failure detected	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A22	20/02/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A40	27/02/2015	Spindle indexing error with overfeed	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A70	28/11/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A89	17/01/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A50	31/01/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A46	26/02/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A60	26/02/2015	Maintenance on milling spindle needed	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A35	09/06/2015	Spindle fails to index, overfeeding	Michele Williams noted: No further details.	michele_williams
A9	05/07/2015	Spindle fails to index, overfeeding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A34	30/04/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A69	10/06/2015	Maintenance on milling spindle needed	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A17	25/12/2015	Milling spindle requires repair	Michele Williams noted: No further details.	michele_williams
A82	09/09/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: No further details.	michele_williams
A12	14/08/2015	Power supply failure detected	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A20	19/07/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado

A26	07/04/2015	Repair work needed on milling spindle	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A22	01/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A31	11/11/2015	Repair work needed on milling spindle	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A81	21/09/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A13	29/03/2015	Accumulators need checking and charging	Gina Moore noted: No further details.	gina_moore, dylan_miller
A79	25/10/2015	Repair work needed on milling spindle	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A41	16/09/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A73	19/10/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A47	20/06/2015	Leak in side B hydraulic line	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A11	12/09/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Detail not recorded.	michele_williams
A34	06/06/2015	Repair work needed on milling spindle	Michele Williams noted: Fixed and tested.	michele_williams
A23	20/07/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A59	19/01/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A86	21/10/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Maintenance action successful.	michele_williams
A8	26/01/2015	Turret sections A & B showing leaks	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A71	22/03/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A95	03/03/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A46	08/07/2015	Leaks found at turrets A and B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A54	31/08/2015	Leak in side B hydraulic line	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A38	20/08/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A46	07/01/2016	Power supply failure detected	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A63	19/08/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A20	07/11/2015	Repair work needed on milling spindle	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A42	31/01/2015	Leaks found at turrets A and B	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A61	16/09/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: No further details.	nathan_maldonado
A26	01/07/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A90	31/01/2015	Accumulator inspection and charging required	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A89	05/03/2015	Power supply failure detected	Michele Williams noted: No additional information provided.	michele_williams
A18	20/07/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A95	16/03/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A56	16/06/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A36	23/05/2015	Power supply failure detected	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A6	21/08/2015	Milling spindle requires repair	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A97	21/07/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A20	11/02/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A59	18/03/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A82	04/04/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A50	01/10/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A51	11/11/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A38	11/04/2015	Repair work needed on milling spindle	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A41	23/10/2015	Turret sections A & B showing leaks	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A13	14/03/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A55	03/04/2015	Accumulator inspection and charging required	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A37	23/02/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A7	10/03/2015	Spindle indexing error with overfeed	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A96	18/11/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A71	11/02/2015	Turret sections A & B showing leaks	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A1	10/08/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A6	30/07/2015	Repair work needed on milling spindle	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A98	29/01/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A17	12/03/2015	Turret sections A & B showing leaks	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A21	03/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A59	11/07/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Fixed and tested.	cristian_santos
A61	29/07/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A5	08/07/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Fixed and tested.	michele_williams
A59	21/07/2015	Leaks found at turrets A and B	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A16	01/11/2015	Hydraulic line leak on side B	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A81	05/12/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A44	15/05/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A15	18/05/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A89	29/05/2015	Accumulators need checking and charging	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A71	15/03/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A96	13/02/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A88	22/08/2015	Hydraulic line leak on side B	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A52	28/12/2015	Machine is unpowered	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A2	22/05/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A77	21/01/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A39	04/12/2015	Spindle indexing error with overfeed	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A25	16/07/2015	Milling spindle requires repair	Nathan Maldonado noted: No further details.	nathan_maldonado
A19	27/12/2015	Accumulators need checking and charging	Michele Williams noted: Repair completed.	michele_williams

A12	14/11/2015	Machine is unpowered	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A79	07/09/2015	Inspect and recharge accumulators	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A68	19/02/2015	Milling spindle requires repair	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A53	16/04/2015	Power supply failure detected	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A25	08/06/2015	Accumulators need checking and charging	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A94	09/06/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A54	20/03/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A25	10/02/2015	Unit lost electrical power	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A58	01/10/2015	Turret A and B are leaking	Michele Williams noted: Fixed and tested.	michele_williams
A77	23/05/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A12	02/11/2015	Accumulator inspection and charging required	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A9	03/06/2015	Power supply failure detected	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A54	27/03/2015	Leak in side B hydraulic line	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A13	05/12/2015	Leaks found at turrets A and B	Cristian Santos noted: Maintenance action successful.	cristian_santos
A14	28/02/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: No further details.	michele_williams
A3	23/09/2015	Hydraulic line leak on side B	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A18	18/07/2015	Unit lost electrical power	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A6	29/01/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A70	14/08/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A90	10/06/2015	Power supply failure detected	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A7	22/08/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A61	10/03/2015	Milling spindle requires repair	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A92	29/05/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A37	21/08/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A94	08/01/2016	Unit lost electrical power	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A11	18/07/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A69	06/10/2015	Unit lost electrical power	Cristian Santos noted: Maintenance action successful.	cristian_santos
A8	05/05/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A7	01/08/2015	Machine is unpowered	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A35	30/08/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: No further details.	cristian_santos
A8	10/07/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A59	05/03/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A60	07/03/2015	Maintenance on milling spindle needed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A55	12/10/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A15	18/02/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A11	22/07/2015	Accumulators need checking and charging	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A56	03/10/2015	Accumulators need checking and charging	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A80	14/09/2015	Leaks found at turrets A and B	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A57	17/08/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Repair completed.	michele_williams
A16	26/02/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A61	06/06/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A74	30/07/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A60	14/06/2015	Spindle fails to index, overfeeding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A5	03/07/2015	Repair work needed on milling spindle	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A79	19/09/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A78	11/12/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A9	11/02/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A74	06/05/2015	Maintenance on milling spindle needed	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A78	16/12/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A69	11/11/2015	Repair work needed on milling spindle	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A97	10/10/2015	Power supply failure detected	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A20	18/03/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A46	06/04/2015	Spindle indexing error with overfeed	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A81	02/09/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: No additional information provided.	cristian_santos
A21	15/08/2015	Accumulator inspection and charging required	Michele Williams noted: Maintenance action successful.	michele_williams
A37	02/10/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A60	15/02/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A1	08/11/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A55	02/04/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Detail not recorded.	cristian_santos
A9	02/06/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A96	31/10/2015	Repair work needed on milling spindle	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A3	10/05/2015	Spindle fails to index, overfeeding	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A11	03/08/2015	Machine is unpowered	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A51	20/04/2015	Spindle fails to index, overfeeding	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A92	03/08/2015	Power supply failure detected	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A1	17/07/2015	Leak in side B hydraulic line	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A33	18/01/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A29	05/06/2015	Leak in side B hydraulic line	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A9	02/04/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A98	05/05/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams

A84	23/03/2015	Hydraulic line leak on side B	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A46	21/01/2015	Spindle indexing error with overfeed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A47	21/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A77	04/02/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A42	18/05/2015	Maintenance on milling spindle needed	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A80	09/08/2015	Accumulator inspection and charging required	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A31	07/12/2015	Unit lost electrical power	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A71	22/06/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A45	09/05/2015	Repair work needed on milling spindle	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A21	25/02/2015	Spindle indexing error with overfeed	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A23	12/05/2015	Milling spindle requires repair	Michele Williams noted: Fixed and tested.	michele_williams
A6	16/09/2015	Turret sections A & B showing leaks	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A55	29/01/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A94	23/09/2015	Milling spindle requires repair	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A24	19/10/2015	Accumulator inspection and charging required	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A21	09/08/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Maintenance action successful.	michele_williams
A8	21/07/2015	Hydraulic line leak on side B	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A17	24/04/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A79	18/04/2015	Inspect and recharge accumulators	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A94	24/01/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Maintenance action successful.	michele_williams
A48	26/08/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A19	26/10/2015	Milling spindle requires repair	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A63	16/09/2015	Spindle indexing error with overfeed	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A23	06/01/2016	Saw attachment is leaking hydraulics	Gina Moore noted: No further details.	gina_moore, dylan_miller
A4	17/08/2015	Power supply failure detected	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A9	29/06/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A2	02/01/2016	Turret sections A & B showing leaks	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A44	26/11/2015	Leak in side B hydraulic line	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A67	23/06/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A32	19/12/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A46	03/07/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A57	05/06/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A59	30/05/2015	Milling spindle requires repair	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A91	24/09/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A8	23/08/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A19	01/12/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A67	13/10/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A61	10/12/2015	Spindle fails to index, overfeeding	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A86	08/02/2015	Unit lost electrical power	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A26	19/10/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A80	01/03/2015	Milling spindle requires repair	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A98	23/08/2015	Leak in side B hydraulic line	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A63	23/02/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A47	23/07/2015	Milling spindle requires repair	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A18	28/01/2015	Power supply failure detected	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A33	21/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A41	12/11/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: System checked and accumulators charged.	michele_williams
A4	26/10/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A62	16/09/2015	Repair work needed on milling spindle	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A59	03/08/2015	Leaks found at turrets A and B	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A82	10/12/2015	Turret A and B are leaking	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A29	12/05/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A56	26/10/2015	Leak in side B hydraulic line	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A49	24/08/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A3	28/03/2015	Spindle indexing error with overfeed	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A39	21/12/2015	Power supply failure detected	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A68	03/06/2015	Accumulators need checking and charging	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A68	17/09/2015	Turret sections A & B showing leaks	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A75	14/10/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A61	25/05/2015	Spindle indexing error with overfeed	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A57	01/08/2015	Leaks found at turrets A and B	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A18	15/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A47	21/06/2015	Repair work needed on milling spindle	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A78	17/01/2015	Inspect and recharge accumulators	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A22	29/10/2015	Accumulators need checking and charging	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A51	02/03/2015	Accumulator inspection and charging required	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A13	12/01/2016	Leaks found at turrets A and B	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A85	13/12/2015	Hydraulic line leak on side B	Cristian Santos noted: Maintenance action successful.	cristian_santos
A46	03/01/2016	Hydraulic line leak on side B	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A19	11/07/2015	Leaks found at turrets A and B	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams

A80	05/04/2015	Accumulator inspection and charging required	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A88	07/12/2015	Repair work needed on milling spindle	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A70	15/05/2015	Machine is unpowered	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A44	09/02/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A76	11/05/2015	Maintenance on milling spindle needed	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A11	17/08/2015	Accumulators need checking and charging	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A72	22/03/2015	Turret A and B are leaking	Cristian Santos noted: Fixed and tested.	cristian_santos
A77	11/01/2016	Accumulator inspection and charging required	Michele Williams noted: Detail not recorded.	michele_williams
A56	11/02/2015	Unit lost electrical power	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A34	22/09/2015	Accumulators need checking and charging	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A2	22/02/2015	Hydraulic line leak on side B	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A17	28/07/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A32	15/06/2015	Maintenance on milling spindle needed	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A41	22/04/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A66	10/11/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A60	21/03/2015	Leak in side B hydraulic line	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A23	06/08/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A73	30/09/2015	Repair work needed on milling spindle	Michele Williams noted: Fixed and tested.	michele_williams
A31	23/09/2015	Repair work needed on milling spindle	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A92	07/01/2016	Spindle fails to index, overfeeding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A63	01/04/2015	Turret sections A & B showing leaks	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A91	19/09/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A17	27/05/2015	Leaks found at turrets A and B	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A67	12/01/2016	Hydraulic hose on side B is leaking	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A99	25/07/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A71	30/03/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A34	10/05/2015	Accumulators need checking and charging	Gina Moore noted: No further details.	gina_moore, dylan_miller
A80	02/06/2015	Turret sections A & B showing leaks	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A26	08/09/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A53	13/02/2015	Machine is unpowered	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A27	09/11/2015	Milling spindle requires repair	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A20	13/06/2015	Hydraulic line leak on side B	Nathan Maldonado noted: No further details.	nathan_maldonado
A76	22/01/2015	Inspect and recharge accumulators	Gina Moore noted: No further details.	gina_moore, dylan_miller
A19	17/08/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A28	20/07/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A16	08/09/2015	Spindle indexing error with overfeed	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A26	05/02/2015	Repair work needed on milling spindle	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A67	14/11/2015	Spindle indexing error with overfeed	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A80	26/10/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A16	07/07/2015	Accumulators need checking and charging	Cristian Santos noted: Fixed and tested.	cristian_santos
A62	28/07/2015	Leak in side B hydraulic line	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A2	25/01/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A3	01/06/2015	Maintenance on milling spindle needed	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A41	29/12/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A90	13/01/2016	Leaks found at turrets A and B	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A27	09/11/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A28	13/03/2015	Accumulators need checking and charging	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A8	09/05/2015	Turret A and B are leaking	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A9	07/02/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A82	27/11/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A36	22/11/2015	Hydraulic hose on side B is leaking	Michele Williams noted: No further details.	michele_williams
A6	26/11/2015	Turret A and B are leaking	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A45	24/11/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A38	01/06/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A91	13/04/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A54	25/10/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A25	02/11/2015	Milling spindle requires repair	Cristian Santos noted: No additional information provided.	cristian_santos
A5	11/06/2015	Hydraulic line leak on side B	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A7	27/08/2015	Leaks found at turrets A and B	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A52	16/03/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A85	09/03/2015	Power supply failure detected	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A82	26/05/2015	Leak in side B hydraulic line	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A93	30/08/2015	Turret sections A & B showing leaks	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A63	13/11/2015	Leak in side B hydraulic line	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A7	02/06/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A34	31/07/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A65	06/01/2016	Unit lost electrical power	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A15	31/10/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A68	01/02/2015	Machine is unpowered	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A47	09/10/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Repair completed.	nathan_maldonado

A3	17/09/2015	Spindle indexing error with overfeed	Michele Williams noted: Fixed and tested.	michele_williams
A77	28/01/2015	Hydraulic line leak on side B	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A84	31/12/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A53	14/12/2015	Leaks found at turrets A and B	Michele Williams noted: Fixed and tested.	michele_williams
A26	14/04/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A35	10/01/2016	Turret A and B are leaking	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A54	03/09/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A56	24/02/2015	Leak in side B hydraulic line	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A42	23/12/2015	Machine is unpowered	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A48	17/07/2015	Milling spindle requires repair	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A85	30/08/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A27	20/06/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A39	02/02/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A27	16/12/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A12	05/02/2015	Turret sections A & B showing leaks	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A94	04/04/2015	Inspect and recharge accumulators	Gina Moore noted: No further details.	gina_moore, dylan_miller
A70	15/02/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A11	03/07/2015	Power supply failure detected	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A54	01/09/2015	Leaks found at turrets A and B	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A96	27/04/2015	Spindle indexing error with overfeed	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A86	06/01/2016	Leak in side B hydraulic line	Cristian Santos noted: Fixed and tested.	cristian_santos
A34	25/09/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A58	20/12/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A55	08/07/2015	Inspect and recharge accumulators	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A78	24/07/2015	Turret sections A & B showing leaks	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A25	24/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A88	07/05/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A81	08/08/2015	Milling spindle requires repair	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A15	05/10/2015	Machine is unpowered	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A69	26/10/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A37	25/03/2015	Leaks found at turrets A and B	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A91	21/10/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A58	17/03/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A9	24/09/2015	Leaks found at turrets A and B	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A85	18/03/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A24	24/02/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A89	10/04/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A63	17/01/2015	Maintenance on milling spindle needed	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A27	09/03/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: No further details.	nathan_maldonado
A88	29/01/2015	Hydraulic line leak on side B	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A66	18/02/2015	Turret A and B are leaking	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A55	03/01/2016	Turret sections A & B showing leaks	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A20	24/08/2015	Spindle fails to index, overfeeding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A73	23/07/2015	Machine is unpowered	Michele Williams noted: System checked and accumulators charged.	michele_williams
A43	04/01/2016	Repair work needed on milling spindle	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A47	06/05/2015	Repair work needed on milling spindle	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A33	31/08/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A33	20/02/2015	Accumulator inspection and charging required	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A86	14/04/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A32	23/04/2015	Repair work needed on milling spindle	Michele Williams noted: Fixed and tested.	michele_williams
A94	13/02/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A15	30/01/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A71	05/08/2015	Machine is unpowered	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A54	12/01/2016	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A16	24/06/2015	Turret sections A & B showing leaks	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A45	10/08/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A18	04/02/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A80	12/03/2015	Milling spindle requires repair	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A79	25/05/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A6	18/02/2015	Repair work needed on milling spindle	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A6	12/12/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A19	14/07/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A51	13/06/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A17	16/08/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A96	01/06/2015	Accumulators need checking and charging	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A28	08/11/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A77	11/09/2015	Accumulator inspection and charging required	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A22	14/06/2015	Machine is unpowered	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A28	13/10/2015	Leak in side B hydraulic line	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A73	08/08/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller

A19	09/04/2015	Turret A and B are leaking	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A68	01/05/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A73	07/10/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A1	25/09/2015	Turret A and B are leaking	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A20	08/12/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A11	12/09/2015	Turret sections A & B showing leaks	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A33	20/11/2015	Accumulator inspection and charging required	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A37	19/09/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A40	08/05/2015	Maintenance on milling spindle needed	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A37	13/10/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A68	19/12/2015	Maintenance on milling spindle needed	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A89	27/10/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A27	28/11/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A35	07/07/2015	Milling spindle requires repair	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A29	12/02/2015	Maintenance on milling spindle needed	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A29	19/02/2015	Power supply failure detected	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A76	07/03/2015	Turret A and B are leaking	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A71	10/01/2016	Machine is unpowered	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A76	21/03/2015	Turret A and B are leaking	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A2	11/02/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A49	12/03/2015	Power supply failure detected	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A15	20/05/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A82	08/06/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Repair completed.	michele_williams
A65	21/11/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A16	14/07/2015	Repair work needed on milling spindle	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A38	27/08/2015	Repair work needed on milling spindle	Cristian Santos noted: No further details.	cristian_santos
A64	13/04/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A91	19/11/2015	Leak in side B hydraulic line	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A81	20/12/2015	Hydraulic line leak on side B	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A93	18/03/2015	Leak in side B hydraulic line	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A91	13/04/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A97	16/12/2015	Milling spindle requires repair	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A52	10/03/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A51	19/05/2015	Accumulators need checking and charging	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A39	31/07/2015	Turret sections A & B showing leaks	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A67	09/05/2015	Unit lost electrical power	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A93	17/09/2015	Milling spindle requires repair	Michele Williams noted: Repair completed.	michele_williams
A58	26/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A55	30/07/2015	Machine is unpowered	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A40	02/04/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A52	31/10/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A81	08/02/2015	Machine is unpowered	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A18	01/10/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A37	04/12/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A54	17/06/2015	Accumulators need checking and charging	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A15	14/05/2015	Accumulators need checking and charging	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A63	24/09/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A19	15/03/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A3	24/01/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A95	31/07/2015	Repair work needed on milling spindle	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A3	02/09/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A41	01/03/2015	Turret A and B are leaking	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A5	19/05/2015	Power supply failure detected	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A88	25/03/2015	Maintenance on milling spindle needed	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A73	11/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A36	05/02/2015	Repair work needed on milling spindle	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A15	11/03/2015	Accumulator inspection and charging required	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A74	07/06/2015	Hydraulic line leak on side B	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A72	03/01/2016	Milling spindle requires repair	Cristian Santos noted: Detail not recorded.	cristian_santos
A30	07/07/2015	Leak in side B hydraulic line	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A72	31/05/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A17	19/04/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Fixed and tested.	michele_williams
A74	16/12/2015	Inspect and recharge accumulators	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A74	23/09/2015	Turret A and B are leaking	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A74	24/04/2015	Accumulators need checking and charging	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A7	25/03/2015	Turret sections A & B showing leaks	Michele Williams noted: No further details.	michele_williams
A19	22/10/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A2	06/06/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A50	24/06/2015	Hydraulic line leak on side B	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A83	30/11/2015	Spindle indexing error with overfeed	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller

A44	20/08/2015	Unit lost electrical power	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A88	20/01/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A49	18/04/2015	Turret sections A & B showing leaks	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A57	09/07/2015	Spindle fails to index, overfeeding	Michele Williams noted: System checked and accumulators charged.	michele_williams
A72	09/10/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A30	05/08/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A31	22/04/2015	Inspect and recharge accumulators	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A32	11/09/2015	Spindle indexing error with overfeed	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A83	28/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A53	09/05/2015	Saw attachment gears are binding and grinding	Michele Williams noted: No additional information provided.	michele_williams
A7	05/11/2015	Accumulator inspection and charging required	Cristian Santos noted: Repair completed.	cristian_santos
A84	10/09/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A31	05/12/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A50	24/01/2015	Turret sections A & B showing leaks	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A12	27/04/2015	Machine is unpowered	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A83	23/06/2015	Spindle indexing error with overfeed	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A12	02/02/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A91	18/01/2015	Maintenance on milling spindle needed	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A44	13/06/2015	Leak in side B hydraulic line	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A94	10/05/2015	Leak in side B hydraulic line	Michele Williams noted: No further details.	michele_williams
A13	17/03/2015	Hydraulic line leak on side B	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A17	16/06/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A49	01/10/2015	Spindle indexing error with overfeed	Michele Williams noted: System checked and accumulators charged.	michele_williams
A51	07/03/2015	Leak in side B hydraulic line	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A97	05/04/2015	Unit lost electrical power	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A95	13/08/2015	Turret sections A & B showing leaks	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A60	09/09/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A96	22/03/2015	Leaks found at turrets A and B	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A37	30/01/2015	Spindle indexing error with overfeed	Michele Williams noted: Maintenance action successful.	michele_williams
A19	20/01/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A72	18/02/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A98	18/02/2015	Leaks found at turrets A and B	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A35	14/03/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: No further details.	gina_moore, dylan_miller
A43	08/02/2015	Power supply failure detected	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A39	06/09/2015	Accumulators need checking and charging	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A12	23/06/2015	Turret sections A & B showing leaks	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A47	27/11/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A35	12/04/2015	Leak in side B hydraulic line	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A87	21/05/2015	Turret A and B are leaking	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A44	20/04/2015	Maintenance on milling spindle needed	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A49	07/06/2015	Accumulator inspection and charging required	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A53	23/02/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A44	03/12/2015	Leaks found at turrets A and B	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A67	31/08/2015	Machine is unpowered	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A92	03/09/2015	Repair work needed on milling spindle	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A49	14/04/2015	Leak in side B hydraulic line	Michele Williams noted: Maintenance action successful.	michele_williams
A38	20/07/2015	Turret A and B are leaking	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A89	03/10/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A53	07/09/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A15	16/05/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A41	26/10/2015	Leaks found at turrets A and B	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A52	06/02/2015	Machine is unpowered	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A83	21/10/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A19	10/06/2015	Spindle indexing error with overfeed	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A18	29/09/2015	Milling spindle requires repair	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A38	27/02/2015	Machine is unpowered	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A33	23/04/2015	Milling spindle requires repair	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A52	23/10/2015	Leak in side B hydraulic line	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A40	27/04/2015	Milling spindle requires repair	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A93	29/12/2015	Accumulator inspection and charging required	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A71	09/09/2015	Spindle fails to index, overfeeding	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A28	30/07/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A49	12/04/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A81	20/02/2015	Power supply failure detected	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A2	10/04/2015	Maintenance on milling spindle needed	Cristian Santos noted: Repair completed.	cristian_santos
A80	08/12/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A12	20/07/2015	Accumulator inspection and charging required	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A51	09/11/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A43	09/12/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A73	01/11/2015	Milling spindle requires repair	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams

A88	21/06/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A20	18/05/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A94	31/07/2015	Turret sections A & B showing leaks	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A29	17/05/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A61	01/04/2015	Leak in side B hydraulic line	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A97	11/11/2015	Turret A and B are leaking	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A94	08/06/2015	Power supply failure detected	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A14	23/11/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A34	10/03/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A4	04/09/2015	Accumulator inspection and charging required	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A48	30/12/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A7	20/02/2015	Leak in side B hydraulic line	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A15	18/03/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A64	09/05/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A95	30/07/2015	Turret A and B are leaking	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A90	28/08/2015	Spindle indexing error with overfeed	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A2	20/03/2015	Accumulators need checking and charging	Michele Williams noted: No additional information provided.	michele_williams
A23	19/02/2015	Leak in side B hydraulic line	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A53	04/04/2015	Accumulators need checking and charging	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A10	09/12/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A29	07/08/2015	Leaks found at turrets A and B	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A94	22/01/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A67	24/05/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A94	07/12/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A75	18/04/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A3	21/06/2015	Milling spindle requires repair	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A70	19/06/2015	Leak in side B hydraulic line	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A35	28/06/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A52	23/07/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A58	18/05/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A1	13/11/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A28	12/11/2015	Accumulators need checking and charging	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A34	30/08/2015	Turret A and B are leaking	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A46	15/12/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A45	07/05/2015	Power supply failure detected	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A9	21/08/2015	Machine is unpowered	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A21	23/11/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A96	29/07/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A57	06/03/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A17	22/04/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A16	23/01/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A52	21/09/2015	Leak in side B hydraulic line	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A45	11/11/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A47	15/03/2015	Milling spindle requires repair	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A86	28/06/2015	Maintenance on milling spindle needed	Michele Williams noted: System checked and accumulators charged.	michele_williams
A77	31/07/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A48	29/08/2015	Unit lost electrical power	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A89	14/11/2015	Machine is unpowered	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A18	21/07/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A83	25/09/2015	Leaks found at turrets A and B	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A70	22/03/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A48	19/06/2015	Maintenance on milling spindle needed	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A72	01/08/2015	Spindle fails to index, overfeeding	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A55	31/10/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A25	08/07/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A38	03/08/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A95	18/05/2015	Turret A and B are leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A48	15/08/2015	Spindle indexing error with overfeed	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A48	15/03/2015	Hydraulic line leak on side B	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A78	29/01/2015	Spindle fails to index, overfeeding	Michele Williams noted: No further details.	michele_williams
A55	07/08/2015	Power supply failure detected	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A29	30/06/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A1	25/06/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A7	17/11/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A69	10/02/2015	Hydraulic line leak on side B	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A93	03/12/2015	Unit lost electrical power	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A22	19/09/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A55	30/11/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A36	08/12/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A12	05/09/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams

A63	13/10/2015	Turret A and B are leaking	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A89	20/07/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A4	14/12/2015	Turret A and B are leaking	Michele Williams noted: Fixed and tested.	michele_williams
A17	26/08/2015	Milling spindle requires repair	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A63	18/10/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A20	23/12/2015	Leaks found at turrets A and B	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A16	13/06/2015	Maintenance on milling spindle needed	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A77	24/01/2015	Inspect and recharge accumulators	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A4	13/01/2016	Saw attachment is leaking hydraulics	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A33	30/11/2015	Accumulator inspection and charging required	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A41	25/01/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A15	08/08/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A6	11/07/2015	Power supply failure detected	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A53	13/06/2015	Inspect and recharge accumulators	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A51	17/08/2015	Inspect and recharge accumulators	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A88	02/03/2015	Spindle fails to index, overfeeding	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A45	29/09/2015	Maintenance on milling spindle needed	Michele Williams noted: Maintenance action successful.	michele_williams
A23	24/08/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A58	20/03/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A39	02/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A80	28/08/2015	Turret sections A & B showing leaks	Michele Williams noted: No further details.	michele_williams
A13	27/06/2015	Repair work needed on milling spindle	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A75	25/08/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A51	12/05/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A97	04/06/2015	Leaks found at turrets A and B	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A58	21/03/2015	Spindle indexing error with overfeed	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A15	09/08/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A64	01/04/2015	Unit lost electrical power	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A7	10/11/2015	Spindle indexing error with overfeed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A10	14/08/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A36	05/05/2015	Machine is unpowered	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A35	03/05/2015	Spindle fails to index, overfeeding	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A29	25/07/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A89	02/03/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A33	28/07/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A1	07/01/2016	Power supply failure detected	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A92	09/09/2015	Leak in side B hydraulic line	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A23	13/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A84	20/09/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A70	22/01/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A5	14/07/2015	Leaks found at turrets A and B	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A91	30/09/2015	Hydraulic line leak on side B	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A26	28/11/2015	Milling spindle requires repair	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A29	24/12/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A59	25/06/2015	Power supply failure detected	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A10	26/09/2015	Repair work needed on milling spindle	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A57	09/02/2015	Turret A and B are leaking	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A13	15/04/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A44	07/08/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A48	17/09/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A20	12/08/2015	Milling spindle requires repair	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A83	20/12/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A44	05/12/2015	Repair work needed on milling spindle	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A46	11/03/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A89	08/01/2016	Leak in side B hydraulic line	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A38	17/03/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A25	08/03/2015	Inspect and recharge accumulators	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A70	21/05/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A85	19/09/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A38	20/11/2015	Turret A and B are leaking	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A11	25/10/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A38	21/05/2015	Accumulator inspection and charging required	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A41	01/07/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A36	28/04/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A2	08/07/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A93	24/09/2015	Accumulators need checking and charging	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A37	26/11/2015	Milling spindle requires repair	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A65	20/08/2015	Leak in side B hydraulic line	Michele Williams noted: Maintenance action successful.	michele_williams
A8	13/09/2015	Hydraulic line leak on side B	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A76	10/10/2015	Leak in side B hydraulic line	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams

A78	08/01/2016	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A33	25/11/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A32	26/02/2015	Spindle indexing error with overfeed	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A39	18/05/2015	Maintenance on milling spindle needed	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A31	10/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A5	02/06/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A92	08/11/2015	Leaks found at turrets A and B	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A63	16/01/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A46	16/11/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A90	08/02/2015	Accumulator inspection and charging required	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A69	29/06/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A57	01/12/2015	Leak in side B hydraulic line	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A36	03/09/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A38	09/09/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A6	10/09/2015	Leaks found at turrets A and B	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A80	06/11/2015	Leaks found at turrets A and B	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A6	07/12/2015	Power supply failure detected	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A60	25/07/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A75	12/05/2015	Leaks found at turrets A and B	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A87	23/03/2015	Spindle indexing error with overfeed	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A32	07/10/2015	Spindle indexing error with overfeed	Cristian Santos noted: Fixed and tested.	cristian_santos
A76	22/12/2015	Maintenance on milling spindle needed	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A24	19/06/2015	Leaks found at turrets A and B	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A81	25/11/2015	Power supply failure detected	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A33	18/02/2015	Saw attachment gears are binding and grinding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A78	28/04/2015	Turret sections A & B showing leaks	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A91	26/03/2015	Accumulator inspection and charging required	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A24	11/07/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A94	06/04/2015	Turret A and B are leaking	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A97	19/08/2015	Leaks found at turrets A and B	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A37	07/01/2016	Repair work needed on milling spindle	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A88	13/04/2015	Milling spindle requires repair	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A93	06/03/2015	Leaks found at turrets A and B	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A55	13/06/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A40	18/07/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A41	10/05/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A77	15/02/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A69	31/01/2015	Accumulator inspection and charging required	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A31	11/10/2015	Accumulator inspection and charging required	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A48	20/09/2015	Unit lost electrical power	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A98	04/10/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A2	09/12/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A60	04/06/2015	Turret A and B are leaking	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A74	11/07/2015	Maintenance on milling spindle needed	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A80	03/09/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: No further details.	gina_moore, dylan_miller
A2	30/01/2015	Repair work needed on milling spindle	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A25	19/09/2015	Accumulator inspection and charging required	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A2	29/06/2015	Maintenance on milling spindle needed	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A30	22/03/2015	Turret sections A & B showing leaks	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A28	22/08/2015	Machine is unpowered	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A82	23/02/2015	Inspect and recharge accumulators	Michele Williams noted: No additional information provided.	michele_williams
A88	15/07/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A28	13/06/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A46	21/01/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A11	21/04/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A30	19/01/2015	Unit lost electrical power	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A3	24/03/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A47	04/11/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A29	26/12/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A53	07/04/2015	Turret A and B are leaking	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A58	24/12/2015	Accumulators need checking and charging	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A33	11/04/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A97	22/06/2015	Milling spindle requires repair	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A46	28/08/2015	Hydraulic line leak on side B	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A87	08/12/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A45	02/05/2015	Hydraulic line leak on side B	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A38	02/11/2015	Leak in side B hydraulic line	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A61	21/03/2015	Unit lost electrical power	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A56	11/04/2015	Unit lost electrical power	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A37	27/02/2015	Turret sections A & B showing leaks	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams

A75	26/05/2015	Repair work needed on milling spindle	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A54	31/10/2015	Leaks found at turrets A and B	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A62	11/12/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Maintenance action successful.	cristian_santos
A59	31/03/2015	Unit lost electrical power	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A89	06/12/2015	Repair work needed on milling spindle	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A66	03/05/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A3	19/04/2015	Leak in side B hydraulic line	Michele Williams noted: Repair completed.	michele_williams
A23	04/02/2015	Machine is unpowered	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A53	23/12/2015	Accumulator inspection and charging required	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A30	01/08/2015	Power supply failure detected	Cristian Santos noted: Maintenance action successful.	cristian_santos
A85	13/06/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A76	07/08/2015	Leaks found at turrets A and B	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A79	11/03/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A66	08/12/2015	Hydraulic line leak on side B	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A79	12/05/2015	Spindle indexing error with overfeed	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A46	25/06/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A27	02/01/2016	Leak in side B hydraulic line	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A73	20/09/2015	Milling spindle requires repair	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A13	25/06/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A65	04/10/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A21	16/11/2015	Leaks found at turrets A and B	Cristian Santos noted: No further details.	cristian_santos
A57	08/02/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: No further details.	cristian_santos
A2	14/04/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A38	23/12/2015	Turret sections A & B showing leaks	Cristian Santos noted: Maintenance action successful.	cristian_santos
A33	16/02/2015	Maintenance on milling spindle needed	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A74	23/07/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A38	15/03/2015	Accumulators need checking and charging	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A98	11/08/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A5	01/11/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A36	15/11/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A77	18/03/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A48	05/05/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A3	07/07/2015	Accumulator inspection and charging required	Cristian Santos noted: Detail not recorded.	cristian_santos
A48	05/11/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A17	07/06/2015	Leaks found at turrets A and B	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A98	18/01/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A85	29/11/2015	Turret sections A & B showing leaks	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A41	18/01/2015	Leak in side B hydraulic line	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A52	01/09/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A55	30/11/2015	Machine is unpowered	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A66	27/05/2015	Saw attachment is leaking hydraulics	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A66	22/03/2015	Turret A and B are leaking	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A62	26/02/2015	Leak in side B hydraulic line	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A19	17/03/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A64	28/07/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A19	26/03/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A43	13/11/2015	Leak in side B hydraulic line	Nathan Maldonado noted: No further details.	nathan_maldonado
A84	16/07/2015	Machine is unpowered	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A56	10/12/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A37	13/04/2015	Turret sections A & B showing leaks	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A40	13/07/2015	Accumulators need checking and charging	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A62	17/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A19	14/05/2015	Unit lost electrical power	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A38	02/11/2015	Hydraulic line leak on side B	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A98	03/12/2015	Maintenance on milling spindle needed	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A95	26/06/2015	Inspect and recharge accumulators	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A39	30/01/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A51	05/08/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A22	24/12/2015	Hydraulic line leak on side B	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A98	22/02/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A29	06/12/2015	Saw attachment gears are binding and grinding	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A46	21/09/2015	Maintenance on milling spindle needed	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A42	20/07/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A18	25/02/2015	Machine is unpowered	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A18	27/04/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: No additional information provided.	cristian_santos
A40	29/06/2015	Milling spindle requires repair	Nathan Maldonado noted: No further details.	nathan_maldonado
A27	29/03/2015	Milling spindle requires repair	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A30	23/04/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A24	13/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A83	29/04/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos

A94	11/08/2015	Milling spindle requires repair	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A7	19/01/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A27	05/12/2015	Spindle fails to index, overfeeding	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A68	26/03/2015	Turret A and B are leaking	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A96	07/02/2015	Hydraulic line leak on side B	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A23	02/03/2015	Milling spindle requires repair	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A78	29/05/2015	Machine is unpowered	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A82	26/02/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A52	17/11/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A81	28/11/2015	Repair work needed on milling spindle	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A28	30/06/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A9	03/01/2016	Leak in side B hydraulic line	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A65	13/07/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A99	25/12/2015	Inspect and recharge accumulators	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A61	13/12/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A94	25/03/2015	Power supply failure detected	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A76	18/01/2015	Inspect and recharge accumulators	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A74	22/09/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A3	14/10/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: No further details.	michele_williams
A78	13/11/2015	Repair work needed on milling spindle	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A7	26/05/2015	Inspect and recharge accumulators	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A63	19/12/2015	Power supply failure detected	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A6	01/12/2015	Leaks found at turrets A and B	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A83	21/12/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A77	08/06/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A90	28/02/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A94	08/12/2015	Accumulator inspection and charging required	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A76	24/02/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A29	17/05/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A11	14/07/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A23	16/05/2015	Turret sections A & B showing leaks	Michele Williams noted: Detail not recorded.	michele_williams
A74	17/07/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A35	01/12/2015	Hydraulic line leak on side B	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A31	21/07/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A89	20/04/2015	Hydraulic line leak on side B	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A10	13/05/2015	Turret sections A & B showing leaks	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A51	18/11/2015	Turret A and B are leaking	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A41	22/05/2015	Machine is unpowered	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A97	07/10/2015	Maintenance on milling spindle needed	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A28	16/06/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A4	15/06/2015	Machine is unpowered	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A48	05/07/2015	Spindle fails to index, overfeeding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A68	04/01/2016	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A73	16/02/2015	Milling spindle requires repair	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A61	30/07/2015	Milling spindle requires repair	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A60	07/07/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A31	26/09/2015	Inspect and recharge accumulators	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A53	13/06/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A10	29/05/2015	Milling spindle requires repair	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A29	29/01/2015	Spindle indexing error with overfeed	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A76	05/09/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A75	04/07/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A15	05/12/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A37	27/12/2015	Turret sections A & B showing leaks	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A39	06/06/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A69	04/12/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A4	15/02/2015	Machine is unpowered	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A46	15/01/2015	Milling spindle requires repair	Michele Williams noted: System checked and accumulators charged.	michele_williams
A10	20/02/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A10	09/05/2015	Turret sections A & B showing leaks	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A10	01/11/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A29	31/07/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A31	24/02/2015	Milling spindle requires repair	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A94	14/01/2015	Machine is unpowered	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A59	11/10/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A86	15/12/2015	Accumulator inspection and charging required	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A79	10/01/2016	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A42	28/12/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: No additional information provided.	cristian_santos
A64	01/11/2015	Leak in side B hydraulic line	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A14	27/01/2015	Turret sections A & B showing leaks	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller

A1	15/03/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A28	08/07/2015	Spindle fails to index, overfeeding	Michele Williams noted: No further details.	michele_williams
A47	29/09/2015	Leak in side B hydraulic line	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A20	23/07/2015	Milling spindle requires repair	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A1	28/06/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A65	12/12/2015	Leaks found at turrets A and B	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A98	22/10/2015	Milling spindle requires repair	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A88	07/07/2015	Milling spindle requires repair	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A20	08/08/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A55	15/03/2015	Turret A and B are leaking	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A37	30/03/2015	Power supply failure detected	Michele Williams noted: Detail not recorded.	michele_williams
A97	22/09/2015	Unit lost electrical power	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A11	04/03/2015	Repair work needed on milling spindle	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A2	25/02/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A40	04/10/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A53	24/06/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A84	28/01/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A23	02/05/2015	Hydraulic line leak on side B	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A90	28/11/2015	Accumulator inspection and charging required	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A1	06/04/2015	Unit lost electrical power	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A79	09/10/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A77	18/04/2015	Machine is unpowered	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A90	24/07/2015	Inspect and recharge accumulators	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A74	03/08/2015	Leak in side B hydraulic line	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A5	15/12/2015	Power supply failure detected	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A99	28/07/2015	Unit lost electrical power	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A82	09/05/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Maintenance action successful.	michele_williams
A74	09/05/2015	Hydraulic line leak on side B	Cristian Santos noted: No further details.	cristian_santos
A59	21/06/2015	Leaks found at turrets A and B	Gina Moore noted: No further details.	gina_moore, dylan_miller
A22	31/07/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A5	29/06/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A89	23/03/2015	Turret A and B are leaking	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A1	17/07/2015	Leak in side B hydraulic line	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A64	22/01/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A32	15/01/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A40	02/07/2015	Inspect and recharge accumulators	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A32	01/10/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A45	15/04/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A71	15/08/2015	Milling spindle requires repair	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A71	28/05/2015	Turret A and B are leaking	Nathan Maldonado noted: No further details.	nathan_maldonado
A46	25/06/2015	Repair work needed on milling spindle	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A88	07/10/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A47	19/01/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A11	24/06/2015	Accumulator inspection and charging required	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A53	14/05/2015	Milling spindle requires repair	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A55	28/01/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A31	05/02/2015	Accumulators need checking and charging	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A68	25/08/2015	Spindle indexing error with overfeed	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A34	14/08/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A13	15/12/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A18	21/12/2015	Accumulators need checking and charging	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A3	28/10/2015	Power supply failure detected	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A16	14/04/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A3	27/11/2015	Turret sections A & B showing leaks	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A38	12/11/2015	Unit lost electrical power	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A88	03/11/2015	Leak in side B hydraulic line	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A29	18/12/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A10	30/03/2015	Accumulator inspection and charging required	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A24	31/05/2015	Milling spindle requires repair	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A80	23/01/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A47	30/03/2015	Spindle indexing error with overfeed	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A95	07/06/2015	Turret A and B are leaking	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A85	26/03/2015	Machine is unpowered	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A81	08/05/2015	Accumulators need checking and charging	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A71	19/07/2015	Turret A and B are leaking	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A74	22/02/2015	Hydraulic line leak on side B	Michele Williams noted: Fixed and tested.	michele_williams
A15	22/01/2015	Unit lost electrical power	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A37	13/02/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A81	22/09/2015	Power supply failure detected	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A37	26/06/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado

A66	14/08/2015	Repair work needed on milling spindle	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A68	05/02/2015	Milling spindle requires repair	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A95	22/07/2015	Spindle indexing error with overfeed	Cristian Santos noted: No additional information provided.	cristian_santos
A74	16/02/2015	Hydraulic line leak on side B	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A72	16/09/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A40	24/08/2015	Machine is unpowered	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A16	22/07/2015	Accumulator inspection and charging required	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A90	25/11/2015	Leaks found at turrets A and B	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A15	10/06/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A17	11/07/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A57	09/06/2015	Turret A and B are leaking	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A54	27/08/2015	Maintenance on milling spindle needed	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A71	16/11/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A48	04/05/2015	Spindle fails to index, overfeeding	Michele Williams noted: Maintenance action successful.	michele_williams
A9	09/10/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A84	18/05/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: No further details.	cristian_santos
A62	25/03/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A45	25/09/2015	Unit lost electrical power	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A12	06/04/2015	Hydraulic line leak on side B	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A56	14/08/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A83	28/06/2015	Inspect and recharge accumulators	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A35	04/05/2015	Accumulator inspection and charging required	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A85	24/05/2015	Accumulators need checking and charging	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A4	09/03/2015	Inspect and recharge accumulators	Cristian Santos noted: Detail not recorded.	cristian_santos
A88	06/08/2015	Turret A and B are leaking	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A13	22/01/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A24	20/03/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A4	22/01/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A75	13/04/2015	Repair work needed on milling spindle	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A38	11/09/2015	Power supply failure detected	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A3	06/01/2016	Spindle indexing error with overfeed	Cristian Santos noted: Detail not recorded.	cristian_santos
A66	31/03/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A30	26/01/2015	Accumulator inspection and charging required	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A61	05/06/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A68	27/08/2015	Spindle indexing error with overfeed	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A20	29/10/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A59	30/07/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A38	07/04/2015	Machine is unpowered	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A37	21/01/2015	Unit lost electrical power	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A67	09/08/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A59	20/05/2015	Machine is unpowered	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A45	23/08/2015	Leaks found at turrets A and B	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A32	13/05/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A15	14/12/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A13	26/04/2015	Turret sections A & B showing leaks	Michele Williams noted: Repair completed.	michele_williams
A10	20/02/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A77	16/07/2015	Accumulator inspection and charging required	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A45	17/04/2015	Power supply failure detected	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A16	29/05/2015	Repair work needed on milling spindle	Michele Williams noted: Fixed and tested.	michele_williams
A18	07/05/2015	Maintenance on milling spindle needed	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A25	15/05/2015	Repair work needed on milling spindle	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A4	26/11/2015	Accumulators need checking and charging	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A38	08/04/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A16	08/02/2015	Accumulator inspection and charging required	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A6	29/11/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A13	07/01/2016	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A55	07/01/2016	Accumulator inspection and charging required	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A53	17/10/2015	Spindle indexing error with overfeed	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A10	26/03/2015	Power supply failure detected	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A64	01/02/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A13	19/06/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A26	11/09/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A93	22/04/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A26	29/01/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A90	16/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A32	25/04/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A28	07/09/2015	Milling spindle requires repair	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A62	03/05/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: No additional information provided.	michele_williams
A23	10/10/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A4	19/05/2015	Leak in side B hydraulic line	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams

A72	07/07/2015	Unit lost electrical power	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A40	17/07/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A50	07/05/2015	Repair work needed on milling spindle	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A77	27/12/2015	Milling spindle requires repair	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A27	04/08/2015	Spindle indexing error with overfeed	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A6	22/06/2015	Inspect and recharge accumulators	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A35	08/06/2015	Inspect and recharge accumulators	Michele Williams noted: No further details.	michele_williams
A32	15/01/2015	Turret A and B are leaking	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A85	30/11/2015	Maintenance on milling spindle needed	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A78	02/06/2015	Accumulators need checking and charging	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A66	21/01/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A24	07/12/2015	Hydraulic line leak on side B	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A5	02/11/2015	Machine is unpowered	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A87	23/09/2015	Repair work needed on milling spindle	Cristian Santos noted: Fixed and tested.	cristian_santos
A11	30/09/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A40	11/05/2015	Maintenance on milling spindle needed	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A71	27/04/2015	Leaks found at turrets A and B	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A47	09/01/2016	Leaks found at turrets A and B	Nathan Maldonado noted: No further details.	nathan_maldonado
A65	06/03/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A54	30/06/2015	Hydraulic line leak on side B	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A63	06/06/2015	Unit lost electrical power	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A92	23/10/2015	Turret sections A & B showing leaks	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A54	05/04/2015	Accumulators need checking and charging	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A91	28/07/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A64	12/09/2015	Turret sections A & B showing leaks	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A78	22/10/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A76	22/05/2015	Milling spindle requires repair	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A92	28/01/2015	Turret A and B are leaking	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A90	25/06/2015	Accumulators need checking and charging	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A53	08/06/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A67	05/12/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A82	10/03/2015	Leaks found at turrets A and B	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A6	23/05/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A17	06/05/2015	Turret sections A & B showing leaks	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A93	16/01/2015	Repair work needed on milling spindle	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A1	10/10/2015	Spindle indexing error with overfeed	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A19	15/12/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A9	16/03/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A66	02/11/2015	Accumulators need checking and charging	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A4	21/06/2015	Turret sections A & B showing leaks	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A19	25/11/2015	Machine is unpowered	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A84	10/01/2016	Accumulator inspection and charging required	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A99	06/11/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A88	10/07/2015	Turret sections A & B showing leaks	Cristian Santos noted: Maintenance action successful.	cristian_santos
A30	11/11/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A19	15/01/2015	Maintenance on milling spindle needed	Michele Williams noted: No additional information provided.	michele_williams
A49	28/11/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A46	30/07/2015	Accumulator inspection and charging required	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A30	27/07/2015	Power supply failure detected	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A80	10/07/2015	Hydraulic line leak on side B	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A86	17/12/2015	Turret sections A & B showing leaks	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A26	25/12/2015	Unit lost electrical power	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A86	06/07/2015	Milling spindle requires repair	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A86	19/08/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A85	20/01/2015	Accumulator inspection and charging required	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A19	01/08/2015	Accumulators need checking and charging	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A17	19/02/2015	Machine is unpowered	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A76	08/06/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A65	04/11/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A92	13/05/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A49	18/08/2015	Hydraulic line leak on side B	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A86	01/10/2015	Accumulator inspection and charging required	Michele Williams noted: No additional information provided.	michele_williams
A94	16/07/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A50	17/12/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A97	22/07/2015	Inspect and recharge accumulators	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A63	25/11/2015	Inspect and recharge accumulators	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A4	10/02/2015	Accumulators need checking and charging	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A44	22/10/2015	Leak in side B hydraulic line	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A39	08/08/2015	Turret sections A & B showing leaks	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A93	20/02/2015	Inspect and recharge accumulators	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams

A14	07/04/2015	Hydraulic line leak on side B	Michele Williams noted: Repair completed.	michele_williams
A45	10/07/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A87	27/06/2015	Inspect and recharge accumulators	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A25	27/04/2015	Machine is unpowered	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A65	30/09/2015	Grinding noise from tight gears on saw attachment	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A53	16/10/2015	Spindle indexing error with overfeed	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A19	26/08/2015	Inspect and recharge accumulators	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A48	07/10/2015	Repair work needed on milling spindle	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A49	27/10/2015	Maintenance on milling spindle needed	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A15	16/04/2015	Unit lost electrical power	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A27	25/01/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Repair completed.	cristian_santos
A74	14/05/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A7	09/08/2015	Spindle indexing error with overfeed	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A68	19/06/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A77	05/09/2015	Turret sections A & B showing leaks	Gina Moore noted: No further details.	gina_moore, dylan_miller
A48	06/01/2016	Turret sections A & B showing leaks	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A16	18/06/2015	Inspect and recharge accumulators	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A38	01/02/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A26	22/01/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A41	22/11/2015	Unit lost electrical power	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A33	15/11/2015	Hydraulic line leak on side B	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A29	03/03/2015	Machine is unpowered	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A58	29/01/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Repair completed.	cristian_santos
A67	15/12/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A78	25/01/2015	Accumulators need checking and charging	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A25	18/03/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A73	13/10/2015	Leaks found at turrets A and B	Gina Moore noted: No further details.	gina_moore, dylan_miller
A91	15/09/2015	Leak in side B hydraulic line	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A62	04/03/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A3	15/10/2015	Turret A and B are leaking	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A92	22/05/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues.	nathan_maldonado
A95	24/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A60	23/07/2015	Leaks found at turrets A and B	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A79	15/08/2015	Leaks found at turrets A and B	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A71	28/12/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A66	04/10/2015	Inspect and recharge accumulators	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A59	18/08/2015	Accumulators need checking and charging	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A62	04/09/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A67	20/07/2015	Machine is unpowered	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A54	08/01/2016	Maintenance on milling spindle needed	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A79	18/09/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A32	12/03/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A70	05/04/2015	Power supply failure detected	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A66	10/09/2015	Leak in side B hydraulic line	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A4	07/05/2015	Power supply failure detected	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A65	28/09/2015	Hydraulic line leak on side B	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A6	31/05/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A98	16/04/2015	Spindle indexing error with overfeed	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A90	26/07/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A19	22/05/2015	Maintenance on milling spindle needed	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A74	02/12/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A86	05/04/2015	Spindle indexing error with overfeed	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A35	15/12/2015	Spindle indexing error with overfeed	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A61	24/11/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A77	13/06/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A37	02/05/2015	Accumulator inspection and charging required	Michele Williams noted: Maintenance action successful.	michele_williams
A2	16/07/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A85	12/08/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A10	15/12/2015	Maintenance on milling spindle needed	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A65	09/07/2015	Maintenance on milling spindle needed	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A24	16/03/2015	Milling spindle requires repair	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A85	06/12/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A68	24/07/2015	Power supply failure detected	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A3	25/10/2015	Hydraulic line leak on side B	Cristian Santos noted: No additional information provided.	cristian_santos
A79	12/02/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A16	31/01/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A82	30/01/2015	Accumulators need checking and charging	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A96	31/03/2015	Accumulators need checking and charging	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A11	26/05/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A79	09/02/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams

A84	14/05/2015	Spindle fails to index, overfeeding	Michele Williams noted: No further details.	michele_williams
A83	11/01/2016	Saw attachment gears are binding and grinding	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A1	13/09/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A83	26/04/2015	Machine is unpowered	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A67	28/02/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A87	30/03/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A24	05/06/2015	Turret sections A & B showing leaks	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A40	10/06/2015	Leak in side B hydraulic line	Cristian Santos noted: Repair completed.	cristian_santos
A20	03/08/2015	Leaks found at turrets A and B	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A76	25/12/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A14	19/08/2015	Hydraulic line leak on side B	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A55	18/02/2015	Unit lost electrical power	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A98	13/03/2015	Turret A and B are leaking	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A2	17/10/2015	Leak in side B hydraulic line	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A82	16/12/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A23	22/05/2015	Machine is unpowered	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A58	28/03/2015	Indexing issue causing overfeed on spindle	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A87	10/07/2015	Repair work needed on milling spindle	Cristian Santos noted: Maintenance action successful.	cristian_santos
A93	11/01/2016	Accumulators need checking and charging	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A74	05/05/2015	Unit lost electrical power	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A65	27/09/2015	Unit lost electrical power	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A49	08/10/2015	Machine is unpowered	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A74	01/08/2015	Turret A and B are leaking	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A94	15/12/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A46	30/03/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A16	13/03/2015	Leak in side B hydraulic line	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A79	02/01/2016	Accumulators need checking and charging	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A64	08/10/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A16	11/02/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A59	18/12/2015	Turret A and B are leaking	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A28	21/02/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Fixed and tested.	nathan_maldonado
A68	17/04/2015	Spindle indexing error with overfeed	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A34	13/05/2015	Accumulator inspection and charging required	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A75	10/03/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A82	21/08/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A32	13/01/2016	Spindle indexing error with overfeed	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A81	12/07/2015	Turret A and B are leaking	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A52	07/05/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A66	25/10/2015	Accumulators need checking and charging	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A73	24/05/2015	Leak in side B hydraulic line	Cristian Santos noted: Repair completed.	cristian_santos
A74	28/09/2015	Accumulators need checking and charging	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A63	03/03/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A25	27/03/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A73	07/10/2015	Spindle fails to index, overfeeding	Michele Williams noted: No further details.	michele_williams
A94	20/04/2015	Leaks found at turrets A and B	Cristian Santos noted: Repair completed.	cristian_santos
A49	03/03/2015	Leak in side B hydraulic line	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A18	10/07/2015	Power supply failure detected	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A37	09/06/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A95	12/09/2015	Leak in side B hydraulic line	Nathan Maldonado noted: No further details.	nathan_maldonado
A50	19/04/2015	Repair work needed on milling spindle	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A14	12/09/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A40	12/06/2015	Hydraulic line leak on side B	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A95	25/03/2015	Repair work needed on milling spindle	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A98	09/03/2015	Unit lost electrical power	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A12	01/06/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A92	13/10/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams
A84	21/01/2015	Spindle fails to index, overfeeding	Michele Williams noted: No additional information provided.	michele_williams
A84	03/06/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A73	25/01/2015	Maintenance on milling spindle needed	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A9	23/06/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A43	29/03/2015	Power supply failure detected	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A35	17/02/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A41	22/07/2015	Accumulators need checking and charging	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A55	23/01/2015	Leak in side B hydraulic line	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A79	27/10/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A6	23/07/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A31	21/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A87	25/07/2015	Accumulators need checking and charging	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A52	01/09/2015	Maintenance on milling spindle needed	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A31	06/01/2016	Saw attachment gears are binding and grinding	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller

A28	27/06/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A71	29/09/2015	Milling spindle requires repair	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A41	02/07/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A81	14/12/2015	Turret A and B are leaking	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A73	24/01/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues	angie_henderson, michele_williams
A13	11/05/2015	Maintenance on milling spindle needed	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A27	11/09/2015	Leaks found at turrets A and B	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A25	30/10/2015	Machine is unpowered	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A71	24/11/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A79	20/06/2015	Turret sections A & B showing leaks	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A67	02/06/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A99	29/08/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A22	09/03/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A95	19/05/2015	Unit lost electrical power	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A81	14/10/2015	Inspect and recharge accumulators	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A93	07/10/2015	Milling spindle requires repair	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A4	02/08/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Turrets dismantled and chip debris removed.	nathan_maldonado
A64	04/11/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A4	14/08/2015	Hydraulic line leak on side B	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A90	12/02/2015	Machine is unpowered	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A18	22/09/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A38	26/06/2015	Hydraulic line leak on side B	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A90	26/04/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A50	21/11/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A34	07/05/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A5	14/09/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A89	26/03/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A81	05/09/2015	Leak in side B hydraulic line	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A49	20/07/2015	Unit lost electrical power	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A74	24/04/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Performed inspection and accumulator charging.	nathan_maldonado
A13	25/11/2015	Inspect and recharge accumulators	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A58	15/02/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A66	02/01/2016	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A62	21/10/2015	Leak in side B hydraulic line	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A48	15/06/2015	Turret A and B are leaking	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A12	24/06/2015	Milling spindle requires repair	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A51	12/06/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A70	25/04/2015	Power supply failure detected	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A9	26/02/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A7	21/08/2015	Power supply failure detected	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A41	29/12/2015	Milling spindle requires repair	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A57	31/10/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A22	12/05/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A29	01/02/2015	Inspect and recharge accumulators	Cristian Santos noted: Detail not recorded.	cristian_santos
A15	16/04/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A93	25/11/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A69	09/02/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A24	09/06/2015	Accumulator inspection and charging required	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A87	27/07/2015	Leak in side B hydraulic line	Michele Williams noted: Repair completed.	michele_williams
A19	23/04/2015	Maintenance on milling spindle needed	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A30	08/06/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A28	01/07/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A24	23/04/2015	Turret sections A & B showing leaks	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A58	04/08/2015	Leak in side B hydraulic line	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A41	20/04/2015	Milling spindle requires repair	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A26	09/02/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A14	03/07/2015	Turret sections A & B showing leaks	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A32	26/08/2015	Turret sections A & B showing leaks	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A88	01/07/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A30	06/11/2015	Hydraulic line leak on side B	Cristian Santos noted: Maintenance action successful.	cristian_santos
A68	24/04/2015	Milling spindle requires repair	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A12	01/01/2016	Leak in side B hydraulic line	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A64	26/07/2015	Turret A and B are leaking	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A16	05/01/2016	Hydraulic line leak on side B	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A11	01/04/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Maintenance action successful.	cristian_santos
A98	26/07/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A17	23/01/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A7	10/05/2015	Maintenance on milling spindle needed	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A91	11/12/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A88	27/08/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado

A77	21/02/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: No further details.	nathan_maldonado
A38	18/03/2015	Accumulator inspection and charging required	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A96	13/05/2015	Milling spindle requires repair	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A38	08/11/2015	Turret A and B are leaking	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A40	21/11/2015	Milling spindle requires repair	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A55	05/10/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A53	28/06/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Maintenance action successful.	michele_williams
A18	11/06/2015	Milling spindle requires repair	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A67	30/01/2015	Spindle indexing error with overfeed	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A68	23/06/2015	Leaks found at turrets A and B	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A12	09/02/2015	Milling spindle requires repair	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A77	20/07/2015	Leaks found at turrets A and B	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A61	26/05/2015	Machine is unpowered	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A43	03/11/2015	Leaks found at turrets A and B	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A13	20/11/2015	Machine is unpowered	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A36	20/04/2015	Turret A and B are leaking	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A65	31/03/2015	Hydraulic line leak on side B	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A7	26/02/2015	Accumulator inspection and charging required	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A81	21/05/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A6	26/11/2015	Turret A and B are leaking	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A97	03/05/2015	Spindle fails to index, overfeeding	Michele Williams noted: Detail not recorded.	michele_williams
A95	13/08/2015	Spindle fails to index, overfeeding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A20	28/06/2015	Turret sections A & B showing leaks	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A21	03/02/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A76	08/06/2015	Spindle indexing error with overfeed	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A43	18/08/2015	Accumulators need checking and charging	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A43	05/08/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A27	16/04/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A94	24/07/2015	Leak in side B hydraulic line	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A63	31/10/2015	Repair work needed on milling spindle	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A36	21/01/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A37	17/05/2015	Spindle indexing error with overfeed	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A35	08/04/2015	Turret A and B are leaking	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A73	16/06/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A34	24/10/2015	Unit lost electrical power	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A73	12/03/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A83	30/12/2015	Machine is unpowered	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A96	23/12/2015	Leaks found at turrets A and B	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A65	02/05/2015	Spindle indexing error with overfeed	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A11	11/01/2016	Hydraulic hose on side B is leaking	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A58	29/08/2015	Hydraulic line leak on side B	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A48	12/01/2016	Accumulators need checking and charging	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A40	07/01/2016	Accumulators need checking and charging	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A96	15/03/2015	Power supply failure detected	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A78	14/02/2015	Maintenance on milling spindle needed	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A98	16/12/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A77	24/06/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A32	11/04/2015	Leaks found at turrets A and B	Cristian Santos noted: Saw attachment seal changed, yet hydraulic leak continues.	cristian_santos
A72	22/08/2015	Spindle indexing error with overfeed	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A65	12/09/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Saw attachment seal changed, yet hydraulic leak continues.	angie_henderson, michele_williams
A24	30/10/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A3	04/07/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A34	28/06/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A69	20/02/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A43	28/01/2015	Repair work needed on milling spindle	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A97	06/11/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A82	12/12/2015	Inspect and recharge accumulators	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A77	02/10/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A60	28/02/2015	Machine is unpowered	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A20	13/08/2015	Hydraulic line leak on side B	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A67	04/08/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: No further details.	gina_moore, dylan_miller
A23	09/04/2015	Maintenance on milling spindle needed	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A55	18/12/2015	Maintenance on milling spindle needed	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A4	14/09/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A37	11/10/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A13	24/09/2015	Maintenance on milling spindle needed	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A42	24/05/2015	Leaks found at turrets A and B	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A23	09/08/2015	Inspect and recharge accumulators	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A19	09/08/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A41	12/09/2015	Unit lost electrical power	Michele Williams noted: No further details.	michele_williams

A71	02/09/2015	Inspect and recharge accumulators	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A29	10/10/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Repair completed.	michele_williams
A62	19/02/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A62	09/05/2015	Milling spindle requires repair	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A79	14/10/2015	Accumulators need checking and charging	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A65	09/03/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A47	30/11/2015	Turret sections A & B showing leaks	Michele Williams noted: Replaced pendant pin and restarted the machine.	michele_williams
A16	25/04/2015	Milling spindle requires repair	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A65	27/08/2015	Spindle fails to index, overfeeding	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A46	21/07/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A13	23/04/2015	Repair work needed on milling spindle	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A24	07/04/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A89	22/01/2015	Accumulator inspection and charging required	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A33	26/06/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Turrets dismantled and chip debris removed.	ethan_adams, michele_williams
A7	10/06/2015	Accumulator inspection and charging required	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A85	05/12/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Fixed and tested.	cristian_santos
A44	24/07/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A63	08/01/2016	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A14	11/12/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A80	20/09/2015	Accumulator inspection and charging required	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A40	17/05/2015	Inspect and recharge accumulators	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A83	05/01/2016	Hydraulic hose on side B is leaking	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A93	16/01/2015	Leak in side B hydraulic line	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A62	05/06/2015	Hydraulic line leak on side B	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A57	17/03/2015	Spindle indexing error with overfeed	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A39	21/11/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A27	28/08/2015	Turret A and B are leaking	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A71	11/07/2015	Repair work needed on milling spindle	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A35	25/03/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continu	nathan_maldonado
A25	01/11/2015	Spindle indexing error with overfeed	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A12	27/10/2015	Repair work needed on milling spindle	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A97	20/05/2015	Power supply failure detected	Gina Moore noted: Fixed and tested.	gina_moore, dylan_miller
A47	14/05/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A16	28/02/2015	Hydraulic hose on side B is leaking	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A74	02/10/2015	Accumulators need checking and charging	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A85	03/06/2015	Inspect and recharge accumulators	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A39	07/10/2015	Accumulators need checking and charging	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A54	09/03/2015	Leak in side B hydraulic line	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A18	23/11/2015	Milling spindle requires repair	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A2	30/05/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A38	06/12/2015	Milling spindle requires repair	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A80	13/01/2016	Repair work needed on milling spindle	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A14	28/06/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Fixed and tested.	michele_williams
A32	30/05/2015	Leaks found at turrets A and B	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A8	16/12/2015	Leak in side B hydraulic line	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A53	12/11/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: Replaced pendant pin and restarted the machine.	angie_henderson, michele_williams
A35	09/07/2015	Repair work needed on milling spindle	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A69	12/12/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A85	23/10/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: No further details.	cristian_santos
A1	02/04/2015	Leaks found at turrets A and B	Cristian Santos noted: Fixed and tested.	cristian_santos
A66	22/10/2015	Repair work needed on milling spindle	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A86	12/02/2015	Spindle indexing error with overfeed	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A49	19/10/2015	Repair work needed on milling spindle	Cristian Santos noted: Removed turrets to clean off metal shavings.	cristian_santos
A91	25/04/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A40	13/08/2015	Unit lost electrical power	Michele Williams noted: Fixed and tested.	michele_williams
A25	28/08/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A81	27/11/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A59	23/01/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A47	17/02/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A58	14/08/2015	Leak in side B hydraulic line	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A84	03/08/2015	Leaks found at turrets A and B	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A28	06/05/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A9	06/08/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A84	08/12/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A39	18/12/2015	Leak in side B hydraulic line	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A59	09/01/2016	Indexing issue causing overfeed on spindle	Michele Williams noted: Fixed and tested.	michele_williams
A46	20/06/2015	Maintenance on milling spindle needed	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A16	06/03/2015	Maintenance on milling spindle needed	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A15	01/02/2015	Spindle indexing error with overfeed	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A97	15/02/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller

A34	15/07/2015	Inspect and recharge accumulators	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A43	14/06/2015	Spindle indexing error with overfeed	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A81	04/01/2016	Spindle indexing error with overfeed	Cristian Santos noted: Repair completed.	cristian_santos
A20	13/12/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A91	29/10/2015	Inspect and recharge accumulators	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A49	28/11/2015	Turret A and B are leaking	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A85	31/10/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A82	29/03/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A13	27/01/2015	Repair work needed on milling spindle	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A97	08/03/2015	Spindle indexing error with overfeed	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A26	30/07/2015	Milling spindle requires repair	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A91	17/06/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A74	05/07/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A43	12/03/2015	Accumulators need checking and charging	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A26	29/09/2015	Machine is unpowered	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A70	17/07/2015	Accumulators need checking and charging	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A11	08/11/2015	Leak in side B hydraulic line	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A6	23/12/2015	Power supply failure detected	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A1	13/03/2015	Turret sections A & B showing leaks	Michele Williams noted: System checked and accumulators charged.	michele_williams
A66	03/02/2015	Accumulator inspection and charging required	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A76	18/04/2015	Repair work needed on milling spindle	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A2	05/04/2015	Saw attachment gears are binding and grinding	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A8	19/12/2015	Milling spindle requires repair	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A23	20/12/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A24	22/07/2015	Spindle indexing error with overfeed	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A32	02/08/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A29	20/07/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A18	05/12/2015	Unit lost electrical power	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A70	07/03/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A48	18/06/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A75	24/04/2015	Accumulator inspection and charging required	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A60	31/12/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A55	07/08/2015	Accumulators need checking and charging	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A12	17/02/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A79	27/07/2015	Repair work needed on milling spindle	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A49	11/02/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A51	10/08/2015	Accumulators need checking and charging	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A85	16/12/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: Seal on saw attachment replaced, but leak persists.	nathan_maldonado
A45	25/12/2015	Repair work needed on milling spindle	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A30	30/03/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A48	28/02/2015	Turret sections A & B showing leaks	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A77	29/04/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A47	22/07/2015	Leak in side B hydraulic line	Cristian Santos noted: No further details.	cristian_santos
A69	11/10/2015	Maintenance on milling spindle needed	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A27	14/02/2015	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A37	22/10/2015	Unit lost electrical power	Cristian Santos noted: No additional information provided.	cristian_santos
A54	24/02/2015	Hydraulic line leak on side B	Gina Moore noted: No further details.	gina_moore, dylan_miller
A38	09/08/2015	Repair work needed on milling spindle	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A42	29/10/2015	Power supply failure detected	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A20	07/12/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A93	10/12/2015	Inspect and recharge accumulators	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A5	29/12/2015	Spindle fails to index, overfeeding	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A74	15/11/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A44	15/07/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A21	31/07/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A87	31/03/2015	Hydraulic line leak on side B	Cristian Santos noted: Maintenance action successful.	cristian_santos
A6	19/11/2015	Hydraulic hose on side B is leaking	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A57	16/04/2015	Power supply failure detected	Cristian Santos noted: Detail not recorded.	cristian_santos
A81	08/02/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: Checked status and recharged accumulators.	angie_henderson, michele_williams
A76	27/02/2015	Unit lost electrical power	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A39	26/05/2015	Milling spindle requires repair	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A84	22/06/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A3	26/08/2015	Maintenance on milling spindle needed	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A45	22/10/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A33	21/12/2015	Leaks found at turrets A and B	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A13	16/10/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A55	05/07/2015	Inspect and recharge accumulators	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A44	21/05/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A57	20/01/2015	Hydraulic line leak on side B	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A5	14/09/2015	Turret A and B are leaking	Ethan Adams noted: Fixed and tested.	ethan_adams, michele_williams

A30	11/12/2015	Leak in side B hydraulic line	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A69	29/07/2015	Power supply failure detected	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A96	17/02/2015	Machine is unpowered	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A96	07/03/2015	Spindle indexing error with overfeed	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A29	01/06/2015	Spindle fails to index, overfeeding	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A86	24/08/2015	Spindle indexing error with overfeed	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A81	27/04/2015	Accumulators need checking and charging	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A47	30/04/2015	Machine is unpowered	Michele Williams noted: Detail not recorded.	michele_williams
A95	25/03/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A89	02/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A59	23/02/2015	Spindle fails to index, overfeeding	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A7	01/11/2015	Leaks found at turrets A and B	Michele Williams noted: Rewiring done on threading unit, procedure finished.	michele_williams
A56	28/07/2015	Power supply failure detected	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A50	22/06/2015	Power supply failure detected	Cristian Santos noted: Maintenance action successful.	cristian_santos
A58	05/09/2015	Machine is unpowered	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A95	20/11/2015	Power supply failure detected	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A66	15/03/2015	Hydraulic line leak on side B	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A71	04/10/2015	Leak in side B hydraulic line	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A90	26/06/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A28	03/12/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A1	22/07/2015	Spindle fails to index, overfeeding	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A59	10/06/2015	Accumulators need checking and charging	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A67	09/04/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A39	04/01/2016	Turret sections A & B showing leaks	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A97	11/10/2015	Machine is unpowered	Ethan Adams noted: Reviewed; system operating normally.	ethan_adams, michele_williams
A59	02/07/2015	Leaks found at turrets A and B	Nathan Maldonado noted: No further details.	nathan_maldonado
A83	09/02/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A22	03/05/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: No further details.	gina_moore, dylan_miller
A92	25/10/2015	Leaks found at turrets A and B	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A4	11/08/2015	Indexing issue causing overfeed on spindle	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A73	09/01/2016	Accumulator inspection and charging required	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A91	03/06/2015	Machine is unpowered	Cristian Santos noted: Maintenance action successful.	cristian_santos
A13	21/06/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A28	21/02/2015	Unit lost electrical power	Cristian Santos noted: Installed new saw attachment seal; leakage remains.	cristian_santos
A32	21/09/2015	Hydraulic line leak on side B	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A54	20/04/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A39	25/08/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A30	10/02/2015	Inspect and recharge accumulators	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A73	15/08/2015	Hydraulic fluid leak at saw attachment	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A77	03/12/2015	Power supply failure detected	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A4	22/08/2015	Saw attachment is leaking hydraulics	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A28	31/07/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Maintenance action successful.	michele_williams
A69	03/07/2015	Power supply failure detected	Michele Williams noted: Completed rewiring of the threading unit.	michele_williams
A43	08/03/2015	Power supply failure detected	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A85	13/05/2015	Accumulators need checking and charging	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A15	31/12/2015	Leak in side B hydraulic line	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A53	29/06/2015	Saw attachment is leaking hydraulics	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A87	25/11/2015	Accumulator inspection and charging required	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A78	07/09/2015	Unit lost electrical power	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A29	07/03/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller
A69	20/05/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: No further details.	cristian_santos
A6	13/04/2015	Turret sections A & B showing leaks	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A58	05/08/2015	Hydraulic line leak on side B	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A19	20/03/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: System checked and accumulators charged.	michele_williams
A86	14/10/2015	Repair work needed on milling spindle	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A64	27/02/2015	Maintenance on milling spindle needed	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A13	18/12/2015	Leak in side B hydraulic line	Gina Moore noted: Reviewed; system operating normally.	gina_moore, dylan_miller
A49	01/09/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Performed inspection and accumulator charging.	ethan_adams, michele_williams
A64	18/08/2015	Spindle indexing error with overfeed	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A34	09/10/2015	Spindle indexing error with overfeed	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A58	24/10/2015	Leak in side B hydraulic line	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A29	22/08/2015	Leak in side B hydraulic line	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A71	26/12/2015	Saw attachment gears are binding and grinding	Cristian Santos noted: Detail not recorded.	cristian_santos
A9	21/05/2015	Maintenance on milling spindle needed	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A12	05/12/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A1	25/01/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A62	15/10/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Check performed; everything looks fine.	ethan_adams, michele_williams
A24	18/11/2015	Machine is unpowered	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A84	25/10/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A48	19/09/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado

A38	17/03/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A32	22/11/2015	Maintenance on milling spindle needed	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A25	05/12/2015	Gears on the saw attachment are too tight and grinding	Michele Williams noted: Performed inspection and accumulator charging.	michele_williams
A75	09/08/2015	Repair work needed on milling spindle	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A58	06/11/2015	Saw attachment gears are binding and grinding	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A73	05/05/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A99	13/06/2015	Power supply failure detected	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A24	05/01/2016	Accumulator inspection and charging required	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A84	27/09/2015	Unit lost electrical power	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A84	07/12/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A33	25/11/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A9	25/07/2015	Accumulators need checking and charging	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A10	24/07/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A75	20/03/2015	Spindle fails to index, overfeeding	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A68	06/07/2015	Turret A and B are leaking	Angie Henderson noted: Fixed and tested.	angie_henderson, michele_williams
A24	07/12/2015	Hydraulic hose on side B is leaking	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A12	23/01/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Detail not recorded.	cristian_santos
A92	21/03/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A69	18/09/2015	Unit lost electrical power	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A72	01/07/2015	Unit lost electrical power	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A42	18/11/2015	Repair work needed on milling spindle	Cristian Santos noted: Maintenance action successful.	cristian_santos
A99	12/04/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A64	13/08/2015	Accumulators need checking and charging	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A53	27/04/2015	Accumulator inspection and charging required	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A70	02/06/2015	Unit lost electrical power	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A29	15/08/2015	Turret A and B are leaking	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A74	11/09/2015	Repair work needed on milling spindle	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A92	05/07/2015	Power supply failure detected	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A7	23/04/2015	Spindle fails to index, overfeeding	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A89	11/01/2016	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A63	17/07/2015	Leaks found at turrets A and B	Angie Henderson noted: System checked and accumulators charged.	angie_henderson, michele_williams
A92	05/09/2015	Turret sections A & B showing leaks	Angie Henderson noted: Inspection complete; no issues found.	angie_henderson, michele_williams
A44	23/03/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: Detail not recorded.	cristian_santos
A77	28/09/2015	Leaks found at turrets A and B	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A91	06/07/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Chips cleared and turrets cleaned.	michele_williams
A90	10/08/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A54	10/03/2015	Milling spindle requires repair	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A13	27/05/2015	Milling spindle requires repair	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A48	27/09/2015	Repair work needed on milling spindle	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A44	08/01/2016	Hydraulic hose on side B is leaking	Cristian Santos noted: Performed inspection and accumulator charging.	cristian_santos
A77	26/10/2015	Power supply failure detected	Gina Moore noted: Performed inspection and accumulator charging.	gina_moore, dylan_miller
A6	03/10/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Fixed and tested.	michele_williams
A2	03/03/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Fixed and tested.	michele_williams
A52	08/05/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Inspection complete; no issues found.	michele_williams
A18	16/11/2015	Milling spindle requires repair	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A8	23/05/2015	Saw attachment gears are binding and grinding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A7	12/07/2015	Leak in side B hydraulic line	Michele Williams noted: Fixed and tested.	michele_williams
A55	12/01/2016	Inspect and recharge accumulators	Michele Williams noted: No further details.	michele_williams
A82	22/02/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A52	13/05/2015	Leak in side B hydraulic line	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A19	14/11/2015	Accumulator inspection and charging required	Cristian Santos noted: Checked status and recharged accumulators.	cristian_santos
A28	22/05/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A56	18/10/2015	Turret sections A & B showing leaks	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A93	19/01/2015	Leak in side B hydraulic line	Cristian Santos noted: Chips cleared and turrets cleaned.	cristian_santos
A82	27/06/2015	Leaks found at turrets A and B	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A20	06/05/2015	Power supply failure detected	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A77	31/01/2015	Hydraulic hose on side B is leaking	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A5	28/04/2015	Leak in side B hydraulic line	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A53	02/07/2015	Gears on the saw attachment are too tight and grinding	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A94	18/10/2015	Machine is unpowered	Angie Henderson noted: Reviewed; system operating normally.	angie_henderson, michele_williams
A11	23/11/2015	Turret A and B are leaking	Ethan Adams noted: Threading unit rewired; job completed.	ethan_adams, michele_williams
A13	09/02/2015	Spindle fails to index, overfeeding	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A60	25/06/2015	Accumulators need checking and charging	Angie Henderson noted: Maintenance action successful.	angie_henderson, michele_williams
A73	24/06/2015	Leaks found at turrets A and B	Ethan Adams noted: Installed new saw attachment seal; leakage remains.	ethan_adams, michele_williams
A11	24/11/2015	Spindle fails to index, overfeeding	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A75	24/12/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A64	02/12/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Repair completed.	michele_williams
A61	06/06/2015	Milling spindle requires repair	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A89	29/08/2015	Accumulator inspection and charging required	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A4	16/12/2015	Repair work needed on milling spindle	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams

A4	14/03/2015	Hydraulic line leak on side B	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A47	07/09/2015	Turret A and B are leaking	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A44	10/04/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A32	09/08/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A90	14/06/2015	Turret sections A & B showing leaks	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A46	21/03/2015	Power supply failure detected	Ethan Adams noted: Rewiring done on threading unit, procedure finished.	ethan_adams, michele_williams
A16	26/11/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A71	26/08/2015	Unit lost electrical power	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A29	08/04/2015	Hydraulic hose on side B is leaking	Ethan Adams noted: System checked and accumulators charged.	ethan_adams, michele_williams
A30	09/09/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Maintenance action successful.	cristian_santos
A89	01/06/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: No additional information provided.	gina_moore, dylan_miller
A15	18/03/2015	Hydraulic hose on side B is leaking	Cristian Santos noted: No further details.	cristian_santos
A80	22/11/2015	Leak in side B hydraulic line	Angie Henderson noted: Rewiring done on threading unit, procedure finished.	angie_henderson, michele_williams
A31	09/04/2015	Inspect and recharge accumulators	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A28	18/06/2015	Maintenance on milling spindle needed	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A85	09/03/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Saw attachment seal changed, yet hydraulic leak continues.	ethan_adams, michele_williams
A35	07/01/2016	Leak detected in hydraulic line of saw attachment	Ethan Adams noted: Inspection complete; no issues found.	ethan_adams, michele_williams
A91	01/01/2016	Grinding noise from tight gears on saw attachment	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A61	25/05/2015	Accumulators need checking and charging	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A39	16/05/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A24	05/07/2015	Milling spindle requires repair	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A54	15/03/2015	Repair work needed on milling spindle	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A19	11/08/2015	Accumulators need checking and charging	Nathan Maldonado noted: Saw attachment seal changed, yet hydraulic leak continues	nathan_maldonado
A80	03/05/2015	Maintenance on milling spindle needed	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A87	31/08/2015	Turret A and B are leaking	Cristian Santos noted: Fixed and tested.	cristian_santos
A26	14/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A38	22/02/2015	Saw attachment is leaking hydraulics	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A46	09/01/2016	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A68	25/04/2015	Power supply failure detected	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A32	08/12/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A54	24/03/2015	Inspect and recharge accumulators	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A71	26/12/2015	Accumulators need checking and charging	Gina Moore noted: Repair completed.	gina_moore, dylan_miller
A2	08/05/2015	Leaks found at turrets A and B	Michele Williams noted: Installed new saw attachment seal; leakage remains.	michele_williams
A43	28/05/2015	Leaks found at turrets A and B	Angie Henderson noted: Removed turrets to clean off metal shavings.	angie_henderson, michele_williams
A25	26/10/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Completed rewiring of the threading unit.	gina_moore, dylan_miller
A79	22/01/2015	Hydraulic line leak on side B	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A5	07/02/2015	Repair work needed on milling spindle	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A86	27/10/2015	Turret A and B are leaking	Angie Henderson noted: Detail not recorded.	angie_henderson, michele_williams
A60	12/03/2015	Hydraulic fluid leak at saw attachment	Michele Williams noted: System checked and accumulators charged.	michele_williams
A47	03/01/2016	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A4	11/04/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Check performed; everything looks fine.	nathan_maldonado
A7	14/05/2015	Spindle indexing error with overfeed	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A83	12/12/2015	Inspect and recharge accumulators	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A55	28/05/2015	Hydraulic line leak on side B	Cristian Santos noted: Reviewed; system operating normally.	cristian_santos
A68	18/02/2015	Leaks found at turrets A and B	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A68	19/11/2015	Inspect and recharge accumulators	Gina Moore noted: Inspection complete; no issues found.	gina_moore, dylan_miller
A81	15/06/2015	Leak in side B hydraulic line	Cristian Santos noted: Check performed; everything looks fine.	cristian_santos
A78	01/11/2015	Unit lost electrical power	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A27	30/07/2015	Turret A and B are leaking	Ethan Adams noted: No further details.	ethan_adams, michele_williams
A81	03/10/2015	Machine is unpowered	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A59	20/07/2015	Spindle indexing error with overfeed	Gina Moore noted: Maintenance action successful.	gina_moore, dylan_miller
A18	01/05/2015	Milling spindle requires repair	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A88	26/11/2015	Machine is unpowered	Gina Moore noted: Seal on saw attachment replaced, but leak persists.	gina_moore, dylan_miller
A98	24/01/2015	Turret sections A & B showing leaks	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A45	30/05/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A50	27/03/2015	Turret A and B are leaking	Michele Williams noted: Repair completed.	michele_williams
A75	12/07/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: Repair completed.	nathan_maldonado
A30	13/01/2016	Accumulator inspection and charging required	Nathan Maldonado noted: Installed new saw attachment seal; leakage remains.	nathan_maldonado
A40	27/11/2015	Spindle fails to index, overfeeding	Gina Moore noted: Threading unit rewired; job completed.	gina_moore, dylan_miller
A93	16/07/2015	Accumulator inspection and charging required	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A17	25/10/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A65	02/11/2015	Indexing issue causing overfeed on spindle	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A48	04/12/2015	Accumulators need checking and charging	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A74	17/06/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A59	14/05/2015	Maintenance on milling spindle needed	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A90	25/02/2015	Saw attachment is leaking hydraulics	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A65	19/11/2015	Power supply failure detected	Gina Moore noted: Saw attachment seal changed, yet hydraulic leak continues.	gina_moore, dylan_miller
A1	11/09/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Checked status and recharged accumulators.	nathan_maldonado
A68	13/11/2015	Leak in side B hydraulic line	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A23	19/07/2015	Turret sections A & B showing leaks	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos

A83	04/03/2015	Grinding noise from tight gears on saw attachment	Gina Moore noted: No further details.	gina_moore, dylan_miller
A37	03/11/2015	Indexing issue causing overfeed on spindle	Nathan Maldonado noted: System checked and accumulators charged.	nathan_maldonado
A15	30/04/2015	Turret A and B are leaking	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A49	31/03/2015	Milling spindle requires repair	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A68	18/11/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Rewiring done on threading unit, procedure finished.	gina_moore, dylan_miller
A86	16/02/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A1	10/03/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Completed rewiring of the threading unit.	nathan_maldonado
A51	19/11/2015	Maintenance on milling spindle needed	Gina Moore noted: Removed turrets to clean off metal shavings.	gina_moore, dylan_miller
A11	22/06/2015	Unit lost electrical power	Nathan Maldonado noted: Replaced pendant pin and restarted the machine.	nathan_maldonado
A27	11/03/2015	Accumulator inspection and charging required	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A38	05/12/2015	Spindle fails to index, overfeeding	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A39	11/07/2015	Saw attachment is leaking hydraulics	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A32	01/05/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A97	30/11/2015	Leak detected in hydraulic line of saw attachment	Michele Williams noted: Detail not recorded.	michele_williams
A4	12/05/2015	Leaks found at turrets A and B	Cristian Santos noted: No additional information provided.	cristian_santos
A31	28/09/2015	Leaks found at turrets A and B	Nathan Maldonado noted: Removed turrets to clean off metal shavings.	nathan_maldonado
A35	17/05/2015	Machine is unpowered	Cristian Santos noted: Replaced pendant pin and restarted the machine.	cristian_santos
A52	11/06/2015	Leak in side B hydraulic line	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A51	17/08/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A8	20/09/2015	Machine is unpowered	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A98	04/07/2015	Turret A and B are leaking	Michele Williams noted: Control pendant pin swapped and machine reactivated.	michele_williams
A70	03/10/2015	Hydraulic fluid leak at saw attachment	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A8	23/02/2015	Indexing issue causing overfeed on spindle	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A52	18/10/2015	Spindle fails to index, overfeeding	Nathan Maldonado noted: Control pendant pin swapped and machine reactivated.	nathan_maldonado
A93	23/08/2015	Leak detected in hydraulic line of saw attachment	Gina Moore noted: Turrets dismantled and chip debris removed.	gina_moore, dylan_miller
A49	11/09/2015	Leaks found at turrets A and B	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A13	20/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Maintenance action successful.	cristian_santos
A85	27/05/2015	Gears on the saw attachment are too tight and grinding	Gina Moore noted: Control pendant pin swapped and machine reactivated.	gina_moore, dylan_miller
A71	06/03/2015	Power supply failure detected	Ethan Adams noted: Control pendant pin swapped and machine reactivated.	ethan_adams, michele_williams
A33	12/07/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Chips cleared and turrets cleaned.	angie_henderson, michele_williams
A89	24/12/2015	Power supply failure detected	Gina Moore noted: Replaced pendant pin and restarted the machine.	gina_moore, dylan_miller
A14	16/12/2015	Accumulator inspection and charging required	Angie Henderson noted: Threading unit rewired; job completed.	angie_henderson, michele_williams
A20	31/10/2015	Power supply failure detected	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A26	03/01/2016	Accumulators need checking and charging	Cristian Santos noted: Seal on saw attachment replaced, but leak persists.	cristian_santos
A81	12/05/2015	Spindle fails to index, overfeeding	Michele Williams noted: No additional information provided.	michele_williams
A36	04/09/2015	Unit lost electrical power	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A26	22/08/2015	Unit lost electrical power	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues.	michele_williams
A54	14/08/2015	Leaks found at turrets A and B	Gina Moore noted: Chips cleared and turrets cleaned.	gina_moore, dylan_miller
A3	01/02/2015	Power supply failure detected	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A47	02/04/2015	Leaks found at turrets A and B	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A80	06/02/2015	Spindle indexing error with overfeed	Cristian Santos noted: Detail not recorded.	cristian_santos
A30	04/12/2015	Leaks found at turrets A and B	Angie Henderson noted: Seal on saw attachment replaced, but leak persists.	angie_henderson, michele_williams
A87	19/02/2015	Leak detected in hydraulic line of saw attachment	Angie Henderson noted: No further details.	angie_henderson, michele_williams
A33	26/05/2015	Spindle indexing error with overfeed	Nathan Maldonado noted: Maintenance action successful.	nathan_maldonado
A81	20/02/2015	Hydraulic hose on side B is leaking	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A28	31/07/2015	Grinding noise from tight gears on saw attachment	Ethan Adams noted: Repair completed.	ethan_adams, michele_williams
A22	13/01/2016	Accumulators need checking and charging	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A49	20/09/2015	Inspect and recharge accumulators	Michele Williams noted: Seal on saw attachment replaced, but leak persists.	michele_williams
A43	19/11/2015	Turret A and B are leaking	Michele Williams noted: Fixed and tested.	michele_williams
A90	17/01/2015	Unit lost electrical power	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A28	10/12/2015	Spindle fails to index, overfeeding	Cristian Santos noted: Inspection complete; no issues found.	cristian_santos
A5	11/05/2015	Power supply failure detected	Michele Williams noted: Repair completed.	michele_williams
A74	06/02/2015	Leaks found at turrets A and B	Angie Henderson noted: Turrets dismantled and chip debris removed.	angie_henderson, michele_williams
A1	25/01/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: No additional information provided.	michele_williams
A87	18/12/2015	Grinding noise from tight gears on saw attachment	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A32	10/02/2015	Leak in side B hydraulic line	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A4	01/11/2015	Turret A and B are leaking	Ethan Adams noted: Replaced pendant pin and restarted the machine.	ethan_adams, michele_williams
A60	17/10/2015	Spindle indexing error with overfeed	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A17	18/04/2015	Power supply failure detected	Nathan Maldonado noted: Inspection complete; no issues found.	nathan_maldonado
A41	22/01/2015	Maintenance on milling spindle needed	Michele Williams noted: Turrets dismantled and chip debris removed.	michele_williams
A98	19/12/2015	Unit lost electrical power	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A96	30/10/2015	Hydraulic fluid leak at saw attachment	Nathan Maldonado noted: Threading unit rewired; job completed.	nathan_maldonado
A10	19/08/2015	Saw attachment gears are binding and grinding	Michele Williams noted: Fixed and tested.	michele_williams
A15	25/12/2015	Turret sections A & B showing leaks	Angie Henderson noted: Installed new saw attachment seal; leakage remains.	angie_henderson, michele_williams
A82	23/09/2015	Turret A and B are leaking	Ethan Adams noted: Detail not recorded.	ethan_adams, michele_williams
A84	08/11/2015	Leaks found at turrets A and B	Cristian Santos noted: Threading unit rewired; job completed.	cristian_santos
A53	20/06/2015	Maintenance on milling spindle needed	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A9	04/08/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Control pendant pin swapped and machine reactivated.	angie_henderson, michele_williams
A20	31/01/2015	Maintenance on milling spindle needed	Michele Williams noted: Pin in control pendant replaced; system powered up.	michele_williams
A82	08/04/2015	Leak in side B hydraulic line	Gina Moore noted: Check performed; everything looks fine.	gina_moore, dylan_miller

A18	01/10/2015	Accumulators need checking and charging	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A15	12/06/2015	Spindle indexing error with overfeed	Angie Henderson noted: Completed rewiring of the threading unit.	angie_henderson, michele_williams
A12	30/06/2015	Power supply failure detected	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A45	22/06/2015	Inspect and recharge accumulators	Angie Henderson noted: No additional information provided.	angie_henderson, michele_williams
A81	31/03/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: No further details.	nathan_maldonado
A2	11/07/2015	Leak in side B hydraulic line	Michele Williams noted: Saw attachment seal changed, yet hydraulic leak continues	michele_williams
A33	01/10/2015	Accumulators need checking and charging	Ethan Adams noted: No additional information provided.	ethan_adams, michele_williams
A11	05/06/2015	Leak in side B hydraulic line	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams
A71	26/06/2015	Machine is unpowered	Nathan Maldonado noted: No additional information provided.	nathan_maldonado
A33	04/05/2015	Hydraulic line leak on side B	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A92	14/09/2015	Spindle fails to index, overfeeding	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A41	01/11/2015	Turret sections A & B showing leaks	Cristian Santos noted: Turrets dismantled and chip debris removed.	cristian_santos
A40	15/08/2015	Leaks found at turrets A and B	Michele Williams noted: Threading unit rewired; job completed.	michele_williams
A32	16/05/2015	Leak in side B hydraulic line	Gina Moore noted: Detail not recorded.	gina_moore, dylan_miller
A93	13/09/2015	Unit lost electrical power	Cristian Santos noted: Rewiring done on threading unit, procedure finished.	cristian_santos
A94	07/12/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Maintenance action successful.	ethan_adams, michele_williams
A39	11/05/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Chips cleared and turrets cleaned.	nathan_maldonado
A73	27/06/2015	Machine is unpowered	Ethan Adams noted: Pin in control pendant replaced; system powered up.	ethan_adams, michele_williams
A26	09/11/2015	Accumulator inspection and charging required	Michele Williams noted: No additional information provided.	michele_williams
A20	20/09/2015	Saw attachment is leaking hydraulics	Gina Moore noted: Checked status and recharged accumulators.	gina_moore, dylan_miller
A55	30/07/2015	Inspect and recharge accumulators	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A15	11/06/2015	Leak detected in hydraulic line of saw attachment	Cristian Santos noted: Maintenance action successful.	cristian_santos
A25	11/08/2015	Accumulators need checking and charging	Michele Williams noted: Removed turrets to clean off metal shavings.	michele_williams
A14	22/05/2015	Accumulator inspection and charging required	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A40	31/10/2015	Hydraulic fluid leak at saw attachment	Angie Henderson noted: Performed inspection and accumulator charging.	angie_henderson, michele_williams
A53	19/08/2015	Saw attachment gears are binding and grinding	Angie Henderson noted: Repair completed.	angie_henderson, michele_williams
A38	12/07/2015	Accumulator inspection and charging required	Michele Williams noted: Detail not recorded.	michele_williams
A49	03/04/2015	Gears on the saw attachment are too tight and grinding	Ethan Adams noted: Checked status and recharged accumulators.	ethan_adams, michele_williams
A26	01/11/2015	Accumulators need checking and charging	Ethan Adams noted: Seal on saw attachment replaced, but leak persists.	ethan_adams, michele_williams
A43	05/05/2015	Machine is unpowered	Gina Moore noted: System checked and accumulators charged.	gina_moore, dylan_miller
A10	01/11/2015	Grinding noise from tight gears on saw attachment	Michele Williams noted: System checked and accumulators charged.	michele_williams
A23	09/03/2015	Power supply failure detected	Ethan Adams noted: Removed turrets to clean off metal shavings.	ethan_adams, michele_williams
A94	22/08/2015	Accumulator inspection and charging required	Ethan Adams noted: Completed rewiring of the threading unit.	ethan_adams, michele_williams
A9	28/04/2015	Turret A and B are leaking	Gina Moore noted: Installed new saw attachment seal; leakage remains.	gina_moore, dylan_miller
A1	25/01/2015	Hydraulic fluid leak at saw attachment	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A74	15/12/2015	Hydraulic hose on side B is leaking	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A64	09/09/2015	Machine is unpowered	Nathan Maldonado noted: Detail not recorded.	nathan_maldonado
A73	16/06/2015	Unit lost electrical power	Michele Williams noted: Check performed; everything looks fine.	michele_williams
A32	05/03/2015	Gears on the saw attachment are too tight and grinding	Nathan Maldonado noted: Rewiring done on threading unit, procedure finished.	nathan_maldonado
A44	22/03/2015	Turret sections A & B showing leaks	Cristian Santos noted: Pin in control pendant replaced; system powered up.	cristian_santos
A86	28/05/2015	Leak detected in hydraulic line of saw attachment	Nathan Maldonado noted: Reviewed; system operating normally.	nathan_maldonado
A27	24/02/2015	Indexing issue causing overfeed on spindle	Michele Williams noted: Fixed and tested.	michele_williams
A33	04/09/2015	Grinding noise from tight gears on saw attachment	Nathan Maldonado noted: Pin in control pendant replaced; system powered up.	nathan_maldonado
A93	27/07/2015	Gears on the saw attachment are too tight and grinding	Angie Henderson noted: Pin in control pendant replaced; system powered up.	angie_henderson, michele_williams
A85	25/05/2015	Maintenance on milling spindle needed	Cristian Santos noted: System checked and accumulators charged.	cristian_santos
A64	26/04/2015	Accumulator inspection and charging required	Cristian Santos noted: Control pendant pin swapped and machine reactivated.	cristian_santos
A62	23/05/2015	Spindle indexing error with overfeed	Michele Williams noted: Reviewed; system operating normally.	michele_williams
A38	27/08/2015	Accumulators need checking and charging	Cristian Santos noted: Completed rewiring of the threading unit.	cristian_santos
A94	05/12/2015	Leak in side B hydraulic line	Michele Williams noted: Checked status and recharged accumulators.	michele_williams
A84	18/01/2015	Milling spindle requires repair	Ethan Adams noted: Chips cleared and turrets cleaned.	ethan_adams, michele_williams
A3	29/07/2015	Accumulators need checking and charging	Gina Moore noted: Pin in control pendant replaced; system powered up.	gina_moore, dylan_miller
A92	30/11/2015	Leaks found at turrets A and B	Angie Henderson noted: Check performed; everything looks fine.	angie_henderson, michele_williams