

 C86
  C79
  C62
 RVL-CPU-30 and earlier boards utilised capacitors instead of the V1-V3 varistors. Knowing the value of either is trivial for completing a safe replacement of the component video circuitry.

Sheet: /		
File: miniRGBii.sch		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. kicad (5.1.5-0-10_14)		Id: 1/1