









TABLE OF CONTENTS:

- 1. CONTENTS
- 2. BATTERY
- 3. POWER
- 4. MICROCONTROLLER
- 5. MOTOR DRIVER





PAGE 1 IN AZ2117-ADJ DATASHEET:
 $V_{OUT} = V_{REF} * (1 + R2 / R1) + I_{ADJ} * R2$
 FOR 3V3, R2=7k5, R1=4k7
 FOR 1V8, R2=2k0, R1=4k7



Sheet: /power/
 File: power.sch

Title:


Size: A4

Date:

KiCad E.D.A. kicad 5.0.1

Rev:

Id: 2/5



○ NPTH1
2mm

○ NPTH2
2mm

○ NPTH3
2mm

○ NPTH4
2mm

○ NPTH5
2mm

○ NPTH6
2mm

○ NPTH7
2mm

○ NPTH8
2mm

MOTOR CONNECTIONS


Sheet: /driver/
File: driver.sch





Title:

Size: A4
KiCad E.D.A. kicad 5.0.1

Date:

Rev:
Id: 3/5





Sheet: /battery/
File: battery.sch

Title:

Size: A4
KiCad E.D.A. kicad 5.0.1

Date:

Rev:
Id: 5/5