


NOT NECESSARY TO LEVEL SHIFT
INT
FSYNC not needed
AUX_CL
AUX_DA not needed

Technically, MISO does not need to be level shifted, but it's on the same pin as SDA



Decoupling considerations:
See AN0002.0: EFM32 and EZR32 Wireless MCU Series 0 Hardware Design Considerations

