



ENSURE ALL SHARP EDGES ARE BROKEN 0.03 MAX
WELD AS NEEDED

5	43a41500-3946	See Drawing		4
4	43a41500-3945	See Drawing		1
3	43a41500-3944	See Drawing		2
2	43a41500-3943	See Drawing		1
1	43a41500-3947	See Drawing		4
ITEM	PART NUMBER	STOCK SIZE	DESCRIPTION	QTY

TOLERANCES UNLESS OTHERWISE SPECIFIED							
</							