




TITLE: CPU		REV: 1.0
	Company: Denisov Foundation Limited	Sheet: 1/1
	Date: 2024-09-04	Drawn By: LittleBuster







TITLE: Relays_10A_1		REV: 1.0
	Company: Denisov Foundation Limited	Sheet: 1/1
	Date: 2024-09-04	Drawn By: LittleBuster




TITLE: Inputs_1		REV: 1.0
	Company: Your Company	Sheet: 1/1
	Date: 2024-09-05 Drawn By: denisovs21	











TITLE: Peripheral		REV: 1.0
	Company: Denisov Foundation Limited	Sheet: 1/1
	Date: 2024-09-05	Drawn By: LittleBuster




TITLE: GSM		REV: 1.0
		Sheet: 1/1
Date: 2024-09-12		Drawn By: LittleBuster




TITLE: Relays_10A_2		REV: 1.0
	Company: Denisov Foundation Limited	Sheet: 1/1
	Date: 2024-09-19 Drawn By: LittleBuster	



TITLE: Relays_16A		REV: 1.0
	Company: Denisov Foundation Limited	Sheet: 1/1
	Date: 2024-09-19 Drawn By: LittleBuster	



TITLE: Inputs_2		REV: 1.0
	Company: Denisov Foundation Limited	Sheet: 1/1
	Date: 2024-09-19 Drawn By: LittleBuster	



TITLE: Ethernet		REV: 1.0
		Sheet: 1/1
	Company: Your Company	Date: 2024-09-23 Drawn By: denisovs21