




C1,C6,C5 needs to be close enough to both chips



C2 should be close to both LDO out and U1 VDD



Mounting Mounting



Think3dPrint3d and Escher3d

Sheet: /
File: FilamentMonitor.sch

Title: Filament Monitor

Size: A4 Date: 2018-10-28

KiCad E.D.A. kicad (5.0.0)

Rev: v2.0

Id: 1/1