

arduino  
pinhole

C4 C3  
( ) ( )

J5

1. meter

servo

serial

XTAL2

J4

R2  
rst  
+

u1n2003

J6

atmega

pwr in  
pwr sw

stepper

rst cntr

shutter

ready led

status led

J1

R4  
R3

R6  
R5

power led

R1

U2

U2