

atmega
pinhole

C4 C3
() ()

J5

1. meter

servo

serial

R2

rst
+

XTAL2

J4

J6

u1n2003

atmega

pwr in
pwr sw



U2

status led

J1

shutter

ready led



stepper

rst
+

rst cntr



R1

power led

