




1. Table of Contents (This Page)


Created on Thu Jan 21 09:01:36 2016


- 2. top
- 3. bottom
- 4. outline
- 5. plated-drill
- 6. unplated-drill
- 7. componentmask
- 8. soldermask
- 9. topsilk
- 10. bottomsilk
- 11. toppaste
- 12. topassembly
- 13. bottomassembly
- 14. fab

































There are 7 different drill sizes used in this

| Symbol | Diam. (Inch) | Count | Plated? |
|--------|--------------|-------|---------|
| Y | 0.020 | 34 | YES |
| + | 0.038 | 4 | YES |
| x | 0.039 | 3 | NO |
| o | 0.039 | 3 | YES |
| □ | 0.048 | 6 | YES |
| ▽ | 0.060 | 5 | YES |
| ⊕ | 0.068 | 2 | YES |
| ⊗ | 0.129 | 4 | YES |

Title: (unknown) - Fabrication Drawing
Author: Nathan D. Holmes
Date: Thu 21 Jan 2016 04:01:36 PM GMT



Board outline is the centerline of this path