



## LISTA DE GRANDES REPAROS E GRANDES ALTERAÇÕES

| Responsável<br>Owner<br>Manutenção | Formulário  |
|------------------------------------|---|
| Código<br>Code<br>0000             | Classificação<br>Classification Level<br>DI - Domínio Interno |
| Revisão<br>Revision<br>03          | Data<br>Date<br>01/03/2019                                    |

MODELO: 525B

S/N: 525B-0278

MATRÍCULA: PR-ADL

| STC   | CST  | DESCRIPTION  | ACCEPTED<br>DATE   | ICA NUMBER  | ICA<br>REVISION       | TASK NUMBER<br>ON<br>CAMP/MYCOMP | INSPECTION CODE<br>RELATED                                  | INTERVAL                                | COMMENTS |
|---|--|--|--------------------|---|-----------------------|----------------------------------|---|---|----------|
| CESSNA REPAIR<br>DEFINITION REPORT<br>NUMBER S-525B-<br>0278/02 RD, REPAIR OF<br>LOWER CENTER R/H<br>FITTING P/N: 6311312-<br>17 AND FAA FORM<br>8100-9 DATED<br>07/27/2012 | -  | <ul style="list-style-type: none"><li>REMOVED AND REPLACED CABIN FORWARD B.L 0.0 STRINGER P/N: 6311336-13 I.A.W CESSNA DRAWING NO. 6311375.</li><li>REMOVED AND REPLACED CABIN AFT B.L 0.0 STRINGER P/N: 6311336-14 I.A.W CESSNA DRAWING NO. 6311320.</li><li>REMOVED AND REPLACED FORWARD CABIN BELLY SKIN ASSY. P/N: 6311136-1 I.A.W CESSNA DRAWING NUMBERS: 6311172, 6311171, 6311184, 6311182, 6311189, 6311190, 6311172, 6311171, CESSNA REPAIR DEFINITION REPORT NUMBERS S-525B-0278/01RD DATED 06/16/2012 AND FAA FORM 8100-9 DATED 07/27/2012.</li><li>ACCOMPLISHED CESSNA REPAIR DEFINITION REPORT NUMBER S-525B-0278/02 RD, REPAIR OF LOWER CENTER R/H FITTING P/N: 6311312-17 AND FAA FORM 8100-9 DATED 07/27/2012.</li></ul> | July 31,<br>2012   | N/A   | -                     | N/A                              | There is no<br>maintenance/inspection<br>task for this ICA. | N/A                                     | N/A      |
| MODIFIED CABIN<br>PASSENGER TO<br>AEROMEDICAL<br>TRANSPORT<br>SUPPLEMENTAL TYPE<br>CERTIFICATE Nº<br>2014503-14, RITTER<br>CONSULTORIA AND<br>PROJETOS LTDA.                | TECHNICAL<br>DOCUMENTATION<br>MASTER LIST Nº<br>301-2-CST, DO<br>ENG. FREDERICO<br>J. RITTER REV. N<br>DATA 03/07/2020 | <ul style="list-style-type: none"><li>PERFORMED ELECTROMAGNETIC INTERFERENCE TEST IN SOIL (EMI) - I.A.W. REL.: 301-MNA001 ALL TESTS SATISFACTORY.</li><li>PERFORM INSTALLED LIMITER P/N AN140 S/N N/A (NEW), SWITCH P/N MS24658-220 S/N N/A (NEW), COVER P/N MS5043-28DA S/N N/A (NEW), CIRCUIT BK P/N 7277-2-5 S/N N/A (NEW), CONNECTOR P/N MS3100R28-10S S/N N/A (NEW), I.A.W. PACKING LIST Nº 1508996 ORGANIZATION SOUTHERN CROSS AVIATION - I.A.W. AEROMEDICAL KIT INSTALLATION MANUAL Nº 301-MNA003 REV.: H DATED 26/JULY/2020.</li></ul>   | August<br>07, 2020 | INSTRUCTIONS<br>FOR CONTINUED<br>AIRWORTHINESS<br>(ICA) Nº 301-14-<br>CST | REV. A<br>16/06/2020. | N/A                              | N/<br>N/A   | 100 HOURS/12<br>MONTHS AND 60<br>MONTHS | N/A      |

Aeronave PR-ADL não possui mais nenhum Grande Reparo e ou Grande Alteração até a presente data.

São Paulo, 19 de Outubro de 2022.

Gabriel Barreto Silva

Gerente de Manutenção

Voar Aviation Tâxi Aéreo e Manutenção LTDA