


Buck voltage converter




Adjust output voltage to 5V with this pot

GND already connected


Rotary Encoder





Don't forget this!



CNC Arduino shield
(Place onto Arduino Uno)



Limit switch



4x20 LCD screen with I2C adapter



12 V input

NEMA17 Motor X

Y

Z

A

