








Ethernet X 8





8 x 1G Ethernet







```
LED_MODE[1:0]= 0 1
```















K4B2G1646F-BYMA Sumasung 2Gb FBGA96
2 SCB13H2G1608F-09N Unilic 2Gb FBGA96
3 NT5CC128M16JR-EK Nanya 2Gb TFBA96
4 IS43TR16128B-125KBLI ISSI 2Gb FBGA96








1G Serdes x 4



TRX2-2 b869s2-0030-y018



10G Serdes x 2



Title	<Title>	Rev	<RevCode>
Size	A3	Document Number	<Doc>
Date:	Monday, December 04, 2023	Sheet	1 of 1