



A circuit diagram showing an OR gate labeled 'OR R14'. The inputs are labeled 'PWM2' and 'PWM1'. The output of the OR gate is connected to a ground symbol labeled 'GND'.

Driving PWM signals must be provide BEFORE power supply in order to avoid unexpected transistors behaviours.

Id: 1/1