


5S Visual Audit – Before and After

Rev. 0

Date: 25.04.2025

Location: Restplate Rack – production floor, hall 4.

BEFORE



Before:
Unstandardized labeling format on the rack. Each material is labeled differently, and often several labels refer to the same compartment.

AFTER



After:
A color-coding system was implemented for material groups. A unified visual format was applied to all racks. Where necessary, material thickness ranges were specified.