



LAPIS Motion Sensor rev 1



I2C Slave Addr

	JP1(A)	JP2(M)
0	0x6A	0x1C
1	0x6B	0x1E