


Note: Strain Gauge connected
across screw terminals




Sheet: /ampA0/sensora0/
File: sensor.sch


Title:


Size: A4
KiCad E.D.A. kicad (5.1.8)-1


Date:


Rev:
Id: 3/41












Note: Strain Gauge connected
across screw terminals




Sheet: /ampB0/sensorb2/
File: sensor.sch


Title:

Size: A4 Date:
KiCad E.D.A. kicad (5.1.8)-1

Rev:
Id: 9/41



Note: Strain Gauge connected
across screw terminals




Sheet: /ampC0/sensorc0/
File: sensor.sch


Title:


Size: A4
KiCad E.D.A. kicad (5.1.8)-1


Date:


Rev:
Id: 11/41


















Note: Strain Gauge connected
across screw terminals





Sheet: /ampA1/sensora0/
File: sensor.sch


Title:


Size: A4 Date:
KiCad E.D.A. kicad (5.1.8)-1


Rev:
Id: 19/41
















































Note: Strain Gauge connected
across screw terminals



Sheet: /ampA2/sensora2/
File: sensor.sch

Title:

Size: A4
KiCad E.D.A. kicad (5.1.8)-1

Date:

Rev:
Id: 37/41

