



v1.3
adjust the position of the vibration sensor;
replace the main controller with an 8-pin one;

v1.3 fix
add power path
replace the sensor.

MagiClick



CC BY-NC-SA 4.0

Size: A4

Date: 2024-03-20

Rev:

1.3 fix