



Pin 2 on H4 is used for an open collector to ground for frame advance
H2 is for an LDR to control the display LCD brightness.
The battery sensor is to detect the battery voltage. It does not power the device.





TITLE: External Wiring		REV: 1.0
	Company: Nohr Photo	Sheet: 1/1
	Date: 2020-09-08	Drawn By: MartinNohr