

A

B

C

D


A

B

C

D

Verify pinouts and ordering for sound sensor and servo motor



IDK which is ground and which isn't try switching it around before pcb and seeing if warning comes

Make sure to make overlay square for the boost converter

Title		
Size	Number	Revision
A4		
Date:	1/11/2023	Sheet of
File:	PowerSupply.SchDoc	Drawn By: