

Contoso Safety 360

<input checked="" type="checkbox"/> Hazardous Condition	<input type="checkbox"/> At Risk Behavior	<input type="checkbox"/> Safety Suggestion	<input checked="" type="checkbox"/> Safety Recognition
---	---	--	--

<input checked="" type="checkbox"/> Equipment	<input type="checkbox"/> Material Handling
<input type="checkbox"/> Slips, Trips, Falls	<input checked="" type="checkbox"/> Spill, Release, Environmental
<input type="checkbox"/> Electrical	<input type="checkbox"/> PPE
<input type="checkbox"/> Ergonomics	<input type="checkbox"/> Other Safety

<input checked="" type="checkbox"/> Significant	<input type="checkbox"/> Not Significant
---	--

Findings: Control room temperatures vary significantly during the normal hours of operations.

Suggested Solutions: Find out the root causes quickly and address the problems

Submitter: Ben van Zyl
Department: Operations Date: January 5, 2022

Owner: <u>Anisa Meta</u>	
Solutions: <u>Run equipment maintenance test set ab01</u>	
Target Date: <u>July 10, 2021</u>	Close Date: <u>January 11, 2022</u>
Submitter Approval: <u>Yes</u>	