




<https://www.hackster.io/hardikrathod/pir-motion-sensor-with-raspberry-pi-415c04>





Connection is on GPIO pin 25(GREEN). Straight connection, no resistors needed. Other connections are 5V(RED) in and ground(BLACK).