




Other Handyman Repairs




Driveway widened with 11" deep gravel




Old deck skirting replaced



Other Handyman Repairs




Weatherstripping installed around door





Fire escape landing boards replaced



Other Handyman Repairs



Weakened fire escape step boards replaced




Fabric and crushed brick installed after weeding



Other Handyman Repairs



Fence raised by 17" and solidified



Basement outlet secured and covered