




U1 alternatives:
MX29F800CB (Macronix)
29F800BA (Fujitsu)



Adress lines pull-ups



AMIGA



PCB solder pins ED90325-ND(Digikey) 9081-0-00-15-00-00-08-0'

JP1 and JP2 configuration:
1-2 (Default) Normal configuration. Also required for flashing with TL866
2-3 BYTE and A17 swap due to OOPS bug of Rev 5 mainboards